

ESTIMATE TO REPAIR

VEHICLE NO. : SBV 8887 R
MAKE : TOYOTA
MODEL : CAMRY 2.4G A
YEAR : 2009
CHASSIS NO : ACV403189250

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 20-Apr-18
DATE OF ACCIDENT : 19-Apr-18
THIRD PARTY REF : SLR 1579 D / AXA INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper			<i>BT 1/2M</i> \$	989.70 ✓
1 pc	Front Bumper Reinforcement			<i>B</i> \$	568.70 ✓
2 pcs	Front Bumper Retainer		\$ 88.40	<i>N/S CM</i> \$	176.80 ✓
10 pcs	Front Bumper Clips		\$ 4.90	<i>M</i> \$	49.00 ✓
1 pc	N/S Front Bumper Fog Lamp			<i>Bro</i> \$	358.70 ✓
1 pc	N/S Front Bumper Fog Lamp Cover			<i>Mit</i> \$	104.80 ✓
1 pc	Front Grille			\$	457.70 ✓
1 pc	N/S Headlamp			<i>Bu CM</i> \$	1,057.61 ✓
1 pc	N/S Front Fender			\$	568.70 ✓
1 pc	N/S Front Fender Under-Shield			<i>CM</i> \$	189.80 ✓
				\$	4,521.51
	Less 25%			\$	1,130.38
				\$	3,391.13
1 pc	Front Number Plate	S.Nett		<i>Det</i> \$	40.00 ✓
	To putty & spray painting.			<i>600</i> \$	900.00
	To check front wiring and focus headlights.			<i>200</i> \$	30.00
	To anti-rust.			<i>300</i> \$	50.00
	Labour Charges.			<i>400</i> \$	500.00
					<i>Not withark</i>
					<i>612m 87</i>
					<i>Putty After Paint</i>
					<i>4 days</i>
TG-RA/-	TOTAL				\$ 4,911.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date: Lim Tan Motor Pte Ltd