

REPAIR ESTIMATE

VEHICLE NO : SHD 3606S

DATE : 24.04.2018

MAKE :

MODEL : TOYOTA PRIUS

PbyP
AXA
Like

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR BUMPER <i>x repair</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT ?			\$ 318.80
REAR BUMPER UNDER COVER <i>x</i>			\$ 552.60
REAR BUMPER SIDE RETAINER ?			\$ 112.70
REAR BUMPER SPONGE <i>x</i>			\$ 143.40
REAR BUMPER CLIPS <i>x</i>			\$ 22.00
SUB TOTAL			\$ 1,608.10
LESS 25%			\$ 402.03
DISCOUNTED TOTAL			\$ 1,206.08
REAR BUMPER REVERSE SENSOR <i>x</i>			\$ 135.70
REAR BUMPER RUBBER MAT <i>/</i>			\$ 50.00
			\$ 185.70
LABOUR CHARGE			
Panel Beating			\$ 250.00 ¹⁰⁰
Spray Painting Charge			\$ 250.00 ²⁰⁰
Wiring Charge			\$ 50.00 <i>x</i>
Remove/Refix Reverse Sensor			\$ 120.00 <i>x</i>
TOTAL LABOUR			\$ 670.00
ESTIMATE TOTAL			\$ 2,061.78

NETT
NETT

Kalvin 11/11/18
25/4/18 1100hrs
2 Pys
P/P
After Repair photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.