

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3052841701	Date of Loss:	20/04/2018
Vehicle Reg. No.:	YN8528Y	Driveable?	
Driver Age/Info:	30 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LE FONG ENGINEERING PTE LTD		
Driver:	CHINNADURAI THIRUNAVUKKARASU		

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)	Vehicle Reg. Date:	23/07/2015
Vehicle Colour:	WHITE	Chassis No:	FEB21EA10210
Engine No:	4P10B73435		
Odometer:	5 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	6

Tan Jhin 97445749
26/4/18 @ 1730
Ex 9550
Revert, Not Authorise
6 days
sure lkk auto.com
hompson Resurvey after repair

Description of Accident/Loss

ON 20/04/2018 @ ABT 1940HRS. I WAS TRAVELLING ALONG AYE(TUAS) ON THE 2ND LANE. WHEN THE VEHICLE B (YN9062S) WHICH IS IN FRONT OF ME SUDDENLY JAMMED HIS BRAKE. AS FOLLOWER, I THEN JAMMED MY BRAKE TOO BUT DUE TO THE ROAD SURFACE WAS WET, MY VEHICLE COULD NOT STOP IN TIME & KNOCKED ONTO THE SAID VEHICLE AT REAR. NO ONE WAS INJURED. THAT'S ALL.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	LKK Auto Consultants hence notify the Repairer of the following:	Amount
Parts	• To resurvey before/after spray painting	7,870.00
Miscellaneous Items	• To display damaged part(s) during resurvey	0.00
Labour	• Parts prices are subject to confirmation	1,860.00
Paintwork Labour	• Third party survey is on a "Without Prejudice" basis	0.00
Towing	• No illegal modification(s) is allowed	0.00
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	0.00
	Acknowledged by Repairer	Gross Total (\$\$)
	Signature:	+ GST 7.00% (\$\$)
	Date:	9,730.00
		681.10
		Nett Amount (\$\$)
		10,411.10

This claim is handled by: JANICE CHANG SIEW YIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 24 Apr 2018)**Parts:** N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for YN8528Y)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt - *20.00 FS
2	1		*FRT BUMPER	0.00	0.00	bt - *600.00 F
3	1		*FRT BUMPER SIDE COVER(RH) (LH)	0.00	0.00	de - *185.00 F
4	1		*FRT CROSSMEMBER	0.00	0.00	? *1,340.00 F
5	1		*FRT GRILLE	0.00	0.00	can - *900.00 F
6	1		*FRT GRILLE EMBLEM	0.00	0.00	ner - *80.00 F
7	1		*FRT GRILLE CANTER LOGO	0.00	0.00	ner - *70.00 F
8	1		*FRT PANEL	0.00	0.00	bt - *1,250.00 F
9	1		*FRT PANEL FUSO LOGO	0.00	0.00	ner - *70.00 F
10	2		*FRT CORNER PANEL LH-wh✓, RH-x	0.00	0.00	*580.00 F
11	1		*FRT HEADLAMP(LH)	0.00	0.00	can - *300.00 F
12	1		*FRT SIGNAL LAMP(LH)	0.00	0.00	ner - *155.00 F
13	1		*FRT HEADLAMP SIDE(LH)	0.00	0.00	? *120.00 F
14	1		*AIRCON HEATER	0.00	0.00	? *2,000.00 F
15	1		*FRT WINDSCREEN RUBBER	0.00	0.00	ner - *200.00 F

F=Franchise part. S=SpcNett.

Total Parts (S\$)**7,870.00**

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING	New	30.00
2	TO REMOVE & FIX FRT WINDSCREEN	New <i>photo</i>	100.00
3	TO REMOVE & FIX DASHBOARD	New <i>photo</i>	180.00
4	TO KNOCK,WELD,REMOVE & FIX ABOVE PARTS	New <i>Gov</i>	750.00
5	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New <i>Gov</i>	800.00
Gross Labour Cost (S\$)			1,860.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >