

Surveyor: Tantikh

DOI: 26/4/18

Date / Time: 26/4/18

Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No. : SFL 3220T

Claim No. : _____

Name of Insured : KIM MYUN TAI

Policy No. : 8-VU007524-mvlt-Red4

Insured Tel No. : _____ HP: _____

Make / Model : TOYOTA

Excess Sec II :SS _____ D.O.A: 20/7/18

Place of Accident : BKT TANAH RO

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO. Driver Name / Age : PARK EUN KEE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : _____ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SJT 6447G → _____ → _____



INSRS: Sng Ah Tee
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
<u>26/4/18</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OE:	
	After call ltr to OE:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OE:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 26/4/18 Sent By: AM

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: SS _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: 14/11/19 Confirm with: Sharon Email Call

Final Liability: 50% (Agreed / Assessed) BOLA S/N No.: NIL If NO or B 28, Ass. Lia: _____

Repair Cost: (w/hm) SS 930.90 DND HIR PARKED TP

Loss of Rental (LOR): SS - (_____ days)

Loss of Use (LOU): SS 240.00 (5 120 x 2 days)

Loss of Income (LOI): SS - (5 x _____ days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: SS 2.00

Medical: SS -

Disbursement: SS - (e.g. Tow/Independent)

Legal Cost: SS -

Total: SS 1172.90 Global Sum SS: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: SS 1172.90 Name 1: Sng Ah Tee Motor & Panel Service Pte Ltd

Payee 2: (Strike if N.A.) SS Name 2: _____

Payee 3: (Strike if N.A.) SS Name 3: _____

COPY SENT 4/12/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE18007628/T1eb3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 25-04-2018	
		Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKL 3220T	Veh. Inspected	SJT 6447G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	25/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/02/2018	Inspection Date	24/04/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/QBE18007628/T1eb3

Date: 25.04.2018

The Motor Claims Department
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJT6447G

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24.04.2018 at the premises of M/s Sng Ah Tee Motor & Panel Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	9,497.50
Revised Estimate Amount	: S\$	870.00
"Check" Items Amount	: S\$	142.50
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003764

QBE INSURANCE (SINGAPORE) PTE LTD

1 RAFFLES QUAY
#29-10 SOUTH TOWER
SINGAPORE 048583
ATTENTION :
CONTACT : 62246633

FAX NO: 65345356

DATE : 24/04/2018
ACCIDENT DATE : 20/02/2018
VEHICLE NO : SJT6447G
CHASSIS/ENG.NO :
VEHICLE MODEL : TOYOTA ALPHARD
CLAIM NO :
POLICY NO :
REMARK : 6447 QBE TP AGGT
SKL3220T

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	600.00	25	450.00	de 450.00 ✓
2	2	PC	REAR BUMPER SIDE RETAINER	95.00	25	71.25	h 142.50 X
3	4	PC	REAR BUMPER SENSOR	535.00	25	401.25	X 1,605.00
4	1	PC	REAR BUMPER REFLECTOR (LH)	60.00	25	45.00	X 45.00
5	1	PC	REAR BUMPER TOP APRON (LH)	200.00	25	150.00	X 150.00
6	1	PC	REAR TAILGATE	1,870.00	25	1,402.50	✓ 1,402.50
7	1	PC	REAR TAILGATE "ALPHARD" LOGO	80.00	25	60.00	X 60.00
8	1	PC	REAR TAILGATE OUTER GARNISH	1,970.00	25	1,477.50	m X 1,477.50
9	1	PC	REAR TAILGATE EMBLEM	90.00	25	67.50	X 67.50
10	1	PC	REAR TAILGATE LAMP(LH)(INNER)	270.00	25	202.50	X 202.50
11	1	PC	REAR TAILGATE LAMP(LH)(OUTER)	495.00	25	371.25	X 371.25
12	1	PC	REAR TAILGATE INNER TRIM	755.00	25	566.25	X 566.25
13	1	PC	REAR END PANEL TOP GARNISH	175.00	25	131.25	X 131.25
14	1	PC	REAR END PANEL	915.00	25	686.25	X 686.25
-----							SUB-TOTAL: 7,357.50
** SPECIAL NETT PRICE **							
1	1	PC	REAR WINDSCREEN SEALANT	40.00		40.00	✓ 40.00 X
-----							SUB-TOTAL 40.00
** WORK LABOUR **							
			TO CHECK WIRING			150.00	20 150.00

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003764

QBE INSURANCE (SINGAPORE) PTE LTD

1 RAFFLES QUAY
#29-10 SOUTH TOWER
SINGAPORE 048583
ATTENTION:
CONTACT: 62246633

FAX NO: 65345356

DATE : 24/04/2018
ACCIDENT DATE : 20/02/2018
VEHICLE NO : SJT6447G
CHASSIS/ENG.NO :
VEHICLE MODEL : TOYOTA ALPHARD
CLAIM NO :
POLICY NO :
REMARK : 6447 QBE TP AGGT
SKL3220T

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO REMOVE & FIX REAR WINDSCREEN	150.00		150.00	150.00
			TO APPLY ANTI RUST COATING	150.00		150.00	150.00
			TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	800.00		200	800.00
			TO PUTTY RESPRAY PAINTING ON RR BUMPER, RR BUMPER TOP APRON(LH),RR TAILGATE,RR END PANEL & AFFECTED AREAS	850.00		200	850.00
				0.00			0.00
				0.00			0.00
SUB-TOTAL							2,100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
'wp'
24/4/18 @ 1720
02 days
Resurvey before after repair.
Sun @ lkk auto.con
* Rear tailgate damage not consistent
to accident, old damage

JOYCE

PAGE: 2 of 2

SUB-TOTAL : S\$ 9,497.50
ADD 7% GST. S\$ 664.83
GRAND TOTAL : S\$ 10,162.33

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003764

QBE INSURANCE (SINGAPORE) PTE LTD

1 RAFFLES QUAY
 #29-10 SOUTH TOWER
 SINGAPORE 048583
 ATTENTION :
 CONTACT : 62246633

FAX NO: 65345356

DATE : 24/04/2018
 ACCIDENT DATE : 20/02/2018
 VEHICLE NO : SJT6447G
 CHASSIS/ENG.NO :
 VEHICLE MODEL : TOYOTA ALPHARD
 CLAIM NO :
 POLICY NO :
 REMARK : 6447 QBE TP AGGT
 SKL3220T

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	600.00	25	450.00	de ✓ 450.00 ✓
2	2	PC	REAR BUMPER SIDE RETAINER	95.00	25	71.25	? 142.50
3	4	PC	REAR BUMPER SENSOR	535.00	25	401.25	✗ 1,605.00
4	1	PC	REAR BUMPER REFLECTOR (LH)	60.00	25	45.00	✗ 45.00
5	1	PC	REAR BUMPER TOP APRON (LH)	200.00	25	150.00	✗ 150.00
6	1	PC	REAR TAILGATE	1,870.00	25	1,402.50	✗ 1,402.50
7	1	PC	REAR TAILGATE "ALPHARD" LOGO	80.00	25	60.00	✗ 60.00
8	1	PC	REAR TAILGATE OUTER GARNISH	1,970.00	25	1,477.50	✗ 1,477.50
9	1	PC	REAR TAILGATE EMBLEM	90.00	25	67.50	✗ 67.50
10	1	PC	REAR TAILGATE LAMP(LH)(INNER)	270.00	25	202.50	✗ 202.50
11	1	PC	REAR TAILGATE LAMP(LH)(OUTER)	495.00	25	371.25	✗ 371.25
12	1	PC	REAR TAILGATE INNER TRIM	755.00	25	566.25	✗ 566.25
13	1	PC	REAR END PANEL TOP GARNISH	175.00	25	131.25	✗ 131.25
14	1	PC	REAR END PANEL	915.00	25	686.25	✗ 686.25

SUB-TOTAL:							7,357.50
<i>4000</i>							
** SPECIAL NETT PRICE **							
1	1	PC	REAR WINDSCREEN SEALANT	40.00		40.00	✗ 40.00

SUB-TOTAL							40.00
** WORK LABOUR **							
TO CHECK WIRING							150.00
							<i>20</i> 150.00

JOYCE

PAGE: 1 of 2

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003764

QBE INSURANCE (SINGAPORE) PTE LTD

1 RAFFLES QUAY
 #29-10 SOUTH TOWER
 SINGAPORE 048583
 ATTENTION:
 CONTACT: 62246633

FAX NO: 65345356

DATE: 24/04/2018
 ACCIDENT DATE: 20/02/2018
 VEHICLE NO: SJT6447G
 CHASSIS/ENG.NO:
 VEHICLE MODEL: TOYOTA ALPHARD
 CLAIM NO:
 POLICY NO:
 REMARK: 6447 QBE TP AGGT SKL3220T

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO REMOVE & FIX REAR WINDSCREEN	150.00		X	150.00
			TO APPLY ANTI RUST COATING	150.00		X	150.00
			TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	800.00		200	800.00
			TO PUTTY RESPRAY PAINTING ON RR BUMPER, RR BUMPER TOP APRON(LH),RR TAILGATE,RR END PANEL & AFFECTED AREAS	850.00		200	850.00
				0.00			0.00
				0.00			0.00
SUB-TOTAL							2,100.00

\$420/-

Tauhin 97495749
 'wp'
 24/4/18 @ 1720
 02 days
 Remony before after repair.
 Sun @ 1kk auto.com
 *Rear tailgate damage not consistent
 to accident, old damage

total \$270/-

part by part

or? by Remont.

shmm 30/08/2018

JOYCE

PAGE: 2 of 2

SUB-TOTAL: S\$ 9,497.50
 ADD 7% GST: S\$ 664.83
 GRAND TOTAL: S\$ 10,162.33

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7506G
Vehicle Details	
Vehicle No.:	SJT6447G
Vehicle to be Exported:	No
Intended De-registration Date:	24 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD 2.4X A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	2AZC674469
Chassis No.:	ANH208062195
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$37,568.00
Original Registration Date:	23 Oct 2009
First Registration Date:	23 Oct 2009
Transfer Count:	0
Actual ARF Paid:	\$37,568.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2019
PARF Rebate Amount:	\$20,662.00
Intended COE Rebate Details	
COE Expiry Date:	22 Oct 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,801.00
COE Rebate Amount:	\$3,285.00
Total Rebate Amount:	\$23,947.00

The information contained herein is correct as at 22 Feb 2018

Catherine Chong (LKK Auto)

From: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Sent: Tuesday, 24 April, 2018 1:54 PM
To: assignments
Subject: NEW ASSIGNMENT : ACCIDENT INVOLVING OUR CLIENT VEHICLE SJT6447G AND YOUR INSURED SKL3220T ON 20/02/2018
Attachments: SAS2363641.pdf; SAS2362073.pdf

Hi Sir,

Please proceed with third party survey.

Thank you.

Syaheeda Othman
Senior Executive, Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
DID: +6477 1130 Fax: +6533 3270
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

*24/04/2018 @ 2:18pm
Joyce veh in
Tanjung*

From: ADMIN SAT [mailto:admin@sngahtee.com]
Sent: Tuesday, 24 April, 2018 9:44 AM
To: Jenny Toh <jenny.toh@qbe.com>
Cc: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Subject: Re: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJT6447G AND YOUR INSURED SKL3220T ON 20/02/2018

Dear Jenny,


Please arrange survey for 24/04/2018.

Thanks

Best Regards

Joyce Tan | admin@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: ADMIN SAT
Sent: Monday, April 23, 2018 6:14 PM
To: Jenny Toh
Subject: Re: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJT6447G AND YOUR INSURED SKL3220T ON 20/02/2018

Dear Jenny,

Please arrange survey for 24/04/2018.

Thanks

Best Regards

Joyce Tan | admin@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457

TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: [Jenny Toh](#)

Sent: Wednesday, March 21, 2018 10:59 AM

To: ADMIN SAT

Subject: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJT6447G AND YOUR INSURED SKL3220T ON 20/02/2018

Dear Joyce

We have already replied to you.

Please see below.

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Jenny Toh

Sent: Friday, 9 March, 2018 9:07 AM

To: ADMIN SAT <admin@sngahtee.com>

Cc: Jenny Toh <jenny.toh@qbe.com>

Subject: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJT6447G AND YOUR INSURED SKL3220T ON 20/02/2018

Our ref: VC011214

Dear Joyce

We refer to this matter.

We are not disputing liability in this case.

You may submit the claim documents to us for our assessment.

Regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: ADMIN SAT [mailto:admin@sngahtee.com]
Sent: Wednesday, 7 March, 2018 12:03 PM
To: Jenny Toh <jenny.toh@qbe.com>
Cc: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Subject: Re: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJT6447G AND YOUR INSURED SKL3220T ON 20/02/2018

Dear Jenny,

We refer to above and wish to check liability for this case.

Hope to hear from you soon

Best Regards

Joyce Tan | admin@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Syaheeda Nacah Binte Mohamed Othman
Sent: Friday, February 23, 2018 9:45 AM
To: [Jenny Toh](mailto:jenny.toh@qbe.com)
Cc: admin@sngahtee.com
Subject: FW: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJT6447G AND YOUR INSURED SKL3220T ON 20/02/2018

Hi Jenny,

Please assist,

Thanks.

Syaheeda Othman
Senior Executive, Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
DID: +6477 1130 Fax: +6533 3270
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

From: ADMIN SAT [mailto:admin@sngahtee.com]
Sent: Thursday, 22 February, 2018 10:40 AM
To: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Subject: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJT6447G AND YOUR INSURED SKL3220T ON 20/02/2018

Dear All,

We refer to above and wish to check liability for this case.

Hope to hear from you soon

Best Regards

Joyce Tan | admin@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 13 July 2019 8:52 AM
To: 'sharon@sngahtee.com'
Cc: Taufikh (LKKAuto); Jia Le (LKK Auto); Admin A
Subject: FW: SJT6447G - FINALISE & BEFORE PAINT *LKK REF: CC4/QBE18007628/T1db3
Attachments: img-180830170129.pdf; IMG_4211.JPG; IMG_4212.JPG

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

For COR, recommended amount at **P/P \$870.00(before GST)** with **02 repair days**.

** Kindly forward your LOD with all the relevant documents (ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

By copy to Jia Le.

FYI & follow up.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Wednesday, 3 July 2019 4:15 PM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: FW: SJT6447G - FINALISE & BEFORE PAINT

REMINDER

From: Sharon Sng
Sent: Wednesday, March 6, 2019 4:34 PM
To: 'Asher Sng (LKKAuto)' <AsherSng@lkkauto.com>
Subject: FW: SJT6447G - FINALISE & BEFORE PAINT

REMINDER

From: Sharon Sng <sharon@sngahtee.com>
Sent: Thursday, August 30, 2018 5:32 PM
To: 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Subject: SJT6447G - FINALISE & BEFORE PAINT

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC4/QBE18007628/T1db3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 09-12-2019



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKL 3220T	Veh. Inspected	SJT 6447G
Policy No.	8-V0007824-MVA-R004	Coverage (\$)	0.00
Claim No.	VC011214	Excess (\$)	0.00
Assign From		Assign Date	24/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALPHARD	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ANH208062195	Colour	BLACK
Odometer	139521	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/65 R16	YOKOHAMA	6 mm
L/H Front Tyre	215/65 R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/65 R16	YOKOHAMA	6 mm
L/H Rear Tyre	215/65 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/02/2018	Inspection Date	24/04/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 6447G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	600.00	600.00
2	REAR BUMPER SIDE RETAINER @\$95.00	NOT NECESSARY	190.00	-
4	REAR BUMPER SENSOR @\$535.00	NOT NECESSARY	2,140.00	-
1	REAR BUMPER REFLECTOR (LH)	NOT NECESSARY	60.00	-
1	REAR BUMPER TOP APRON (LH)	NOT NECESSARY	200.00	-
1	REAR TAILGATE	NOT NECESSARY	1,870.00	-
1	REAR TAILGATE 'ALPHARD' LOGO	NOT NECESSARY	80.00	-
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	1,970.00	-
1	REAR TAILGATE EMBLEM	NOT NECESSARY	90.00	-
1	REAR TAILGATE LAMP (LH) (INNER)	NOT NECESSARY	270.00	-
1	REAR TAILGATE LAMP (LH) (OUTER)	NOT NECESSARY	495.00	-
1	REAR TAILGATE INNER TRIM	NOT NECESSARY	755.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	175.00	-
1	REAR END PANEL	NOT NECESSARY	915.00	-
	LESS 25% DISCOUNT		-2,452.50	-150.00
			7,357.50	450.00
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	40.00	-
			40.00	-
LABOUR				
	TO CHECK WIRING.		150.00	20.00
	TO REMOVE & FIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO APPLY RUST COATING.	NOT NECESSARY	150.00	-
	TO KNOCK ,WEDL ,REMOVE & REPLACE ABOVE PARTS.		800.00	200.00
	TO PUTTY RESPRAY PAINTING ON RR BUMPER,RR BUMPER TOP APRON (LH),RR TAILGATE ,RR END PANEL & AFFECTED AREAS.		850.00	200.00
			2,100.00	420.00
GRAND TOTAL			9,497.50	870.00
RECOMMENDED COST OF REPAIRS				870.00

Report Ref No. CC4/QBE18007628/T1db3q2



Report Ref No. CC4/QBE18007628/T1db3q2

A handwritten signature in black ink, appearing to read 'Taufikh'.

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

A handwritten signature in black ink, appearing to read 'Ho Leong Chuan'.

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.