

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

EST/QUOTE NO. SQ003764

QBE INSURANCE (SINGAPORE)PTE LTD

RCB. Reg. / GST Reg. No: 200810440N

1 RAFFLES QUAY
 #29-10 SOUTH TOWER
 SINGAPORE 048583
 ATTENTION :
 CONTACT : 62246633

FAX NO: 65345356

DATE 24/04/2018
 ACCIDENT DATE : 20/02/2018
 VEHICLE NO : SJT6447G
 CHASSIS/ENG.NO :
 VEHICLE MODEL : TOYOTA ALPHARD
 CLAIM NO :
 POLICY NO :
 REMARK : 6447 QBE TP AGGT
 SKL3220T

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	600.00	25	450.00	<i>de</i> 450.00
2	2	PC	REAR BUMPER SIDE RETAINER	95.00	25	71.25	? 142.50
3	4	PC	REAR BUMPER SENSOR	535.00	25	401.25	× 1,605.00
4	1	PC	REAR BUMPER REFLECTOR (LH)	60.00	25	45.00	× 45.00
5	1	PC	REAR BUMPER TOP APRON (LH)	200.00	25	150.00	× 150.00
6	1	PC	REAR TAILGATE	1,870.00	25	1,402.50	× 1,402.50
7	1	PC	REAR TAILGATE "ALPHARD" LOGO	80.00	25	60.00	× 60.00
8	1	PC	REAR TAILGATE OUTER GARNISH	1,970.00	25	1,477.50	× 1,477.50
9	1	PC	REAR TAILGATE EMBLEM	90.00	25	67.50	× 67.50
10	1	PC	REAR TAILGATE LAMP(LH)(INNER)	270.00	25	202.50	× 202.50
11	1	PC	REAR TAILGATE LAMP(LH)(OUTER)	495.00	25	371.25	× 371.25
12	1	PC	REAR TAILGATE INNER TRIM	755.00	25	566.25	× 566.25
13	1	PC	REAR END PANEL TOP GARNISH	175.00	25	131.25	× 131.25
14	1	PC	REAR END PANEL	915.00	25	686.25	× 686.25

SUB-TOTAL:							7,357.50
** SPECIAL NETT PRICE **							
1	1	PC	REAR WINDSCREEN SEALANT	40.00		40.00	× 40.00

SUB-TOTAL							40.00
** WORK LABOUR **							
TO CHECK WIRING						150.00	<i>20</i> 150.00

JOYCE

PAGE: 1 of 2

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ003764

RCB. Reg. / GST Reg. No: 200810440N

QBE INSURANCE (SINGAPORE)PTE LTD

1 RAFFLES QUAY
 #29-10 SOUTH TOWER
 SINGAPORE 048583
 ATTENTION :
 CONTACT : 62246633 FAX NO: 65345356

DATE 24/04/2018
 ACCIDENT DATE : 20/02/2018
 VEHICLE NO : SJT6447G
 CHASSIS/ENG.NO :
 VEHICLE MODEL : TOYOTA ALPHARD
 CLAIM NO :
 POLICY NO :
 REMARK : 6447 QBE TP AGGT
 SKL3220T

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO REMOVE & FIX REAR WINDSCREEN	150.00		X	150.00
			TO APPLY ANTI RUST COATING	150.00		X	150.00
			TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	800.00		200	800.00
			TO PUTTY RESPRAY PAINTING ON RR BUMPER, RR BUMPER TOP APRON(LH),RR TAILGATE,RR END PANEL & AFFECTED AREAS	850.00		200	850.00
				0.00			0.00
				0.00			0.00
SUB-TOTAL							2,100.00

Tauhin 97495749

'wp'
 24/4/18 @ 1720

02 days

Resurvey before after repair.

sun @ lkk auto.com

*Rear tailgate damage not consistent
 to accident, old damage

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOYCE

PAGE: 2 of 2

SUB-TOTAL : S\$ 9,497.50
 ADD 7% GST. S\$ 664.83
 GRAND TOTAL : S\$ 10,162.33