

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 186G**AAD1804-230**

Not Authorised
Resony B4paint \$3125.47

Vehicle No.:	SHD 186G
Chassis No.:	VF1ABL15AUC282239
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	20.4.2018
Third Party Insurer :	CHINA TAIPING

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77 X
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP RH	\$	<i>nd/can</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46
1	DOOR MIRROR ASSY RH	\$	<i>Sn</i> 1,483.40
1	DOOR PANEL FRT RH	\$	<i>Report</i> 2,844.66

TOTAL	\$	20,244.28
10%	\$	2,024.43
	\$	18,219.85

Trans-cab Auto Services Pte Ltd

AAD1804-230

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 186G

Specical Nett

1SET	BUMPER CLIP FRT	\$	nn	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	}
1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	} X
1SET	WHEELARCH CLIP FRT RH	\$	nn	30.50	
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	

TOTAL	\$	438.00
--------------	-----------	---------------

TOTAL PARTS	\$	18,657.85
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	4001
Putty and spray painting of the affected portion.	\$	3,000.00	4401
To rust-proofing of the affected areas.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	· 170.00	201

Trans-cab Auto Services Pte Ltd**AAD1804-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 186G

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>na</i> 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i> 170.00 X

TOTAL	\$	8,710.00
--------------	-----------	-----------------

Over All Total	\$	27,367.85
-----------------------	-----------	------------------

PART-BY-PART (REPAIR DAY)**~~10-DAYS~~***2 days*