

2/03/2018

ACC. RE. BY:

REF:

CS/CTU8007637/Ttb

Special Instruction:

Surveyor

Merimen

Tat Fith

ASSIGNMENT (Office)

From (Person):

Jowyn Jay

of

CT

Date/Time:

03042018 258pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

S 5310CD

Insured:

at Workshop m/s

Performance

Tel:

71214600

of

303 Alexandra Rd

Policy No:

DMP/CSN1112531807

Claim No:

SNM18002112C01

Sum Insured:

Excess:

\$2000.00

Make of Veh:

(Client's Record)

D.O.A.

24042018

CA / REP / REP. / REV 24 HRS

26042018 @ Murring

H.O.D. Endorsement:

Date/Time:

25042018 3pm

Person Contacted:

Intiran

Vehicle: IN OUT

Date/Time

Action/Instruction (✓) Estimate

S 5310CD - x

27/4

Reef via merimen

27/4

Authorise repair by Susan Teo

27/4

email to intiran authorise repair excess \$0

Surveyor

Taylin

REF:

CTL

CS/CTLI 8007637/T14b

ASSIGNMENT

From: Date: 26/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S 5310 CD

at Workshop m/s

of

Performance
303 Alexandra

Insured:

Policy No.

Claims No.

Sum Insured: Excess: \$ 1000.00

(Client's Record)

Make of Veh:

Enthiran

(Policy Condition)

Morning

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$90K.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REF / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: S 5310 CD Yr Regn: 2011, April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X5 C.C. 2979

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 65420 TiRadio: Insured / Std / NI / NA

Eng/No:

C/No: W154ZV420X 0L491346

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/55R18

R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 26/4/18 2100.

Survey held at: PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Part by Part \$9712/- (Red: 4995.30 : 33%)

RECEIVED 05 JUL 2018

RECEIVED 26 JUN 2018

Date/Time, File Pass to?

26/6 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

OD
9712

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$

Interview (\$

Tech. Invs (\$

Week-end (\$

Survey Fee:

Transportation

S + PS (\$

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		25 Apr 2018 14:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		EMBASSY OF THE PEOPLE'S REPUBLIC OF CHINA, Co. Reg. No.: G1487211L [Created by insurer]							
Vehicle Reg. No.:		S5310CD	Date of Loss:	24/04/2018 11:00 - :59					
Claim Type:		OD / SNM18D02112C01	Policy/Cover Note No.:	DMPCSN1112531807 (Comprehensive) Coverage: 12/04/2018 - 11/04/2019					
			Excess:	S\$2,000.00					
Repairer:		Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/05/2018]							
Driver/Custodian:		ZHONG SHIJUN (41 / Male), NRIC: G1487211L, Tel: +6581290885							
Adj Asg. Remarks:		PLEASE PROCEED TO SURVEY AND REVERT AND CHECK FOR CONSISTENCY OF DAMAGES. EXCESS OF \$2,000.00 APPLIES.							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***S5310CD (SNM18D02112C01)**
OD
Apr 24 2018 11:00AM
[EMBASSY OF THE PEOPLE'S REPUBLIC OF CHINA]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 27/04/2018 11:25 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11034.85) - S5310CD - Claim Handler: Jowyn Tay

Approved:11034.85.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 27 April 2018 3:28 PM
To: Inthiran Thurasamy; Admin-D (LKKAUTO)
Subject: RE: CTI OD S5310CD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **S5310CD (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Inthiran Thurasamy [mailto:inthiran.thurasamy@simedarby.com.sg]
Sent: Friday, 27 April 2018 9:55 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: RE: CTI OD S5310CD

Dear Catherine,

Chassis No :WBAZV420X0L491346

Engine No. :04027611NB30A

Reg. Date : 11.04.2011

Thank you.

Warm regards

Inthiran

Customer Service Advisor

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Body & Paint Department

H/P : 81214600

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/04/2018 09:18
Date Of Accident	24/04/2018 11:45
Exact Location Of Accident	150 TANGLIN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	S5310CD
Insured/Policyholder	
Name Of Registered Owner	EMBASSY OF THE PEOPLE'S REPUBLIC OF CHINA
Co Reg No	G1487211L
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81290885

Vehicle Particulars

Manufacturer	BMW
Model	X5
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	ZHONG SHIJUN
Passport No/FIN	G1487211L
Date Of Birth	04/08/1976
Occupation	INDOOR
Date Of Driving Pass	17/04/2015
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81290885
Fax Number	
Contact Number	
Email Address	2SGPWGC@DA.MIL.CN

Address	150 TANGLIN RD.
Postcode	267969
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	S5356CD
	-
	-
Insurance Company of Driver's Own Vehicle	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form; and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:



PERFORMANCE MOTORS (PTE)
Reporting Centre Representative's Signature
Name: Sime Dasty Pinnon
Singapore 11
NRIC/FIN No.: Tel: 6319 0110
6319 0111 (V)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I drove inside the Embassy,
There was a mechanical problem with
automatic barrier which hit the front
bumper and caused the damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre

Name:

NRIC/PIH No.:

FINANCE INCORPORATED LIMITED
300, Alexandra Road
City Performance Centre
Singapore 159941
Tel: 6 0111 (Kuala Lumpur)
Fax: 6 0111 (Kuala Lumpur)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740155PM-GST Reg. No M2-0020081-X

301, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64796624

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63195528 (AfterSales)
63195533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46726
Date Estimated : 25/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Embassy Of The People's Republic Of China
150 Tanglin Road
Singapore 247969

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
S5310CD	L491346	11/04/2011	X5 xDRIVE35i	0

DESCRIPTION

To replace front bumper, fender liner right, underbody covering, air duct (inner support) and attachments.

Painting front bumper.

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

~~To supply front emboss number plate.~~

To remove and install radiator assembly, fan housing with fan including pressure test, bleed cooling system and check for leak. (For 7 Series only).

To replace charge air cooler including conduct checks for leak and proper function.

To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak. (For all models except for 7 series).

Sundries. *N*

VALUE

~~1700~~ 5,100.00

~~934~~ 1,038.00

~~150~~ 177.00

~~ant~~ 83.00

~~651?~~ 767.00

~~451?~~ 531.00

~~852?~~ 1,003.00

~~80 ?~~ 150.00

Total Labour 1:

8,849.00

DESCRIPTION

SHEET METAL NUT, SELF-LOCKING
MODULE CARRIER BOTTOM
CHARGE-AIR COOLER
Set of mount
CASING LOWER PART SCHWARZ (PDC)
FRT BUMPER PRIMED
UNDERRIDE PROTECTION FRT (ALU MATT)
COVER TOWING EYE FRT
TRIM BAR RH (ALU MATT)

QTY	PRIC
6	1.35
1	92.55
1	701.25
1	31.00
1	402.35
1	924.10
1	176.75
1	35.55
1	32.75

VALUE

~~ant~~ 8.10

~~ant~~ 92.55

~~ant~~ 701.25

~~ant~~ 31.00

~~ant~~ 402.35

~~ant~~ 924.10

~~ant~~ 176.75

~~ant~~ 35.55

~~ant~~ 32.75

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747070

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190328 (AfterSales)
63190533/530 (Motorrad)
64796501 (AfterSales)
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46726
Date Estimated : 25/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
S5310CD	L491346	11/04/2011	X5 xDRIVE35i	0

DESCRIPTION	QTY	PRIC	VALUE
COVER RH	1	37.40	mis 37.40 X
GRILLE CENTER LOWER (SCHWARZ)	1	75.20	? 75.20 X
CLOSED GRID RH	1	72.30	mis 72.30 X
FRT BUMPER CARRIER	1	708.15	? 708.15 X
LICENSE PLATE HOLDER (ECE)	1	64.20	? 64.20 X
AIR DUCT RADIATOR	1	489.15	de 489.15 X
COVER WHEELHOUSING FR. SEC. FRT RH	1	179.25	de 179.25 X
COVER WHEEL HOUSING FRT RH	1	123.25	de 123.25 X
FRT RH BRAKE AIR DUCT	1	51.50	de 51.50 X
FRT RH PRESSURE LIP SEAL	1	57.70	de 57.70 X
ENGINE ENCAPSULATION FRONT	1	425.90	de 425.90 X
CONDENSER AIRCON WITH DRIER	1	1,028.45	bt ? 1,028.45 X
Total Parts :			5,716.85

24/5/14 0100
Tanfikh
97495749
Revent
tanfikh@urando.com
5 days

Labour 1	:	8,849.00
Parts	:	5,716.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,019.61
Grand Total	:	15,585.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63447770

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190888 (AfterSales)
63190933/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46726 Page No. : 1 of 2
Date Estimated : 25/04/2018
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -
Embassy Of The People's Republic Of China
150 Tanglin Road

Singapore 247969

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
S5310CD	L491346	11/04/2011	X5 xDRIVE35i	0

DESCRIPTION

VALUE

To replace front bumper, fender liner right, underbody covering, air duct (inner support) and attachments.

1700 5,100.00

Painting front bumper.

934 1,038.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To supply front emboss number plate.

ant 83.00

To remove and install radiator assembly, fan housing with fan including pressure test, bleed cooling system and check for leak. (For 7 Series only).

651? 767.00

To replace charge air cooler including conduct checks for leak and proper function.

451? 531.00

To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak. (For all models except for 7 series).

852? 1,003.00

Sundries.

? 150.00

Total Labour 1: 8,849.00

DESCRIPTION

QTY PRIC

VALUE

SHEET METAL NUT, SELF-LOCKING

6 1.35

? 8.10

MODULE CARRIER BOTTOM

1 92.55

? 92.55

CHARGE-AIR COOLER

1 701.25

? 701.25

Set of mount

1 31.00

? 31.00

CASING LOWER PART SCHWARZ (PDC)

1 402.35

? 402.35

FRT BUMPER PRIMED

1 924.10

de 924.10

UNDERRIDE PROTECTION FRT (ALU MATT)

1 176.75

? 176.75

COVER TOWING EYE FRT

1 35.55

m.s. 35.55

TRIM BAR RH (ALU MATT)

1 32.75

? 32.75

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. MD-000081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Tel: 63180100 (Sales & Admin)
63180111 (AfterSales)
Fax: 64747770

250, Kampong Arang Road
East Coast Centre
Singapore 438160
Tel: 63180688 (AfterSales)
Fax: 63448772

313, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Tel: 63180528 (AfterSales)
63180533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46726
Date Estimated : 25/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
S5310CD	L491346	11/04/2011	X5 xDRIVE35i	0

DESCRIPTION	QTY	PRIC	VALUE
COVER RH	1	37.40	mis 37.40
GRILLE CENTER LOWER (SCHWARZ)	1	75.20	? 75.20
CLOSED GRID RH	1	72.30	mis 72.30
FRT BUMPER CARRIER	1	708.15	? 708.15
LICENSE PLATE HOLDER (ECE)	1	64.20	? 64.20
AIR DUCT RADIATOR	1	489.15	? 489.15
COVER WHEELHOUSING FR. SEC. FRT RH	1	179.25	de 179.25
COVER WHEEL HOUSING FRT RH	1	123.25	de 123.25
FRT RH BRAKE AIR DUCT	1	51.50	? 51.50
FRT RH PRESSURE LIP SEAL	1	57.70	? 57.70
ENGINE ENCAPSULATION FRONT	1	425.90	? 425.90
CONDENSER AIRCON WITH DRIER	1	1,028.45	? 1,028.45

Total Parts : 5,716.85

Claim 07 / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 26/5/14 @ 10:00 Excess \$ 2000

Surveyor's Name Taufik Sign [Signature]

Surveyor's Tel 97495749 Authorised Yes / No

Al-Bosom's Name Revent Time _____

Insured's Name _____ Insured's Tel _____ Insured's Email _____

Surveyor's Email taufik@khanh.com

Period of Survey 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	8,849.00
Parts	:	5,716.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,019.61
Grand Total	:	15,585.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740155BW. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46726
Date Estimated : 25/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Embassy Of The People's Republic Of China
150 Tanglin Road
Singapore 247969

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
S5310CD	L491346	11/04/2011	X5 xDRIVE35i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, front underride protection, air duct radiator and attachments, front RH wheelhousing cover, front engine encapsulation include knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint front bumper	934.00		934.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
To supply front emboss number plate.	83.00		83.00	
* To remove and install radiator assembly, fan housing with fan including pressure tests, bleed cooling system and conducting checks for leak	651.00		651.00	
* To replace charge air cooler include conducting checks for leak and proper function	451.00		451.00	
* To replace air con condenser and air con hose include vacuum system, top up freon gas and conducting checks for leak	852.00		852.00	
Sundries.	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.10	10.00		11.00
# BRACKET F RADIATOR *	33.60	1.00		33.60
# RUBBER MOUNTING *	21.15	1.00		21.15
MODULE CARRIER BOTTOM	92.55	1.00		92.55 ✓
# RH MODULE CARRIER *	75.70	1.00		75.70
CHARGE-AIR COOLER	701.25	1.00		701.25 ✓
CASING LOWER PART SCHWARZ (PDC)	402.35	1.00		402.35 ✓
FRT BUMPER PRIMED	924.10	1.00		924.10
UNDERRIDE PROTECTION FRT (ALU MATT)	176.75	1.00		176.75
COVER TOWING EYE FRT	35.55	1.00		35.55
TRIM BAR RH (ALU MATT)	32.75	1.00		32.75

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W / GST Reg. No. M2-0020081-X



FINAL REPORT

CLOSED GRID RH	72.30	1.00	72.30
AIR DUCT RADIATOR	489.15	1.00	489.15
COVER WHEELHOUSING FR. SEC. FRT RH	179.25	1.00	179.25
FRT RH BRAKE AIR DUCT	51.50	1.00	51.50
FRT RH PRESSURE LIP SEAL	57.70	1.00	57.70
ENGINE ENCAPSULATION FRONT	425.90	1.00	425.90
CONDENSER AIRCON WITH DRIER	1,028.45	1.00	1,028.45

SUPPLEMENTARY ITEMS

Total Labour :	4,901.00
Total Parts :	4,811.00
Total Labour & Parts :	9,712.00
Deduction for Excess :	
Total Repair Costs less Excess:	9,712.00
GST @7%:	679.84
Grand Total :	10,391.84

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46726
Date Estimated : 25/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -

Embassy Of The People's Republic Of China
150 Tanglin Road

Singapore 247969

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
S5310CD	L491346	11/04/2011	X5 xDRIVE35i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.10	10.00	net	11.00
# BRACKER F RADIATOR *	33.60	1.00	net	33.60
# RUBBER MOUNTING *	21.15	1.00	net	21.15
# RH MODULE CARRIER *	75.70	1.00	net	75.70

Total Labour :	
Total Parts :	141.45
Total Labour & Parts :	141.45

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		25 Apr 2018 14:58 Edit Adj Rpt	S\$9,712.00 Edit Estimates	S\$9,712.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	EMBASSY OF THE PEOPLE'S REPUBLIC OF CHINA , Co. Reg. No.: G1487211L								
Vehicle Reg. No.:	S5310CD	Date of Loss:	24/04/2018 11:00 - :59 [84 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D02112C01	Policy/Cover Note No.:	DMPCSN1112531807 (Comprehensive) Coverage: 12/04/2018 - 11/04/2019						
		Excess:	S\$0.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/05/2018]								
Driver/Custodian:	ZHONG SHIJUN (41 / Male), NRIC: G1487211L, Tel: +6581290885								
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY AND REVERT AND CHECK FOR CONSISTENCY OF DAMAGES. EXCESS OF \$2,000.00 APPLIES.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPING (27/04/2018): Alert - Adj Mandate Approved (S\$11034.85) - S5310CD - Claim Handler: Jowyn Tay									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*S5310CD (SNM18D02112C01)

OD

Apr 24 2018 11:00AM

[EMBASSY OF THE PEOPLE'S REPUBLIC OF CHINA]

Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page		☐	☒		
No	Finalized On	Performance Motors Limited (Alexandra)								Thumbnail	Print			
1	25/04/18 09:30	Accident Statement								Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	27/04/18 10:40	Adjuster Immediate Advice								Load HTM				
Photos/Images									3 per page		☐	☒		
No	Finalized On	Performance Motors Limited (Alexandra)								Thumbnail	Print			
1	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
2	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
3	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
4	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
5	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
6	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
7	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
8	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
9	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
10	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
11	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
12	25/04/18 09:26	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	27/04/18 10:41	General View								Load JPG	☒			
2	27/04/18 10:41	General View								Load JPG	☒			
3	27/04/18 10:41	General View								Load JPG	☒			
4	27/04/18 10:41	General View								Load JPG	☒			
5	27/04/18 10:41	General View								Load JPG	☒			
6	27/04/18 10:41	General View								Load JPG	☒			
7	27/04/18 10:41	General View								Load JPG	☒			
8	27/04/18 10:41	General View								Load JPG	☒			
9	27/04/18 10:41	General View								Load JPG	☒			
10	27/04/18 10:41	General View								Load JPG	☒			
11	27/04/18 10:41	General View								Load JPG	☒			
12	27/04/18 10:41	General View								Load JPG	☒			
13	27/04/18 10:41	General View								Load JPG	☒			
14	27/04/18 10:41	General View								Load JPG	☒			
15	27/04/18 10:41	General View								Load JPG	☒			
16	27/04/18 10:41	General View								Load JPG	☒			
17	27/04/18 10:41	General View								Load JPG				

Assessment Reports			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
				☒
18	27/04/18 10:41	General View	 Load JPG	☒
19	27/04/18 10:41	General View	 Load JPG	☒
20	27/04/18 10:41	General View	 Load JPG	☒
21	27/04/18 10:41	General View	 Load JPG	☒
22	27/04/18 10:41	General View	 Load JPG	☒
23	27/04/18 10:41	General View	 Load JPG	☒
24	27/04/18 10:41	General View	 Load JPG	☒
25	27/04/18 10:41	General View	 Load JPG	☒
26	27/04/18 10:41	General View	 Load JPG	☒
27	27/04/18 10:41	General View	 Load JPG	☒
28	27/04/18 10:41	General View	 Load JPG	☒
29	27/04/18 10:41	General View	 Load JPG	☒
30	27/04/18 10:41	General View	 Load JPG	☒
31	27/04/18 10:41	General View	 Load JPG	☒
32	27/04/18 10:41	General View	 Load JPG	☒
33	27/04/18 10:41	General View	 Load JPG	☒
34	27/04/18 10:41	General View	 Load JPG	☒
35	27/04/18 10:41	General View	 Load JPG	☒
36	27/04/18 10:41	General View	 Load JPG	☒
37	27/04/18 10:41	General View	 Load JPG	☒
38	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
39	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
40	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
41	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
42	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
43	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
44	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
45	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
46	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
47	26/06/18 10:30	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/04/18 14:55	Quotation/Replacement/Repair invoice	 Load PDF	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/04/18 09:25	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 10:43	estimate	 Load PDF	
2	06/07/18 09:42	SUPPLEMENTARY PART	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/04/18 09:30	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/04/18 09:26	Accident Photo	 Load JPG	☒
2	25/04/18 09:26	Accident Photo	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
				☒
3	25/04/18 09:26	Accident Photo	 Load JPG	☒
4	25/04/18 09:26	Accident Photo	 Load JPG	☒
5	25/04/18 09:26	Accident Photo	 Load JPG	☒
6	25/04/18 09:26	Accident Photo	 Load JPG	☒
7	25/04/18 09:26	Accident Photo	 Load JPG	☒
8	25/04/18 09:26	Accident Photo	 Load JPG	☒
9	25/04/18 09:26	Accident Photo	 Load JPG	☒
10	25/04/18 09:26	Accident Photo	 Load JPG	☒
11	25/04/18 09:26	Accident Photo	 Load JPG	☒
12	25/04/18 09:26	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	25/04/18 09:25	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18007637/T1TBQ2

Date: 06/07/2018

REFERENCE

Insured/Claimant: EMBASSY OF THE PEOPLE'S
REPUBLIC OF CHINA

Policy No: DMPCSN1112531807

Date of Loss: 24/04/2018

Nature of
Claim: ODClaim
No: SNM18D02112C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: S5310CD

Make & Model: BMW X5, 3.0 xDrive35i (E70) (A)

Reg. Date: 11/04/2011 (Man. Year: 2011)

Colour: Black

Engine Capacity: 2979 cc

Market Value/New Car Price: S\$90,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: 04027611NB30A

Chassis No: WBAZV420X0L491346

Odometer: 65420 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R18

Front Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Tyre Size: 255/55 R18

Rear Left Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,046.30	4,974.00	1,072.30	17.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,616.00	4,738.00	3,878.00	45.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,662.30	9,712.00	4,950.30	33.76
+ GST 7.00/7.00% (S\$)	1,026.36	679.84	346.52	33.76
Nett Amount (S\$)	15,688.66	10,391.84	5,296.82	33.76

INSPECTION

Date of Assignment: 25/04/2018

Date Inspected: 26/04/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2018)
Parts: M1-SUV	BMW X5 3.0 xDrive35i (E70) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for S5310CD)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	105.00 FS	*80.00 FS
2	1		*FRONT EMBOSS NUMBER PLATE	Cut	83.00 FS	*83.00 FS
3	6		*SHEET METAL NUT ,SELF-LOCKING	Not Necessary	8.10 FS	*- FS
4	1		*MODULE CARRIER BOTTOM	Distorted	92.55 FS	*92.55 FS
5	1		*CHARGE -AIR COOLER	Bent	701.25 FS	*701.25 FS
6	1		*SET OF MOUNT	Not Necessary	31.00 FS	*- FS
7	1		*CASING LOWER PART SCHWARZ (PDC)	Deformed	402.35 FS	*402.35 FS
8	1		*FRT BUMPER PRIMED	Deformed	924.10 FS	*924.10 FS
9	1		*UNDERRIDE PROTECTION FRT (ALU MATT)	Deformed	176.75 FS	*176.75 FS
10	1		*COVER TOWING EYE FRT	Missing	35.55 FS	*35.55 FS
11	1		*TRIM BAR RH (ALU MATT)	Bent	32.75 FS	*32.75 FS
12	1		*COVER RH	Not Necessary	37.40 FS	*- FS
13	1		*GRILLE CENTER LOWER (SCHWARZ)	Not Necessary	75.20 FS	*- FS
14	1		*CLOSED GRID RH	Missing	72.30 FS	*72.30 FS
15	1		*FRT BUMPER CARRIER	Not Necessary	708.15 FS	*- FS
16	1		*LICENSE PLATE HOLDER (ECE)	Not Necessary	64.20 FS	*- FS
17	1		*AIR DUCT RADIATOR	Deformed	489.15 FS	*489.15 FS
18	1		*COVER WHEELHOUSING FR.SEC.FRT RH	Deformed	179.25 FS	*179.25 FS
19	1		*COVER WHEEL HOUSING FRT RH	Not Necessary	123.25 FS	*- FS
20	1		*FRT RH BRAKE AIR DUCT	Deformed	51.50 FS	*51.50 FS
21	1		*FRT RH PRESSURE LIP SEAL	Deformed	57.70 FS	*57.70 FS
22	1		*ENGINE ENCAPSULATION FRONT	Deformed	425.90 FS	*425.90 FS
23	1		*CONDENSER AIRCON WITH DRIER	Bent	1,028.45 FS	*1,028.45 FS
24	10		*BLIND RIVET	Necessary	11.00 FS	*11.00 FS
25	1		*BRACKET F RADIATOR	Distorted	33.60 FS	*33.60 FS
26	1		*RUBBER MOUNTING	Necessary	21.15 FS	*21.15 FS
27	1		*RH MODULE CARRIER	Distorted	75.70 FS	*75.70 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	6,046.30	4,974.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER ,FENDER LINER RIGHT ,UNDERBODY COVERING ,AIR DUCT (INNER SUPPORT) AND ATTACHMENTS	New	5,100.00	1,700.00
2	PAINTING FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO REMOVE AND INSTALL RADIATOR ASSEMBLY ,FAN HOUSING WITH FAN INCLUDING PRESSURE TEST ,BLEED COOLING SYSTEM AND CHECK FOR LEAK (FOR 7 SERIES ONLY)	New	767.00	651.00
5	TO REPLACE CHARGE AIR COOLER INCLUDING CONDUCT CHECKS FOR LEAK AND PROPER FUNCTION	New	531.00	451.00
6	TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM ,TOP UP FREON GAS AND CHECK FOR LEAK (FOR ALL MODELS EXCEPT FOR 7 SERIES)	New	1,003.00	852.00
Gross Labour Cost (\$\$)			8,616.00	4,738.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >