



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SDK72L
Make & Model : MERCEDES
BENZ,C180K,WDD2040452A522836
Year of Manufacture : 2011

Estimation No. : E18040063
DOA : 23/04/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bootlid / BT	1.00	1,900.00	1,900.00 ?
2	Rear bootlid logo / MC	1.00	98.00	98.00
3	Rear bootlid emblem - C180 /	1.00	133.90	133.90
4	Rear bootlid emblem - Cycle & Carriage / } MC	1.00	133.90	133.90
5	Rear bootlid emblem - Kompressor /	1.00	133.90	133.90
6	Rear bootlid lock X	1.00	637.00	637.00
7	Rear bootlid weather strip X } NN	1.00	270.00	270.00
8	Rear bumper / Re.	1.00	1,672.00	1,672.00 ?
9	Rear bumper clip / MC	10.00	5.00	50.00
10	Rear bumper retainer (LH) / } MC	1.00	76.00	76.00
11	Rear bumper retainer (RH) /	1.00	76.00	76.00
12	Rear bumper bracket (RH) X	1.00	45.00	45.00
13	Rear bumper reinforcement X	1.00	715.00	715.00
14	Rear bumper reinforcement bracket/garnish X } NN	1.00	0.00	0.00
15	Rear bumper inner centre garnish / Re	1.00	377.00	377.00
16	Rear bumper reverse sensor / 2pc	4.00	294.00	1,176.00 ?
17	Rear bumper reverse sensor harness X	1.00	196.30	196.30
18	Rear bumper chrome pieces / MC.	3.00	476.00	1,428.00 ?
19	Rear bumper towing cap / mis	1.00	96.00	96.00
20	Rear bumper air duct (LH) X	1.00	60.00	60.00
21	Rear bumper air duct (RH) X } NN	1.00	60.00	60.00
22	Tail lamp (RH) / CNA	1.00	684.00	684.00
23	Tail lamp clip (RH) / MC.	2.00	5.00	10.00
24	Tail lamp panel (RH) X NN	1.00	187.20	187.20
25	Rear fender (RH) Repair X	1.00	1,600.00	1,600.00

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SDK72L
Make & Model : MERCEDES
BENZ,C180K,WDD2040452A522836
Year of Manufacture : 2011

Estimation No. : E18040063
DOA : 23/04/2018

No	Description	Qty	U/P	Amt
26	Rear fender cowling (RH) / TN	1.00	220.00	220.00
27	Rear fender cowling clip (RH) / MBL	10.00	5.00	50.00
28	Rear end panel X	1.00	1,464.00	1,464.00
29	Rear end panel top garnish X	1.00	168.90	168.90
30	Rear end panel top garnish clip X	10.00	5.00	50.00

Amt S\$ 13,768.10
Discount (0.00%) S\$ 0.00
Subtotal S\$ 13,768.10

Section: Special Nett Items

31	Rear number plate X	1.00	50.00	50.00
32	Rear end panel sealant X	1.00	80.00	80.00

Amt S\$ 130.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 130.00

Section: Labour Items

33	To R&R accident affected areas	1.00	1,300.00	1,300.00	400
34	To putty & respray accident affected areas	1.00	1,250.00	1,250.00	600
35	To rust proof accident affected areas	1.00	60.00	60.00	40
36	To R&R rear boot mechanism	1.00	80.00	80.00	60
37	To R&R rear luggage compartment	1.00	200.00	200.00	X NN
38	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00	40
39	To check wiring layout of tail lamp	1.00	80.00	80.00	30
40	To check, diagnose & reset any fault codes	1.00	380.00	380.00	X
41	To check wheel alignment	1.00	180.00	180.00	X
42	To check for water seepage	1.00	80.00	80.00	X NN

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SDK72L
Make & Model : MERCEDES
BENZ,C180K,WDD2040452A522836
Year of Manufacture : 2011

Estimation No. : E18040063
DOA : 23/04/2018

No	Description	Qty	U/P	Amt
				Amt S\$ 3,690.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 3,690.00

4 Days.

Unpainted repair.

After repair photos.

Guo Qian - 8288 082

24/4/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal	S\$ 13,768.10
Special Nett Items Subtotal	S\$ 130.00
Labour Items Subtotal	S\$ 3,690.00
Total	S\$ 17,588.10