

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/485/2018/GW
Date : 25-Apr-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Low Ee Kheng, Ignatius
Address : 75 Lorong 101 Changi
Singapore 426670

Telephone : HP +65 81331188
Type of Claim : Own Damage Claim
Policy No. : 1700009444
Vehicle No : **SDX 8129 L**
Model Code : Audi S3 Sedan 2.0 TFSI Qu
Model / Year : May-17
Engine No : DJH 008634
Chassis No : WAUZZZ8V4H1055619
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Apr-18
Place of Accident : Lorong 101 Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDX 8129 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door's multi lock system and power window devices.	S/N \$ 280.00 ✓	
2	To dismantle and renew lhs front door, transfer lhs wing mirror assy and align to position. Reinstall all parts removed.	\$ 900.00 500	
3	To respray lhs front door.	\$ 900.00 550	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,272.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDX 8129 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR-LH <i>Dented</i>	\$ 2,190.00	✓
2	FRONT OUTER DOOR SEAL-LH <i>new</i>	\$ 139.00	✓
3	BONDING AGENT <i>?</i>	\$ 43.00	?
4	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
5	FRONT DOOR CATCH-LH <i>new</i>	\$ 92.00	X
6	DOOR ATTACHMENT PARTS <i>?</i>	\$ 206.00	?
7	PILLAR B TRIM <i>new</i>	\$ 85.00	X
8	SUNDRIES <i>?</i>	\$ 200.00	?
TOTAL SPARE PARTS		: \$ 3,019.00	
TOTAL LABOUR CHARGES		: \$ 2,272.00	
GRAND TOTAL		: \$ 5,291.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian King

Surveyed Date

: 25/04/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised Repair, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant