

ASS. REC. BY:

REF:

TMI/ CC3/TML18007674/Kvb2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: (78D) 5227K

Policy No. MW010469


Claims No. m1802168

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 5688 Yr Regn: 06, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Peugeot Longitude c.c. 1995

Colour: m White / R A/C: Insured / Std / NI / NA

Sp. Reading 278149 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL15AUC 281648

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/A / S/Rlm / STD A/Rlm or

Tyre Size: F: Giti 215/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 24/4/18

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 25/4/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/4 15h pass to Carman

8 12,405.99 (Real 36,010.48, 747)

27/4/18 Email GIA to TMI

SHC 5688Y - CC3/TML16016498 / Kvb2

(78D) 5227K

DIA: 200816

RECEIVED 27 APR 2018 waiting for merimen update make & model

RECEIVED 08 MAY 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 27/4 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$) 12,405.99

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2018		27 Apr 2018 10:48 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)
CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ILA GROUP PTE LTD , Co. Reg. No.: 201102296H		
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5688Y	Date of Loss:	24/04/2018 09:00 - :59
Claim Type:	TP / M1802168	Policy/Cover Note No.:	MW010469 (Comprehensive) Coverage: 27/11/2017 - 26/11/2018
Vehicle Reg. No. (Insured):	GBD5227K	Policy No. (Claimant):	VPX/P1680520
		Excess:	S\$2,500.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/05/2018]		
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE.		

ASSOCIATED MAIL RECEIVED
[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 27 April 2018 9:26 AM
To: motorclaims@tokiomarine.com.sg
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 24/4/2018, SHC 5688Y (TP VEHICLE), GBD 5227K (OI VEHICLE)
Attachments: EST.pdf; GIA.pdf; POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5688Y M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111 on 25/4/2018.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	5HC5688Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	24 Apr 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002556
Chassis No.:	VF1ABL15AUC281648
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	05 Jun 2015
First Registration Date:	05 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2023
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	04 Jun 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,886.00
COE Rebate Amount:	\$33,802.00
Total Rebate Amount:	\$43,175.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/04/2018 17:10
Date Of Accident	24/04/2018 08:50
Exact Location Of Accident	BEDOK NORTH ROAD TOWARDS BEDOK NORTH FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5688Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LIM KIN HOCK
NRIC No	S1254950D
Date Of Birth	29/03/1957
Occupation	OUTDOOR
Date Of Driving Pass	26/09/1978
Driving Experience	39 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82694286
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	2 LORONG 15 GEYLANG
Postcode	388596
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180424/2028

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD5227K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	SWAMI NATHAN SELVA KANNAN
NRIC/Passport Number	G8310931P
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM KIN HOCK

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5688Y

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180424/2028

1 of 3

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20180424/2028

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/04/2018 12:19		Vide Report No.:		Station Diary No.: 56
Informant's Particulars				
Name of Informant: LIM KIN HOCK		Address: 2 LORONG 15 GEYLANG SINGAPORE 388596		
ID Type / ID No.: NRIC NO / S1254950D		Contact No.: Home/Office: Mobile: 82694286		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 61	Date of Birth: 29/03/1957	Type of Informant: Driver	
Race: Chinese		Language: Mandarin		Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 24/04/2018 08:50	Type of Location: Straight Road
Location: Along Road 1 BEDOK NORTH ROAD				
Towards Bedok North Flyover, near to Bus Stop B02.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD5227K	Lorry				Slightly Damaged	2
SHC5688Y	Taxi				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180424/2028

2 of 3

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20180424/2028

CONTINUATION OF REPORT

Driver			
Name	Swami Nathan Selva Kannan		ID No. G8310931P
Related Vehicle	GBD5227K (Lorry)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of injury	NIL
Driver			
Name	LIM KIN HOCK		ID No. S1254950D
Related Vehicle	SHC5688Y (Taxi)		Contact No. 82694286
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	24/04/2018	Date Discharge	24/04/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 24/4/18 at about 0850hrs, I pick up a female passenger (Rogayal Binte Hussian, NRIC No. S1585341G) along Bedok North Road and was heading towards Changi Airport. As I was approaching a bus stop (Bedok North Road B02), I observed that there was a bus driving out from the bus stop. And I also noticed that there was a yellow box (give way to bus) as such I stopped my taxi (registration no. SHC5688Y) before the yellow box. At that juncture, I was telling my passenger that I need to stop before the 'give way to bus' yellow box so that buses can exit from the bus stop.

Subsequently, about 20 - 30 seconds later, I felt an impact coming from the rear of my taxi. I alighted from my taxi and realized that a lorry (registration no. GBD5227K) had collided into the rear portion of my taxi. The driver of said lorry raised his voice against me, questioning me why did I stopped along the main road. I explained to the driver that there was a yellow box and I should stop for the bus which was exiting. The driver and I exchanged particulars thereafter. And I took several photographs of the vehicles involved.

I started to experience pain on my neck and upper back thereafter. However, I still ferried my passenger to her destination before heading to Mount Alvernia Hospital for a medical examination. I was granted 5 days medical leave from 24/4/18 to 28/4/18. I wish to state that my vehicle was not installed with an in-built camera. No government property was damaged.



**SINGAPORE
POLICE FORCE**



T/20180424/2028

3 of 3

Report No. T/20180424/2028

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Staff Sgt NG YONG SHENG, GERALD

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

24/04/2018 12:19

Officer In Charge Of Case:

TP / AEIT /

SSI KASMAWATI BTE SAMIAN

Contact No.: 65476179

SN 168

Classification Of Case:

Authentication Stamp

NR165

SIGNATURE

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y**AAD1804-247***Not Authored
Presurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHC 5688Y

VF1ABL15AUC281648

RENAULT

LATITUDE

24.4.2018

*Tokio Marine***PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bt</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Pl</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Pl</i> 113.47	✓
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>Bt</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Dis</i> 225.95	✓
13	1 BOOT REAR	\$	<i>Bt</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Bu</i> 470.06	✓
15	1 BOOT WHEATERSTRIP	\$	<i>Dis / M</i> 323.05	✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Pl</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>M</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>M</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	X
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	X
25	1 BOOT SWITCH	\$	<i>R</i> 168.13	X
26	1 BOOT LOCK	\$	<i>R</i> 202.67	X
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	X
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

AAD1804-247

SHC 5688Y

30	1 DOOR PANEL REAR LH
31	1 FENDER PANEL INNER TRIM REAR LH
32	1 FENDER PANEL REAR LH
33	1 WHEELARCH REAR LH
34	1 FENDER PANEL INNER TRIM REAR RH
35	1 FENDER PANEL REAR RH
36	1 WHEELARCH REAR RH
37	1 TAILLAMP RH
38	1 TAILLAMP PANEL RH
39	1 TAILLAMP LH
40	1 TAILLAMP PANEL LH
41	1 OUTER PANEL REAR (End Panel)
42	1 OUTER PANEL REAR (End Panel)TRIM
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)
44	1 SPARE WHEEL PANEL TRIM
45	1 EXHAUST REAR
46	1 EXHAUST CAP REAR
47	1 FUEL FLAP L70Y

\$	R	2,844.66	X
\$	Sn	671.45	X
\$	R	3,299.13	X
\$	Sn	543.47	X
\$	Seq	671.45	X
\$	R	3,299.13	X
\$	Sn	543.47	X
\$	mycm	552.55	✓
\$	R	986.70	X
\$	mycm	552.55	✓
\$	R	986.70	X
\$	Ry	1,471.77	✓
\$	nu	404.56	✓
\$	R	2,189.88	X
\$	Sn	612.21	X
\$	R	7,489.05	X
\$	R	230.49	X
\$	Sn	343.57	X
TOTAL	\$	39,057.17	15
10%	\$	3,905.72	
	\$	35,151.45	

Special Nett

1	1SET PARKING AID
2	1SET REAR BUMPER CLIP
3	1SET BUMPER BRACKET CTR CLIP
4	1SET BUMPER BRACKET SIDE CLIP RH RR
5	1SET BUMPR RETAINER RH CLIP RR
6	1SET BUMPR BRACKET SIDE CLIP LH RR
7	1SET BUMPR RETAINER CLIP LH RR
8	1SET BUMPER LOWER REAR RIVET
9	1SET BUMPER LOWER REAR CLIP
10	1 EXHAUST MOUNTING REAR
11	1SET BOOT FINISHER CLIP
12	1 BOOT STICKER "Trans-cab"
13	1 BOOT STICKER "6555-3333"
14	1 BOOT INNER TRIM CLIP
15	1SET FENDER WHEELARCH REAR RH CLIP

\$	phon	700.00	✓
\$	nu	66.00	✓
\$	nu	33.00	✓
\$	nu	10.00	X
\$	nu	20.00	X
\$	nu	10.00	X
\$	nu	20.00	X
\$	nu	22.00	X
\$	nu	66.00	✓
\$	Sn	17.82	X
\$	nu	24.20	X
\$	nu	30.00	✓
\$	nu	30.00	✓
\$	nu	45.00	X
\$	nu	35.00	X

Trans-cab Auto Services Pte Ltd

AAD1804-247

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

16	1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19	1 TAILLAMP CLIP RH	\$	nn	5.00	—
20	1 TAILLAMP CLIP LH	\$	nn	5.00	—
21	2 REAR WINDSCREEN SELANT	\$	nn	80.00	X
22	1 WINDSCREEN MOULDING	\$	nn	100.00	X
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	X
25	1 SPARE TYRE	\$	nn	330.00	X

TOTAL \$ 2,225.02**TOTAL PARTS \$ 37,376.47****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	600
To Rust-Proofing Of The Affected Areas.	\$	170.00	600
To reinstall rear bumper parking sensor.	\$	170.00	600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	600
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	600

Trans-cab Auto Services Pte Ltd

AAD1804-247

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	nn	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn	380.00	X
TOTAL	\$		11,040.00	11420

Over All Total \$ 48,416.47 48796.45

(LUMP SUM)

Repair Days

15 Days

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts for survey
- Parts prices - subject to survey
- Third party - subject to "no fault" basis
- No illegal modifications
- Supply of any item(s) not included in the estimate and is subject to final approval of Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TM18007674/KVBN2

Date: 08/05/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MW010469
Claimant Vehicle No :	SHC5688Y	Insured Vehicle No :	GBD5227K
Date of Loss:	24/04/2018	Nature of Claim:	TP
		Claim No:	M1802168

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5688Y		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002556
Reg. Date:	05/06/2015 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC281648
Colour:	Metallic White/Red	Odometer:	278149 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,376.45	10,905.99	26,470.46	70.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,420.00	1,500.00	9,920.00	86.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	48,796.45	12,405.99	36,390.46	74.58
+ GST 7.00/7.00% (\$\$)	3,415.75	868.42	2,547.33	74.58
Nett Amount (\$\$)	52,212.20	13,274.41	38,937.79	74.58

INSPECTION

Date of Assignment:	27/04/2018	
Date Inspected:	25/04/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2018)
Parts:	143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5688Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Distorted	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Distorted	225.95 FL	*225.95 FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Buckled	470.06 FL	*470.06 FL
15	1		*BOOT WEATHERSTRIP	Distorted/Dented	323.05 FL	*323.05 FL
16	1		*BOOT REFLECTOR LAMP LH	Cracked	493.35 FL	*493.35 FL
17	1		*BOOT REFLECTOR LAMP RH	Dented	493.35 FL	*493.35 FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Repair	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
31	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
32	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
33	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
34	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
35	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
36	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
37	1		*TAILLAMP RH	Mtg Cracked	552.55 FL	*552.55 FL
38	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
39	1		*TAILLAMP LH	Mtg Cracked	552.55 FL	*552.55 FL
40	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
41	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
42	1		*OUTER PANEL REAR (END PANEL) TRIM	Dented	404.56 FL	*404.56 FL
43	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR)	Repair	2,189.88 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		PANEL) *SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
45	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
46	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
47	1		*FUEL FLAP L70Y	Serviceable	343.57 FL	*- FL
48	1		*SET PARKING AID	Shorted	700.00 FS	*700.00 FS
49	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
50	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
51	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
52	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
53	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
54	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
55	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
56	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
57	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
58	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
59	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
60	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
61	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
62	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
63	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
64	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
65	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
66	1		*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
67	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
68	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
69	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
70	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
71	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
72	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$) **41,282.17** **12,013.88**
 - List Item Discount on L Items 10.00/10.00% (S\$) 3,905.72 1,107.89

Total Parts (S\$) 37,376.45 10,905.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	660.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	600.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	-
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
14	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
Gross Labour Cost (\$\$)			11,420.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >