

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JNISC 2F 24 Z0 85 0270

KO HONG CONSTRUCTION PTE LTD
3016 BEDOK NORTH AVE 4
#01-27
S 489947

TP Direct Asia
Xiao Tong

Date : 08.06.2018
Vehicle no : GBC 2953 Y
Make/Model : NISSAN CABSTAR
Accident date : 23.04.2018

No	Description	Qty	Amount (\$S)
Nett Items			
1	Rear end panel RH side bracket <i>new</i>	1	\$ 102.4 X
2	Rear end panel RH side bracket stopper @ \$38.00 <i>missing</i>	2	\$ 76 ✓
3	Rear RH mudguard <i>Dented</i>	1	\$ 167.6 ✓
4	Rear RH front mudguard <i>Dented</i>	1	\$ 189.5 ✓
5	Rear RH front mudguard bracket @ \$65.00 <i>not new</i>	2	\$ 130 X
6	Rear exhaust pipe <i>new</i>	1	\$ 766.4 X
7	Rear exhaust pipe mounting <i>new</i>	1	\$ 42.6 X
8	Rear axle <i>not new</i>	1	\$ 3830.9 X
9	Rear RH wheel bearing @ \$2038.50 <i>new</i>	2	\$ 4077 X
			\$ 9382.4
Less 10% Disc			\$ 938.24
Total			\$ 8444.16

Special Nett Items

1	Rear RH wheel rim <i>lit</i>	780	1	\$ 456.6 <i>280</i>
2	Rear RH tyre <i>lit</i>	580	1	\$ 234 <i>180</i>
3	Advertisement sticker <i>new</i>	400	Total	\$ 690.6

Labour Cost

1	Remove & reinstall rear suspension	\$ 300 <i>220</i>
2	Remove, replace & repair consistent to the accident	1070 \$ 900 <i>400</i>
3	Respray painting	\$ 1000 <i>450</i>
Total		\$ 2200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand Total \$ 11334.76

total: 2239.79

L/S: 1.8k

04 Days

1.8k