

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 27 Apr 2018

Preliminary Advice

Vehicle No	: S2969CD	Accident Date	: 17/12/2017
Make	: TOYOTA WISH	Policy No.	: A27636075MCY
Assignment Date	: 25/04/2018	Excess	: S\$700.00
Date of Inspection	: 26/04/2018	Est. Duration of Repair	: 10.00
Inspection At	: PRESTIGE AUTO AIR-CON ACCESSORIES (HQ) 191 TANJONG KATONG ROAD, SHELL SERVICE STATION SINGAPORE 436993		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,677.10
Revised Amount	:S\$	14,458.90
Check Items (Estimated)	:S\$	2,208.80
Total	:S\$	16,667.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- (X) The vehicle is economical for repair.
- (X) Vehicle repair on part by part base on list price.