

ASS. REC. BY:

REF: CS/FCL18007680/Ks6m2

Special Instruction:

Survivor: Kenneth ASSIGNMENT (Office)From (Person): LWS Karen Tan of FCL Date/Time: 26042018 11:19am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJH 8183S Insured: SHA 7336Kat Workshop m/s Supreme Auto Tel: 6752 8211of 176 Sin Ming Dr #02-01Policy No: _____ Claim No: D18003265MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' 27-04-2018 H.O.D. Endorsement: _____Date/Time: 26042018 11:30am Person Contacted: Amunda Vehicle IN / OUT: (IN)

Date/Time	Action/Instruction (✓) Estimate
	<u>SJH 8183S - CC3/A7616017868/H1hg3g2</u> <u>DOA: 19092016</u>
	<u>SHA 7336K - CC3/A7314013428/H1hg3g2</u> <u>DOA: 1207-2014</u>
<u>30/04/18</u>	<u>@ 15:03 pm. revised to Karen Tan V.i.e email.</u>

REF: F01

ASSIGNMENT

From:

Date: 27/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJH 8183S

at Workshop m/s

Supreme Auto

of

176 Sin Ming Ave #02-01

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$466

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS'DSI

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJH 8183S

Yr Regn:

03 11

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Ceny (A)

C.C.

2362

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

135296

T/Radio: Insured / Std / NI / NA

Eng/No:

G/No:

NR053FK4000015209

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

8

mm

L/Bal.

6

mm

L/Bal.

8

mm

D.O.A.

24/4/18

D.O.I.

27/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rn

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/4 Rn pass to Customer

(\$3,692/- Red -49%)

RECEIVED 24 AUG 2018

Date/Time, File Pass to?

24/08/18

1)

Typst

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + PG SI

Photos

Others

TOTAL

150

50

50+50

32

332

Report Format :

Lump Sum / I.B.I. (\$ 3,850/- 41%)

MOTOR SURVEY ASSIGNMENT

Date	25-04-2018	Our Ref No. D18003265MFSH
Accident Date	24-04-2018	Claim Type. Third Party
Insured Vehicle	SHA7336K	Third Party Vehicle. SJH8183S
Survey Location	176 SIN MING DRIVE #02-01	
Contact Person.	NA	
Contact No.	64528211/ 64528211	Fax No. 64517420
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SUPREME AUTO SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 30 April 2018 3:03 PM
To: 'Catherine Chong (LKK Auto)'; 'Claim Workflow System';
ASSIGNMENTS@LKKAUTO.COM
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18003265MFSH/1
Attachments: SJH 8183S - Preli Advise.pdf

Dear Karen,

Enclosed herewith preliminary advice of SJH 8183S.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 26 April 2018 11:32 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18003265MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 26 April, 2018 11:19 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003265MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003265MFSH

Date: 30 April 2018

Our Ref: CS/FCI18007680/Ks3b

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJH 8183S.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/04/2018 at the premises of M/s Supreme Auto Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,930.00</u>
Revised Estimate Amount (Labour)	: S\$ <u>1,250.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.
Pending Parts Prices
Repair days: 5 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUEEN RENTALS PTE LTD

c/o 46 Lenton Plain
Singapore 786548

* Copy
proposal

Not Notified
11 days & ?
Resurvey After Paint
3 days

Date: 25/04/18

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA CAMRY HYBRID / SJH8183S		
1 pc	front bonnet <i>RM</i>	
1 pc	front head lamp (HID) <i>Brn</i>	
1 pc	front fender <i>RM</i>	
1 pc	front fender dust cover <i>CRM</i>	
1 pc	front bumper <i>CRM</i>	
1 pc	front bumper retainer <i>Di</i>	
1 pc	front bumper fog lamp <i>Sm X</i>	
1 pc	front bumper fog lamp cover <i>Sm X</i>	
1 pc	front bumper moulding <i>RM</i>	
1 pc	front grille <i>?</i>	
2 pc	front shock absorber <i>?</i>	
1 pc	front lower arm <i>?</i>	
1 pc	knuckle arm <i>?</i>	
1 pc	tie rod <i>Pen X</i>	
1 pc	tie rod end <i>X Sm</i>	
Sub-total		0.00
1 pc	alloy rim <i>RM</i> s.nett	450.00
	To remove and replace all the parts mentined above, knocking and straighten up the necessary affected areas.	600.00
	To checking wiring system.	200 30.00
	To spray painting on affected areas.	700 800.00
	To remove and install front undercarriage parts to enable repair.	300.00 ?
	To perform 4 wheels computerised alignment.	600 100.00
	To replace alloy rims & perform wheel balancing.	200 100.00
Total		1,930.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUEEN RENTALS PTE LTD

c/o 46 Lentor Plain
Singapore 786548

Not Notified
11 hrs @ 3850/hr
Presumy After Paint

5 days

Date: 25/04/18

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA CAMRY HYBRID / SJH8183S		
1 pc	front bonnet <i>R1</i>	1207.80
1 pc	front head lamp (HID) <i>Bm</i> 1154.00	1352.90
1 pc	front fender <i>R1</i>	617.50
1 pc	front fender dust cover <i>CRM</i>	206.10
1 pc	front bumper <i>CRM</i> 468.60	1183.50
1 pc	front bumper retainer <i>DIT</i>	82.70
1 pc	front bumper fog lamp <i>sm X MCM</i>	279.30
1 pc	front bumper fog lamp cover <i>sm</i>	98.60
1 pc	front bumper moulding <i>sm</i>	109.20
1 pc	front grille <i>?</i>	438.50
1 pc	front shock absorber <i>?</i>	396.70 X
1 pc	front lower arm <i>?</i>	383.50 X
1 pc	knuckle arm <i>?</i>	425.70 X
1 pc	tie rod <i>sm X</i>	103.00
1 pc	tie rod end <i>X sm</i>	131.00
		Sub-total 7016.00
1 pc	alloy rim	5262.00
		Total 12278.00
		Total 1,930.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

To remove and replace all the parts mentined above, knocking and straighten up the necessary affected areas.

To checking wiring system.

To spray painting on affected areas.

To remove and install front undercarriage parts to enable repair.

To perform 4 wheels computerised alignment.

To replace alloy rims & perform wheel balancing.

Sub-total

s.nett \$350.00

Total



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118007680/Ksbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 7336K	Veh. Inspected	SJH 8183S
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18003265MFSH	Excess (\$)	0.00
	Assign From	KARENT	Assign Date	26/04/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY (A)	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	MR053FK4000015209	Colour	METALLIC GREY
	Odometer	135296	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	8 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	8 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	24/04/2018	Inspection Date	27/04/2018
	Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 8183S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	BENT	1,207.80	1,207.80
1	FRONT HEAD LAMP (HID)	BROKEN	1,352.90	1,154.00
1	FRONT FENDER	BENT	617.50	617.50
1	FRONT FENDER DUST COVER	CRACKED	206.10	206.10
1	FRONT BUMPER	CRACKED	1,183.50	468.60
1	FRONT BUMPER RETAINER	DISTORTED	82.70	82.70
1	FRONT BUMPER FOG LAMP	MTG CRACKED	279.30	279.30
1	FRONT BUMPER FOG LAMP COVER	SERVICEABLE	98.60	-
1	FRONT BUMPER MOULDING	NECESSARY	109.20	109.20
1	FRONT GRILLE	MTG CRACKED	438.50	438.50
1	FRONT SHOCK ABSORBER	SERVICEABLE	396.70	-
1	FRONT LOWER ARM	SERVICEABLE	383.50	-
1	KNUCKLE ARM	SERVICEABLE	425.70	-
1	TIE ROD	SERVICEABLE	103.00	-
1	TIE ROD END	SERVICEABLE	131.00	-
	LESS 25% DISCOUNT		-1,754.00	-1,140.93
			5,262.00	3,422.77
SPECIAL NETT ITEMS				
1	ALLOY RIM (SN)	DENTED	350.00	280.00
			350.00	280.00
LABOUR				
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS.		600.00	450.00
	TO CHECKING WIRING SYSTEM.		30.00	20.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		800.00	700.00
	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR.	NOT NECESSARY	300.00	-
	TO PERFORM 4 WHEELS COMPUTERISED ALIGNMENT.		100.00	60.00

Report Ref No. CS/FCI18007680/Ksbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE ALLOY RIMS & PERFORM WHEEL BALANCING.		100.00	20.00
			1,930.00	1,250.00
GRAND TOTAL			7,542.00	4,952.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,850.00

Report Ref No. CS/FCI18007680/Ksbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.