



# LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 Tel: 6741-1730 / 731 Fax: 6741-5746 Email: liubro@gmail.com

Invoice/Ref No: GBB5651D180214

## Estimate

### Customer

Name: AXA Insurance Singapore Pte Ltd

Address: Motor Claims Department

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Date: 25-04-18

Vehicle No: GBB5651D

Model/Make: Mitsubishi

FB70BB1SRDEA

| Item No. | Descriptions Of Parts                                                           | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|----------|---------------------------------------------------------------------------------|---------------------------------|------------------------------------|
| 1        | Front Lh Door <i>21/2nd 1645.12</i>                                             | \$ 1,995.00                     |                                    |
| 2        | Door Rubber <i>neu 281.15</i>                                                   | \$ 408.30                       |                                    |
| 3        | Door Outer Garnish <i>dis</i>                                                   | \$ 233.10                       |                                    |
| 4        | Door Outer Garnish Bottom <i>NS</i>                                             | \$ 365.80                       |                                    |
| 5        | Door "ROC" Sticker <i>neu</i>                                                   | \$ 45.00                        |                                    |
| 6        | Side Lamp <i>11</i>                                                             | \$ 227.40                       |                                    |
| 7        | Signal Lamp <i>11</i>                                                           | \$ 245.00                       |                                    |
| 8        | Wheel Fender Outer <i>mudguard dis</i>                                          | \$ 545.10                       |                                    |
| 9        | Wheel Fender Inner <i>11</i>                                                    | \$ 366.10                       |                                    |
| 10       | Cabin Lock <i>3rd/2nd 345.10</i>                                                | \$ 1,090.00                     |                                    |
| 11       | Fuel Box <i>neu</i>                                                             | \$ 970.00                       |                                    |
| 12       | Battery <i>11</i>                                                               | \$ 380.00                       |                                    |
| 13       | Rear Lh Box Fridge Corner Panel <i>neu</i>                                      | \$ 1,400.00                     |                                    |
| 14       | Box Fridge Lower Panel <i>Step bracket</i>                                      | \$ 1,400.00                     |                                    |
| 15       | Box Fridge Stainless Panel <i>neu</i>                                           | \$ 1,600.00                     |                                    |
| 16       | Box Fridge Support Rubber 02 pcs (@ \$180.00) <i>11</i>                         | \$ 360.00                       |                                    |
| 17       | Freezer Side Door Rubber <i>11</i>                                              | \$ 700.00                       |                                    |
| 18       | Step Panel <i>garnish</i>                                                       | \$ 480.00                       |                                    |
| 19       | Wheel Fender <i>mudguard 11</i>                                                 | \$ 665.00                       |                                    |
|          | 'Corporate' Advertisement & Artwork <i>11</i>                                   | \$ 600.00                       |                                    |
|          | To check all wiring & electrical component for proper function                  | \$ 60.00                        |                                    |
|          | Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc            | \$ 1,400.00                     |                                    |
|          | To putty & spray painting & including touch up paint on accident affected areas | \$ 1,200.00                     |                                    |
|          | To remove, replace and transfer door panel, fitting and mechanisms              | \$ 80.00                        |                                    |
|          | To apply Rust Proofing, reseal tuff coating treatment on accident area          | \$ 60.00                        |                                    |

Total Parts & Labour of estimate for damaged vehicle

\$ 16,875.80

Total amount in Lump Sum Basis for repaired vehicle

\$

SDLS:



M/s Liu's Brother Auto Engrg Wks

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized  
LKK  
2/5/2000  
4dy

26/4/18  
take photo after repair

P-4934.67  
282  
3701.00  
s.w - 1130  
labr - 1430  
total  
5008.00