

INS. CASE OWNER:

Sham. ~~Joseph~~
AURAN

CC 6, 011 1800 2693, Aug 3 2018

LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

25/4/18

Date / Time:

25/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFF 7535 R

Claim No.:

SM1800205702

Name of Insured:

Leo Chong Mary Philip Arminis

Policy No.:

DMPUSN1400682004

Insured Tel No.:

6725 9011 HP: 9087 7111

Make / Model:

POPO MONDRO

Excess Sec II :SS

D.O.A.:

25/4/2018

Place of Accident:

FAB COAST PAPERWAY (ECP) ?
CHANGAI

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SFF 7535 R


SUB 8904 L

SJV 3475 J



INSRS:
WSP:
Tel:
Liability:
RMKS:

07




INSRS:
WSP:
Tel:
Liability:
RMKS:

Konglav
TP



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

SUB 8904 L - X; SFF 7535 R - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Man date/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

3 vehicle chain collision, of last vehicle.
called OI, overseas done.

2/1/19 - file pass to Neo the leader

RECEIVED 02 OCT 2019

PRELIMINARY ADVICE

Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 3/12/18

Confirm with SHAM

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.: 28 (see A ltr)

If NO or B 28, Ass. Lia: 100%

Repair Cost: W6H

SS

38413.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

2300.00 (\$100 x 23 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

8/1/19

TP
\$44w.w

Total:

SS

40715.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

40715.00

Name 1:

Kang Car Repairs Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18007693/Aua3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 26-04-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKF 7535R	Veh. Inspected	SLB 8904L
Policy No.	SNM18D02057C02	Coverage (\$)	0.00
Claim No.	DMPCSN1400681804	Excess (\$)	0.00
Assign From		Assign Date	26/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/04/2018	Inspection Date	25/04/2018
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST: 201300201N

Attn: Adrian Ling

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

Estimate No: EST1800113
 Date: 24 Apr 2018

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Veh Reg No: SLB8904L
 Make/Model: AUDI A6 1.6 TFSI
 ULTRA (PI) (NAV)
 Chasis No: WAUZZZ4G8GN086774
 Reg. Date: 26/04/2016
 Your Ref No: SKF7535R

Claim Type: Third Party
 Accident Date: 23/04/2018
 TP Veh Reg No: SKF7535R

Estimate Repair Cost to Vehicle No :SLB8904L

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR BUMPER <i>Deformed</i>	2,017.60	✓
2	1 PC REAR BUMPER REINFORCEMENT <i>Bent</i>	756.70	✓
3	1 PC REAR BUMPER SPONGE	336.70	*
4	2 PCS REAR BUMPER BRACKET <i>new</i>	151.80	*
5	2 PCS REAR BUMPER RETAINER <i>new</i>	77.00	✓
6	1 PC REAR TOWING COVER <i>Deformed</i>	49.60	✓
7	1 PC REAR LOWER BUMPER	528.20	✓
8	2 PCS REAR BUMPER INNER SIDE RETAINER <i>new</i>	193.80	✓
9	1 PC EXHAUST PIPE <i>Repair</i>	2,668.10	*
10	1 PC REAR EXHAUST HEAT COVER <i>crumpled</i>	269.70	✓
11	1 PC EXHAUST CHROME RH <i>cut</i>	652.70	497
12	1 PC EXHAUST CHROME LH <i>cut</i>	652.70	497
13	4 PCS EXHAUST MOUNTING <i>new new</i>	118.40	*
14	1 PC BOOT LID <i>Buckled</i>	2,600.80	2485
15	1 PC BOOT LID LOGO	101.60	✓
16	1 PC BOOTLID "A6" EMBLEM <i>new</i>	72.30	✓
17	1 PC BOOTLID "TFSI" EMBLEM	86.20	✓
18	1 PC BOOT LID RUBBER <i>cut</i>	190.70	✓
19	1 PC BOOT LID CHROME MOULDING <i>cut</i>	274.40	✓
20	1 PC BOOT LID LAMP LH <i>new</i>	1,072.50	*
21	1 PC BOOT LID LAMP RH <i>new</i>	1,072.50	*
22	1 PC BOOT LID TRIM <i>new new</i>	506.40	*
23	1 PC BOOT LID LOCK <i>Damaged</i>	443.80	✓
24	1 PC BOOT LID LOCK CHECKER	98.10	*
25	1 PC REVERSE CAMERA <i>new</i>	1,400.93	*
26	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	333.40	*
27	1 PC BOOT LID AUTO OPENER SENSOR <i>new</i>	243.80	*
28	1 PC BOOT LID AUTO MOTOR	487.60	*
29	1 PC SPARE TYRE COVER <i>Deformed</i>	496.80	✓

17954.83

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6744 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111

FAX: 62247175

ATTN: Motor Claim Department

Estimate No: EST1800113

Date: 24 Apr 2018

Veh Reg No: SLB8904L

Make/Model: AUDI A6 1.6 TFSI
 ULTRA (PI) (NAV)

Chasis No: WAUZZZ4G8GN086774

Reg. Date: 26/04/2016

Your Ref No: SKF7535R

Claim Type: Third Party

Accident Date: 23/04/2018

TP Veh Reg No: SKF7535R

Estimate Repair Cost to Vehicle No :SLB8904L

Quantity	Description	List Price	Amount
		S\$	S\$
30	1 PC SPARE TYRE SPONGE <i>Deformed</i>	174.80 ✓	
31	1 PC REAR FENDER TRIM RII <i>Not Nec</i>	800.70 ✗	
32	1 PC REAR FENDER TRIM LH <i>Not Nec</i>	800.70 ✗	
33	1 PC TAIL LAMP LH <i>Not</i>	1,170.90 <i>1094</i>	
34	1 PC TAIL LAMP - RH <i>Not</i>	1,170.90 <i>1094</i>	
35	1 PC REAR PANEL <i>Reps</i>	1,400.70 ✗	
36	1 PC REAR PANEL TRIM <i>Deformed</i>	266.70 ✓	
37	1 PC BONNET <i>Dented</i>	4,576.10 ✓	
38	1 PC BONNET TRIM <i>Not Nec</i>	264.10 ✗	
39	2 PCS BONNET SIDE LOCK <i>Damaged</i>	598.80 ✓	
40	1 PC FRT SUPPORT PANEL <i>Deformed</i>	1,009.70 ✓	
41	1 PC FRT SUPPORT PANEL TOP COVER <i>cracked</i>	196.40 ✓	
42	1 PC HEADLAMP LH <i>cracked</i>	9,454.20 <i>8386</i>	
43	1 PC HEADLAMP RH <i>cracked</i>	9,454.20 <i>8386</i>	
44	2 PCS FRT HEAD LAMP SIDE BRACKET <i>Damaged</i>	192.80 ✓	
45	1 PC FRT GRILLE <i>cracked</i>	1,640.00 ✓	
46	1 PC FRT BUMPER <i>Deformed</i>	2,225.10 ✓	
47	1 PC FRT BUMPER REINFORCEMENT <i>Bent</i>	762.10 ✓	
48	1 PC FRT BUMPER SPONGE <i>cracked</i>	187.00 ✓	
49	2 PCS FRT BUMPER BRACKET <i>Bent</i>	409.40 ✓	
50	2 PCS FRT BUMPER SIDE RETAINER <i>New</i>	241.40 ✓	
51	1 PC FRT TOWING COVER <i>Not Nec</i>	45.30 ✗	
52	1 PC FRT FOG LAMP COVER LH <i>Deformed</i>	289.70 ✓	
53	1 PC FRT FOG LAMP COVER CHROM LH <i>Not Nec</i>	116.70 ✗	
54	1 PC FRT BUMPER LOWER CENTRE CHROM <i>cracked</i>	523.70 <i>260</i>	
55	1 PC FRT AIR CONDENSER <i>Dented</i>	989.70 ✓	
56	2 PCS FRT AIR CONDENSER SIDE GARNISH <i>cracked</i>	314.26 ✓	
57	1 PC RADIATOR <i>Not Nec</i>	900.93 ✗	
58	4 PCS REVERSE SENSORS <i>2 pieces damaged</i>	883.88 <i>440</i>	
59	4 PCS FRT PARKING SENSORS <i>2 pieces damaged</i>	883.88 <i>440</i>	

41,944.75

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
TEL: 63896111 **FAX:** 62247175
ATTN: Motor Claim Department

Estimate No: EST1800113
Date: 24 Apr 2018

Veh Reg No: SLB8904L
Make/Model: AUDI A6 1.6 TFSI
 ULTRA (PI) (NAV)
Chasis No: WAUZZZ4G8GN086774
Reg. Date: 26/04/2016
Your Ref No: SKF7535R

Claim Type: Third Party
Accident Date: 23/04/2018
TP Veh Reg No: SKF7535R

Estimate Repair Cost to Vehicle No :SLB8904L

Quantity	Description	List Price	Amount
		SS	SS
60	1 PC FRT FOG LAMP COVER RH <i>ut</i>	289.70 ✓	
61	1 PC FRT FOG LAMP COVER CHROM RH <i>Not Rec</i>	116.70 ✗	
62	1 PC REAR BUMPER CENTRE RETAINER <i>cracked</i>	96.20 ✓	
63	1 PC REAR BUMPER INNERBOOTLID AUTO SENSOR <i>Damaged</i>	426.90 ✓	
		60,829.08	<i>63</i>
	<i>44024.16</i>	Less 5%	<i>3,041.45</i> 57,787.28
	<i>41822.95</i>		
	Special Net		
64	1 SET REAR BUMPER CLIPS <i>rec</i>	50.00 <i>30</i>	
65	1 SET BOOTLID TRIM CLIPS <i>Not Rec</i>	40.00 ✗	
66	1 PC REAR NUMBER PLATE <i>sent</i>	50.00 ✓	
67	1 SET REAR FENDER RH TRIM CLIPS <i>Not Rec</i>	40.00 ✗	
68	1 SET REAR FENDER TRIM CLIPS LH <i>Not Rec</i>	40.00 ✗	
69	1 SET REAR PANEL TRIM CLIPS <i>rec</i>	80.00 <i>10</i>	
70	1 SET BONNET TRIM CLIPS <i>Not Rec</i>	80.00 ✗	
71	1 SET FRT SUPPORT PANEL TOP COVER CLIPS <i>rec</i>	60.00 <i>10</i>	
72	1 SET FRT GRILLE CLIPS <i>rec</i>	40.00 <i>20</i>	
73	1 SET FRT BUMPER CLIPS <i>rec</i>	80.00 <i>30</i>	
74	1 PC FRT NUMBER PLATE <i>sent</i>	50.00 <i>30</i>	
		610.00	610.00
	Labour		
75	1 TO CHECK WIRING	50.00 <i>30</i>	
76	1 TO REMOVE AND REFIT REVERSE SENSOR	100.00 <i>60</i>	
77	1 TO REMOVE AND REFIT REVERSE CAMERA	100.00 <i>60</i>	
78	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	250.00 <i>120 ✗</i>	
79	1 TO SPRAY UNDERSEAL	150.00 <i>60</i>	
80	1 (REAR) TO SPRAY PAINTING	1,500.00 <i>600</i>	
81	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00 <i>600</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

Estimate No: EST1800113
 Date: 24 Apr 2018

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Veh Reg No: SLB8904L
 Make/Model: AUDI A6 1.6 TFSI
 ULTRA (PI) (NAV)
 Chasis No: WAUZZZ4G8GN086774
 Reg. Date: 26/04/2016
 Your Ref No: SKF7535R

Claim Type: Third Party
 Accident Date: 23/04/2018
 TP Veh Reg No: SKF7535R

Estimate Repair Cost to Vehicle No :SLB8904L

Quantity	Description	List Price	Amount
		S\$	S\$
82	1 TO CHECK WIRING	50.00	30
83	1 TO REFILL AIRCON GAS	120.00	✓
84	1 TO REMOVE AND REFIT PARKING SENSOR	80.00	60
85	1 TO SPRAY UNDERSEAL	100.00	50
86	1 (FRONT) TO SPRAY PAINTING	1,300.00	500
87	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,300.00	800
		6,700.00	6,700.00
		Total	S\$ 65,097.78 ⁶³
		Add GST @ 7%	4,556.84
		Total Amount Payable	S\$ 69,654.62 ⁴⁶

TOTAL: SINGAPORE DOLLAR SIXTY NINE THOUSAND SIX HUNDRED FIFTY FOUR AND CENTS SIXTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

LKK Auto Consultants advise notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian King

4/2 25/04/18

17 Days

total: 24972.95

H/S: 35-9K

Mei Kwan (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 27 April, 2018 4:11 PM
To: Mei Kwan (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SKF7535R (OI : CTI - SNM18D02057C02) and SLB8904L (TP : LKK REF - CC6/CTI18007693/Aua3) on 23.04.2018
Attachments: leeSZ_SNM18D02057C02-SKF7535R-LKKDirectSettlementAccidentLtr_CLCR95.063.pdf; MCCA18053146-SKF7535R.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Jowyn Tay

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 27 April, 2018 10:27 AM
To: Claims Dept of CTI
Cc: Jowyn Tay; Lucas Lee; Thin Thin (LKKAuto); Vivian Lau (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving SKF7535R (OI : CTI - TBA) and SLB8904L (TP : LKK REF - CC6/CTI18007693/Aua3) on 23.04.2018



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200206384E

Our Reference: **SNM18D02057/C02/4**

Date : **27 APRIL 2018**

via Ordinary & Registered Mail

**TEO CHONG MENG PHILIP DOMINIC
BLK 123 TAMPINES ST 11
#08-364
SINGAPORE 521123**

Dear Sir / Madam

**ACCIDENT INVOLVING SKF7535R AND SLB8904L ON 23 APRIL 2018
ALONG EAST COAST PARKWAY (ECP) TOWARDS CHANGI**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SLB8904L**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : THIN THIN

Ref : CC6/CT118007693/AUA3

Contact No : 68412360

via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0444A) - META AGENCY PTE LTD

F01/LKKDS-2013



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref : KCR0420188904CTI
Your Ref : SKF7535R

Date : 24 AUG 2018

WITHOUT PREJUDICE

China Taiping Insurance (Singapore) Pte Ltd
Motor Claim Department
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Dear Sirs,

Accident involving SLB8904L / SKF7535R and others on 23.04.2018 along ECP twds Changi Airport.

We refer to the above accident. On our record showed that you are the insurer of motor vehicle SKF7535R.

We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense.

On behalf of and as authorized by M/S Singapore Mobility Corporation Pte Ltd, the owner of motor-vehicle no: SLB8904L, we submit their claim to you:

Cost of repairs (Inclusive of 7% GST)	\$38,413.00
Loss of use (23 days x \$200.00-Private Hire(Chauffeur))	\$ 4,600.00
GIA search fee	\$ 2.00
	\$ 43,015.00
	=====

Our claim for the loss of use is as follows :

<u>No of days</u>	<u>Date</u>	<u>Remarks</u>
	23.04.18	Date of Accident
1	24.04.18	} Accident reporting
2	25.04.18	} Survey by LKK Auto
3	26-04.18	} Day 1 repair Sunday
4	27.04.18	} Day 2
5	28-04.18	} Day 3
6	29.04.18	} Sunday
7	30.04.18	} Day 4
8	01.05.18	} P.Holiday (Labour Day)
9	02.05.18	} Day 5
10	03.05.18	} Day 6

<u>No of days</u>	<u>Date</u>	<u>Remarks</u>
11	04.05.18	} Day 7
12	05.05.18	} Day 8
13	06.05.18	} Sunday
14	07.05.18	} Day 9
15	08-05.18	} Day 10
16	09.05.18	} Day 11
17	10-05.18	} Day 12
18	11.05.18	} Day 13
19	12.05.18	} Day 14
20	13.05.18	} Sunday
21	14.05.18	} Day 15
22	15.05.18	} Day 16
<u>23</u>	16.05.18	} <u>Day 17</u>
23 days		recommended 17 repair days

Enclosed herewith are copies of the following documents in support of our client's claim:

- 1) Tax invoice no: KCR-INV1800446
- 2) GIA report and insurance certificate of SLB8904L
- 3) Police Report No : T/20180423/2076
- 4) GIA search fee and invoice
- 5) Vehicle registration card

We hope to receive your early reply soon.

Thank you.

Yours faithfully,
KANG CAR REPAIRERS PTE LTD

.....



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

M/S: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	TEL: 63896111 ATTN: Motor Claim Department	FAX: 62247175	Final No: KCR-INV1800446 Claim No: EST1800113 Date: 16 Aug 2018 Policy No: 5070670731-03 Veh Reg No: SLB8904L Make/Model: AUDI A6 1.6 TFSI ULTRA (PI) (NAV) Chassis No: WAUZZZ4G8GN086774 Engine No: CYG009812 Reg. Date: 26/04/2016
Your Ref No: SKF7535R Claim Type: Third Party Accident Date: 23/04/2018 TP Veh Reg No: SKF7535R			

Tax Invoice to Vehicle No :SLB8904L

PAGE:1

Description	Quantity	List Price S\$	Amount S\$
As recommended by surveyor to proceed repair at total cost/lumpsum cost			S\$ 35,900.00
Add GST @ 7%			2,513.00
Total Amount payable			S\$ 38,413.00

TOTAL: SINGAPORE DOLLAR THIRTY EIGHT THOUSAND FOUR HUNDRED THIRTEEN ONLY

For Kang Car Repairers Pte-Ltd

E. & O. E.

AUTHORISED SIGNATURE

0% 25% 50% 75% 100%

Register New Vehicle (Acknowledgement)**Vehicle Particulars**

Vehicle No.:	SLB8904L		
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car	Vehicle Scheme:	Normal
Vehicle Attachment 1:	No Attachment		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	AUDI	Vehicle Model:	A6 1.8 TFSI ULTRA (PI) (NAV)
Chassis No.:	WAUZZZ4G8GN086774	Engine No.:	CYG009812
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Petrol	Passenger Capacity:	4
Engine Capacity:	1798 cc	Power Rating:	-
Maximum Power Output:	140.0 kW (187 bhp)		
Unladen Weight:	1645 kg	Maximum Laden Weight:	2150 kg
Primary Colour:	Black	Secondary Colour:	-
First Registration Date:	26 Apr 2016	Original Registration Date:	26 Apr 2016
Manufacturing Year:	2015	Open Market Value:	\$39,435.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$21,104.00
No. of Transfers:	0	Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$19,435.00 (140%)
Actual ARF Paid:	\$42,209.00		

Owner Particulars

Owner Name:	SINGAPORE MOBILITY CORPORATION PTE. LTD.
Owner ID Type:	Company
Owner ID:	200603234Z
Registered Address Type:	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:	1A
Registered Street Name:	KUO CHUAN AVENUE
Registered Unit No.:	-
Registered Building Name:	-
Registered Postal Code:	426888
COE No. / Expiry Date:	2016040107000482N / 25 Apr 2026
COE Bid Category:	E - Open Category
QP Paid:	\$46,667.00

Transaction Details

Business Transaction Ref. No.:	20160426122640229598
Business Transaction Date:	26 Apr 2016
Business Transaction Time:	12:26:40

Message

The above vehicle has been successfully registered

Please note that \$79,943.00 will be deducted from your GIRO account.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18007693/Apa3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 09-01-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKF 7535R	Veh. Inspected	SLB 8904L
Policy No.	DMPCSN1400681804	Coverage (\$)	0.00
Claim No.	SNM18D02057C02	Excess (\$)	0.00
Assign From		Assign Date	25/04/2018
2. Vehicle Particulars & Condition			
Make & Model	AUDI A6	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WAUZZZ4G8GN086774	Colour	BLACK
Odometer	150933	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/55R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/04/2018	Inspection Date	25/04/2018
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		17 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 8904L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	2,017.60	2,017.60
1	REAR BUMPER REINFORCEMENT	BENT	756.70	756.70
1	REAR BUMPER SPONGE	NOT NECESSARY	336.70	-
2	REAR BUMPER BRACKET	NOT NECESSARY	151.80	-
2	REAR BUMPER RETAINER	NECESSARY	77.00	77.00
1	REAR TOWING COVER	DEFORMED	49.60	49.60
1	REAR LOWER BUMPER	DEFORMED	528.20	528.20
2	REAR BUMPER INNER SIDE RETAINER	NECESSARY	193.80	193.80
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	2,668.10	-
1	REAR EXHAUST HEAT COVER	CRUMPLED	269.70	269.70
1	EXHAUST CHROME RH	CUT	652.70	497.00
1	EXHAUST CHROME LH	CUT	652.70	497.00
4	EXHAUST MOUNTING	NOT NECESSARY	118.40	-
1	BOOT LID	BUCKLED	2,600.80	2,485.00
1	BOOT LID LOGO	NECESSARY	101.60	101.60
1	BOOTLID "A6" EMBLEM	NECESSARY	72.30	72.30
1	BOOTLID "TFSI" EMBLEM	NECESSARY	86.20	86.20
1	BOOT LID RUBBER	CUT	190.70	190.70
1	BOOT LID CHROME MOULDING	CUT	274.40	274.40
1	BOOT LID LAMP LH	NOT NECESSARY	1,072.50	-
1	BOOT LID LAMP RH	NOT NECESSARY	1,072.50	-
1	BOOT LID TRIM	NOT NECESSARY	506.40	-
1	BOOT LID LOCK	DAMAGED	443.80	443.80
1	BOOT LID LOCK CHECKER	NOT NECESSARY	98.10	-
1	REVERSE CAMERA	NOT NECESSARY	1,400.93	-
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	333.40	-
1	BOOT LID AUTO OPENER SENSOR	NOT NECESSARY	243.80	-
1	BOOT LID AUTO MOTOR	NOT NECESSARY	487.60	-
1	SPARE TYRE COVER	DEFORMED	496.80	496.80
1	SPARE TYRE SPONGE	DEFORMED	174.80	174.80

Report Ref No. CC6/CTI18007693/Apa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER TRIM LH	NOT NECESSARY	800.70	-
1	REAR FENDER TRIM LH	NOT NECESSARY	800.70	-
1	TAIL LAMP LH	CUT	1,170.90	1,094.00
1	TAIL LAMP - RH	CUT	1,170.90	1,094.00
1	REAR PANEL	TO REPAIR SEE LABOUR	1,400.70	-
1	REAR PANEL TRIM	DEFORMED	266.70	266.70
1	BONNET	DENTED	4,576.10	4,576.10
1	BONNET TRIM	NOT NECESSARY	264.10	-
2	BONNET SIDE LOCK	DAMAGED	598.80	598.80
1	FRT SUPPORT PANEL	DEFORMED	1,009.70	1,009.70
1	FRT SUPPORT PANEL TOP COVER	CRACKED	196.40	196.40
1	HEADLAMP LH	CRACKED	9,454.20	8,386.00
1	HEADLAMP RH	CRACKED	9,454.20	8,386.00
2	FRT HEAD LAMP SIDE BRACKET	DAMAGED	192.80	192.80
1	FRT GRILLE	CRACKED	1,640.00	1,640.00
1	FRT BUMPER	DEFORMED	2,225.10	2,225.10
1	FRT BUMPER REINFORCEMENT	BENT	762.10	762.10
1	FRT BUMPER SPONGE	CRACKED	187.00	187.00
2	FRT BUMPER BRACKET	BENT	409.40	409.40
2	FRT BUMPER SIDE RETAINER	NECESSARY	241.40	241.40
1	FRT TOWING COVER	NOT NECESSARY	45.30	-
1	FRT FOG LAMP COVER LH	DEFORMED	289.70	289.70
1	FRT FOG LAMP COVER CHROME LH	NOT NECESSARY	116.70	-
1	FRT BUMPER LOWER CENTRE CHROME	CRACKED	523.70	260.00
1	FRT AIR CONDENSER	DENTED	989.70	989.70
2	FRT AIR CONDENSER SIDE GARNISH	CRACKED	314.26	314.26
1	RADIATOR	NOT NECESSARY	900.93	-
4	REVERSE SENSORS	DAMAGED 2PCS ONLY	883.88	440.00
4	FRT PARKING SENSORS	DAMAGED 2PCS ONLY	883.88	440.00
1	FRT FOG LAMP COVER RH	CUT	289.70	289.70
1	FRT FOG LAMP COVER CHROME RH	NOT NECESSARY	116.70	-

Report Ref No. CC6/CTI18007693/Apa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER CENTRE RETAINER	CRACKED	96.20	96.20
1	REAR BUMPER INNER BOOTLID AUTO SENSOR	DAMAGED	426.90	426.90
	LESS 5% DISCOUNT		-3,041.45	-2,201.21
			57,787.63	41,822.95
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET BOOTLID TRIM CLIPS (SN)	NOT NECESSARY	40.00	-
1	REAR NUMBER PLATE (SN)	BENT	50.00	50.00
1	SET REAR FENDER RH TRIM CLIPS (SN)	NOT NECESSARY	40.00	-
1	SET REAR FENDER TRIM CLIPS LH (SN)	NOT NECESSARY	40.00	-
1	SET REAR PANEL TRIM CLIPS (SN)	NECESSARY	80.00	10.00
1	SET BONNET TRIM CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET FRT SUPPORT PANEL TOP COVER CLIPS (SN)	NECESSARY	60.00	10.00
1	SET FRT GRILLE CLIPS (SN)	NECESSARY	40.00	20.00
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRT NUMBER PLATE (SN)	BENT	50.00	30.00
			610.00	180.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		100.00	60.00
	TO REMOVE AND REFIT REVERSE SENSOR.		100.00	60.00
	TO REMOVE AND REFIT REVERSE CAMERA.		100.00	60.00
	TO REMOVE AND REFIT REAR EXHAUST PIPE.	NOT NECESSARY	250.00	-
	TO SPRAY UNDERSEAL.		250.00	110.00
	(REAR) TO SPRAY PAINTING.		1,500.00	600.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING / WELDING WORKS. INCLUSIVE OF THE REPAIR OF EXHAUST PIPE AND REAR PANEL.		2,900.00	1,400.00
	TO REFILL AIRCON GAS.		120.00	120.00
	TO REMOVE AND REFIT PARKING SENSOR.		80.00	60.00
	(FRONT) TO SPRAY PAINTING.		1,300.00	500.00
			6,700.00	2,970.00
	GRAND TOTAL		65,097.63	44,972.95

Report Ref No. CC6/CTI18007693/Apa3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			35,900.00
---	--	--	-----------

Report Ref No. CC6/CT118007693/Apa3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.