

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2078C

DATE 25/4/2018 14:58

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate -			\$ 43.60
	Boot Lid Hyundai Plate -			\$ 24.20
	Boot Lid 'H' Emblem -			\$ 26.10
	Boot Lid CRDI Plate -			\$ 22.70
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip -			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ✕			\$ 185.80
	Rear Bumper Protector (LH/RH) ✕		\$ 38.00	\$ 76.00
	Rear Panel ✕			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	SUB TOTAL			\$ 3,709.90
	LESS 20%			\$ 741.98
	DISCOUNTED TOTAL			\$ 2,967.92
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Rear Bumper Reverse Sensor ✓			\$ 135.70
				\$ 165.70
	Labour Charge			
	Panel Beating			\$ 850.00 400
	Spray Painting Charge			\$ 600.00 400
	Wiring Charge			\$ 50.00 5
	Tuff Kote			\$ 50.00 20
	Remove/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 4,803.62
	<i>K. L. K. K.</i> <i>26/4/18 1076.</i> <i>3 R.</i> <i>45</i> <i>A. S. K. R. R. P. L. C.</i>			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

LKK Auto

the Repair

- To resurvey before
- To disassemble
- Parts prices
- Third party sub
- No illegal mod
- Supplementary

is subject to final

Acknowledged by Repair

Signature:

and

ce Company