

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2018)
 Parts: M1-MPV TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ETHOZ Protect Pte Ltd/SGQ4288M/26/04/2018 12:12
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	PA ✓ *240.00 F
2	1		*FRONT BONNET HINGE LH	0.00	0.00	X *30.00 F
3	1		*FRONT BONNET HINGE RH	0.00	0.00	X *30.00 F
4	1		*FRONT BONNET LOCK	0.00	0.00	PA ✓ *45.00 F
5	1		*FRONT BONNET LOGO	0.00	0.00	neu ✓ *30.00 F
6	1		*FRONT FENDER LH	0.00	0.00	
7	1		REPAIR *FRONT FENDER RH	0.00	0.00	
8	1		*HEADLAMP LH CHECK ITEM	0.00	0.00	? *280.00 F
9	1		*HEADLAMP RH	0.00	0.00	CRG ✓ *280.00 F
10	1		*FRONT GRILLE CHECK ITEM	0.00	0.00	? *70.00 F
11	10		*FRONT GRILLE CLIP	0.00	0.00	neu ✓ *15.00 F
12	1		*FRONT BUMPER	0.00	0.00	OCV ✓ *280.00 F
13	10		*FRONT BUMPER CLIP	0.00	0.00	neu ✓ *15.00 F
14	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	neu ✓ *35.00 F
15	1		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	neu ✓ *35.00 F
16	1		*FRONT BUMPER LOWER GRILLE LH CHECK ITEM	0.00	0.00	? *35.00 F
17	1		*FRONT BUMPER LOWER GRILLE RH	0.00	0.00	? *35.00 F
18	1		*FOG LAMP COVER LH	0.00	0.00	X *38.00 F
19	1		*FOG LAMP COVER RH	0.00	0.00	X *38.00 F
20	1		*FOG LAMP LH	0.00	0.00	X *95.00 F
21	1		*FOG LAMP RH	0.00	0.00	X *95.00 F
22	1		*FRONT BUMPER FOAM	0.00	0.00	? *45.00 F
23	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *95.00 F
24	1		*BRACE PANEL	0.00	0.00	? *50.00 F
25	1		*SUPPORT PANEL	0.00	0.00	? *500.00 F
26	1		*SUPPORT PANEL TOP GARNISH	0.00	0.00	X *40.00 F
27	10		*SUPPORT PANEL TOP GARNISH CLIP CHECK ITEM	0.00	0.00	X *20.00 F
28	1		*CONDENSER SIDE COVER LH	0.00	0.00	? *35.00 F
29	1		*CONDENSER SIDE COVER RH	0.00	0.00	? *35.00 F
30	1		*CONDENSER 3 CHECK ITEM	0.00	0.00	? *180.00 F
31	1		*RADIATOR	0.00	0.00	? *550.00 F
32	1		*RADIATOR TOP GARNISH	0.00	0.00	? *40.00 F
33	1		*RADIATOR FAN COWLING	0.00	0.00	? *90.00 F
34	1		*RADIATOR FAN BLADE	0.00	0.00	? *90.00 F
35	1		*RADIATOR FAN MOTOR	0.00	0.00	? *150.00 F

F=Franchise part.

Total Parts (S\$) ¥ 3161.50 3,639.00

ETHOZ Protect Pte Ltd/SGQ4288M/26/04/2018 12:12. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT NUMBER PLATE	
2	1	RADIATOR COOLANT	CHECK ITEM

CRA ✓ 35.00
? 30.00

Sub Total (S\$)

65.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	LABOUR TO CARRY OUT FRONT REPAIR	New	400 700.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	35.00 ✓
3	TO SPRAY PAINTING ON FRONT AFFECTED AREA	New	600 700.00
4	TO REMOVE & FIX AIR COND CONDENSER INCLUDING TOP UP AIR COND GAS	New	(100?) 150.00

Gross Labour Cost (S\$) 1335 / 1,585.00

ETHOZ Protect Pte Ltd/SGQ4288M/26/04/2018 12:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

Company Registration No. 199005791M

SUPPLEMENTARY ITEM :

- 1) FRONT AIR BAG SENSOR L/H - \$ 140.00
- 2) FRONT AIR BAG SENSOR R/H - \$ 140.00
- 3) FRONT BONNET STOPPER x 3 PCS - \$ 3.50 x 3PCS
- 4) RADIATOR AIR GUIDE LOWER L/H - \$ 18.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- 5) FRONT BUMPER REINFORCEMENT ARM L/H - \$ 35.00
- 6) FRONT BUMPER REINFORCEMENT ARM R/H - \$ 35.00
- 7) RADIATOR HOSE EXTENSION - \$ 28.00

PARTS - \$ 3,161.50

SN - \$ 65.00

LABOUR - \$ 1,335.00

\$ 4,561.50

RASUL
Hp 90010068

5 days - P/P

27/04/18 @ 1630

EXCESS: 600

Revert

Resurvey by paint

COR: \$ 4561.50

5 DAYS REPAIR

EXCESS: \$ 600



(SUPPLEMENTARY)

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00008128	Date of Loss:	20/04/2018
Vehicle Reg. No.:	SGQ4288M	Driveable?	
Driver Age/Info:	65 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN KAI PIN		
Driver:	TAN CHIN HEE		
Make/Model:	TOYOTA WISH, 1.8 CVT (A)	Vehicle Reg. Date:	10/11/2011
Vehicle Colour:	METALLIC BROWN		
Engine No:	2ZRA811781	Chassis No:	JTDGG20W805002429
Odometer:	191015 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	KINDLY REFER TO SKETCH PLAN.		
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)		

COST OF CLAIMS	Amount
Parts	406.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	406.50
+ GST 7.00% (S\$)	28.46
Nett Amount (S\$)	434.96
+ Previous Estimates (S\$)	5,659.23
Claim Total (S\$)	6,094.19

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 May 2018)

Parts: M1-MPV TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SGQ4288M/11/05/2018 17:14

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT AIR BAG SENSOR LH	0.00	0.00	*140.00 F <i>CR</i>
2	1		*FRONT AIR BAG SENSOR RH	0.00	0.00	*140.00 F <i>CR</i>
3	3		*FRONT BONNET STOPPER	0.00	0.00	*10.50 F <i>CR</i>
4	1		*RADIATOR AIR GUIDE LH (LOWER)	0.00	0.00	*18.00 F <i>CR</i>
5	1		*FRONT BUMPER REINFORCEMENT ARM LH	0.00	0.00	*35.00 F <i>CR</i>
6	1		*FRONT BUMPER REINFORCEMENT ARM RH	0.00	0.00	*35.00 F <i>CR</i>
7	1		*RADIATOR HOSE EXTENSION	0.00	0.00	*28.00 F <i>CR</i>

F=Franchise part.

Total Parts (SS)

406.50

ETHOZ Protect Pte Ltd/SGQ4288M/11/05/2018 17:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

5/11/2018

Repairer Estimates Suppl. #1

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ETHOZ Protect Pte Ltd/SGQ4288M/11/05/2018 17:14. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

Company Registration No. 199005791M

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494988, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 ax: 62992158, 62942354, 62935021
 mail: ftgprnet@mbx3.singnet.com.sg
 ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
 UKUT BATOK CRESCENT
 APORE 658075
 T TO; 22 TAMPINES ST92]
 R BY BRYAN

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
01-68020 HOOD		1	240.000	240.000	240.00
10-68050 HOOD LOCK		1 PCS	45.000	45.000	45.00
75-02086 F/EMBLEM		1	30.000	30.000	30.00
30-68070 HEADLAMP UNIT		1	280.000	280.000	280.00
61-16010 BUMPER CLIP		10	1.500	15.000	15.00
19-68909 F/BUMPER		1 PCS	280.000	280.000	280.00
61-16010 BUMPER CLIP		10	1.500	15.000	15.00
15-68030 F/RETAINER		1 PCS	35.000	35.000	35.00
16-68030 F/RETAINER		1 PCS	35.000	35.000	35.00

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

Lee Chen Sin

SIGNATURE

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494988, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 ax: 62992158, 62942354, 62935021
 mail: ftgprnet@mbx3.singnet.com.sg
 ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
 UKUT BATOK CRESCENT
 APORE 658075
 T TO; 22 TAMPINES ST92]
 R BY BRYAN

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
288m					
156641					
GST Excl Amount :					975.00
Special Discount :					
GST @ 7 % :					68.25

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

1043.25

PRINT BY :
 YAW 02/05/2018 10:54:38

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62965333 67455824

MAZDA/FORD DIV
 TEL: 62935722
 67420368

HONDA/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588

MAZDA/FORD DIV
 TEL: 62935722
 67420368

AIRCON/W/S GLASS
 TEL: 62952336
 67495997

TAX INVOICE

TAX INVOICE NO.: CL383730

INVOICE DATE : 02/05/2018

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YAW

PAGE(S) : 1

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62965333 67455824

MAZDA/FORD DIV
 TEL: 62935722
 67420368

HONDA/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588

MAZDA/FORD DIV
 TEL: 62935722
 67420368

AIRCON/W/S GLASS
 TEL: 62952336
 67495997

TAX INVOICE

TAX INVOICE NO.: CL383730

INVOICE DATE : 02/05/2018

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YAW

PAGE(S) : 2

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgprnet@mbox3.singnet.com.sg
ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
UKUT BATOK CRESCENT
APORE 658075
T TO; 22 TAMPINES ST92]
R BY BRYAN

GST Reg. No.: M2-0059747-8

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
70-68070	HEADLAMP UNIT		1	(SIN) 280.000	(SIN) 280.00
11-68070	GRILLE		1	70.000	70.00
13-68010	F/B COVER (Return)		1 PCS	35.000	35.00
08-68020	BRACE PANEL		1 PCS	50.000	50.00
67-07211	CLIP		10	2.000	20.00
88450-12280	DI447780-3340 CG CONDENSER		1	180.000	180.00
10-22150	RADIATOR		1 PCS	550.000	550.00
73-39375	SENSOR, AIR BAG, FR		2	140.000	280.00
49-68010	PROTECTOR, RADIATOR		1	18.000	18.00
41-09117	F/D STOPPER(2)		3	3.500	10.50
21-68020	REINFORCEMENT		1 PCS	95.000	95.00

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

Lee Chen Sin

SIGNATURE

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgprnet@mbox3.singnet.com.sg
ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
UKUT BATOK CRESCENT
APORE 658075
T TO; 22 TAMPINES ST92]
R BY BRYAN

GST Reg. No.: M2-0059747-8

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
01-68020	SUPPORT PANEL		1 PCS	(SIN) 500.000	(SIN) 500.00
42-68010	F/CHASIS BRACKET		1 PCS	35.000	35.00
288M					
156641					
				GST Excl Amount :	2123.50
				Special Discount :	
				GST @ 7 % :	148.65

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

REPRINT BY :
KAL 03/05/2018 13:16:00

Lee Chen Sin

SIGNATURE

TOTAL

2272.15

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON
TEL: 62954551
67496954

HONDA/HYUNDAI DIV
TEL: 62970688 64542288
67493588

MAZDA/FORD DIV
TEL: 62935722
67420368

AIRCON/W/S GLASS
TEL: 62952336
67495997

TAX INVOICE

TAX INVOICE NO.: CL383799

INVOICE DATE : 03/05/2018

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YAW

PAGE(S) : 1

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON
TEL: 62954551
67496954

HONDA/HYUNDAI DIV
TEL: 62970688 64542288
67493588

MAZDA/FORD DIV
TEL: 62935722
67420368

AIRCON/W/S GLASS
TEL: 62952336
67495997

TAX INVOICE

TAX INVOICE NO.: CL383799

INVOICE DATE : 03/05/2018

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YAW

PAGE(S) : 2

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949632
 Tel: 62992158, 62942354, 62935021
 Email: ftrpnet@mbx3.singnet.com.sg
 ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
 UKUT BATOK CRESCENT
 APORE 658075
 T TO; 22 TAMPINES ST92]
 R BY BRYAN

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62985333 67455824
 MITSUBISHI/PROTON
 TEL: 62954551
 67496954
 HONDA/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588
 MAZDA/FORD DIV
 TEL: 62935722
 67420368
 AIRCON/W/S GLASS
 TEL: 62952336
 67495997

TAX INVOICE
 TAX INVOICE NO.: CL383822
 INVOICE DATE : 04/05/2018
 CREDIT TERMS : 30 DAYS
 SALES ORDER NO.:
 SALESMAN : YAW
 PAGE(S) : 1



DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
41-68010 F/CHASIS BRACKET		1	(SIN) 35.000	(SIN) 35.00
288M 156641			GST Excl Amount : 35.00	
			Special Discount : 2.45	
			GST @ 7 % : 2.45	

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

37.45

PRINT BY :
 YAW 04/05/2018 09:40:46

Lee Chen Sin

SIGNATURE

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949632
 Tel: 62992158, 62942354, 62935021
 Email: ftrpnet@mbx3.singnet.com.sg
 ICB Reg No.: 198301435R

ETHOZ PROTECT PTE LTD
 UKUT BATOK CRESCENT
 APORE 658075
 T TO; 22 TAMPINES ST92]
 R BY BRYAN

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62985333 67455824
 MITSUBISHI/PROTON
 TEL: 62954551
 67496954
 HONDA/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588
 MAZDA/FORD DIV
 TEL: 62935722
 67420368
 AIRCON/W/S GLASS
 TEL: 62952336
 67495997

TAX INVOICE
 TAX INVOICE NO.: CL383855
 INVOICE DATE : 04/05/2018
 CREDIT TERMS : 30 DAYS
 SALES ORDER NO.:
 SALESMAN : YAW
 PAGE(S) : 1



DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
57-21010 TOP HOSE ASSY		1	(SIN) 28.000	(SIN) 28.00
288M 156641			GST Excl Amount : 28.00	
			Special Discount : 1.96	
			GST @ 7 % : 1.96	

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

29.96

PRINT BY :
 YAW 04/05/2018 16:21:11

Lee Chen Sin

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 16 May 2018 5:33 PM
To: 'Lee Chen Sin'; Rasul (LKKAUTO); SUR
Subject: RE: FINALIZATION REPORT OF SGQ-4288-M TOYOTA WISH (OD)(FWD)

Dear Chen Sin,

Confirmed COR \$ 4,561.50 before excess \$600 and GST

Repair days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lee Chen Sin [mailto:ChenSin.Lee@ethozgroup.com]
Sent: Friday, 11 May 2018 5:50 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FINALIZATION REPORT OF SGQ-4288-M TOYOTA WISH (OD)(FWD)

Hi Rasul / Veron,

Attached are the finalization report, supplier invoice, check item photo, supplementary item photo and photo before paint of above mention vehicle.

Please send acceptance once the COR is confirm.

COR : \$ 4,561.50 (Part By Part)
Repair days : 5
Excess : \$600.00

Kindly revert.

Remark :

1. Front Bonnet Stopper 3 pcs – Drop Off item.

Thank you.

Warmest Regards,
Lee Chen Sin

ETHOZ

ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075

Mobile: (65) 8822 8339 / DID: 6654 7520 / Fax: 6654 7542

Website: www.ethozgroup.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018 Sendback Est	26 Apr 2018 12:12 S\$5,289.00	26 Apr 2018 14:06 Edit Adj Rpt	S\$4,561.50 Edit Estimates	S\$4,561.50 View Rpt		Pending for Survey Report Cancel Case
Supp #1	11 May 2018 17:12	11 May 2018 17:14 S\$406.50	11 May 2018 17:14			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TAN KAI PIN, ID: S8103679I		
Vehicle Reg. No.:	SGQ4288M	Date of Loss:	20/04/2018 19:00 - :59 [77 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800004946	Policy/Cover Note No.:	PNPV2017-00008128 (Comprehensive)
		Excess:	S\$600.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/05/2018]		
Driver/Custodian:	TAN CHIN HEE (65 / Male), NRIC: S2513574A, Tel: +6597525532		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (16/05/2018): Alert - Adj Mandate Approved (S\$4561.50) - SGQ4288M - Claim Handler: Clara Li Zi...
- FWD_SG (02/05/2018): Alert - Adj Mandate Approved (S\$4653.00) - SGQ4288M - Claim Handler: Clara Li Zi...
- FWD_SG (30/04/2018): Alert - Adj Mandate Maintained - SGQ4288M - Claim Handler: Clara Li Zi Rong

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGQ4288M (1201800004946)

OD

Apr 20 2018 7:00PM

[TAN KAI PIN]

ETHOZ Protect Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

Assessment Reports

1 per page
☒

No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)		Thumbnail	Print
1	26/04/18 12:12	Repairer Estimates		Load HTM	
2	11/05/18 17:14	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/04/18 12:16	Adjuster Immediate Advice		Load HTM	
2	02/05/18 09:44	Adjuster Immediate Advice		Load HTM	
3	16/05/18 11:17	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page
☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/04/18 12:09	General View		Load JPG	☒
2	30/04/18 12:09	General View		Load JPG	☒
3	30/04/18 12:09	General View		Load JPG	☒
4	30/04/18 12:09	General View		Load JPG	☒
5	30/04/18 12:09	General View		Load JPG	☒
6	30/04/18 12:09	General View		Load JPG	☒
7	30/04/18 12:09	General View		Load JPG	☒
8	30/04/18 12:09	General View		Load JPG	☒
9	30/04/18 12:09	General View		Load JPG	☒
10	30/04/18 12:09	General View		Load JPG	☒
11	30/04/18 12:09	General View		Load JPG	☒
12	30/04/18 12:09	General View		Load JPG	☒
13	30/04/18 12:09	General View		Load JPG	☒
14	30/04/18 12:09	General View		Load JPG	☒
15	30/04/18 12:09	General View		Load JPG	☒
16	30/04/18 12:09	General View		Load JPG	☒
17	30/04/18 12:09	General View		Load JPG	☒
18	30/04/18 12:09	General View		Load JPG	☒
19	30/04/18 12:09	General View		Load JPG	☒
20	30/04/18 12:09	General View		Load JPG	☒
21	30/04/18 12:09	General View		Load JPG	☒
22	30/04/18 12:09	General View		Load JPG	☒
23	30/04/18 12:09	General View		Load JPG	☒
24	30/04/18 12:09	General View		Load JPG	☒
25	30/04/18 12:09	General View		Load JPG	☒
26	30/04/18 12:09	General View		Load JPG	☒
27	30/04/18 12:09	General View		Load JPG	☒
28	30/04/18 12:09	General View		Load JPG	☒
29	30/04/18 12:09	General View		Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
30	30/04/18 12:09	General View	 Load JPG	✓
31	30/04/18 12:09	General View	 Load JPG	✓
32	30/04/18 12:09	General View	 Load JPG	✓
33	30/04/18 12:09	General View	 Load JPG	✓
34	30/04/18 12:09	General View	 Load JPG	✓
35	30/04/18 12:09	General View	 Load JPG	✓
36	30/04/18 12:09	General View	 Load JPG	✓
37	30/04/18 12:09	General View	 Load JPG	✓
38	30/04/18 12:09	General View	 Load JPG	✓
39	30/04/18 12:09	General View	 Load JPG	✓
40	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
41	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
42	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
43	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
44	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
45	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
46	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
47	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
48	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
49	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
50	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
51	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
52	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
53	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
54	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
55	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
56	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
57	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
58	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
59	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
60	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
61	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
62	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
63	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
64	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
65	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
66	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
67	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
68	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
69	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
70	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
71	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
72	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
73	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
74	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
75	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
76	16/05/18 11:05	Reinspection Photo	 Load JPG	✓
77	16/05/18 11:05	Reinspection Photo	Load JPG	✓

Assessment Reports			1 per page	✓
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
78	16/05/18 11:05	Reinspection Photo	Load JPG	✓
79	16/05/18 11:05	Reinspection Photo	Load JPG	✓
80	16/05/18 11:05	Reinspection Photo	Load JPG	✓
81	16/05/18 11:05	Reinspection Photo	Load JPG	✓
82	16/05/18 11:05	Reinspection Photo	Load JPG	✓
83	16/05/18 11:05	Reinspection Photo	Load JPG	✓
84	16/05/18 11:05	Reinspection Photo	Load JPG	✓
85	16/05/18 11:05	Reinspection Photo	Load JPG	✓
86	16/05/18 11:05	Reinspection Photo	Load JPG	✓
87	16/05/18 11:05	Reinspection Photo	Load JPG	✓
88	16/05/18 11:05	Reinspection Photo	Load JPG	✓
89	16/05/18 11:06	Reinspection Photo	Load JPG	✓
90	16/05/18 11:06	Reinspection Photo	Load JPG	✓
91	16/05/18 11:06	Reinspection Photo	Load JPG	✓
92	16/05/18 11:06	Reinspection Photo	Load JPG	✓

Documentation			1 per page	✓
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	25/04/18 12:37	Claimant's NRIC/Driver Nric	Load PDF	
2	25/04/18 12:37	Certificate of Insurance	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/18 09:45	MARK ESTIMATE	Load PDF	
2	16/05/18 11:10	SUPPLEMENTARY	Load PDF	
3	21/05/18 16:57	PARTS INVOICE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	✓
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	23/04/18 11:35	Accident Statement	Load HTM	
2	24/04/18 16:02	Addendum Sheet	Load TIF	
3	24/04/18 16:02	Accident Statement Addm. #1	Load HTM	

Photos/Images			3 per page	✓
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	23/04/18 11:33	Accident Photo	Load JPG	✓
2	23/04/18 11:33	Accident Photo	Load JPG	✓
3	23/04/18 11:33	Accident Photo	Load JPG	✓
4	23/04/18 11:33	Accident Photo	Load JPG	✓
5	23/04/18 11:33	Accident Photo	Load JPG	✓
6	23/04/18 11:33	Accident Photo	Load JPG	✓
7	23/04/18 11:33	Accident Photo	Load JPG	✓
8	23/04/18 11:33	Accident Photo	Load JPG	✓
9	23/04/18 11:33	Accident Photo	Load JPG	✓
10	23/04/18 11:33	Accident Photo	Load JPG	✓
11	23/04/18 11:33	Accident Photo	Load JPG	✓
12	23/04/18 11:33	Accident Photo	Load JPG	✓
13	23/04/18 11:33	Accident Photo	Load JPG	✓
14	23/04/18 11:33	Accident Photo	Load JPG	✓
15	23/04/18 11:33	Accident Photo	Load JPG	✓

Assessment Reports				1 per page ▾	✔
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)		Thumbnail	Print
16	23/04/18 11:33	Accident Photo	i	Load JPG	✔
17	23/04/18 11:33	Accident Photo	i	Load JPG	✔
18	23/04/18 11:33	Driving License	i	Load JPG	✔
19	23/04/18 11:33	Accident Photo	i	Load JPG	✔
20	23/04/18 11:33	Accident Photo	i	Load JPG	✔
21	23/04/18 11:33	Accident Photo	i	Load JPG	✔
22	23/04/18 11:33	Accident Photo	i	Load JPG	✔
23	23/04/18 11:33	Identification Card	i	Load JPG	✔
Documentation				1 per page ▾	✔
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)		Thumbnail	Print
1	23/04/18 11:10	Sketch Plan	i	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Repairer

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18007699/R1VBS2

Date: 21/05/2018

REFERENCE

Insured/Claimant:	TAN KAI PIN	Policy No:	PNPV2017-00008128	Claim No:	1201800004946
Date of Loss:	20/04/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGQ4288M		Engine No:	2ZRA811781
Make & Model:	TOYOTA WISH, 1.8 CVT (A)		Chassis No:	JTDGG20W805002429
Reg. Date:	10/11/2011 (Man. Year: 2011)		Odometer:	191015 km
Colour:	Brown			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	S\$57,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,045.50	3,161.50	884.00	21.85
Miscellaneous Items	65.00	65.00	0.00	0.00
Labour	1,585.00	1,335.00	250.00	15.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,695.50	4,561.50	1,134.00	19.91
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	5,695.50	3,961.50	1,734.00	30.45
+ GST 7.00/7.00% (S\$)	398.69	277.31	121.38	30.44
Nett Amount (S\$)	6,094.19	4,238.81	1,855.38	30.45

INSPECTION

Date of Assignment:	26/04/2018	Present Location:	ETHOZ Protect Pte Ltd (Bukit Batok)
			ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected:	27/04/2018	Inspected At:	30 Bukit Batok Crescent
			Singapore 658075
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=703457&extid=270845&CFID=34147817&CFTOKEN=6

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 May 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGQ4288M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	240.00 F	*240.00 F
2	1		*FRONT BONNET HINGE LH	Serviceable	30.00 F	*- F
3	1		*FRONT BONNET HINGE RH	Serviceable	30.00 F	*- F
4	1		*FRONT BONNET LOCK	Bent	45.00 F	*45.00 F
5	1		*FRONT BONNET LOGO	Necessary	30.00 F	*30.00 F
6	1		*FRONT FENDER LH (NPA)	Repair	-	-
7	1		*FRONT FENDER RH (NPA)	Repair	-	-
8	1		*HEADLAMP LH	Cracked	280.00 F	*280.00 F
9	1		*HEADLAMP RH	Cracked	280.00 F	*280.00 F
10	1		*FRONT GRILLE	Cracked	70.00 F	*70.00 F
11	10		*FRONT GRILLE CLIP	Necessary	15.00 F	*15.00 F
12	1		*FRONT BUMPER	Deformed	280.00 F	*280.00 F
13	10		*FRONT BUMPER CLIP	Necessary	15.00 F	*15.00 F
14	1		*FRONT BUMPER SIDE RETAINER LH	Necessary	35.00 F	*35.00 F
15	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	35.00 F	*35.00 F
16	1		*FRONT BUMPER LOWER GRILLE LH	Cracked	35.00 F	*35.00 F
17	1		*FRONT BUMPER LOWER GRILLE RH	Serviceable	35.00 F	*- F
18	1		*FOG LAMP COVER LH	Serviceable	38.00 F	*- F
19	1		*FOG LAMP COVER RH	Serviceable	38.00 F	*- F
20	1		*FOG LAMP LH	Serviceable	95.00 F	*- F
21	1		*FOG LAMP RH	Serviceable	95.00 F	*- F
22	1		*FRONT BUMPER FOAM	Serviceable	45.00 F	*- F
23	1		*FRONT BUMPER REINFORCEMENT	Bent	95.00 F	*95.00 F
24	1		*BRACE PANEL	Bent	50.00 F	*50.00 F
25	1		*SUPPORT PANEL	Cracked	500.00 F	*500.00 F
26	1		*SUPPORT PANEL TOP GARNISH	Serviceable	40.00 F	*- F
27	10		*SUPPORT PANEL TOP GARNISH CLIP	Necessary	20.00 F	*20.00 F
28	1		*CONDENSER SIDE COVER LH	Serviceable	35.00 F	*- F
29	1		*CONDENSER SIDE COVER RH	Serviceable	35.00 F	*- F
30	1		*CONDENSER	Bent	180.00 F	*180.00 F
31	1		*RADIATOR	Bent	550.00 F	*550.00 F
32	1		*RADIATOR TOP GARNISH	Serviceable	48.00 F	*- F
33	1		*RADIATOR FAN COWLING	Serviceable	90.00 F	*- F
34	1		*RADIATOR FAN BLADE	Serviceable	80.00 F	*- F
35	1		*RADIATOR FAN MOTOR	Serviceable	150.00 F	*- F
Supplementary #1						
36	1		*FRONT AIR BAG SENSOR LH	Cracked	140.00 F	*140.00 F
37	1		*FRONT AIR BAG SENSOR RH	Cracked	140.00 F	*140.00 F
38	3		*FRONT BONNET STOPPER	Necessary	10.50 F	*10.50 F
39	1		*RADIATOR AIR GUIDE LH (LOWER)	Cracked	18.00 F	*18.00 F
40	1		*FRONT BUMPER REINFORCEMENT ARM LH	Bent	35.00 F	*35.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT BUMPER REINFORCEMENT ARM RH	Bent	35.00 F	*35.00 F
42	1		*RADIATOR HOSE EXTENSION	Cracked	28.00 F	*28.00 F
F=Franchise part.						
				Total Parts (S\$)	4,045.50	3,161.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE (CRACKED)	35.00	35.00
2	1	RADIATOR COOLANT (NECESSARY)	30.00	30.00
Sub Total (S\$)			65.00	65.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO CARRY OUT FRONT REPAIR	New	700.00	600.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	35.00	35.00
3	TO SPRAY PAINTING ON FRONT AFFECTED AREA	New	700.00	600.00
4	TO REMOVE & FIX AIR COND CONDENSER INCLUDING TOP UP AIR COND GAS	New	150.00	100.00
Gross Labour Cost (S\$)			1,585.00	1,335.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >