



INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00008128	Date of Loss:	20/04/2018
Vehicle Reg. No.:	SGQ4288M	Driveable?	
Driver Age/Info:	65 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN KAI PIN		
Driver:	TAN CHIN HEE		
Make/Model:	TOYOTA WISH, 1.8 CVT (A)	Vehicle Reg. Date:	10/11/2011
Vehicle Colour:	METALLIC BROWN		
Engine No:	2ZRA811781	Chassis No:	JTDGG20W805002429
Odometer:	191015 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	KINDLY REFER TO SKETCH PLAN.		
Remarks:	VEHICLE AT ETHOZ BUKIT BATOK		
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)		

COST OF CLAIMS	Amount
Parts	3,639.00
Miscellaneous Items	65.00
Labour	1,585.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,289.00
+ GST 7.00% (S\$)	370.23
Nett Amount (S\$)	5,659.23

This claim is handled by: **JACKSON TEO BAN CHYE / SIN / 8822 8339**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2018)**Parts:** M1-MPV TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ETHOZ Protect Pte Ltd/SGQ4288M/26/04/2018 12:12**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	PA ✓ *240.00 F
2	1		*FRONT BONNET HINGE LH	0.00	0.00	X *30.00 F
3	1		*FRONT BONNET HINGE RH	0.00	0.00	X *30.00 F
4	1		*FRONT BONNET LOCK	0.00	0.00	PA ✓ *45.00 F
5	1		*FRONT BONNET LOGO	0.00	0.00	PA ✓ *30.00 F
6	1		*FRONT FENDER LH	0.00	0.00	-
7	1		*FRONT FENDER RH	0.00	0.00	-
8	1		*HEADLAMP LH	0.00	0.00	? *280.00 F
9	1		*HEADLAMP RH	0.00	0.00	CA ✓ *280.00 F
10	1		*FRONT GRILLE	0.00	0.00	? *70.00 F
11	10		*FRONT GRILLE CLIP	0.00	0.00	PA ✓ *15.00 F
12	1		*FRONT BUMPER	0.00	0.00	PA ✓ *280.00 F
13	10		*FRONT BUMPER CLIP	0.00	0.00	PA ✓ *15.00 F
14	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	PA ✓ *35.00 F
15	1		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	PA ✓ *35.00 F
16	1		*FRONT BUMPER LOWER GRILLE LH	0.00	0.00	? *35.00 F
17	1		*FRONT BUMPER LOWER GRILLE RH	0.00	0.00	? *35.00 F
18	1		*FOG LAMP COVER LH	0.00	0.00	X *38.00 F
19	1		*FOG LAMP COVER RH	0.00	0.00	X *38.00 F
20	1		*FOG LAMP LH	0.00	0.00	X *95.00 F
21	1		*FOG LAMP RH	0.00	0.00	X *95.00 F
22	1		*FRONT BUMPER FOAM	0.00	0.00	? *45.00 F
23	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *95.00 F
24	1		*BRACE PANEL	0.00	0.00	? *50.00 F
25	1		*SUPPORT PANEL	0.00	0.00	? *500.00 F
26	1		*SUPPORT PANEL TOP GARNISH	0.00	0.00	X *40.00 F
27	10		*SUPPORT PANEL TOP GARNISH CLIP	0.00	0.00	X *20.00 F
28	1		*CONDENSER SIDE COVER LH	0.00	0.00	? *35.00 F
29	1		*CONDENSER SIDE COVER RH	0.00	0.00	? *35.00 F
30	1		*CONDENSER	0.00	0.00	? *180.00 F
31	1		*RADIATOR	0.00	0.00	? *550.00 F
32	1		*RADIATOR TOP GARNISH	0.00	0.00	? *48.00 F
33	1		*RADIATOR FAN COWLING	0.00	0.00	? *90.00 F
34	1		*RADIATOR FAN BLADE	0.00	0.00	? *80.00 F
35	1		*RADIATOR FAN MOTOR	0.00	0.00	? *150.00 F

F=Franchise part.

Total Parts (\$\$)**3,639.00**

ETHOZ Protect Pte Ltd/SGQ4288M/26/04/2018 12:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT NUMBER PLATE	CRA ✓ 35.00
2	1	RADIATOR COOLANT	? 30.00
Sub Total (\$\$)			65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR TO CARRY OUT FRONT REPAIR	New	? 600 - sprt paint 400 700.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	35.00 ✓
3	TO SPRAY PAINTING ON FRONT AFFECTED AREA	New	600 700.00
4	TO REMOVE & FIX AIR COND CONDENSER INCLUDING TOP UP AIR COND GAS	New	100? 150.00
Gross Labour Cost (\$\$)			1,585.00

ETHOZ Protect Pte Ltd/SGQ4288M/26/04/2018 12:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

Company Registration No. 199005791M

RASUL

HP 90010068

5 days - P/P

27/04/18 @ 1630

EXCESS: 600

REVERT

Resurvey 54 part

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: