

INS. CASE OWNER:

CC 6/AIG1800

7708, Aebb

LKK:
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

25/4/18

Date / Time:

25/4/18

Registered in Merimen:

26/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLM 84AR

Name of Insured:

SOV chai kam

Insured Tel No.:

HP:

25/4/18

Excess Sec II :S\$

D.O.A.:

Claim No.:

393165M0454

Policy No.:

Make / Model:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SUM 6478A



INSRS:

WSP:

Tel:

Liability:

RMKS:

NHT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

15/18
As her

14.5.18

SUM 6478A - 4

SUM 84AR - 4

- NO OIL 1714, SENT VNT 26 LETTER.

TP WITHDRAWN CLAIM AS CASE WAS SETTLED PRIVATELY.

RECEIVED 13 JUN 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st): 2.5.18

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler: Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle /wq

2) Report Format:

TP

3) Survey fee:

+250

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY: Adrian King**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM6578A Yr Regn: 2017, AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienta cc 1496Colour: White A/C: Insured / Std / NI / NASp. Reading: 41563 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NSP1707057180Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60 R15R: 185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 25/04/18Survey held at NHT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPA/G45: 43700 (BED: 7 12.281-65 77%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18007708/Aeb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 26-04-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLU 849R	Veh. Inspected	SLM 6578A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/04/2018	Inspection Date	25/04/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

AUTO FLEETLEASE PTE LTD

25/04/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPA16
Ashis.

NSP1707057180

Accident date: 24/04/2018

Estimated repair cost for vehicle no: SLM6578A TOYOTA SIENTA 1.5 '17

CHASSIS NO: NSP1707057180

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Head Lamp R/H <i>lot</i>		\$2,226.20 ✓
2	1	Front Head Lamp Lower Bracket R/H <i>not m</i>		\$128.00 x
3	1	Front Bumper <i>deformed</i>		\$1,584.50 67890
4	1	Front Bumper Side Retainer R/H <i>new</i>		\$171.95 98
5	1	Front Bumper R/H Fog Lamp Cover <i>lot</i>		\$152.00 ✓
6	1	Front Bumper R/H Fog Lamp <i>not m</i>		\$366.50 x
7	10	Front Bumper Clips <i>new</i>	\$6.50	\$65.00 30
8	1	Front R/H Fender <i>deformed</i>		\$561.45 ✓
9	1	Front R/H Fender Cowling <i>2nd</i>		\$368.85 x
10	10	Front R/H Fender Cowling Clips <i>new</i>	\$6.50	\$65.00 x
11	1	Front R/H Rim <i>lot</i>		\$850.00 400(3w)
12	1	Front R/H Tyre <i>not m</i>		\$350.00 x
13	1	Front R/H Lower Arm <i>not m</i>		\$374.45 ✓
14	1	Front R/H Knuckle Arm <i>deformed</i>		\$381.90 ✓
15	1	Front R/H Knuckle Arm Bearing <i>new</i>		\$174.25 ✓
16	1	Front R/H Shock Absorbers <i>not m</i>		\$381.80 x
17	1	Front R/H Drive Shaft <i>2nd</i>		\$1,621.50 x
18	1	Front Steering Rack <i>new</i>		\$1,278.50 x
19	1	Front Bumper Center Inner Top Rubber <i>2nd</i>		\$366.20 x
20	1	Front R/H Side Mirror Assy <i>new</i>		\$383.60 x

Subtotal:- \$11,851.65

43027

SN: 400

3207.02

Labour charges

To remove & refit R/H front undercarriage

\$380.00 150

To remove & refit R/H drive shaft & steering rack	\$450.00 X
To check wheel alignment computer	\$150.00 80
To check wiring	\$100.00 30
Tuff kote	\$150.00 X
Towing fee	1060 \$100.00 X
Panel beating	\$1,400.00 400
Spray painting	\$1,400.00 400

Subtotal:- \$4,130.00

Total:- \$15,981.65

total 468702
1/5: 3TK.
04 days

Private
settle.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Undertaken by Repairer

TAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 8614Z

Vehicle Details

Vehicle No.: SLM6578A
Vehicle to be Exported: Yes
Intended De-registration Date: 25 Apr 2018
Vehicle Make: TOYOTA
Vehicle Model: SIENTA 1.5G CVT
Primary Colour: White
Manufacturing Year: 2016
Engine No.: 2NR8680263
Chassis No.: NSP1707057180
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$20,994.00
Original Registration Date: 05 Apr 2017
First Registration Date: 05 Apr 2017
Transfer Count: 0
Actual ARF Paid: \$11,392.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 04 Apr 2027
PARF Rebate Amount: \$8,544.00

Intended COE Rebate Details

COE Expiry Date: 04 Apr 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$51,765.00
COE Rebate Amount: \$41,412.00
Total Rebate Amount: \$49,956.00

The information contained herein is correct as at 25 Apr 2018

OK

View Received Message

This mail is associated with :

***SLM6578A (3931652104SG)**
[SLU849R]

TP
AUTO FLEETLEASE PTE LTD
Apr 24 2018 9:00PM
[Sor Chai Kam]
New Hock Teck Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **27/04/2018 16:17 PM.**
To LKK_HQ
CC syazairdina.azlan@aig.com
Subject No OI GIA Report

Hi

Pls be advice that no OI GIA report received
Pls find OI details below for your further actions.

OI name : Sor Chai Kam

Address : 120A KIM TIAN PLACE #06-50
SINGAPORE 161120

Phone no. : 97933994

Thank you.

Regards,

Syaza Irdina

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18007708/Aeb3

02ND May 2018

Sor Chai Kam

120A KIM TIAN PLACE #06-50
SINGAPORE 161120

Dear Sirs,

**ACCIDENT INVOLVING SLU 849R AND SLM 6578A ON 24/04/2018 ALONG/ AT
JURONG LAKE LINK SLIP ROAD BOON LAY WAY**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Asher Sng

Claims

Tel : 6841 6051

Fax: 6741 4108

Email : AsherSng@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

PRIVATE SETTLEMENT

(No Personal Injuries, Minor Damages)

Date of Accident

Date Time

Location

Motor Vehicle Registration No.

Driven by

Motor Vehicle Registration No.

Driven by

There are no personal injuries or death involved

The parties have agreed to settle this matter amicably as follows: (delete a) or b) as applicable

a. Neither party shall be liable to compensate the other party for any loss or damages (direct or indirect) incurred or to be incurred as a result of the accident.

b. Without any admission of liability, (paying party) has paid a sum of \$ 1500 (owner receiving compensation) hereby acknowledges receipt thereof in full and final settlement of all damages and costs incurred and/or to be incurred as a result of the accident.

Both parties have not and will not make a police report of this accident.

Name SOR CHAI KIM (Paying Party)

Tel 97933994 NRIC/Fin No 87576756J

Signature

Name Auto Fleetlease Pte Ltd (Owner Receiving Compensation)

Tel 6408-3833 NRIC/Fin No 2016086142

Signature:



Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 12 June 2018 3:29 PM
To: Lee, Ming-Yao
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: Your Ref: 3931652104SG, Accident Involving SLU 849R & SLM 6578A on 24/04/2018
Attachments: Re: SLM6578A CLAIMING AGAINST SLU849R DOA:24.04.18 *** LKK REF : CC6/AIG18007708/Aeb3

Your Ref: 3931652104SG
Our Ref: CC6/AIG18007708/Aeb3

Hi George,

Accident Involving SLU 849R & SLM 6578A on 24/04/2018

We refer to the above matter.

We were informed by TP workshop that our insured had private settle with claimant.

In view of the above, We will proceed to close file and submit our without prejudice report to your office

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018 Edit Reg		25 Apr 2018 00:00 Edit Adj Rpt	S\$3,700.00 Edit Estimates	S\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Sor Chai Kam , ID: S7576756J									
Main Claimant: AUTO FLEETLEASE PTE LTD , Co. Reg. No.: 201608614Z									
Vehicle Reg. No.: SLM6578A		Date of Loss: 24/04/2018 21:00 - :59 [12 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 3931652104SG		Policy/Cover Note No.: 1800038297							
Vehicle Reg. No. (Insured): SLU849R		Policy No. (Claimant): 99994676							
		Excess:							
Repairer: New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/05/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (21/05/2018): NO OI GIA REPORT - AIG_SG (27/04/2018): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM6578A (3931652104SG)
[SLU849R]
TP
AUTO FLEETLEASE PTE LTD
Apr 24 2018 9:00PM
[Sor Chai Kam]
New Hock Teck Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images										3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	06/06/18 10:59	General View									Load JPG	☒	
2	06/06/18 10:59	General View									Load JPG	☒	
3	06/06/18 10:59	General View									Load JPG	☒	
4	06/06/18 10:59	General View									Load JPG	☒	
5	06/06/18 10:59	General View									Load JPG	☒	
6	06/06/18 10:59	General View									Load JPG	☒	
7	06/06/18 10:59	General View									Load JPG	☒	
8	06/06/18 10:59	General View									Load JPG	☒	
9	06/06/18 10:59	General View									Load JPG	☒	
10	06/06/18 10:59	General View									Load JPG	☒	
11	06/06/18 10:59	General View									Load JPG	☒	
12	06/06/18 10:59	General View									Load JPG	☒	
13	06/06/18 10:59	General View									Load JPG	☒	
14	06/06/18 10:59	General View									Load JPG	☒	
15	06/06/18 10:59	General View									Load JPG	☒	
16	06/06/18 10:59	General View									Load JPG	☒	
17	06/06/18 10:59	General View									Load JPG	☒	
18	06/06/18 10:59	General View									Load JPG	☒	
19	06/06/18 10:59	General View									Load JPG	☒	
20	06/06/18 10:59	General View									Load JPG	☒	
21	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
22	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
23	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
24	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
25	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
26	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
27	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
28	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
29	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
30	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
31	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
32	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
33	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
34	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
35	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
36	06/06/18 10:59	Reinspection Photo									Load JPG	☒	
37	06/06/18 10:59	Reinspection Photo									Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/06/18 10:59	Reinspection Photo	 Load JPG	☒
39	06/06/18 10:59	Reinspection Photo	 Load JPG	☒
40	06/06/18 10:59	Reinspection Photo	 Load JPG	☒
41	06/06/18 10:59	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/04/18 15:47	TP GIA REPORT	 Load PDF	
2	02/05/18 10:22	Non reporting letter	 Load PDF	
3	12/06/18 15:25	PRIVATE SETTLEMENT AGREEMENT	 Load PDF	
4	12/06/18 15:29	EMAIL TO AIG DD 120618	 Load PDF	
5	12/06/18 15:30	EMAIL FROM WSP DD 140518	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18007708/AEB3Q2

Date: 18/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800038297
Claimant Vehicle No : SLM6578A **Insured Vehicle No :** SLU849R
 Date of Loss: 24/04/2018 Nature of Claim: TP Claim No: 3931652104SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM6578A**
 Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 2NR8680263
 Reg. Date: 05/04/2017 (Man. Year: 2016) Chassis No: NSP1707057180
 Colour: White Odometer: 41563 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,851.65	3,627.02	8,224.63	69.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	1,060.00	3,070.00	74.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,981.65	4,687.02	11,294.63	70.67
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	15,981.65	3,700.00	12,281.65	76.85
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/04/2018
 Date Inspected: 25/04/2018 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEAD LAMP R/H	Cut	2,226.20 F	*2,226.20 FL
2	1		*FRONT HEAD LAMP LOWER BRACKET R/H	Not Necessary	128.00 F	*- FL
3	1		*FRONT BUMPER	Deformed	1,584.50 F	*678.90 FL
4	1		*FRONT BUMPER SIDE RETAINER R/H	Necessary	171.95 F	*98.00 FL
5	1		*FRONT BUMPER R/H FOG LAMP COVER	Cut	152.00 F	*152.00 FL
6	1		*FRONT BUMPER R/H FOG LAMP	Not Necessary	366.50 F	*- FL
7	10		*FRONT BUMPER CLIPS	Necessary	65.00 F	*30.00 FL
8	1		*FRONT R/H FENDER	Dented	561.45 F	*561.45 FL
9	1		*FRONT R/H FENDER COWLING	Not Necessary	368.85 F	*- FL
10	10		*FRONT R/H FENDER COWLING CLIPS	Not Necessary	65.00 F	*- FL
11	1		*FRONT R/H RIM	Cut	850.00 FS	*400.00 FS
12	1		*FRONT R/H TYRE	Not Necessary	350.00 F	*- FL
13	1		*FRONT R/H LOWER ARM	Not Necessary	374.45 F	*- FL
14	1		*FRONT R/H KNUCKLE ARM	Damaged	381.90 F	*381.90 FL
15	1		*FRONT R/H KNUCKLE ARM BEARING	Necessary	174.25 F	*174.25 FL
16	1		*FRONT R/H SHOCK ABSORBERS	Not Necessary	381.80 F	*- FL
17	1		*FRONT R/H DRIVE SHAFT	Not Necessary	1,621.50 F	*- FL
18	1		*FRONT STEERING RACK	Not Necessary	1,278.50 F	*- FL
19	1		*FRONT BUMPER CENTER INNER TOP RUBBER	Not Necessary	366.20 F	*- FL
20	1		*FRONT R/H SIDE MIRROR ASSY	Not Necessary	383.60 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,851.65	4,702.70
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,075.68

Total Parts (\$\$)	11,851.65	3,627.02
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT R/H FRONT UNDERCARRIAGE	New	380.00	150.00
2	TO REMOVE & REFIT R/H DRIVE SHAFT & STEERING RACK	New	450.00	0.00
3	TO CHECK WHEEL ALIGNMENT COMPUTER	New	150.00	80.00
4	TO CHECK WIRING	New	100.00	30.00
5	TUFF KOTE	New	150.00	0.00
6	TOWING FEE	New	100.00	0.00
7	PANEL BEATING	New	1,400.00	400.00
8	SPRAY PAINTING	New	1,400.00	400.00
Gross Labour Cost (\$\$)			4,130.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >