

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : Mohamad Asyraf Bin Azmi

Accident Date : 23-Apr-18

Vehicle No : JLC 4916

Vehicle Model : Honda Wave

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front cowling inner bracket	45.00 ✓
1	Top inner cowling	48.00 ✓
2	Fork inner tubes	180.00 ✓
2	Fork outer tubes	190.00 ✓
1	Fork under bracket	170.00 ✓
1	Front sport rim	280.00 ✓
1	Front sport rim shift	42.00 ✓
1	Front rim bearing	38.00 ✓
1	Front brake disc	145.00 X
1	Headlamp	80.00 ✓
1	Meter assy	325.00 X
2	Side mirrors	96.00 ✓
2	Front signals	100.00 10 C
1	Handle bar	78.00 ✓
1	Handle bar inner bracket	50.00 ✓
1	Hand grip (1 set)	90.00 ✓
1	Centre inner panel	60.00 ✓
1	Front footrest bracket	48.00 ✓
1	Front footrest rubber - L/H	22.00 ✓
1	Gear pedal	40.00 X
1	Rear footrest - L/H	38.00 ✓
1	Rear footrest bracket - L/H	65.00 X
1	Basket	32.00 ✓
1	Fairing assy (1 set)	395.00 ✓
		\$ 2,657.00
	Less 10%	\$ 265.70
		\$ 2,391.30

not attached

2/5
4/5
30/4/18
take photo after repair

2032

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Mohamad Asyraf Bin Azmi

Accident Date : 23-Apr-18

Vehicle No : JLC 4916

Vehicle Model : Honda Wave

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	<i>nu</i>	\$	28.00	<i>20</i>
2	Fork oils	<i>nu</i>	\$	30.00	<i>—</i>
2	Fork oil seals	<i>nu</i>	\$	56.00	<i>—</i>
1	Steering cone bearing (1 set)	<i>nu</i>	\$	85.00	<i>—</i>
				<u>\$</u>	<u>199.00</u>

S/No. Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing.	\$	80.00	11
3	To provide labour.	\$	380.00	200
4	To check , repair and straighten body frame.	\$	400.00	250
		\$	910.00	

Grand Total

\$ 3,500.30

Dollars: Three Thousand Five Hundred And Thirty Cents Only.



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: