

INS. CASE OWNER:

CC3 / A191800 7775, A Wb39

LKK:
IDAC:

Surveyor:

Admin

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLJ 4654

Name of Insured:

PREMIUM AUTOMOBILES Pte

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

25/4/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

UN Pemporn

Driver Tel No.:

(V/L: ☒ YES / NO)

Claim No.:

19092596954

Policy No.:

999995051/10088785

Make / Model:

BMW

00000

Place of Accident:

HOM PUYOK

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability:

%

Final ? Yes / No

SGN 687



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

30/8/18

Confirm with

Mastura

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27.

If NO or B 28, Ass. Lia:

Repair Cost:

SS

3416.72

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

480.00 (\$80

x 6 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

3896.72

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3896.72

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

RECEIVED 31 AUG 2018

COPY SENT
21/8/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0505/2018/GC
Date : 28-Apr-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Iwan Kurniawan Bin Ahmad
Address : 2 Flora Drive #05-07
#05-07
Singapore 507025
Telephone : 96661039
Type of Claim : Third Party Claims
Policy No. : 5072445272-02
Vehicle No : **SGN 0687 L**
Model Code : Toyota Harrier 2.0 Premium (A)
Model / Year : Jun-15
Engine No : 3ZRB495245
Chassis No : ZSU600034431
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Apr-18
Place of Accident : Flyover along farrer rd opposite sg bible college

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGN 0687 L.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N \$ 200.00 60. /
2	To remove rear fittings, dismantle and renew rear bumper and rear lid. Cut and Weld Rear end panel. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,400.00 600 / (2 Days) 300 x 2
3	To respray rear bumper, rear lid and rear end panel.	\$ 1,600.00 600 / (2 pieces) 300 x 2
4	To renew rear windscreen.	S/N \$ 300.00 X.
5	To rewrap rear lid and rear bumper with 3M Vinyl	S/N TBC ? 650.00
6	Rear windscreen solar film	S/N TBC X.
7	To carry out diagnostic check.	S/N \$ 150.00 60 /
TOTAL LABOUR CHARGES		: \$ <u>4,650.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGN 0687 L.

		<u>Damaged Parts & Prices</u>		
<u>S/N</u>	<u>Parts Description</u>		<u>S/Nett</u>	
1	REAR BUMPER <i>Rehnd</i>	1 \$	1,056.00	✓ 844.80
2	REAR BUMPER LOWER SPOILER <i>Rehnd</i>	1 \$	352.00	✓ 281.60
3	REAR BUMPER LIGHT REFLECTOR - LH/RH <i>new</i>	2 \$	110.00	✓
4	REAR BUMPER RETAINER - LH/RH <i>new</i>	2 \$	66.00	+
5	REAR BUMPER GUIDE - LH/RH <i>new</i>	2 \$	154.00	+
6	REAR BUMPER CLIP <i>not new</i>	15 \$	49.50	✓
7	REAR REINFORCEMENT BEAM <i>new</i>	1		+
8	REAR BUMPER INNER SPONGE <i>not new</i>	1 \$	121.00	✓
9	REAR LID <i>Repair</i>	1 \$	1,760.00	✓
10	REAR LID WINDSCREEN <i>Not new</i>	1 \$	1,540.00	+
11	REAR WINDSCREEN MOULDING <i>new</i>	1 \$	55.00	✓
12	REAR LID 'HARRIER' EMBLEM <i>new</i>	1 \$	66.00	✓ 52.80
13	REAR LID 'TOYOTA' LOGO	1 \$	55.00	✓ 44.00
14	REAR LID GARNISH <i>new</i>	1 \$	836.00	+
15	REAR END PANEL <i>Repair</i>	1 \$	550.00	+
SUB - SPARE PART CHARGES		\$	6,770.50	
TOTAL LABOUR CHARGES		\$	4,650.00	
GRAND TOTAL		\$	11,420.50	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 07/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days. Inclusive of sticker wrap.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0505/2018/GC
Date : 28-Apr-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

6 days - ok - /b - 26 May 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Iwan Kurniawan Bin Ahmad
Address : 2 Flora Drive #05-07
#05-07
Singapore 507025
Telephone : 96661039
Type of Claim : Third Party Claims
Policy No. : 5072445272-02
Vehicle No : **SGN 0687 L**
Model Code : Toyota Harrier 2.0 Premium (A)
Model / Year : Jun-15
Engine No : 3ZRB495245
Chassis No : ZSU600034431
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Apr-18
Place of Accident : Flyover along farrer rd opposite sg bible college

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGN 0687 L.

S/n	Nature of Jobs	Estimated Charges			
1	To remove and transfer rear parking aid. Check function.	S/N	\$	200.00	\$ 60.00
2	To remove rear fittings, dismantle and renew rear bumper and rear lid. Cut and Weld Rear end panel. Re-organise rear crash management components. Reinstall all parts removed.		\$	2,400.00	\$ 600.00
3	To respray rear bumper, rear lid and rear end panel.		\$	1,600.00	\$ 600.00
4	To renew rear windscreen.	S/N	\$	300.00	
5	To rewrap rear lid and rear bumper with 3M Vinyl	S/N	\$	650.00	\$ 650.00
6	Rear windscreen solar film	S/N		TBC	
7	To carry out diagnostic check.	S/N	\$	150.00	\$ 60.00
TOTAL LABOUR CHARGES		:	\$	5,300.00	\$ 1,970.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGN 0687 L.

S/N	Parts Description	<u>Damaged Parts & Prices</u>			
		S/Nett			
1	REAR BUMPER	1	\$	1,056.00	\$ 844.80
2	REAR BUMPER LOWER SPOILER	1	\$	352.00	\$ 281.60
3	REAR BUMPER LIGHT REFLECTOR - LH/RH	2	\$	110.00	
4	REAR BUMPER RETAINER - LH/RH	2	\$	66.00	
5	REAR BUMPER GUIDE - LH/RH	2	\$	154.00	
6	REAR BUMPER CLIP	15	\$	49.50	
7	REAR REINFORCEMENT BEAM	1			
8	REAR BUMPER INNER SPONGE	1	\$	121.00	
9	REAR LID	1	\$	1,760.00	
10	REAR LID WINDSCREEN	1	\$	1,540.00	
11	REAR WINDSCREEN MOULDING	1	\$	55.00	
12	REAR LID 'HARRIER' EMBLEM	1	\$	66.00	\$ 52.80
13	REAR LID 'TOYOTA' LOGO	1	\$	55.00	\$ 44.00
14	REAR LID GARNISH	1	\$	836.00	
15	REAR END PANEL	1	\$	550.00	
SUB - SPARE PART CHARGES			\$	6,770.50	\$ 1,223.20
TOTAL LABOUR CHARGES			\$	4,650.00	\$ 1,970.00
GRAND TOTAL			\$	11,420.50	\$ 3,193.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

CHEAPEST CAR INSURANCE RENEWAL



Choice of \$0 excess



Option of any workshop

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Yaris 1.5G (COE Till 06/2026)



Engine: Good Condition, Sound
Insulation, Pioneer Dvd Sound
System, Low Mileage,
Direct Owner



Browse by Category

Sort by Date Posted

20 results/page

6 vehicles

Toyota Hiace

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Hiace	Any	Any	2014	Any	Any	Any	Available

**Toyota Hiace Commuter**

\$136,800

\$21,200 /yr

03-Jan-2014

2,693 cc

-

MPV

Available

Pte Plate. \$19800 For Down Payment, Monthly At \$1308 Can Be Arranged, Come With Nice Number Plate. No Obligation For View.

Posted: 12-Mar-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

**Toyota Hiace**

\$56,800

\$9,260 /yr

24-Jun-2014

2,982 cc

-

Van

Available

Fuel Type: Diesel

1 Careful Owner, Outstanding Bubble Bee Yellow Or Choice Of Color. Well Kept And Maintain By Previous Owner. No Dings Or Dent Found On Body. Added A Wooden Plank Deck For More Storage Area. Trade In A...

ABWIN (1994) Pte Ltd

Posted: 02-May-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

**Toyota Hiace**

\$51,500

\$8,190 /yr

18-Aug-2014

2,982 cc

67,085 km

Van

Available

Fuel Type: Diesel

Well Kept, Accident Free, Agent Maintained.

Posted: 25-Apr-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

**Toyota Hiace Commuter**

\$69,800

\$10,860 /yr

08-Oct-2014

2,982 cc

118,525 km

Bus

Available

Fuel Type: Diesel

Please Call To Arrange For Viewing. Thanks.

Posted: 04-May-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Buy Types Online!

Latest Special Offers from Tyrexpert

**Toyota Hiace**

\$51,888

\$8,000 /yr

31-Oct-2014

2,982 cc

79,000 km

Van

Available

Fuel Type: Diesel

\$52,000! CONFIRM Cheapest In Town Yet Price Still Negotiable! 5 Doors! Fully Borneo Agent Serviced! Only 1 Owner! Low Mileage Done, 100% Accident Free, Original Paintwork! Famous For Its Low Diesel An...

Net Link Partners Pte Ltd

Posted: 23-Apr-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

**Toyota Hiace**

\$52,800

\$8,100 /yr

12-Nov-2014

2,982 cc

-

Van

Available

Fuel Type: Diesel

1 Owner Only. Selling Due To Under Usage. Tip Top Condition And Accident Free. No Repair Needed Plus Warranty Given. Call And View Before It Gone.

ABWIN Bus Pte Ltd

Posted: 04-May-2018 Tags: 2014 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old adv

view Expired ads

20 results/page

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7236731F



NAME
IWAN KURNIAWAN BIN AHMAD

Race
MALAY
Date of Birth
02-10-1972
Sex
M
Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Identity Number: S7236731F

NAME
IWAN KURNIAWAN BIN AHMAD

Birth Date 02 Oct 1972

Issue Date 03 Mar 2003



NRIC No. S7236731F


Blood Group Date of Issue
09-10-2002

2 FLORA DRIVE #05-07
SINGAPORE 507025
NRIC No. S7236731F

Date: 17/03/2012 No: 7017752

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	25 Mar 1992
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kilograms	21 Mar 2001
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which unladen exceeds 7250 kilograms	17 Apr 2001



NP 428A

Premium Automobiles



AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18007725/wb3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/0505/2018/MAS

30 Aug 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SGN 687 L, Toyota Harrier Premium 2.0 A

With reference to the above-mentioned vehicle, no. **SGN 687 L**, claimant, **Mr. Iwan Kurniawan Bin Ahmad**, please find the related document as per attached.

1. A copy of the Original invoice no. 85012821 – S\$3,416.72
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use – S\$480.00 (S\$80.00 x 6 days)

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SGN 687 L

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6586 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18007725/wb3

03 May 2018

PREMIUM AUTOMOBILES PTE LTD

55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

ACCIDENT INVOLVING SLJ 465Y AND SGN 687Y ON 25/04/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Iwan Kurniawan Bin Ahmad (the third party claimant) of 2 Flora Drive #05-07
Singapore 507025 (address), owner of SGN687L (vehicle no.)
hereby authorize Premium Automobiles Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SGN687L that was damaged pursuant to the accident which occurred on 25/4/2018
(date) along Flyover Along Farrer Rd Opposite Sg Bible College (location) involving vehicle no/s
SLJ465Y ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 12 (day) of May (month) 20 18 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Premium Automobiles Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3416.72 (Repair Cost), S\$ 480.00 (Loss of ~~rental~~/use), S\$ NIL (Disbursement), for vehicle no. SGN687L that was damaged pursuant to the accident which occurred on 25/4/2018 (date) along Flyover Along Farrer Rd Opposite Sg Bible College (location) involving vehicle no/s SLJ465Y. This is pursuant to the inspection conducted on 7/5/2018 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner Iwan Kurniawan Bin Ahmad ("the third party claimant") of vehicle no. SGN687L make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGN687L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 30 (day) of 8 (month) 2018 (year)

LWP 

Signed by appointed surveyor



Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733
Page 1 13:12

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6386 2223
Telefax 6475 1023

Ubi Service Centre
95 Ubi Road 1
Singapore 408693
Telephone 6386 1111
Telefax 6841 1111

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INSURANCE INVOICE
Company No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012821 Date : 07/08/2018 Order : SGN0687L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SGN0687L (V 37701)	Regn Date: 26/06/2015	Mileage: 69917	WIP No.: 63664
Model: TOYOTA HARRIER PREMIUM 2.0 A	Chassis: ZSUG00034431	Engine: 3ZR8495245	Dept: U
USB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	50.00	1.00	50.00
S	BODYWORK	M: TO REMOVE REAR FITTINGS, DISMANTLE AND REPAIR REAR BUMPER, REPAIR REAR LID, CUT AND WELD REAR END PANEL, REORGANISE REAR CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	600.00	1.00	600.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER AND REAR LID	600.00	1.00	600.00
S	BODYWORK	M: TO REWRAP REAR LID AND REAR BUMPER WITH 3M VINYL	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	50.00	1.00	50.00
X	ZJ-TH5219948120	REAR BUMPER Less 020%	1.00	1856.00	844.80
X	ZJ-TH521646060	REAR BUMPER SPOILER Less 020%	1.00	352.00	281.60
X	ZJ-TH7544248140	BOOT PLATE (HARRIER) Less 020%	1.00	66.00	52.80
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733
Page 2 13:12

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408629
Telephone: 6388 2223
Telefax: 6471 3733

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2323
9828 1233

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012821 Date : 07/08/2018 Order : SGN0687L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SGN0687L (V 37701) Regn Date: 26/06/2015 Mileage: 69917 WIP No.: 63664
Model: TOYOTA HARRIER PREMIUM 2.0 A Chassis: ZSU600034431 Engine: 3ZRBA95245 Dept: U
USB No.:
You have been assisted by :- LB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	ZJ-TH3097502071	BOOT LOGO Less 020%	1.00	55.00	44.00

Parts 1,223.20
Labour 0.00
Sublet 1,970.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,193.20

7% GST 223.52

Grand Total 3,416.72



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2018 Edit Reg		07 May 2018 00:00 Edit Adj Rpt	S\$3,193.20 Edit Estimates	S\$3,193.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	PREMIUM AUTOMOBILES PTE LTD , Co. Reg. No.: 199902271W								
Main Claimant:	IWAN KURNIAWAN BIN AHMAD , ID: S7236731F								
Vehicle Reg. No.:	SGN687L	Date of Loss:	25/04/2018 19:00 - :59 [33 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1909359392SG	Policy/Cover Note No.:	0999994629						
Vehicle Reg. No. (Insured):	SLJ465Y	Policy No. (Claimant):	5072445272-02						
		Excess:							
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGN687L (1909359392SG)
[SLJ465Y]
TP
IWAN KURNIAWAN BIN AHMAD
Apr 25 2018 7:00PM
[PREMIUM AUTOMOBILES PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Assessment Reports				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/04/18 10:21	Accident Statement <small>From: OD - Reg. No: SLJ465Y, Claimant: PREMIUM AUTOMOBILES PTE LTD</small>	Load HTML	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
2	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
3	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
4	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
5	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
6	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
7	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
8	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
9	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
10	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
11	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
12	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
13	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
14	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
15	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
16	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
17	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
18	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
19	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
20	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
21	19/07/18 10:22	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/04/18 17:17	TP GIA REPORT	Load PDF	
2	26/04/18 17:17	OI GIA REPORT	Load PDF	
3	08/05/18 18:02	TP ESTIMATE- MARKED	Load PDF	
4	03/09/18 11:24	WORKSHOP INVOICE	Load PDF	
5	03/09/18 11:24	AUTHORISATION TO ACT FORM	Load PDF	
6	03/09/18 11:24	Release Voucher	Load PDF	
7	03/09/18 11:24	LETTER TO OI	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLJ465Y (Insd veh)	Model:	TOYOTA HARRIER 2.0
	SGN687L (TP veh)		PREMIUM (A)
Date of Accident:	25/04/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	12,915.44
Final Repair Cost	:	\$	3,416.72
Loss of Use	:	\$	480.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,896.72

6.00 days at \$80.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____(%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 27

BOLA Liability: 100 _____(%) Assessed Liability (*): _____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 3,896.72
2)		:	\$

JOANNE LEE KHANG MIN

03 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18007725/AWB3Q2

Date: 03/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994629

Claimant Vehicle No: SGN687L

Insured Vehicle No: SLJ465Y

Date of Loss: 25/04/2018

Nature of Claim: TP

Claim No: 1909359392SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGN687L**

Make & Model: TOYOTA HARRIER, 2.0 Premium (A)

Engine No: 3ZRB495245

Reg. Date: 26/06/2015 (Man. Year: 2014)

Chassis No: ZSU600034431

Colour: Blue

Odometer: 69917 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,770.50	1,223.20	5,547.30	81.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	1,970.00	3,330.00	62.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,070.50	3,193.20	8,877.30	73.55
+ GST 7.00/7.00% (S\$)	844.94	223.52	621.42	73.55
Nett Amount (S\$)	12,915.44	3,416.72	9,498.72	73.55
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
Nett Liability (S\$)		3,896.72		

INSPECTION

Date of Assignment: 07/05/2018

Date Inspected: 07/05/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,056.00 FS	*844.80 FS
2	1		*REAR BUMPER LOWER SPOILER	Deformed	352.00 FS	*281.60 FS
3	2		*REAR BUMPER LIGHT REFLECTOR -LH/RH	Not Necessary	110.00 FS	*- FS
4	2		*REAR BUMPER RETAINER -LH/RH	Not Necessary	66.00 FS	*- FS
5	2		*REAR BUMPER GUIDE -LH/RH	Not Necessary	154.00 FS	*- FS
6	15		*REAR BUMPER CLIP	Not Necessary	49.50 FS	*- FS
7	1		*REAR REINFORCEMENT BEAM (NPA)	Not Necessary	0.00 FS	*- FS
8	1		*REAR BUMPER INNER SPONGE	Not Necessary	121.00 FS	*- FS
9	1		*REAR LID	Repair	1,760.00 FS	*- FS
10	1		*REAR LID WINDSCREEN	Not Necessary	1,540.00 FS	*- FS
11	1		*REAR WINDSCREEN MOULDING	Not Necessary	55.00 FS	*- FS
12	1		*REAR LID HARRIER EMBLEM	Necessary	66.00 FS	*52.80 FS
13	1		*REAR LID TOYOTA LOGO	Necessary	55.00 FS	*44.00 FS
14	1		*REAR LID GARNISH	Not Necessary	836.00 FS	*- FS
15	1		*REAR END PANEL	Repair	550.00 FS	*- FS
Total Parts (\$\$)					6,770.50	1,223.20

F=Franchise part. S=SpcNett

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	200.00	60.00
2	TO REMOVE REAR FITTINGS ,DISMANTLE ADN RENEW REAR BUMPER AND REAR LID .CUT AND WELD REAR END PANEL .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,400.00	600.00
3	TO RESPRAY REAR BUMPER ,REAR LID AND REAR END PANEL	New	1,600.00	600.00
4	TO RENEW REAR WINDSCREEN	New	300.00	0.00
5	TO REWRAP REAR LID AND REAR BUMPER WITH 3M VINYL	New	650.00	650.00
6	REAR WINDSCREEN SOLAR FILM (NPA)	New	0.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	150.00	60.00
Gross Labour Cost (S\$)			5,300.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >