

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0505/2018/GC
Date : 28-Apr-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Iwan Kurniawan Bin Ahmad
Address : 2 Flora Drive #05-07
#05-07
Singapore 507025
Telephone : 96661039
Type of Claim : Third Party Claims
Policy No. : 5072445272-02
Vehicle No : **SGN 0687 L**
Model Code : Toyota Harrier 2.0 Premium (A)
Model / Year : Jun-15
Engine No : 3ZRB495245
Chassis No : ZSU600034431
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Apr-18
Place of Accident : Flyover along farrer rd opposite sg bible college

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGN 0687 L.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N \$ 200.00 60.
2	To remove rear fittings, dismantle and renew rear bumper and rear lid. Cut and Weld Rear end panel. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,400.00 500 (2 Days) 300x2.
3	To respray rear bumper, rear lid and rear end panel.	\$ 1,600.00 600 (2 pieces) 300x2.
4	To renew rear windscreen.	S/N \$ 300.00 X.
5	To rewrap rear lid and rear bumper with 3M Vinyl	S/N TBC ?
6	Rear windscreen solar film	S/N TBC X.
7	To carry out diagnostic check.	S/N \$ 150.00 60
TOTAL LABOUR CHARGES		: \$ <u><u>4,650.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGN 0687 L.

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>		<u>S/Nett</u>
1	REAR BUMPER <i>Rehd</i>	1 \$	1,056.00 ✓
2	REAR BUMPER LOWER SPOILER <i>Rehd</i>	1 \$	352.00 ✓
3	REAR BUMPER LIGHT REFLECTOR - LH/RH <i>new</i>	2 \$	110.00 ✗
4	REAR BUMPER RETAINER - LH/RH <i>new</i>	2 \$	66.00 ✗
5	REAR BUMPER GUIDE - LH/RH <i>new</i>	2 \$	154.00 ✗
6	REAR BUMPER CLIP <i>new</i>	15 \$	49.50 ✓
7	REAR REINFORCEMENT BEAM <i>new</i>	1	✗
8	REAR BUMPER INNER SPONGE <i>new ?</i>	1 \$	121.00 ?
9	REAR LID <i>Repair</i>	1 \$	1,760.00 ✗
10	REAR LID WINDSCREEN <i>Not new</i>	1 \$	1,540.00 ✗
11	REAR WINDSCREEN MOULDING <i>new</i>	1 \$	55.00 ✗
12	REAR LID 'HARRIER' EMBLEM <i>new</i>	1 \$	66.00 ✓
13	REAR LID 'TOYOTA' LOGO <i>new</i>	1 \$	55.00 ✓
14	REAR LID GARNISH <i>new</i>	1 \$	836.00 ✗
15	REAR END PANEL <i>Repair</i>	1 \$	550.00 ✗
SUB - SPARE PART CHARGES		\$	6,770.50
TOTAL LABOUR CHARGES		\$	4,650.00
GRAND TOTAL		\$	11,420.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 07/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days. Inclusive of sticker wrap.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant