

S. REC. BY:

REF:

CS/CTU8007726/Urb

Special Instruction:

Surveyor

Marius

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CT

Date/Time:

26/04/2018 4:46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 2174B

Insured:

SJC 9045C

at Workshop m/s:

Pegasus @ GME

Tel:

8338 8418

of

BIR 1 Kaka Bukit Ave 6 #01-15

Policy No:

DMPC SN 3021641800

Claim No:

SNM18D01127C01

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

27-04-2018

H.O.D. Endorsement:

Date/Time:

26/04/2018 5:12pm

Person Contacted:

Gury

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLS 2174B - CCS / LCR 17073380 / Up0392

DUA: 10/12/17

SJC 9045C - X

ASSIGNMENT

From: Date: 27/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 2174B

at Workshop n/s Pegasus @ SME

of Bld 1 Kaki Bukit Ave 6 #02-15

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Toyota

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

QAC Accident Report: Consistent? : Yes or No

PR Seen: 9 Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLS 2174B Yr Regn: 9 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Auto

Make: Toyota prius Hybrid cc 1798

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 5254 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDK B3 Fu 803569871

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 195/65/15

R: 195/65/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / OKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 25/4/18 D.O.I. 27/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rnt.
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: 11/6/18 Action / Instruction: confirmed final by #10272.95 with AH yang
Red: 2558.54, 201.

RECEIVED 25 JUN 2018

Date/Time, File Page 10?

1) 11/6/18

Date/Time, File Return 10?

2)

Report Format:

Lump Sum / I.B.I.: (\$ 10272.95)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S - PC - SI

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2018		26 Apr 2018 16:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN YEW LONG, ID: S7655639C		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLS2174B	Date of Loss:	25/04/2018 10:00 - :59
Claim Type:	TP / SNM18D02127C02	Policy/Cover Note No.:	DMPCSN3021641800 (Comprehensive)
Vehicle Reg. No. (Insured):	SJC9045C	Policy No. (Claimant):	A29069766MKF
		Excess:	S\$0.00
Repairer:	Pegasus Engineering & Trading Pte Ltd - Kaki Bukit (HQ) 1 Kaki Bukit Avenue 6, #02-15 @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67476106		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/05/2018]		
Driver/Custodian (Insured):	TAN YEW LONG (42 / Male), NRIC: S7655639C		
Adj Asg. Remarks:	EST \$13,521.85, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/04/2018 16:03
Date Of Accident	25/04/2018 10:00
Exact Location Of Accident	JUNCTION OF ADMIRALTY RD & MARSILING LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS2174B
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67476106

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	N.A.

Driver

Name of Driver	CHONG KHENG WAH
NRIC No	S7110437J
Date Of Birth	22/03/1971
Occupation	OUTDOOR
Date Of Driving Pass	04/09/1992
Driving Experience	25 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

ACCIDENT STATEMENT (2000 characters)

My car SLS2174B was stationary at ADMIRALTY ROAD traffic light junction & MARSILING LANE. When traffic light turn green I started to move off suddenly a car SJC9045C making a right turn coming from MARSILING LANE heading towards ADMIRALTY ROAD hit onto my front of SLS2174B. No injuries involved. That's all.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

25 April 2018 1:01 pm

Date/Time:

25 April 2018 1:01 pm

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLS2174B
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZRS084562
Chassis No.:	JTDKB3FU803569871
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,008.00
Original Registration Date:	14 Sep 2017
First Registration Date:	14 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Sep 2027
PARF Rebate Amount:	\$4,059.00
Intended COE Rebate Details	
COE Expiry Date:	13 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$50,324.00
Total Rebate Amount:	\$54,383.00

The information contained herein is correct as at 30 Apr 2018

OK



GST / ROC Company No :

201101753C

Third Party Insurer :

CHINA

Insured's Veh No :

SJC9045C SLS2174B SJC9045C

Date of accident :

21/04/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Estimate To Repair

TOYOTA PRIUS

Vehicle No :

SLS2174B

Chassis No :

JTDKB3FU803569871

Quotation No : AR/QO18/04-1080

Quotation Date : 25/04/2018

Pages :

1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1PC	FRT BONNET <i>22/3rd</i>	\$1,038.40
2	2PC	FRT BONNET HINGES <i>2</i>	\$124.00
3	1PC	FRT BONNET LOCK <i>17</i>	\$83.60
4	1PC	FRT BUMPER <i>D.S</i>	\$565.50
5	2PC	FRT BUMPER RETAINER <i>320</i>	\$165.80
6	10PC	FRT BUMPER CLIPS <i>nee</i>	\$50.00
7	1PC	FRT BUMPER LOGO <i>nee</i>	\$92.10
8	1PC	FRT BUMPER TOP RUBBER SEAL <i>nee</i>	\$45.30
9	1PC	FRT GRILLE (TOP) <i>70.1</i>	\$365.60
10	1PC	FRT BUMPER LOWER GRILLE <i>70.1</i>	\$195.00
11	1PC	NUMBER PLATE GARNISH <i>70.1</i>	\$129.80
12	1PC	FRT BUMPER TOWING COVER RH <i>70.1</i>	\$50.00
13	1PC	FRT BUMPER INNER SPONGE <i>70.1</i>	\$80.30
14	1PC	FRT BUMPER REINFORCEMENT <i>3rd</i>	\$731.10
15	1PC	FRT BUMPER LOWER GARNISH (INNER) <i>CR</i>	\$200.10
16	1PC	FRT BUMPER FOG LAMP ASSY RH <i>CR</i>	\$950.20
17	1PC	FRT BUMPER FOG LAMP BASE RH <i>CR</i>	\$186.50
18	1PC	WASHER TANK <i>70.1</i>	\$223.60
19	1PC	WASHER TANK MOTOR <i>17</i>	\$282.00
20	2PC	HEADLAMP <i>0/5 320 n/s bulb CR</i>	\$5,317.80
21	1PC	CENTRE TOP PANEL <i>R</i>	\$394.90
22	2PC	HEADLAMP PANEL (TOP) <i>17</i>	\$173.40
23	2PC	HEADLAMP PANEL (SIDES) <i>17</i>	\$514.00
24	1PC	HEADLAMP SUPPORT TOP GARNISH <i>17</i>	\$267.80
25	8PC	TOP GARNISH CLIPS <i>NV</i>	\$40.00
26	1PC	FRT RH FENDER <i>3rd/3rd</i>	\$963.10
27	1PC	FRT RH FENDER INNER COWLING <i>70.1</i>	\$228.10
28	10PC	INNER COWLING CLIPS <i>nee</i>	\$50.00
29	1PC	FRT RH FENDER "HYBRID" PLATE <i>nee</i>	\$62.90
30	1PC	FRT RH FENDER TOP COVER GARNISH <i>M.S</i>	\$106.90
LESS 20% <i>25%</i>			\$13,677.80
			\$2,735.56
			\$10,942.24

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418



GST / ROC Company No : 201101753C

Third Party Insurer : CHINA

Insured's Veh No : SLS2174B

Date of accident : 21/04/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Quotation No : AR/QO18/04-1080

Quotation Date : 25/04/2018

Estimate To Repair TOYOTA PRIUS
Vehicle No : SLS2174B
Chassis No : JTDKB3FU803569871

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
		MISC ITEMS	
31	1PC <i>for</i>	REAR NUMBER PLATE <i>Bro</i>	\$40.00 ✓
32	1PC <i>for</i>	REAR WINDSCREEN SEALANT <i>11</i>	\$25.00 X
		Total	\$65.00
		LABOUR & MISC. CHARGES	
1		WIRE CHECKING	\$30.00 ✓
2		REMOVE & REFIX AIRCON AND GAS <i>11</i>	\$100.00
3		LABOUR CHARGE	\$750.00 600
4		SPRAY PAINTING	\$750.00 700
		Total	\$1,630.00
		<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	
		Sub Total	\$12,637.24
		GST (7.00%)	\$884.61
		Total	\$13,521.85
			12831.49

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418



Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

GST / KOC Company No : 201101753C
Third Party Insurer : CHINA
Insured's Veh No : SLS2174B
Date of accident : 21/04/2018
Quotation No : AR/QO18/04-1080
Quotation Date : 14/05/2018

SUPPLEMENTARY TOYOTA PRIUS
Vehicle No : SLS2174B
Chassis No : JTDKB3FU803569871

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
1	1 PC	MISC ITEMS	
		FRT BUMPER LOWER BEAM	<i>Ref</i> \$259.00
		Total	\$259.00
		-25.00%	\$64.75
			\$194.25
		Sub Total	\$194.25
		GST (7.00%)	\$13.60
		Total	\$207.85

Please conduct the survey at
Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883
GARY 8338 8418

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2018		26 Apr 2018 16:46 Edit Adj Rpt	S\$10,272.95 Edit Estimates	S\$10,272.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN YEW LONG, ID: S7655639C		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLS2174B	Date of Loss:	25/04/2018 10:00 - :59 [7 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02127C02	Policy/Cover Note No.:	DMPCSN3021641800 (Comprehensive)
Vehicle Reg. No. (Insured):	SJC9045C	Policy No. (Claimant):	A29069766MKF
		Excess:	S\$0.00
Repairer:	Pegasus Engineering & Trading Pte Ltd (Kaki Bukit) 1 Kaki Bukit Avenue 6, #02-15 @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67476106		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/05/2018]		
Driver/Custodian (Insured):	TAN YEW LONG (42 / Female), NRIC: S7655639C		
Adj Asg. Remarks:	EST \$13,521.85, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS2174B (SNM18D02127C02)
[SJC9045C]
TP
GRAB RENTALS PTE LTD
Apr 25 2018 10:00AM
[TAN YEW LONG]
Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			☒		
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)								Thumbnail	Print			
1	25/04/18 16:10	Accident Statement								Load HTM				
Photos/Images									3 per page			☒		
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)								Thumbnail	Print			
1	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
2	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
3	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
4	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
5	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
6	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
7	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
8	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
9	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
10	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
11	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
12	25/04/18 16:09	Accident Photo [Linked Accident Report Documents]								Load JPG	☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	27/04/18 19:53	Chassis Number								Load JPG	☒			
2	27/04/18 19:53	Odometer Reading								Load JPG	☒			
3	27/04/18 19:53	General View								Load JPG	☒			
4	27/04/18 19:53	General View								Load JPG	☒			
5	27/04/18 19:53	General View								Load JPG	☒			
6	27/04/18 19:53	General View								Load JPG	☒			
7	27/04/18 19:53	General View								Load JPG	☒			
8	27/04/18 19:53	General View								Load JPG	☒			
9	27/04/18 19:53	General View								Load JPG	☒			
10	27/04/18 19:53	General View								Load JPG	☒			
11	27/04/18 19:53	General View								Load JPG	☒			
12	27/04/18 19:53	General View								Load JPG	☒			
13	27/04/18 19:53	General View								Load JPG	☒			
14	27/04/18 19:53	General View								Load JPG	☒			
15	27/04/18 19:53	General View								Load JPG	☒			
16	27/04/18 19:53	General View								Load JPG	☒			
17	27/04/18 19:53	General View								Load JPG	☒			
18	27/04/18 19:53	General View								Load JPG	☒			
19	27/04/18 19:53	General View								Load JPG	☒			
20	27/04/18 19:53	General View								Load JPG	☒			
21	27/04/18 19:53	General View								Load JPG	☒			
22	27/04/18 19:53	General View								Load JPG	☒			
23	27/04/18 19:53	General View								Load JPG	☒			

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
				☒
24	27/04/18 19:53	General View	 Load JPG	☒
25	27/04/18 19:53	General View	 Load JPG	☒
26	27/04/18 19:53	General View	 Load JPG	☒
27	27/04/18 19:53	General View	 Load JPG	☒
28	27/04/18 19:53	General View	 Load JPG	☒
29	27/04/18 19:53	General View	 Load JPG	☒
30	27/04/18 19:53	General View	 Load JPG	☒
31	27/04/18 19:53	General View	 Load JPG	☒
32	27/04/18 19:53	General View	 Load JPG	☒
33	27/04/18 19:53	General View	 Load JPG	☒
34	27/04/18 19:53	General View	 Load JPG	☒
35	27/04/18 19:53	General View	 Load JPG	☒
36	27/04/18 19:53	General View	 Load JPG	☒
37	27/04/18 19:53	General View	 Load JPG	☒
38	27/04/18 19:53	General View	 Load JPG	☒
39	27/04/18 19:53	General View	 Load JPG	☒
40	27/04/18 19:53	General View	 Load JPG	☒
41	27/04/18 19:53	General View	 Load JPG	☒
42	27/04/18 19:53	General View	 Load JPG	☒
43	27/04/18 19:53	General View	 Load JPG	☒
44	27/04/18 19:53	General View	 Load JPG	☒
45	27/04/18 19:53	General View	 Load JPG	☒
46	27/04/18 19:53	General View	 Load JPG	☒
47	27/04/18 19:53	General View	 Load JPG	☒
48	27/04/18 19:53	General View	 Load JPG	☒
49	27/04/18 19:53	General View	 Load JPG	☒
50	27/04/18 19:53	General View	 Load JPG	☒
51	27/04/18 19:53	General View	 Load JPG	☒
52	27/04/18 19:53	General View	 Load JPG	☒
53	27/04/18 19:53	General View	 Load JPG	☒
54	27/04/18 19:53	General View	 Load JPG	☒
55	27/04/18 19:53	General View	 Load JPG	☒
56	27/04/18 19:53	General View	 Load JPG	☒
57	27/04/18 19:53	General View	 Load JPG	☒
58	27/04/18 19:53	General View	 Load JPG	☒
59	27/04/18 19:53	General View	 Load JPG	☒
60	27/04/18 19:53	General View	 Load JPG	☒
61	27/04/18 19:53	General View	 Load JPG	☒
62	27/04/18 19:53	General View	 Load JPG	☒
63	27/04/18 19:53	General View	 Load JPG	☒
64	27/04/18 19:53	General View	 Load JPG	☒
65	27/04/18 19:53	General View	 Load JPG	☒
66	27/04/18 19:53	General View	 Load JPG	☒
67	27/04/18 19:53	General View	 Load JPG	☒
68	27/04/18 19:53	General View	 Load JPG	☒
69	27/04/18 19:53	General View	 Load JPG	☒
70	27/04/18 19:53	General View	 Load JPG	☒
71	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
72	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
73	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
74	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
75	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
76	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
77	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
78	14/05/18 19:24	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
79	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
80	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
81	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
82	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
83	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
84	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
85	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
86	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
87	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
88	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
89	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
90	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
91	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
92	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
93	14/05/18 19:24	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/04/18 16:45	REPAIR EST	 Load PDF	
2	26/04/18 16:46	OI GIA REPORT	 Load PDF	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/04/18 16:08	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	25/04/18 16:08	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/04/18 16:10	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/04/18 16:09	Accident Photo	 Load JPG	☒
2	25/04/18 16:09	Accident Photo	 Load JPG	☒
3	25/04/18 16:09	Accident Photo	 Load JPG	☒
4	25/04/18 16:09	Accident Photo	 Load JPG	☒
5	25/04/18 16:09	Accident Photo	 Load JPG	☒
6	25/04/18 16:09	Accident Photo	 Load JPG	☒
7	25/04/18 16:09	Accident Photo	 Load JPG	☒
8	25/04/18 16:09	Accident Photo	 Load JPG	☒
9	25/04/18 16:09	Accident Photo	 Load JPG	☒
10	25/04/18 16:09	Accident Photo	 Load JPG	☒
11	25/04/18 16:09	Accident Photo	 Load JPG	☒
12	25/04/18 16:09	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/04/18 16:08	Sketch Plan	 Load JPG	☒
2	25/04/18 16:08	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007726/URBQ2

Date: 29/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3021641800

Claimant
Vehicle No : SLS2174BInsured Vehicle
No : SJC9045C

Date of Loss: 25/04/2018

Nature of Claim: TP

Claim
No: SNM18D02127C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS2174B

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS084562

Reg. Date: 14/09/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU803569871

Colour: Silver

Odometer: 52554 km

Engine Capacity: 1798 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,214.44	8,942.95	2,271.49	20.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,330.00	300.00	18.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,844.44	10,272.95	2,571.49	20.02
+ GST 7.00/7.00% (S\$)	899.11	719.11	180.00	20.02
Nett Amount (S\$)	13,743.55	10,992.06	2,751.49	20.02

INSPECTION

Date of Assignment: 26/04/2018

Date Inspected: 27/04/2018 Inspected At:

Pegasus Engineering & Trading Pte
Ltd (Kaki Bukit)
1 Kaki Bukit Avenue 6, #02-15 @ Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2018)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS2174B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Dented / Bent	1,038.40 FL	*1,038.40 FL
2	2		*FRT BONNET HINGES	Repair	124.00 FL	*- FL
3	1		*FRT BONNET LOCK	Not Necessary	83.60 FL	*- FL
4	1		*FRT BUMPER	Distorted	565.50 FL	*565.50 FL
5	2		*FRT BUMPER RETAINER	Broken	165.80 FL	*165.80 FL
6	10		*FRT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
7	1		*FRT BUMPER LOGO	Necessary	92.10 FL	*92.10 FL
8	1		*FRT BUMPER TOP RUBBER SEAL	Necessary	45.30 FL	*45.30 FL
9	1		*FRT GRILLE (TOP)	Twisted	365.60 FL	*365.60 FL
10	1		*FRT BUMPER LOWER GRILLE	Torn	195.00 FL	*195.00 FL
11	1		*NUMBER PLATE GARNISH	Torn	129.80 FL	*129.80 FL
12	1		*FRT BUMPER TOWING COVER RH	Torn	50.00 FL	*50.00 FL
13	1		*FRT BUMPER INNER SPONGE	Torn	80.30 FL	*80.30 FL
14	1		*FRT BUMPER REINFORCEMENT	Bent	731.10 FL	*731.10 FL
15	1		*FRT BUMPER LOWER GARNISH (INNER)	Cracked	200.10 FL	*200.10 FL
16	1		*FRT BUMPER FOG LAMP ASSY RH	Cracked	950.20 FL	*950.20 FL
17	1		*FRT BUMPER FOG LAMP BASE RH	Not Necessary	186.50 FL	*- FL
18	1		*WASHER TANK	Torn	223.60 FL	*223.60 FL
19	1		*WASHER TANK MOTOR	Not Necessary	282.00 FL	*- FL
20	2		*HEADLAMP	O/S Broken / N/S HolderCracked	5,317.80 FL	*5,317.80 FL
21	1		*CENTRE TOP PANEL	Repair	394.90 FL	*- FL
22	2		*HEADLAMP PANEL (TOP)	Not Necessary	173.40 FL	*- FL
23	2		*HEADLAMP PANEL (SIDES)	Not Necessary	514.00 FL	*- FL
24	1		*HEADLAMP SUPPORT TOP GARNISH	Not Necessary	267.80 FL	*- FL
25	8		*TOP GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
26	1		*FRT RH FENDER	Bent / Buckled	963.10 FL	*963.10 FL
27	1		*FRT RH FENDER INNER COWLING	Torn	228.10 FL	*228.10 FL
28	10		*INNER COWLING CLIPS	Necessary	50.00 FL	*50.00 FL
29	1		*FRT RH FENDER HYBRID PLATE	Necessary	62.90 FL	*62.90 FL
30	1		*FRT RH FENDER TOP COVER GARNISH	Missing	106.90 FL	*106.90 FL
31	1		*FRT NMBER PLATE	Broken	40.00 FS	*40.00 FS
32	1		*FRT WINDSCREEN SEALANT	Not Necessary	25.00 FS	*- FS
33	1		*FRT BUMPER LOWER BEAM	Bent	259.00 FL	*259.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,001.80	11,910.60
- List Item Discount on L Items 20.00/25.00% (\$\$)	2,787.36	2,967.65
Total Parts (\$\$)	11,214.44	8,942.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	30.00	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	0.00
3	LABOUR CHARGE	New	750.00	600.00
4	SPRAY PAINTING	New	750.00	700.00
Gross Labour Cost (S\$)			1,630.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >