

ASS. REC. BY:

REF:

CS/CTU8007728/Uvb91

Special Instruction:

SUPERVISOR

Mellman

P. J. M. C. S.

ASSIGNMENT (Office)

From (Person):

Adeline Ding

of

CTL

Date/Time:

26042018 5:21pm

Estimated Cost:

Bill to:

OD / HP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JRH JHR 2569

Insured:

SKZ 4809R

at Workshop m/s

Zoom Autoworks

Tel:

9450 7920

of

15 Kaki Bukit Rd 4 #01-53

Policy No:

DMP CSN3090681700

Claim No:

SNM 18D0210602

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22042018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

26042018 4:06pm

Person Contacted:

Elin

Vehicle IN/OUT

Date/Time


Action/Instruction (✓) Estimate

JHR 2569 - X

SKZ 4809R - X

ASSIGNMENT

From: _____ Date: 27/04/2018
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: JRM/2569
at Workshop m/s Zoom Autowerks
of 15 Kaki Bukit Rd 4 #01-53
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: JRM 2569 Yr Regn: 1 / 16
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA /
Make: Hyundai Elantra 1797
Colour: Grey A/C Insured / Std / NI / NA
Sp. Reading: 37135 T/Radio: Insured / Std / NI / NA
Eng/No: PP32M41GR F1100735
C/No: _____
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Good / Jammed / Leaked / Burnt or
Brake: Good / Jammed / Leaked / Burnt or
Modl: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/45 R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental
Front: R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: 22/4/18 D.O.I: 26/4/18
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: 2/5/18 Action/Instruction: 4/5 \$5500 conf. with E/L (Ref 14,590.32, 730)

RECEIVED 03 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2) 3/5- typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 5500)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

1) \$ + RS \$

Phone

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		26 Apr 2018 15:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ANCHOR MARINE SUPPLIES PTE LTD, Co. Reg. No.: 198903360Z								
Main Claimant:	TEY HOCK CHOON								
Vehicle Reg. No.:	JHR2569	Date of Loss:	22/04/2018 16:00 - :59						
Claim Type:	TP / SNM18D02106C02	Policy/Cover Note No.:	DMPCSN3090681700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKZ4809R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Zoom Autowerks Pte Ltd - Sims Avenue (HQ) 832 SIMS AVENUE #12-884 EUNOSVILLE, 400832 Eunos - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/05/2018]								
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUZ AS SJE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



SINGAPORE POLICE FORCE



T/20180422/2069

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3

Report No. T/20180422/2069

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/04/2018 16:14		Vide Report No.:		Station Diary No.: 93
Name of Informant: Tey Hock Choon		Address:		
ID Type / ID No.: NEW MALAYSIAN IC / 710428015315		Contact No.: Home/Office: Mobile: 86562181		
Nationality: MALAYSIAN		Email:		
Sex: Male	Age: 46	Date of Birth: 28/04/1971	Type of Informant: Driver	
Race:		Language:	Institution / School Name:	
Occupation: CONTRACTOR		Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 22/04/2018 15:30	Type of Location: Straight Road
Location: TELOK BLANGAH ROAD Along Telok Blangah Road Towards Alexandra Road				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Vehicle No.	Type	Make	Model	Color	Damage	Passenger
JRH2569	Car				Slightly Damaged	1
SKZ4809R						0

Any Pedestrian Involved: No	
No. of Pedestrians Injured: Nil	



**SINGAPORE
POLICE FORCE**



T/20180422/2069

2 of 3

Report No. T/20180422/2069

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

CONTINUATION OF REPORT

Name	Tey Hock Choon		ID No.	710428015315
Related Vehicle	JRH2569 (Car)		Contact No.	86562181
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location, I was driving along Telok Blangah Road intending to proceed to Alexandra Road.

I was driving on the second left from the left. As I was approaching busstop, B09 Telok Blangah Road, the car in front of me suddenly stopped abruptly as the car from the third lane suddenly changed into the second lane causing the car in front of my to brake abruptly.

However just as I braked, I felt a sudden impact and realized that the car behind me had collided into me. The driver, of SKZ4809R, and I then came out of our vehicle to assess the damage and take pictures. The other driver identified himself as Mr Ho, HP: 96169081, and said that he could not stop in time due to the sudden nature of the stop.

The front right side of his vehicle collided into the rear right side of my vehicle. There were no police called or injuries sustained. I do not have any in-car camera in my vehicle.



**SINGAPORE
POLICE FORCE**



T/20180422/2069

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 3

Report No. T/20180422/2069

CONTINUATION OF REPORT

Name	Tey Hock Choon	ID No.	710428015315
Related Vehicle	JRH2569 (Car)	Contact No.	86562181
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location, I was driving along Telok Blangah Road intending to proceed to Alexandra Road.

I was driving on the second left from the left. As I was approaching busstop, B09 Telok Blangah Road, the car in front of me suddenly stopped abruptly as the car from the third lane suddenly changed into the second lane causing the car in front of my to brake abruptly.

However just as I braked, I felt a sudden impact and realized that the car behind me had collided into me. The driver, of SKZ4809R, and I then came out of our vehicle to assess the damage and take pictures. The other driver identified himself as Mr Ho, HP: 96169081, and said that he could not stop in time due to the sudden nature of the stop.

The front right side of his vehicle collided into the rear right side of my vehicle. There were no police called or injuries sustained. I do not have any in-car camera in my vehicle.

details of person involved

1) No. of passenger: ONE (2 days MC from 24/04/2018)

2) Name: Lim Lay Kuan

3) Malaysia IC: 760731-01-6842

4) Address: No 128 Jalan Ketapang 1
Taman Rinting 81750
Masai Johor

5) & LAST TEL: 012-772 1579

hhu 7160441
Clementi NPC
20 Clementi Ave 5
S (129858)
Tel: 68729999
Fax: 68728039

RTD CODE : 13

CERTIFICATE OF INSURANCE SIJIL INSURANS

M.X.1

ORIGINAL COPY
SALINAN ASAL

ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES 1969 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS & COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1962 (REPUBLIC OF SINGAPORE)
 MOTOR VEHICLES (THIRD PARTY RISKS) ACT (CAP 90) NEGARA BRUNEI DARUSSALAM

CERTIFICATE NO.
No. Sijil

AESG0067888

NCD
Diskaun Tanpa Tertutut

55.00%

1. **Index Mark and Registration Number of Vehicle**
Tanda Indeks Dan Nombor Pendaftaran Kenderaan : JRH2569 1797.00 CC HYUNDAI ELANTRA 1.8 (A)
2. **Name of Policyholder**
Nama Pemegang Polisi : TEY HOCK CHOON
3. **Effective date of the Commencement of Insurance for the purposes for the Regulations, Ordinance or Enactment**
Tarikh efektif permulaan insurans untuk kegunaan Ordinan : 21-01-2018
4. **Date of Expiry of the Insurance**
Tarikh Luput Insurans : 20-01-2019
5. **Persons or Classes of Persons entitled to drive**
Orang atau Kelas Pihak Yang Dibenarkan Memandu
a) THE POLICYHOLDER b) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OF REGULATIONS IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use* Had Penggunaan

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, peace-making reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the motor trade.

Digunakan hanya untuk tujuan sosial, domestik dan keseronokan dan untuk perniagaan Pemegang Polisi.

Polisi ini tidak melindungi kegunaan untuk sewaan atau ganjaran, perlumbaan, mengendarai ketahanan, ujian kebolehpersediaan, ujian ketahanan, membawa barangan selain daripada sampel yang berkaitan dengan apa-apa pekerjaan atau perniagaan.

This Certificate is not transferable to a new owner of the Vehicle.

If for any reason the Insurance is terminated during its currency this Certificate must be returned to the Company or if this Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the compulsory Insurance Legislation.

This Certificate must be returned if the Insurance is suspended during its currency.

IMPORTANT

If you are involved in an accident causing injury to any person or damage to any property or other vehicle you must:

- (a) Try to obtain names and address of any witness to the accident.
- (b) Report to the Company immediately.
- (c) Refer to the Company immediately all communications received from the Police Authorities.
- (d) Send to the Company immediately all letters from Third Parties unanswered.
- (e) Not pay money to any Party involved in the accident without the Company's written permission.

* Limitations rendered inoperative by Section 95 of the Road Transport Act, 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not included under this heading.
 Had yang tidak berkesan oleh Seksyen 95 Akta Pengangkutan Jalan 1987 (Malaysia) atau Seksyen 8 Akta Kenderaan Bermotor (Gedung dan Risiko Pihak Ketiga) (Cap 189) Republik Singapura atau Seksyen 7 Akta Singapura atau Seksyen 7 Akta Insurans Kenderaan Bermotor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam adalah tidak termasuk di bawah tajuk ini.

I/we certify that the Policy to which the Certificate is issued in accordance with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.
 Saya/kami berseru bahwa Polisi di mana Sijil ini dikeluarkan bertakrif di bawah provisions Bahagian IV Akta Pengangkutan Jalan 1987, (Malaysia) Akta Kenderaan Bermotor (Risiko Pihak Ketiga & Gerdung) (Cap 189) Republik Singapura dan Akta Insurans Kenderaan Bermotor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam.

Agent Code
Kod Ejen

: SG01332

ALLIANZ GENERAL INSURANCE COMPANY (MALAYSIA) BERHAD (735425-V)



Authorised Signature

ALPHA-1801332-000148816-5

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO PENDAFTARAN

JRH2569

No. Sn B 9246363
02qi7a42

Nama Pemunya
Berdaftar

TEY HOCK CHOOH

710428015315
[MAL]

Alamat

NO 128 JALAN KETAPANG 1 TAMAN RINTING
81750 JOHOR BAHRU JOHOR

No Enjin 04NBFU892122
 No Chasis PP32M410RF1100735
 Puan HYUNDAI
 Nama Model ELANTRA 1.8 AUTO
 Nombor Enjin 1797
 Bahan Bakar PETROL
 Jantina KELABU
 Kelas Kegunaan PERSendirian-MOTOKAR INDIVIDU
 Jenis Badan MOTOKAR
 Tahun Dibuat 2015
 Tarikh Pendaftaran 21/01/2016
 Status Pemunya PERSendirian
 Negeri Tempatan
 Jarak 5
 Negeri Lesen
 Pendaftaran Motor 6 bulan 12 bulan
 139.40 278.80

B D M/B G k

B T 1

Berat Kerd

B T M

B G 1

B G 2

B G 3

B G 4

B G 5

B G 6

B G 7

B G 8

B G 9

B G 10

B G 11

B G 12

Tandatangan Pemunya Berdaftar

Pendaftaran ini dikeluarkan
oleh Pengerah JPU Negeri UTC JOHOR

PENGANGKUTAN TEMPATAN

UNTUK KEGUNAAN PEJABAT

MAWLIK DITUNTUT OLEH PUBLIC BANK BERHAD

NO DPT H05/510763/16

NOTA PENTING

Perakuan ini di tempat yang selamat. Jika perakuan ini hilang, hendaklah melaporkan kepada polis dengan segera dan menyerahkan perakuan pendaftaran kepada Pengerah Jabatan Pengangkutan Jalan (JPU).

Untuk butiran kenderaan di muka ini dan dilaporkan dengan segera kepada Pengerah JPU jika terdapat sebarang perubahan.

Kenderaan motor yang sah hendaklah sentiasa dipamerkan dan mematuhi lesen 60 hari sebelum tempohnya tamat.

Hendaklah melaporkan secara bertulis dengan segera kepada JPU sekiranya kenderaan anda tidak berlesen.

5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli hendaklah mengisi dan mengemukakan borang (JPJ) JPJ3A kepada Pengerah JPU dalam tempoh tujuh hari dan tarikh penjualan itu.

6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milien telah disimpulkan dan kenderaan telah didaftarkan dengan nama pemilik baru.

7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPU dalam tempoh tujuh hari dan tarikh pertukaran itu.

BAYARAN-BAYARAN

1014011 21/01/2016 18:05:58 MEL01001 N SYAHIDAN
072107 E 0 JRM2500 20/01/2017
2253070RM*****50.00 2103040RM*****00.00
2203000RM*****278.80 RM*****028.80

11

12

13

14

15

16

17

18

19

20

PERTUKARAN-PERTUKARAN MILIKAN DAN ALAMAT

	No. K.P./Def. Negeri/Sykt	Terdengar Pernyataan Berakut
2	No. K.P./Def. Negeri/Sykt	Terdengar Pernyataan Berakut
3	No. K.P./Def. Negeri/Sykt	Terdengar Pernyataan Berakut
4	No. K.P./Def. Negeri/Sykt	Terdengar Pernyataan Berakut
5	No. K.P./Def. Negeri/Sykt	Terdengar Pernyataan Berakut
	No. K.P./Def. Negeri/Sykt	Terdengar Pernyataan Berakut

REKOD-REKOD PEMERIKSAAN

	9	9
	9	10
	3	11
	8	12



ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville

#12-884 Singapore 400832

Tel: 9450 7920

* zoomautowerks@gmail.com

Not Authorized

D.O.A: 22 APRIL 2018

26 APRIL 2018

OWNER: TEY HOCK CHOON

REG NO.: JRH 2569

MAKE/MODEL: HYUNDAI ELANTRA

26/4/18
2/s # 5500/2
Take photo After repair
6 day.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	11 \$ 185.80 X
1	Rear boot lid 1048	306500 \$ 1,528.00 /
2	Rear boot hinges	11 \$ 275.60 X
1	Rear boot inner trim	11 \$ 300.60 X
2	Rear boot lamps	11 \$ 1,800.60 X
1	Rear boot lock 98.50	twi \$ 250.80 /
1	Rear boot lock striker	11 \$ 80.30 X
1	Rear boot logo 48	ren \$ 97.80 /
1	Rear boot rubber 166.30	twi \$ 289.90 /
1	Rear boot "HYUNDAI" emblem 40	ren \$ 88.00 /
1	Rear boot "ELANTRA" emblem 40	ren \$ 90.90 /
1	Rear boot emblem set 50	ren \$ 88.90 /
2	Rear taillamps 785	mscn \$ 1,977.60 1pc
2	Rear taillamp panels 210	mscn \$ 801.80 1pc
1	Rear end panel 442.80	306500 \$ 1,255.80 /
1	Rear end panel inner garnish 133.60	twi \$ 299.30 /
1	Rear smart keyless sensor	11 \$ 477.80 X
1	Rear bumper 666.80	7.5 \$ 900.20 /
1	Rear bumper lower diffuser 305	7.5 \$ 392.00 /
2	Rear bumper reflectors 66.50	mscn \$ 199.60 1pc
1	Rear bumper reinforcement	one \$ 455.80 /
2	Rear bumper reinforcement stays 105	mscn \$ 401.60 1pc
3	Rear bumper reinforcement brackets 30x3=90	twi \$ 434.70 /
2	Rear bumper side retainers 44.60x2=89.60	but \$ 135.60 /
1	Rear bumper undercover	ns \$ 155.80 X
1	Rear floor board	11 \$ 488.80 X
1	Rear floor panel	1 \$ 2,400.30 X
1	Rear exhaust silencer	11 \$ 800.80 X
2	Rear exhaust mountings	11 \$ 171.60 X
1	Rear fender -L/H	R \$ 1,888.90 X
1	Rear fender inner trim 1/s 212	re/wing \$ 500.20 /
		\$ 19,215.40
	Less 20%	\$ 3,843.08
		\$ 15,372.32

505.29
4411.08

c/t:

\$

15,372.32

SPECIAL NETT ITEMS

1	Rear windscreen sealant	11	\$	80.00	X
1	Rear bumper clip (1 set)	rec	\$	50.00	✓
1	Rear reverse sensor (1 set)	shut	\$	480.00	200
			\$	610.00	

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	30
2	To remove and refit inner garnishes.	\$	150.00	80
3	To remove and refit rear reverse sensor.	\$	150.00	50
4	To transfer boot lid mechanism and wiring assembly.	\$	120.00	60
5	To remove and refit rear windscreen glass.	\$	180.00	X
6	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	X
7	To apply undercoating.	\$	180.00	80
8	Panel beating.	\$	1,600.00	1100
9	To re-spray painting on the affected areas.	\$	1,500.00	200
		\$	4,110.00	

2810

GRAND TOTAL :

\$ 20,092.32

PAGE 2 OF 2

Let Auto Consultants hence notify the Repairer of the following:

- To resurvey before water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2018		26 Apr 2018 15:21 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ANCHOR MARINE SUPPLIES PTE LTD , Co. Reg. No.: 198903360Z								
Main Claimant:	TEY HOCK CHOON								
Vehicle Reg. No.:	JRH2569	Date of Loss:	22/04/2018 16:00 - :59 [27 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02106C02	Policy/Cover Note No.:	DMPCSN3090681700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKZ4809R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Zoom Autowerks Pte Ltd - Sims Avenue (HQ) 832 SIMS AVENUE #12-884 EUNOSVILLE, 400832 Eunos - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/05/2018]								
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JRH2569 (SNM18D02106C02)

[SKZ4809R]

TP

TEY HOCK CHOON

Apr 22 2018 4:00PM

[ANCHOR MARINE SUPPLIES PTE LTD]

Zoom Autowerks Pte Ltd - Sims Avenue

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	24/04/18 15:31	Accident Statement		Load HTML	

Photos/Images

3 per page

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
7	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
8	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
9	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
10	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
11	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
12	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
13	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
14	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
15	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
16	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
17	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
18	24/04/18 15:19	Accident Photo [Linked Accident Report Documents]		Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/05/18 14:32	General View		Load PDF	
2	03/05/18 14:33	Reinspection Photo		Load PDF	

Documentation

1 per page

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	26/04/18 15:20	PRS		Load PDF	
2	26/04/18 15:21	Police Report		Load PDF	
3	26/04/18 15:21	OI GIA REPORT		Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	24/04/18 15:20	IC,CI,DL [Linked Accident Report Documents]		Load TIF	

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
2	24/04/18 15:20	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	
3	24/04/18 15:30	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	24/04/18 15:31	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	24/04/18 15:19	Accident Photo	 Load JPG	☒
2	24/04/18 15:19	Accident Photo	 Load JPG	☒
3	24/04/18 15:19	Accident Photo	 Load JPG	☒
4	24/04/18 15:19	Accident Photo	 Load JPG	☒
5	24/04/18 15:19	Accident Photo	 Load JPG	☒
6	24/04/18 15:19	Accident Photo	 Load JPG	☒
7	24/04/18 15:19	Accident Photo	 Load JPG	☒
8	24/04/18 15:19	Accident Photo	 Load JPG	☒
9	24/04/18 15:19	Accident Photo	 Load JPG	☒
10	24/04/18 15:19	Accident Photo	 Load JPG	☒
11	24/04/18 15:19	Accident Photo	 Load JPG	☒
12	24/04/18 15:19	Accident Photo	 Load JPG	☒
13	24/04/18 15:19	Accident Photo	 Load JPG	☒
14	24/04/18 15:19	Accident Photo	 Load JPG	☒
15	24/04/18 15:19	Accident Photo	 Load JPG	☒
16	24/04/18 15:19	Accident Photo	 Load JPG	☒
17	24/04/18 15:19	Accident Photo	 Load JPG	☒
18	24/04/18 15:19	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	24/04/18 15:20	IC,CI,DL	 Load TIF	
2	24/04/18 15:20	POLICE REPORT	 Load TIF	
3	24/04/18 15:30	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007728/UVBQ2

Date: 04/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3090681700

Claimant Vehicle
No : JRH2569Insured Vehicle
No : SKZ4809R

Date of Loss: 22/04/2018

Nature of Claim: TP

Claim
No: SNM18D02106C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JRH2569

Make & Model: HYUNDAI ELANTRA, 1.6 (A)

Reg. Date: 21/01/2016 (Man. Year: 2015)

Colour: Grey

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: G4NBFU892122

Chassis No: PP32M41GRF1100735

Odometer: 37135 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,982.32	4,292.32	11,690.00	73.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	2,600.00	1,510.00	36.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,092.32	6,892.32	13,200.00	65.70
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	20,092.32	5,500.00	14,592.32	72.63

INSPECTION

Date of Assignment: 26/04/2018

Date Inspected: 26/04/2018 Inspected At:

15 KAKI BUKIT RD 4 #01-53
Repairer: Zoom Autowerks Pte Ltd - Sims
Avenue (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2018)
Parts: 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for JRH2569)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	185.80 FL	*- FL
2	1		*REAR BOOT LID	Badly Dented	1,528.00 FL	*1,048.00 FL
3	2		*REAR BOOT HINGES	Not Necessary	275.60 FL	*- FL
4	1		*REAR BOOT INNER TRIM	Not Necessary	300.60 FL	*- FL
5	2		*REAR BOOT LAMPS	Not Necessary	1,800.60 FL	*- FL
6	1		*REAR BOOT LOCK	Twisted	250.80 FL	*98.50 FL
7	1		*REAR BOOT LOCK STRIKER	Not Necessary	80.30 FL	*- FL
8	1		*REAR BOOT LOGO	Necessary	97.80 FL	*48.00 FL
9	1		*REAR BOOT RUBBER	Twisted	289.90 FL	*166.30 FL
10	1		*REAR BOOT HYUNDAI EMBLEM	Necessary	88.00 FL	*40.00 FL
11	1		*REAR BOOT ELANTRA EMBLEM	Necessary	90.90 FL	*40.00 FL
12	1		*SET REAR BOOT EMBLEM	Necessary	88.90 FL	*50.00 FL
13	1		*REAR TAILLAMPS	N/S Cracked	1,977.60 FL	*785.00 FL
14	1		*REAR TAILLAMP PANELS	N/S Dented	801.80 FL	*210.00 FL
15	1		*REAR END PANEL	Badly Dented	1,255.80 FL	*442.80 FL
16	1		*REAR END PANEL INNER GARNISH	Twisted	299.30 FL	*133.60 FL
17	1		*REAR SMART KEYLESS SENSOR	Not Necessary	477.80 FL	*- FL
18	1		*REAR BUMPER	Distorted	900.20 FL	*666.80 FL
19	1		*REAR BUMPER LOWER DIFFUSER	Distorted	392.00 FL	*305.00 FL
20	1		*REAR BUMPER REFLECTORS	N/S Cracked	199.60 FL	*66.50 FL
21	1		*REAR BUMPER REINFORCEMENT	Cracked	455.80 FL	*455.80 FL
22	1		*REAR BUMPER REINFORCEMENT STAYS	N/S Bent	401.60 FL	*105.00 FL
23	3		*REAR BUMPER REINFORCEMENT BRACKETS	Twisted	434.70 FL	*90.00 FL
24	2		*REAR BUMPER SIDE RETAINERS	Bent	135.60 FL	*89.60 FL
25	1		*REAR BUMPER UNDERCOVER	No such part	155.80 FL	*- FL
26	1		*REAR FLOOR BOARD	Not Necessary	488.80 FL	*- FL
27	1		*REAR FLOOR PANEL	Repair	2,400.30 FL	*- FL
28	1		*REAR EXHAUST SILENCER	Not Necessary	800.80 FL	*- FL
29	2		*REAR EXHAUST MOUNTINGS	Not Necessary	171.60 FL	*- FL
30	1		*REAR FENDER -L/H	Repair	1,888.90 FL	*- FL
31	1		*REAR FENDER INNER TRIM N/S	Deformed / Warped	500.20 FL	*212.00 FL
32	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*SET REAR BUMPER CLP	Necessary	50.00 FS	*50.00 FS
34	1		*SET REAR REVERSE SENSOR	Shorted	480.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,825.40	5,302.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,843.08	1,010.58
Total Parts (\$\$)	15,982.32	4,292.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
7	TO APPLY UNDERCOATING	New	180.00	80.00
8	PANEL BEATING	New	1,600.00	1,100.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,200.00
Gross Labour Cost (\$\$)			4,110.00	2,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >