

(08/11/13) waf

ASS. REC. BY: Morley

REF:

47P 18007732/Urb/n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH2718Jat Workshop n/s: 3m

of: _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 70

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: 18 Consistent? : Yes or NoEst. Repairs: 18 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5988/c

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBH2718JYr Regn: 4 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyota HiaceC.C. 2982Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 1425

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH/2015026013

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mmR/Bal. 2 mmL/Bal. 2 mmL/Bal. 2 mmD.O.A. 24/4/18D.O.A. 26/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

47A 38110

Parten NTRC

14/5/18 L/S to 14/5/18 (Red 8354.57, 363)

RECEIVED 14 MAY 2018

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

14/5- typistReport Format: TPLump Sum / I.B.I: (\$ 14,500/2)Days Of Repair: 18Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Ref. No	: CS/TP18007432/uvb ^{m2}	Res. Date:	7/5/18	Date Received:	
Veh. No	: G134/27181	SP:		WKSP:	smf
C/No	:				
Action/Instruction:					
1. File	2. Submit Photo?	YES / NO		Message:	
3. Indicate Res. Date On Photo Page?		YES / NO			
If No, due to	a) No authorisation	b) Days of repair			
others:					
Final Re-inspection or Progress Photos				Inspected By:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18007732/Uvb

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 26-04-2018



Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	GBH 2718J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	26/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date	Inspection Date	26/04/2018
---------------	-----------------	------------

Survey held at BLUWEL AUTOMOTIVE SERVICE PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)
SINGAPORE 417883

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5988K

Vehicle Details

Vehicle No.: GBH2718J

Vehicle to be Exported: No

Intended De-registration Date: 27 Apr 2018

Vehicle Make: TOYOTA

Vehicle Model: HIACE 3.0L AUTO

Primary Colour: Silver

Manufacturing Year: 2017

Engine No.: 1KD2686751

Chassis No.: KDH2015026013

Maximum Power Output: -

Open Market Value: \$32,358.00

Original Registration Date: 09 Apr 2018

First Registration Date: 09 Apr 2018

Transfer Count: 0

Actual ARF Paid: \$1,618.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 08 Apr 2028

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$38,303.00

COE Rebate Amount: \$38,110.00

Total Rebate Amount: \$38,110.00

The information contained herein is correct as at 27 Apr 2018

OK



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2012 Mercedes-Benz C-Class C180K.



Low Mileage, Original
Immaculate Condition, High
COE, Low Depreciation Call
Now!

Direct Owner StarAd

• Free VICO
• Free groom
• In-house w
• Member of
• 100% depo



Browse by Category ▼

« Back (1 2 3 4) Next »

Sort b

61 vehicles

Toyota Hiace

Advan

Make Model Price Depreciation Reg Date Eng Cap Mil

Search Selection

Toyota Hiace

Any

Any

2018

Any



Toyota Hiace

\$70,800

\$7,100 /yr

17-Apr-2018

2,982 cc

Fuel Type: Diesel

Toyota Hiace Promotion, Prices Are Inclusive Of GST, ARF, Registration Fees, Road Tax And COE/ETS. Min. Loan Require
Warranty And Free Servicing Included, No Hidden Cost, ...

Car (S) Pte Ltd

Posted: 26-Apr-2018 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



Toyota Hiace

\$72,800

\$7,320 /yr

06-Apr-2018

2,982 cc

Fuel Type: Diesel

No Gimmicks, Prices Are Inclusive Of GST And Registration Fees Etc! Will Be Delivered As A New Unit With 10 Years COE
Suitable For Class 3/3A Above! HDB Parking \$80! Easy Acc...

Car (S) Pte Ltd

Posted: 26-Apr-2018 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



Toyota Hiace Commuter

\$102,800

\$10,540 /yr

26-Jan-2018

2,982 cc

Fuel Type: Diesel

Will Be Handover As A Brand New Vehicle With New 10 Years COE! Price Above Is Inclusive Of GST & Registration Fees!
Trade-ins Are Very Much Welcomed!

Car (S) Pte Ltd

Posted: 26-Apr-2018 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



Toyota Hiace

\$73,988

\$7,450 /yr

02-Apr-2018

2,982 cc

Fuel Type: Diesel

Undefectable Price In Town, Price Inclusive Of FIRST Ownership, Come With 3 Years Or 100,000km Warranty, MSCP \$11
Van In Whole Market, We Provide The Best Price, Best Service,...

ABWIN Bus Pte Ltd

Posted: 25-Apr-2018 Tags: 2018 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

MYT218054317 / Yow Tuo Automobile Tech Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 25/04/2018 10:56
SUBMITTED BY: Teh Lei Ming

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow Insurance Companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/04/2018 10:59
Date Of Accident 24/04/2018 12:15
Exact Location Of Accident JUNCTION OF TANAH MERAH COAST RD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBH2718J
Insured/Policyholder
Name Of Registered Owner R3 SHIP MANAGEMENT PRIVATE LIMITED
Co Reg No 201215988K
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-91433194
Alternative Phone No OFFICE-91433194
Vehicle Particulars
Manufacturer TOYOTA
Model HIACE
Exact Purpose for which vehicle was being used at time of accident WORK USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5099602039
Cover Note Number
Driver
Name of Driver MUHAMMAD FADZIL BIN ISMAIL
NRIC No S8606461H
Date Of Birth 13/03/1986
Occupation OUTDOOR
Date Of Driving Pass 23/08/2016
Driving Experience 1 YEAR AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91433194
Fax Number
Contact Number
Email Address NOEMAIL

Address APT BLK 121A EDGEDALE PLAINS #16-257
 Postcode 821121
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle
 Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: KYAW NAING OO
 GENDER: MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BEDOK POLICE DIVISIONAL HQ (G DIVISION)
 Police Station Address ROAD: 30 BEDOK NORTH ROAD, POSTCODE: 469678, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-2440000 - FAX NO: 64443009
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XB6732L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MUHAMMAD FADZIL BIN ISMAIL

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBH2718J

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

APT BLK 121A EDGEDALE PLAINS
#16-257

Postcode

821121

DETAILS OF INJURED PERSON 2

Name

KYAW NAING OO

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBH2718J

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

3 JALAN LIMAU NIPIS

Postcode

468256

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Officer.
3. Information provided must be accurate and complete as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reject or reduce liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance company.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the statutory Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulation, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 25/4/18, 10:51AM

Driver's Signature

(If driver is not the policyholder)

Date & Time: 25/4/18, 10:51AM


Reporting Centre Personnel's Signature

NAME:

NRC/PC/17102

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

We declare the foregoing particulars are true in every respect.

Police Officer's Signature 
 Date & Time 24/4/18, 10:59am

CLASSIC Sketch Plan/APP. V3

Driver's Signature 
 (If driver is not the policyholder)
 Date & Time 25/4/18, 10:59am

Reporting Centre Personnel's Signature
 Name
 KRAC/PR No.1



**SINGAPORE
POLICE FORCE**



G/20180425/7001

1 of 3

POLICE REPORT (NP299)

Report No. G/20180425/7001

Police Station Of Origin
Bedok Police Divisional HQ
30 Bedok North Road SINGAPORE 469676
Tel No:1800-2440000

Date/Time Report Made 25/04/2018 01:25	Vide Report No.		Station Diary No.	
Name Of Informant PAN YI XI	Address APT BLK 422 PASIR RIS DRIVE 6 #12-149 SINGAPORE 510422			
ID Type / ID No. NRIC NO / S8005981G	Contact No. Home/Office:	Mobile: 98355094		
Nationality SINGAPORE CITIZEN	Email Address sean@rsm.com.sg			
Occupation Business development manager	Sex Male	Age 38	Date of Birth 06/02/1980	Race Chinese
Institution/School Name	Language English			
Date/Time Of Incident 24/04/2018 12:15 - 24/04/2018 12:30	Location Of Incident 76 TANAH MERAH COAST ROAD CHANGI LODGE 2 SINGAPORE 498754			

Brief details.

On 24 April 2018 at or about 12:15pm, my company van (GBH2718J) with driver, Muhammad Fadzil Bin Ismail, S8606461H and passenger Kyaw Naing Oo, G2545603W, was hit from behind by a tipper truck, XB6732L, driven by Ulaganathan Annamalai, G8231090N, an Indian national, while my van was stationary at the traffic light junction along Tanah Merah Coast Road, outside Changi Lodge.

The impact totally smashed the back of my van and caused the van to move 10 meters ahead.

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

25/04/2018 01:25

Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



G/20180425/7001

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20180425/7001

Fortunately, there were no vehicles in front of the van or moving traffic across the path of the van. Else, the situation would have been worse. The van was sent to a workshop for traffic accident reporting and insurance claim.

At around 2pm, I personally sent both the driver and passenger to Tan Tock Seng Hospital as both complained of headaches and neck pain.

Muhammad Fadzil was given 2 days MC and Kyaw Naing Oo was given 3 days MC due to the accident.

Subjects Involved			
Victim			
Person Name	Kyaw Naing Oo		
ID Type	OTHERS / work permit	ID No	093508106
Gender	Male	Age	44-45
Race	Burmese	Language	English
Occupation	Management executive	Address Type	Private Landed Property / Apartment
Address	3 Jalan Limau Nipis SINGAPORE 468256		Mobile No
Relation To Informant	Worker		98914778
Person Name	Muhammad Fadzil Bin Ismail		
ID Type	NRIC NO	ID No	S8606461H
Gender	Male	Age	31-32

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
25/04/2018 01:25

Classification Of Case:

**SINGAPORE
POLICE FORCE**

G/20180425/7001

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20180425/7001

Race	Malay	Language	English
Occupation	Management executive	Address Type	HDB / HUDC
Address	APT BLK 121A Edgedale Plains #16-257 SINGAPORE 821121	Home/Office No	91433194

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this
report has been authenticated by
SingPass. No signature is required.Date/Time:
25/04/2018 01:25

Classification Of Case:



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-51/53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 2841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

with Abdul
 HAN
 1/5 @ 14500
 18dy.

GSH 2747

	Rear windscreen	shattered	1255.10	/
	Rear windscreen moulding	new	110.10	/
	Tailgate	Body	1969.30	/
	Tailgate Rear legs	new	60.50	/
	Tailgate outer chrome handle	Body	299.30	/
	Tailgate inner lock	gm	359.00	/
	Tailgate lock striker	new	66.50	x
	Tailgate weatherstrip	new	387.30	/
	Tailgate inner trim board	new	480.00	/
1 set	Tailgate inner trim board clips	new	45.00	/
	Tailgate Rear wiper arm	Body	188.20	/
	Tailgate Rear wiper motor	Body/gm	563.50	/
	Tailgate inner top garnish	new	165.30	/
	Tailgate 3rd brake lamp	new	190.10	/
	Tailgate rear view mirror	Body	245.30	/
	Tailgate inner lock outer cover	new	60.80	/
2pc	Tailgate Dampers @ 211.10	new	422.20	x
7pc	Tail lamps @ 303.10	Body	606.20	/
2pc	Tail lamp lower garnishes @ 169.30	Body/gm	338.60	/
2pc	Tail lamp housing parts @ 345.10	Body/gm	690.20	/
2pc	Tail lamp inner housing parts @ 269.50	Body/gm	539.00	/
2pc	Rear bumper	Body/gm	599.30	/
	Rear bumper inner stop panel	Body	197.30	/
1 set	Rear bumper clips	new	40.00	/
2pc	Rear bumper side holders @ 115.00	new	230.00	x
	Rear exhaust	new	971.00	x
	Rear end panel outer	Body	566.10	/
	Rear end panel inner	Body	936.20	/
	Rear end panel top plate	Body	269.50	/
	Rear spare tyre carrier	new	392.50	x

(25m)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref : CS/TP18007732/Uvbn2	
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883			Date : 16-05-2018	
ON BEHALF OF RS SHIP MANAGEMENT PRIVATE LIMITED			Code : TP149	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		GBH 2718J	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		26/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KDH2015026013	Colour	SILVER	
Odometer	1425	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	DUNLOP	8 mm	
L/H Front Tyre	195/80 R15	DUNLOP	8 mm	
R/H Rear Tyre	195/80 R15	DUNLOP	8 mm	
L/H Rear Tyre	195/80 R15	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/04/2018	Inspection Date	26/04/2018	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		18 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 2718J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN	SHATTERED	1,255.10	1,255.10
1	REAR WINDSCREEN MOULDING	NECESSARY	110.10	110.10
1	TAILGATE	BADLY DENTED	1,969.30	1,969.30
1	TAILGATE REAR LOGO	NECESSARY	60.50	60.50
1	TAILGATE OUTER CHROME HANDLE	BENT / CRACKED	299.30	299.30
1	TAILGATE INNER LOCK	JAMMED	359.00	359.00
1	TAILGATE LOCK STRIKER	NOT NECESSARY	66.50	-
1	TAILGATE WEATHERSTRIP	TWISTED	387.30	387.30
1	TAILGATE INNER TRIM BOARD	TORN	480.00	480.00
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	45.00	45.00
1	TAILGATE REAR WIPER ARM	BENT	188.20	188.20
1	TAILGATE REAR WIPER MOTOR	DAMAGED / JAMMED	563.50	563.50
1	TAILGATE INNER TOP GARNISH	CRACKED	165.30	165.30
1	TAILGATE 3RD BRAKE LAMP	CRACKED	190.10	190.10
1	TAILGATE REAR VIEW MIRROR	BROKEN	245.30	245.30
1	TAILGATE INNER LOCK OUTER COVER	DEFORMED	60.80	60.80
2	TAILGATE DAMPERS @\$211.10	NOT NECESSARY	422.20	-
2	TAILLAMPS @\$303.10	BROKEN	606.20	606.20
2	TAILLAMP LOWER GARNISHS @\$169.30	DENTED / TWISTED	338.60	338.60
2	TAILLAMP HOUSING PANELS @\$345.10	BADLY DENTED	690.20	690.20
2	TAILLAMP INNER HOUSING PANELS @\$269.50	BADLY DENTED / TWISTED	539.00	539.00
1	REAR BUMPER	DENTED / TORN	599.30	599.30
1	REAR BUMPER INNER STEP PANEL	BENT	197.30	197.30
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
2	REAR BUMPER SIDE HOLDERS @\$115.00	NOT NECESSARY	230.00	-
1	REAR EXHAUST	NOT NECESSARY	971.00	-
1	REAR END PANEL OUTER	BADLY DENTED	566.10	566.10
1	REAR END PANEL INNER	BENT	936.20	936.20
1	REAR END PANEL TOP PLATE	BENT	269.50	269.50
1	REAR SPARE TYRE CARRIER	NOT NECESSARY	392.50	-
2	REAR FENDERS @\$1419.70	BADLY DENTED / BUCKLED	2,839.40	2,839.40
2	REAR FENDER INNER TRIM BOARDS @\$425.10	N/S TORN	850.20	425.10

Report Ref No. CS/TP18007732/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER LOWER SIDE PANELS @\$166.50	DENTED / TWISTED	333.00	333.00
1	REAR FLOOR PANEL CARPET	NOT NECESSARY	820.10	-
	LESS 25% DISCOUNT		-4,521.53	-3,689.68
			13,564.57	11,069.02
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	380.00	380.00
1	REAR LICENCE PLATE (SN)	BENT	50.00	20.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	TAILGATE "70KM/H" STICKER (SN)	NECESSARY	20.00	10.00
1	TAILGATE "8PAX" STICKER (SN)	NECESSARY	20.00	10.00
1	SET TAILGATE CORPORATE STICKER (SN)	NECESSARY	600.00	400.00
1	SET REAR FENDER CORPORATE STICKER N/S (SN)	NECESSARY	900.00	800.00
1	SET REAR FENDER CORPORATE STICKER O/S (SN)	NECESSARY	900.00	800.00
			3,200.00	2,660.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		120.00	60.00
	TO SPRAY RUST PROOFING.		180.00	120.00
	TO DISMANTLE & REPLACING REVERSE CAMERA.		80.00	50.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS.		3,200.00	2,500.00
	TO PUTTY & SPRAY PAINTING.		2,200.00	1,500.00
			6,090.00	4,430.00
	GRAND TOTAL		22,854.57	18,159.02
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			14,500.00

Report Ref No. CS/TP18007732/Uvbn2


CHUA KANG SENG
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.