



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD MERCEDES-BENZ GLA200 (SJW909P)

Date of Loss

8 January 2018

Time of Loss

18.30

Loss Description

SLG546M (INSD) > SJW909P (TP) > SLB2826T

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

28/06/2018



Days of work completion *

169



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SJW909P

Registration State

SINGAPORE

Mileage

0

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2015

Purchase Date

dd/mm/yyyy



Registration Date *

05/06/2015



Age of Vehicle

2

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

NG YONG NGEE

CATEGORY

Make

POST SURVEY INF...

POLICY INFORMAT... TPVD MERCEDES-BENZ

ASSESSMENT INFO... MERCEDES BENZ

CATEGORY Model

POLICY INFORMAT... GLA200

ASSESSMENT INFO... GLA200 A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... WDC1569432J103908

CATEGORY Date of Birth

FNOL INFORMATI... 4 September 1976

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 41

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... 27091030607659

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1595

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... BLK 90 DAWSON ROAD, 142090,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7627836I

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

27/04/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

235/50R18

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

235/50R18

Front left side

PIRELLI6mm

Front right side

PIRELLI6mm

Rear left side

PIRELLI6mm

Rear right side

PIRELLI6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REM
------	-------	-----------	----------	------	-----------	-------------	------------------------	-----------	------------	--------------	------------	-----------	-----------------	----------------	-----

Labour

Add Approve Deny

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
 	1		TO CHECK ELECTRICAL SYSTEM AND CALIBRATE / FOCUS HEADLAMP	30	0	0	Reviewing		
 	2		TO REMOVE, REPLACE AND / OR TRANSFER FRONT PARKING SENSORS TO NEW BUMPERS	30	0	0	Reviewing		
 	3		TO STRAIGHTEN, REPAIR, REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	400	0	0	Reviewing		
 	4		TO SPRAY FROZEN GREY PAINTING, BLENDING ON FRONT AFFECTED ON FRONT AFFECTED AND ADJACENT AREA	400	0	0	Reviewing		
 	5		TO CHECK REAR ELECTRICAL WIRING SYSTEM	30	0	0	Reviewing		
 	6		TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE	60	0	0	Reviewing		
 	7		TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE	120	0	0	Reviewing		
 	8		TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC, FOR NECESSARY REPAIR	80	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
 	9		TO STRAIGHTEN, REPAIR AND REALIGN REAR EXHAUST SILENCER	60	0	0	Reviewing		
 	10		TO REMOVE, REPLACE AND / OR TRANSFER REAR PARKING SENSORS TO NEW BUMPER. (INCLUDE RESET FRONT AND REAR PARKING SENSOR CONTROL UNIT)	100	0	0	Reviewing		
 	11		TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	700	0	0	Reviewing		
 	12		TO SPRAY FROZEN GREY PAINTING, BLENDING ON REAR AFFECTED AND ADJACENT AREA	900	0	0	Reviewing		
 	13		TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	80	0	0	Reviewing		
 	14		TO REAPPLY CERAMIC COATING ON FRONT AND REAR NEW AND AFFECTED PORTIONS	400	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 12 DAYS	Reviewing			
		2	HEADLAMP ASSY R/L (2PCS)(DISC 10%)	Reviewing	2231.1	O/S REPLACED / N/S NOT NECESSARY	
		3	FRT GRILLE ASSY (W/MOULDING,TRIM) (DISC 10%)	Reviewing	657	REPLACED	
		4	FRT GRILLE EMBLEM ASSY (W/BRACKET) (DISC 10%)	Reviewing	199.8	REPLACED	
		5	FRT BUMPER (DISC 10%)	Reviewing	1048.5	REPLACED	
		6	FRT BUMPER NO. PLATE GARNISH (DISC 10%)	Reviewing	59.4	REPLACED	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		7	FRT BUMPER LOWER TRIM CHROME (DISC 10%)	Reviewing	544.5	REPLACED	
		8	FRT BUMPER PARK SENSOR - 4PCS (DISC 10%)	Reviewing	507.6	REPLACED - 3PCS	
		9	FRT BUMPER LOWER GRILLE (DISC 10%)	Reviewing	114.3	REPLACED	
		10	FRT BUMPER REINFORCEMENT	Deny	0	REFIT	
		11	FRT SUPPORT ASSY	Deny	0	REPAIRED	
		12	TAILGATE (DISC 10%)	Reviewing	1528.2	REPLACED	
		13	TAILGATE EMBLEM (LOGO) (DISC 10%)	Reviewing	49.5	REPLACED	
		14	TAILGATE EMBLEM (AMG) (DISC 10%)	Reviewing	184.5	REPLACED	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		15	TAILGATE CHROME MOULDING (DISC 10%)	Reviewing	124.2	REPLACED	
		16	TAILGATE REFLECTOR LAMP R/L - 2PCS (DISC 10%)	Deny	0	REFIT	
		17	TAILGATE INNER TRIM	Deny	0	USED BACK	
		18	TAILGATE LOCK ASSY	Deny	0	USED BACK	
		19	TAILGATE WEATHERSTRIP (DISC 10%)	Reviewing	186.3	REPLACED	
		20	TAILLAMP R/L - 2PCS (DISC 10%)	Reviewing	522	O/S REPLACED / N/S NOT NECESSARY	
		21	RR BUMPER (DISC 10%)	Reviewing	1015.2	REPLACED	
		22	RR BUMPER TOP SILL PLATE (DISC 10%)	Reviewing	151.2	REPLACED	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		23	RR BUMPER REVERSE SENSOR - 4PCS	Reviewing	338.4	REPLACED - 2PCS	
		24	RR BUMPER LOWER COVER (DISC 10%)	Reviewing	382.5	REPLACED	
		25	RR BUMPER LOWER COVER CHROME (DISC 10%)	Reviewing	706.5	REPLACED	
		26	RR BUMPER CENTER GUIDE (DISC 10%)	Reviewing	43.2	REPLACED	
		27	RR BUMPER SIDE GUIDE R/L - 2PCS (DISC 10%)	Reviewing	45	REPLACED	
		28	RR BUMPER SIDE BRACKET R/L - 2PCS (DISC 10%)	Reviewing	99	REPLACED	
		29	RR BUMPER REINFORCEMENT (DISC 10%)	Reviewing	437.4	REPLACED	
		30	RR END PANEL	Deny	0	REPAIRED	

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		31	RR END PANEL GARNISH (DISC 10%)	Reviewing	127.8	REPLACED	
		32	RR EXHAUST MUFFLER HEAT SHIELD (DISC 10%)	Reviewing	117	REPLACED	
		33	SET FRT NO. PLATE (3D, W/BACKET) (SN)	Reviewing	80	REPLACED	
		34	RR WINDSCREEN SEALANT (SN)	Reviewing	40	REPLACED	
		35	RR END PANEL SEALANT (SN)	Reviewing	40	REPLACED	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$14,970.10

Claim Amount

\$14,970.10

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$30.00	\$3,390.00
Miscellaneous	\$2,231.11	\$11,580.10

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	11950		

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount\$11,950.00

Claim Amount\$11,950.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$11,950.00	\$11,950.00

Submit for Review