

08/11/2013
 Date: 08/11/2013

REF: NIS/INC 18067742 / Klvbn2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / INS / TP RES / OD RES / EVA / INV / MV
 To Insp: _____
 at Work: _____
 of _____
 Insured: SJS 9409C
 Policy No: 5096746614 10-01-2018
 Claims No: MT 0992023-002
 Sum Ins: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SHC 11684 Yr Regn: Jun 2013
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Hyundai i30 c.c. 1921
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 683013 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KM HET 81VMDA 834722
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215 / 60 R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wella
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 25/4/8 D.O.I. 26/4/8
 Survey held at CDE (Loyang)
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 n/s front.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 11684 - NIS/INC 16010526 / HINb2
	SJS 9409C - x
30/4/8	Change LPS \$1900 / 2 hrs. (Red 2159.26, 537)

RECEIVED 02 MAY 2010

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 215- typat

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

99.62

160
35
195

TP
 LS \$1900.2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007742/K1vb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 26-04-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 9409C	Veh. Inspected	SHC 1168H
Policy No.	5096746614	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/04/2018	Inspection Date	26/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Time of Accident	Estimate	Tentative repair cost
1	MT/0989139-002	SMRT TAXIS PTE LTD	SHC 4929J	SLG 4263C	4/4/2018	17:20	\$4,135.10	\$920.28
2	MT/0991109-002	SMRT TAXIS PTE LTD	SHF 155K	SLQ 8843A	18/4/2018	17:20	\$4,997.50	\$430.00
3	MT/0992023-002	COMFORT TRANSPORTATION PTE LTD	SHC 1168H	SJS 9409C	25/4/2018	19:30	\$4,059.26	\$1,900.00

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

+ Change Language

+ Change Password

+ Log Out

My Desktop

Notice of Loss

Policy Query

Policy No.

Date of Accident

25/04/2018 18:35

Vehicle No. (For Motor)

SJS9409C

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5096746614	AVENGERS CAR RENTAL & MOTORING PTE. LTD.	201735090Z	GFT	drive CLASSIC	SJS9409C	SJS9409C	10/01/2018	

Continue

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 26/04/2018 09:47
Date Of Accident 25/04/2018 19:30
Exact Location Of Accident JUNCTION OF BT BATOK CENTRAL AND BT BATOK CENTRAL
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC1168H
Insured/Policyholder
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
Co Reg No 199303821R
Email Address FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-65508768
Vehicle Particulars
Manufacturer HYUNDAI
Model SONATA
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI
Insurance Company
Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number D-18088936MFSH
Cover Note Number
Driver
Name of Driver LAW CHOON SENG
NRIC No S1339453I
Date Of Birth 29/06/1958
Occupation OUTDOOR
Date Of Driving Pass 06/05/1978
Driving Experience 39 YEARS AND 11 MONTHS
Gender MALE
Mobile Number
Fax Number
Contact Number NOEMAIL
Email Address

Address 183 #10-119 BUKIT BATOK WEST AVENUE 8
 Postcode 650183
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJS9409C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage RHT FRT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CC REG NO 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name: 26/4/18

Sketch Plan Pg. 2

Describe Circumstances of the Accident.

On 25 Apr 2018 at about 19:30 hrs, my taxi come out from West Mall taxi stand driving along Bukit Batok Central.

As my taxi approached to the Bukit Batok Cental Link junction, the car SJS9409C traveling in front of my taxi gradually come to stop and pulled to left hand side. Upon seeing this, I keep my taxi to right hand side driving along the lane.

In the process, suddenly the car pulled to right hand side attempting to make a U turn at the junction.

As it happen too sudden, I can't react at all. The car right front portion hit and grazed onto the left front of my taxi.

01 female passenger on board my taxi. No injury at the point of accident.

Declaration

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO REG. NO. 199303821R

Policyholder's Signature/Date &
Time

Driver's Signature (if driver is not the policyholder)/Date
& Time

Witnessed by Reporting
Centre Personnel

26/4/18

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Hotline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

52 Loring Drive Singapore 608905
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 606265
320 Raffles Road Singapore 600132

34 Serangoon Loop Singapore 738156
7 Sungei Kadut Way Singapore 728791
8 Defu Avenue 1 Singapore 539537

Date/Time: 26.04.2018 11:17

Page : 1

JOB CARD Sales Order:

JC NO: 305153618

Team: ARC Repair TP(CLSO)1

CUSTOMER

COMFORT TRANSPORTATION PTE LTD

V/M 7010045

CUSTOMER NO. 383 SIN MING DRIVE

ADDRESS Singapore SINGAPORE 575717

L. (R) 65508755

(O)

(P)

3COUNT CARD NO.

REGN NO:

SHC1168H

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

SONATA

26.04.2018 08:10

DATE/TIME IN

YR OF MANU.

11.06.2013

TARGET DATE

CHASSIS CODE

KMHET41VMDA834722

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 25.04.2018

NATURE: 3P 25.04.18/C

S/NO

LABOR CODE

DESCRIPTION

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Vehicle

Color

Plate No.

SHC1168H

LIMITS

Exit Pass

Vehicle No.:

SHC1168H

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 26.04.2018

Time: 11:38:06

Page: 1/2

REPAIR ESTIMATE

NTUC-45

LKK - Calvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305153618
 REGN NO : SHC1168H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : SONATA
 DATE OF REGN : 11.06.2013
 DATE/TIME IN : 26.04.2018 08:10
 ACCIDENT DATE : 25.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0003-U	FRT BUMPER	1	538.80	20.00	431.04	-
0002 04-01-0101-0029-G	FRT BUMPER UPR BRKT LH	1	20.10	20.00	16.08	X
0003 04-01-0101-0023-G	FRT BUMPER PROTECTOR LH	1	29.20	20.00	23.36	X
0004 04-01-0101-0074-G	FRT BUMPER RETAINER LH	1	9.20	20.00	7.36	X
0005 04-01-0101-0027-U	HEADLAMP LH	1	797.90	20.00	638.32	X
0006 04-01-0101-0016-A	FRT FENDER LH	1	593.00	20.00	474.40	-
0007 03-01-0101-0005-U	FRT FENDER SHIELD LH	1	86.00	20.00	68.80	X
0008 03-01-0101-0002-U	FRT WHEEL CAP LH	1	145.00	20.00	116.00	-
0009 04-01-0101-0087-G	WING MIRROR LH	1 L	545.50	20.00	436.40	X
0010 28-01-0199-0016-A	FRT DOOR 'COMFORT' LH	1	75.00	10.00	67.50	-

SUB-TOTAL : 2,279.26

JOB NATURE

0000 20-05 Frt Fender Adv.Sticker LH

100.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 26.04.2018

Time: 11:38:06

Page: 2p

TS

NTUC-4S
LKK - Calvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305153618
 REGN NO : SHC1168H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : SONATA
 DATE OF REGN : 11.06.2013
 DATE/TIME IN : 26.04.2018 08:10
 ACCIDENT DATE : 25.04.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT	PRICE	DISC%	AMOUNT
0001 20-05	Frt Door Adv.Sticker LH	100.00					me
0002 L	PANEL BEATING	560.00			400		
0003 23-502	SPRAYPAINT ON AFFECTED AREA	800.00			650		
0004 17-01	CHECK ALL LIGHTING	40.00			X 17		
0005 20-00	TUFF COAT ON AFFECTED PARTS.	60.00			20		
0006 L	WHEEL ALIGNMENT	120.00			X 17		
SUB-TOTAL :							1,780.00

TOTAL : 4,059.26

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Kalvin LKK
 26/4/18 1345hrs.
 3 Reps.
 4/s
 After Repair photo.

LKK Auto Consultant will notify the Repairer of the following:

- To resurvey before the spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party insurance on "Without Prejudice" basis
- No illegal modification allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

Fax :

Date of Accident : 25-Apr-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SJS9409C
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges _____
- Total for Part-By-Part Repair Cost** _____
- (c.) Lumpsum Repair (if applicable)
- Total for Lumpsum repair cost after Less: 20% \$1,900.00
- Final Lumpsum Repair cost** \$1,900.00
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount


We confirm the estimates and finalized amount

Signature _____
Name KALVIN
Date 30/4/8

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC18007742/K1vbn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 04-05-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJS 9409C	Veh. Inspected	SHC 1168H
Policy No.	5096746614	Coverage (\$)	0.00
Claim No.	MT/0992023-002	Excess (\$)	0.00
Assign From		Assign Date	26/04/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KMHET41VMDA834722	Colour	BLUE
Odometer	683013	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	WEST LAKE	7 mm
L/H Front Tyre	215/60 R16	WEST LAKE	7 mm
R/H Rear Tyre	215/60 R16	WEST LAKE	7 mm
L/H Rear Tyre	215/60 R16	WEST LAKE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/04/2018	Inspection Date	26/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1168H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER	DEFORMED	538.80	538.80
1	FRT BUMPER UPR BRKT LH	SERVICEABLE	20.10	-
1	FRT BUMPER PROTECTOR LH	TO REPAIR	29.20	-
1	FRT BUMPER RETAINER LH	SERVICEABLE	9.20	-
1	HEADLAMP LH	SERVICEABLE	797.90	-
1	FRT FENDER LH	DENTED	593.00	593.00
1	FRT FENDER SHIELD LH	SERVICEABLE	86.00	-
1	FRT WHEEL CAP LH	GRAZED	145.00	145.00
1	WING MIRROR LH	TO REPAIR	545.50	-
	LESS 20% DISCOUNT		-552.94	-255.36
			2,211.76	1,021.44
NETT ITEMS				
1	FRT DOOR 'COMFORT' LH (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
SPECIAL NETT ITEMS				
1	FRT FENDER ADV STICKER LH (SN)	NECESSARY	100.00	100.00
1	FRT DOOR ADV STICKER LH (SN)	NECESSARY	100.00	100.00
			200.00	200.00
LABOUR				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		720.00	400.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		860.00	670.00
	-		-	-
	-		-	-
	-		-	-
			1,580.00	1,070.00
GRAND TOTAL			4,059.26	2,358.94

Report Ref No. NS/INC18007742/K1vbn2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,900.00
--	--	--	----------

Report Ref No. NS/INC18007742/K1vbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator



K.K. LAU CPT (RET)

BEng (Hons), B. Bus, MBA, PEng, PE,
Minst AEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.