

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD, #17-00
TOWER BLOCK, MND COMPLEX 069110

Attention : Motor Claim Department

Estimate : ES000091

Date : 25/04/2018
Vehicle Num. : SLK 3504T (LCR)
Make/Model : TOYOTA PRIUS HYBRID
Chassis/Eng# :
Accident Date : 24/04/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER		500.00
3.	1	REAR LOWER BUMPER		560.00
		REAR BUMPER REINFORCEMENT		340.00
		List TotalS\$:		1,400.00
		25.00% Discount S\$:		350.00
				1,050.00

1.	1	SPECIAL NETT ITEMS :		
2.	1	REVERSE SENSOR		280.00
		REAR BUMPER CLIP		50.00
		Special Nett Total S\$:		330.00

		LABOUR :		
		LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS, INCLUDING PANEL BEAT & REPLACE ABOVE PARTS.	250	400.00
		PUTTY AND SPRAY PAINT REAR & ALL AFFECTED AREAS.	200	400.00
		Labour Total S\$:		800.00

E. & O.E.

Total S\$: 2,180.00

for WORLD AUTO PTE LTD

Sebastian,
26/4/18.
- Part by part repair.
- Question Mark Item
Photo.
- Photo Before Paint
96036121
sebastianyeang@lkkauto.com

2 days.
LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• Structural modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer