

INSURANCE OWNER:

KC

CC 4 / ASM1800

7745, Aug 3rd

LKK:
IDAC:

41946

ASSIGNMENT

Surveyor:

DOI:

3/5/18

Date / Time:

26/4/2018

Registered in Merimen:

Pre-assign / CCU / FTE

GBA 6053D



Insured Vehicle No.:

Name of Insured:

KITH CAFE PLC

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

25/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Jim Brown 40yrs

Driver Tel No.:

81385599

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

58moo771 Gx

G8265839

Daihatsu Hijet

Farrer Rd

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLE 4286Y

GBA 6053D

SPV833B



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

07



INSRS:

WSP: Premium

Tel:

Liability:

RMKS:

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

6/6/18

SPV833B - 016/00118003903/TUJ63, 009 23/2/18

GBA 6053D - X

- video uploaded

to 2A final

and will mandate as parts was expensive

STAGE	DATE / PIC	
Non-Reporting ltr (1st):		
Non-Reporting ltr (2nd):		
Non-Reporting ltr (Final):		
Notification ltr (if non-pickup):		
Call OI:	18/6/19	
After call ltr to OI:	uun	
Documentation Check List: Handler Typist		
Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☐	☐
Towing Invoice	☐	☐
LTA / GIA :	☒	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☒	☐
LOD	☒	☐
Payment Breakdown Form:	☐	☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE

Date/Time:

2/5

Sent By:

Jim

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

24/6/19

Confirm with: Nona

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.: 28

Repair Cost:

SS

25503.56

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

300.00 (\$100 x 3 days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

25805.56

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

25805.56

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

If NO or B 28, Ass. Lia: CID involved in 4c.c 020 is the 2nd len.

24/6/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

REF: ASM (AXA)

ASSIGNMENT

From: Date: 03052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFV 833B

at Workshop m/s

Premium
55 Ubi Rd 1

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 480K.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 2.6.2% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFV833B Yr Regn: 2017 / Oct

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi RS6 Avant G.C. 3993

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 10060 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WUA2224G0HN 900326.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285/30 R21.

R: 285/30 R21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A.

D.O.I. 03/05/18

Survey held at

Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA

P/P # 23835-10 (Reel # 9629.94/297)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$)

) S + RS. \$

☐ Interview (\$)

) Photos

☐ Tech. Invs (\$)

) Others

☐ Weekend (\$)

)

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18007745/Aua3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-04-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 6053D	Veh. Inspected	SFV 833B	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00F7I	Excess (\$)	0.00	
Assign From		Assign Date	26/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/04/2018	Inspection Date	03/05/2018	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1, SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0494/2018/JT
Date : 26-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no: GBA 6053 D

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Hi Adrian

3 days - ok - jb - 11 Jul 18

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Pang Hsiang -Aun
Address : 20 Trevoise Crescent
Singapore 298034
Telephone : HP +65 9362 7770
Type of Claim : Third Party Claims
Policy No. : SD17V11508/VPC2/R00
Vehicle No : **SFV 833 B**
Model Code : Audi RS6 Avant 4.0 TFSI qu
Model / Year : Oct-17
Engine No : CWU 009570
Chassis No : WUAZZZ4G0HN900326
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Apr-18
Place of Accident : Farrer Road (Outside Serene Centre)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFV 833 B.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 6,547.00	
2	REAR BUMPER SPOILER	\$ 21,708.00	\$ 21,708.00
3	REAR REINFORCEMENT BEAM FOAM	\$ 105.00	
4	REAR REINFORCEMENT BEAM	\$ 1,315.00	
5	REINFORCEMENT BEAM BOLTS	6 \$ 43.00	
6	REINFORCEMENT BEAM SEAL - LHS/RHS	2 \$ 24.00	
7	REAR PARKING AID SENSOR	2 \$ 421.00	
9	SUNDRIES	\$ 200.00	\$ 25.10
TOTAL SPARE PARTS CHARGES		\$ 30,363.00	\$ 21,733.10
TOTAL LABOUR CHARGES		\$ 3,102.00	\$ 2,302.00
GRAND TOTAL		\$ 33,465.00	\$ 24,035.10

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFV 833 B.

S/n	Nature of Jobs	Estimated Charges			
1	To remove and transfer rear parking aid & rear lid kick-open sensor. Check function.	S/N	\$	360.00	\$ 360.00
2	To dismantle and renew rear bumper assy. Re-organize rear crash management components. Reinstall all parts removed.		\$	1,200.00	\$ 700.00 600
3	To respray rear bumper.		\$	1,000.00	\$ 700.00 600
4	To reapply rear bumper protection sticker. (by owner)		TBC		
5	To reinstall rear bumper side spoiler	S/N	\$	350.00	\$ 350.00
6	To carry out diagnostic check.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$	<u>3,102.00</u>	\$ <u>2,302.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0494/2018/JT
Date : 26-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no: GBA 6053 D

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Pang Hsiang -Aun
Address : 20 Trevoise Crescent

Singapore 298034
Telephone : HP +65 9362 7770
Type of Claim : Third Party Claims
Policy No. : SD17V11508/VPC2/R00
Vehicle No : **SFV 833 B**
Model Code : Audi RS6 Avant 4.0 TFSI qu
Model / Year : Oct-17
Engine No : CWU 009570
Chassis No : WUAZZZ4G0HN900326
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Apr-18
Place of Accident : Farrer Road (Outside Serene Centre)

Premium Automobiles


55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFV 833 B.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid & rear lid kick-open sensor. Check function.	S/N \$ 360.00 ✓
2	To dismantle and renew rear bumper assy. Reorganize rear crash management components. Reinstall all parts removed.	\$ 1,200.00 600
3	To respray rear bumper.	\$ 1,000.00 600
4	To reapply rear bumper protection sticker. (by owner)	TBC nn
5	To reinstall rear bumper side spoiler	S/N \$ 350.00 ✓
6	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 3,102.00 2102



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFV 833 B.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Repair</i>	\$ 6,547.00	<i>x.</i>
2	REAR BUMPER SPOILER <i>cracked.</i>	\$ 21,708.00	<i>pricing ??</i>
3	REAR REINFORCEMENT BEAM FOAM	\$ 105.00	<i>x</i>
4	REAR REINFORCEMENT BEAM	\$ 1,315.00	<i>x</i>
5	REINFORCEMENT BEAM BOLTS	6 \$ 43.00	<i>x</i>
6	REINFORCEMENT BEAM SEAL - LHS/RHS	2 \$ 24.00	<i>x</i>
7	REAR PARKING AID SENSOR	2 \$ 421.00	<i>x</i>
8	SUNDRIES	\$ 200.00	<i>25.10</i>
TOTAL SPARE PARTS CHARGES		: \$ 30,363.00	
TOTAL LABOUR CHARGES		: \$ 3,102.00	
GRAND TOTAL		: \$ 33,465.00	<i>21733.10</i>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 03/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



Audi

ETKA - Order Form

Order Form:

SFV833B

18:57

25.04.2018

SFV833B

Editor:

Item Description	Remark	Model	Qty	SGD	D
4G9 807 067 AC GRU VIN: WUAZZZ4G0HN900326 Bumper cover D - MJ 2015>> primed		PR-7X5	1	6547,00	
4G9 807 521 E VIN: WUAZZZ4G0HN900326 Spoiler	Carbon	PR-5L4, 5L6	1	21708,00	
4G9 807 695 VIN: WUAZZZ4G0HN900326 Shock absorber			1	105,00	
4G8 807 309 C VIN: WUAZZZ4G0HN900326 Bumper carrier		PR-1D0, 1D8	1	1315,00	
N 019 530 8 VIN: WUAZZZ4G0HN900326 Hex collared bolt	M8X25	PR-1D0, 1D8	6	42,60	
4G0 807 669 VIN: WUAZZZ4G0HN900326 Seal Bumper carrier	left	PR-1D0, 1D8	1	11,60	
4G0 807 670 VIN: WUAZZZ4G0HN900326 Seal Bumper carrier	right	PR-1D0, 1D8	1	11,60	
1S0 919 275 C GRU VIN: WUAZZZ4G0HN900326 Sensor primed			2	421,00	
1T0 919 133 C 9B9 VIN: WUAZZZ4G0HN900326 seal ring Satin black	inner/outer		4	4,40	
				+ 7.0% VAT	
				30166,20	
				2111,63	
				32277,83	SGD
				=====	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVENUE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 07/05/2018

Survey Details:

Date of loss	25-Apr-18
Date of appointment	26-Apr-18
Date of survey	3-May-18
Location of survey	Premium Automobiles Pte Ltd

Vehicle Details:

Claim Type:	Third party
Vehicle number	SFV 833B
Make and Model	NISSAN SYLPHY 1.45 4AT
Date of registration	06-Oct-08
Excess	
Market Value	\$ 480,000.00
Part Rebate	\$ 166,024.00
Nett Loss	\$ 313,976.00

Repair details:

Initial Estimate	\$ 33,465.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 21,708.00
Check items (estimate)	\$ -
Labour	\$ 2,102.00
Total	\$ 23,810.00
Lump Sum(if applicable)	TBA

Number of days for repair	<u>3 days</u>
---------------------------	---------------



Service Request Details

Claim

S8M00F7I

Reference

None

Loss Date

April 25, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Request Date

April 26, 2018

Due Date

May 4, 2018

26/04/2018 @ 1028am
Veh not in

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SFV833B

Make

TPVD AUDI

Service Address

...

Primary Contact/Insured

KITH CAFE PTE LTD

23 KAMPONG BAHRU ROAD, #03-02 DIMENSIONS BUILDING, 169349, Singapore

85695548

wendy@kith.com.sg

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

NON-REPORTING

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



<MANDATE IA> - S8M00F7I [ACCIDENT INVOLVING GBA 6053D(OI) & SFV 833B(TP) ON 25/04/2018]

Type

🔗 Question

Message

- Liability: 100%. 4 vehicle chain collision, OI was the 2nd vehicle. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$26,011.01(if claim LOU) -\$26,367.01(if claim LOR). Mandate IA and survey photo had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Jia Le - 30 April 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/4/2019

Survey Details:

Date of loss	25-Apr-18
Date of appointment	26-Apr-18
Date of survey	3-May-18
Location of survey	Premium Automobiles Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SFV 833B
Make and Model	AUDI RS6 AVANT 4.0 TFSI QU (PI) S/R - 3993cc
Date of registration	3-Oct-17
Parf Rebate	
Market Value	\$ 480,000.00
Parf Rebate	\$ 166,024.00
Nett Loss	\$ 313,976.00

Repair details:

Initial Estimate	\$ 33,465.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 21,733.10
Check items (estimate)	\$ -
Labour	\$ 2,102.00
Total	\$ 23,835.10
Lump Sum(if applicable)	NIL

Number of days for repair	3
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 25,503.56	\$ 25,503.56
Loss of use (5days x \$100)	\$ 500.00	NIL
Loss of rental (5days x \$160)(w/GST)	NIL	\$ 856.00
Loss of income	NIL	NIL
LTA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
Proposed Total	\$ 26,011.01	\$ 26,367.01

15/4/19



Re:<MANDATE IA> - S8M00F7I [ACCIDENT INVOLVING GBA 6053D(OI) & SFV 833B(TP) ON 25/04/2018]

Type

 Question

Message

WE WILL SEEK 2ND ADVICE ON COR, MEANWHILE PLS REVIEW ON THE PARTS PUT UP.

Reply



Re:<MANDATE IA> - S8M00F7I [ACCIDENT INVOLVING GBA 6053D(OI) & SFV 833B(TP) ON 25/04/2018]

Type

🔗 Question

Message

REAR BUMPER SPOILER???(TYPO ERROR?) @ \$21,708.00??? PLS SHOW DOCUMENTATION PROOF.

Carhu 15 Apr -

Reply

Quotation generated by

→ Document put forward by Pura Automobile
→



RE: Re:<MANDATE IA> - S8M00F7I [ACCIDENT INVOLVING GBA 6053D(OI) & SFV 833B(TP) ON 25/04/2018]

Type

 Question

Message

Hi KC, we have uploaded a copy of documentation submitted by third party repairer, Premium Automobiles Pte Ltd in SC for your review. Kindly let us have your instruction after reviewing the case. Thank you. Hsiao Tong - 22 May 2019

Reply



Re:RE: Re:<MANDATE IA> - S8M00F7I [ACCIDENT INVOLVING GBA 6053D(OI) & SFV 833B(TP) ON 25/04/2018]

Type

🔍 Question

Message

PLS PROCEED QUANTUM AS PROPOSED.

Reply

QUOTATION

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 16:37

Mr H A Pang
20 Trevasa Crescent

Singapore 290034
290034

Invoice: 0

Date : 22/06/2018

Order :

Term : 00

Account: C0001 (T 8149)
CASH SALES - SERVICE SALES

Regn No.: SFV0033B (V 31059)

Regn Date: 03/10/2017

Mileage: 0

WIP No.: 63540

Model: RS6 AVANT 4.0 TFSI qu (PI) 46D

Chassis: WUAZZZ460HN900326

Engine: CHU 009570

Dept: U

USB No.:

You have been assisted by :- UB-Jiayee

(33)

X	A4G9945254A	TRIM(V)	1.00	25.10	25.10
X	A4G9807521E	SPOILER	1.00	21708.00	21708.00

Parts	21,733.10		
Labour	0.00		21733.10
Sublet	0.00		
Menus	0.00		1521.32
Lubricant	0.00		23254.42

Received by

For & on behalf of
Premium Automobiles Pte Ltd



ACTIVE

PI BATCH
WU1AZZ1G2H000326

ACC. RS6

TOOLS 2017 10 8

PI24

SUPPORTWEB

INFOLINE

CHEMICAL MATERIALS

STANDARD HARDWARE

NEW AND DROPPED PARTS

O OFF

STOCK

ORDER FORM

SLUGBATT

DEFERRED FORM

ETKA

Parts Information

1 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

QTY : MODEL

ORDER FORM SLUGBATT

LOCAL MARKET TAN-VW MEXICO SOUTH AFRICA

PART NUMBER 409 807 521 E

DESCRIPTION Speller

REMARK Carbon

QTY 1

PRICE D 22816,00

MODEL PRSL45L6

+7.0% VAT 24413,12

DMS:00 0

Location: ITN-A

Additional Info

Material

Collect

Suppression

Part Number

Quantity

ASSUME

ORDER FORMS

BACK

PRSL45L6

1

1

6

2

8

1

PRSL45L6



Re:RE: Re:<MANDATE IA> - S8M00F7I [ACCIDENT INVOLVING GBA 6053D(OI) & SFV 833B(TP) ON 25/04/2018]

Type

Question

Message

PLS PROCEED QUANTUM AS PROPOSED.

Reply

Premium Automobiles

Adrian

Vivian

AXA Insurance Pte Ltd
No 8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: Motor Claims Dept/ Thin Thin LKK
Yr Ref: CC4/ASM18007745/ua3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/0494/2019/NK

13 June 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SFV 0833 B, Audi RS6 Avant 4.0 TFSI Qu.

With reference to the above-mentioned vehicle, no. **SFV 0833 B**, claimant, **Mr.Pang Hsiang-Aun**, please find the related document as per attached.

1. A copy of the Original invoice no. 85013882 – S\$25,503.56
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. Loss of use – S\$300.00 (S\$100.00 x 3 days)
5. A copy of GIA Search fee – S\$2.00

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls
AXA – SFV 0833 B

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBA 6053D (Insd veh)	Model:	AUDI RS6 AVANT
	SFV 833B (TP veh)		
Date of Accident:	25/04/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	35,807.55
Final Repair Cost	:	\$	25,503.56
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	25,805.56

Is Third Party Workshop GIA Registered?		☒ YES	☐ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____(%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____100_____ (%)		Assessed Liability (*): _____0_____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	PREMIUM AUTOMOBILES PTE LTD	:	\$ 25,805.56

NUR SHAQILAH BTE ABDOL
WAHAB

27/06/2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18007745/Awa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN			Date : 27-06-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 6053D	Veh. Inspected	SFV 833B	
Policy No.	GA265839	Coverage (\$)	0.00	
Claim No.	S8M00F7I	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	26/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	AUDI RS6 AVANT	c.c	3993	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WUAZZZ4G0HN900326	Colour	BLUE	
Odometer	10060	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	285/30 R21	DUNLOP	6 mm	
L/H Front Tyre	285/30 R21	DUNLOP	6 mm	
R/H Rear Tyre	285/30 R21	DUNLOP	6 mm	
L/H Rear Tyre	285/30 R21	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2018	Inspection Date	03/05/2018	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 833B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	6,547.00	-
1	REAR BUMPER SPOILER (SN) (CONSISTENT)	CRACKED	21,708.00	21,708.00
1	REAR REINFORCEMENT BEAM FOAM (SN) (CONSISTENT)	NOT NECESSARY	105.00	-
1	REAR REINFORCEMENT BEAM (SN) (CONSISTENT)	NOT NECESSARY	1,315.00	-
6	REINFORCEMENT BEAM BOLTS (SN) (CONSISTENT)	NOT NECESSARY	43.00	-
2	REINFORCEMENT BEAM SEAL - LHS/RHS (SN) (CONSISTENT)	NOT NECESSARY	24.00	-
2	REAR PARKING AID SENSOR (SN) (CONSISTENT)	NOT NECESSARY	421.00	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	200.00	25.10
			30,363.00	21,733.10
LABOUR				
TO REMOVE AND TRANSFER REAR PARKING AID & REAR LID KICK-OPEN SENSOR. CHECK FUNCTION.			360.00	360.00
TO DISMANTLE AND RENEW REAR BUMPER ASSY. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER.			1,200.00	600.00
TO RESPRAY REAR BUMPER.			1,000.00	600.00
TO REAPPLY REAR BUMPER PROTECTION STICKER. (NPA)			-	-
TO REINSTALL REAR BUMPER SIDE SPOILER.			350.00	350.00
TO CARRY OUT DIAGNOSTIC CHECK.			192.00	192.00
			3,102.00	2,102.00
GRAND TOTAL			33,465.00	23,835.10
RECOMMENDED COST OF REPAIRS				23,835.10

Report Ref No. CC4/ASM18007745/Awa3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.