

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 097/IC/TCAC/CCR/2018
DATE : 25-APR-2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER
S(038986)
TEL : 6820 8888
FAX :
ATTN : CLAIM MANAGER

OWNER'S NAME : MR BUSTAMAM KOSHNI
ADDRESS : BLK 2297B CHOA CHU KANG AVE 2
#08-74
S(682297)
TELEPHONE NO : 92703366

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100452656-02
VEHICLE NO : SCY1714A
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2229016A
CHASSIS NO : SJNFEAJ11U1569769
MILEAGE : 51160 KM
DATE IN : 25/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 28/03/2018

Tanjah 97495749
- WP'
4/5/18 @ 1615
Resurvey before paint
sur@lkkayto.com
3 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCY1714A

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
2 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
3 ZZ/001	RENEW REAR BUMPER, UPPER PANEL, ENERGY ABSORBER ETC PANELS & REPAIR	760.00	190
4 ZZ/002	RESPRAY REAR BUMPER IN 2 COLORS, UPPER PANEL	800.00	380
5 ZZ/003	QC, RETUNE & CONSULT CHECK		300
6 ZZ/004	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES		1735.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCY1714A

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	RIGHT BUMPER BRACKET	85220-4EA0A	35.90 X	
2	LEFT BUMPER BRACKET	85221-4EA0A	35.90 X	
3	CLIP (\$1.20 EA X 4)	01553-05933	4.80 <i>new</i>	
4	RIGHT BUMPER RETAINER	79184-4EA0A	23.80 X	
5	LEFT BUMPER RETAINER	79185-4EA0A	23.80 X	
6	ENERGY ABSORBER	85090-4EA0B	126.40 ?	
7	TOW HOOK COVER	85071-4EA0A	16.80 X	
8	REAR BUMPER	85022-4EA0H	717.00 <i>de</i>	
9	REAR UPPER PANEL	G9110-4EAMA	482.60 X	
SUB TOTAL			1467.00	0.00 0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			293.40	0.00 0.00
GRAND TOTAL			1173.60	0.00 0.00
OVERALL TOTAL			1173.60	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SCY1714A

TOTAL LABOUR CHARGES	1735.00
TOTAL SPARE PARTS CHARGES	1173.60

GRAND TOTAL	2908.60 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.