

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLK MND BUILDING SINGAPORE 069110	Document No.	: SQT18001721	Page	1
Registration No	: SJC6513M	Date	: 26. Apr 2018	Customer No.	: WZE011
Chassis No	: JHMGK5850HX200597	Svc Advisor	: NG SIN HAI	Engine No	: L15B31190351
Model	: JAZZ 1.5VTIR CVT 17YM	Date Time	: 26. Apr 2018 11:13:50 AM	Surveyor Name	:
Owner's Name	: NG TZE HWEE	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 26/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:NG TZE HWEE OWNER INSURER:LIBERTY ACC DATE:26/04/2018 SURVEYED BY: DATE: REF NO: TP INSURER:EQ INSURANCE COMPANY LTD TP VEH:CB6541U						
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	100.00		100.00	7.00	107.00
BOJSE	SEALANT FOR REAR END PANEL	1	100.00		100.00	7.00	107.00
BOJSE	SEALANT FOR LHR FENDER	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BG51D	REMOVE & INSTALL RR. L QTR GLASS.(N)	1	320.00		320.00	22.40	342.40
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL.	1	6800.00		6800.00	476.00	7276.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00		4000.00	280.00	4280.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00		450.00	31.50	481.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	380.00		380.00	26.60	406.60
BOMISC1	REMOVE AND RENEW DVR CAMERA	1	560.00		560.00	39.20	599.20

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLK MND BUILDING SINGAPORE 069110	Document No.	: SQT18001721	Page	2
Registration No	: SJC6513M	Date	: 26. Apr 2018	Customer No.	: WZE011
Chassis No	: JHMGK5850HX200597	Svc Advisor	: NG SIN HAI	Engine No	: L15B31190351
Model	: JAZZ 1.5VTIR CVT 17YM	Date Time	: 26. Apr 2018 11:13:50 AM	Surveyor Name	:
Owner's Name	: NG TZE HWEE	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 26/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOMISC1	REMOVE UPHOLSTERY AND VACUUM SHATTERED GLASS	1	560.00		560.00	39.20	599.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00		450.00	31.50	481.50
Sum Labor					16580.00	1,160.60	17,740.60
RS-4P	BUMPER SENSOR 4PCS	1	180.00		180.00	12.60	192.60
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
33500-T5A-J02	TAILLIGHT ASSYR.	1	217.40	25	163.05	11.41	174.46
33550-T5A-J02	TAILLIGHT ASSYL.	1	217.40	25	163.05	11.41	174.46
34150-T5A-J01	LIGHT ASSYR.LID	1	79.30	25	59.47	4.16	63.63
34155-T5A-J01	LIGHT ASSYL.LID	1	79.30	25	59.47	4.16	63.63
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30	25	69.22	4.85	74.07
74800-T5A-J02	LOCK ASSYTAILGATE	1	76.60	25	57.45	4.02	61.47
74910-T5C-023ZF	SPOILER ASSYTAILGATE	1	311.90	25	233.92	16.37	250.29
75722-T5L-T01	EMBLEMRR.	1	10.50	25	7.87	0.55	8.42
04715-T5B-000ZZ	FACERR.BUMPER	1	492.60	25	369.45	25.86	395.31
71502-T5A-000	GARNISHR.RR.BUMPER	1	14.00	25	10.50	0.74	11.24
71507-T5A-000	GARNISHL.RR.BUMPER	1	14.00	25	10.50	0.74	11.24
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	5	2.00	25	7.50	0.53	8.03
66100-TAR-T10ZZ	PANEL COMPRR.	1	314.00	25	235.50	16.49	251.99
04655-TAS-300ZZ	PANEL SET,RR.FLOOR	1	669.90	25	502.42	35.17	537.59
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
84521-T5A-901ZA	LID ASSYSPARE TIRE	1	186.00	25	139.50	9.77	149.27
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
72841-SH3-315	OILSHEET	3	39.90	25	89.77	6.28	96.05

Printed on 26/4/2018 11:58:34 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLK MND BUILDING SINGAPORE 069110	Document No.	: SQT18001721	Page	3
Registration No	: SJC6513M	Date	: 26. Apr 2018	Customer No.	: WZE011
Chassis No	: JHMGK5850HX200597	Svc Advisor	: NG SIN HAI	Engine No	: L15B31190351
Model	: JAZZ 1.5VTIR CVT 17YM	Date Time	: 26. Apr 2018 11:13:50 AM	Surveyor Name	:
Owner's Name	: NG TZE HWEE	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 26/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	3.05	46.62
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	3.11	47.58
04646-TAS-310ZZ	PANEL SET,L.RR.OUTSIDE	1	559.30	25	419.47	29.36	448.83
73211-T5A-J01	GLASS SETRR.WINDSHIELD	1	625.60	25	469.20	32.84	502.04
73561-T5A-003	GLASSL.QUARTER	1	150.60	25	112.95	7.91	120.86
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.50	25	14.25	1.00	15.25
91501-T5A-003	CLIPQUARTER WINDSHIELD A	1	3.60	25	2.70	0.19	2.89
91502-T5A-003	CLIPQUARTER WINDSHIELD B	1	3.60	25	2.70	0.19	2.89
91503-T5A-003	CLIPQUARTER WINDSHIELD C	1	2.40	25	1.80	0.13	1.93
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
NMDVR-DR750S-2CH	DVR BLACKVUE 2 CHANNEL	1	568.00		568.00	39.76	607.76
Sum Item					4886.88	342.09	5,228.97

BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00		300.00	21.00	321.00
BO-R-COOL-RRQ	SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS.	1	250.00		250.00	17.50	267.50
Sum Ext. Service					550.00	38.50	588.50

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 22,016.88 1,541.19 23,558.07
Total (Inclusive of GST) **23,558.07**

Printed on 26/4/2018 11:58:34 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)