







## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18007750/Kua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-04-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJV 1712M	Veh. Inspected	SJP 5765R
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00DK8	Excess (\$)	0.00
Assign From		Assign Date	26/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/04/2018	Inspection Date	30/04/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Text size + -

**Transfer Of Vehicle Ownership (Acknowledgement)****Vehicle Details**

Vehicle No.:	SJP5765R		
Vehicle Type:	P10 - Passenger Motor Car	Vehicle Scheme:	Normal
Vehicle Make:	MERCEDES BENZ	Vehicle Model:	C180K
Chassis No.:	WDD2040462A243405	Engine No.:	27195231167297
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Petrol	Passenger Capacity:	4
Engine Capacity:	1796 cc	Power Rating:	-
Unladen Weight:	1485 kg	Maximum Laden Weight:	1970 kg
Primary Colour:	Black	Secondary Colour:	-
IU Label No.:	1123599201	Maximum Power Output:	115.0 kW (154 bhp)
First Registration Date:	30 Mar 2009	Original Registration Date:	30 Mar 2009
Manufacturing Year:	2008	Open Market Value:	\$37,090.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$18,545.00
Temporary Start Date:	04 Sep 2017	Temporary End Date:	03 Dec 2017
No. of Transfer:	1	Actual ARF Paid:	\$37,090.00

**Owner Particulars**

Owner Name:	YEW HUP HUAT TRADING
Owner ID Type:	Business
Owner ID:	36268200C
Registered Address Type:	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:	1210
Registered Street Name:	UPPER THOMSON ROAD
Registered Unit No.:	-
Registered Building Name:	-
Registered Postal Code:	787126
COE No./Expiry Date:	2009030107000853E / 29 Mar 2019
COE Bid Category:	E - Open Category
QP Paid:	\$5,889.00

**Transaction Details**

Business Transaction Ref. No.:	20170904155617377204
Business Transaction Date:	04 Sep 2017
Business Transaction Time:	15:56:17

**Message**

Vehicle has been successfully transferred to YEW HUP HUAT TRADING (36268200C).

Please note that \$10.00 will be deducted from your GIRO account.

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJV1712M (AXA)

Accident Date : 09-04-2018

Date : 26-04-2018

Our Ref : SJP5765R /CHAN 218076

YEW HUP HUAT TRADING  
C/O ALAN'S UNITED AUTO PTE LTD  
BLK 7 SIN MING IND.EST. SECTOR C  
#01-76  
SINGAPORE 575642

*Not Notified  
Resurvey After Paint  
\$1000 3days*

## ESTIMATE COST OF REPAIR FOR MERCEDES-BENZ C180 1.8 (A) SJP5765R

TO PANEL BEATING REAR LH DOOR, REAR LH FENDER AND REPAIR REAR BUMPER

\$450.00 *400*

TO PUTTY AND SPRAY ABOVE REPAIR PARTS

\$800.00 *600*  
\$1,250.00

Singapore Dollars One Thousand Two Hundred Fifty Only

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 3/5/2018

### Survey Details:

Date of loss	9-Apr-18
Date of appointment	26-Apr-18
Date of survey	30-Apr-18
Location of survey	Alan's United Auto Pte Ltd

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SJP5765R
Make and Model	MERCEDES-BENZ C180 K - 1796cc
Date of registration	1-Mar-09
Excess	
Market Value	\$ 68,000.00
Parf Rebate	\$ -
Nett Loss	\$ -

### Repair details:

Initial Estimate	\$ 1,250.00
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ -
Check items (estimate)	\$ -
Labour	\$ 1,000.00
<b>Total</b>	<b>\$ 1,000.00</b>
Lump Sum(if applicable)	TBA

Number of days for repair	<u>3 days</u>
---------------------------	---------------

## ◀ Service Request Details

Claim

S8M00DK8

Reference

None 

Loss Date

April 9, 2018

Request Date

April 26, 2018

Due Date

May 4, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*27/04/2018 @ 1007am  
Kenny veh not in.*

### Actions

---

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

---

Incident Vehicle Registration #

SJP5765R

Make

TPVD MERCEDES-BENZ

Service Address

---

...

Primary Contact/Insured

---

PJJ TRADING  
81 ROSEWOOD DRIVE, #03-55 PARC ROSEWOOD, 737788, Singapore  
86994377  
peter.cktan@yahoo.com

Claim Handler

---

CHAN Kian Chuan  
6568804269  
kianchuan.chan@axa.com.sg

Additional Instructions

Messages   Invoices   History   Documents   Assessment   Metrics   Notes

---

New Message



SERVICE REQUESTS

MESSAGES

CLAIMS

## Service Request Details

Claim:	S8M00DK8
Reference	CC4/ASM18007750/Kua3
Loss Date	April 9, 2018
Request Date	April 26, 2018
Due Date	April 27, 2019
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

### Actions

Next Step **Finish the work**

Complete Work

More ▾

### Vehicle Information

Incident	SJP5765R
Vehicle	
Registration #	
Make	TPVD MERCEDES-BENZ
Model	C180-1.8(A)

### Service Address

...

### Primary Contact/Insured

PJJ TRADING  
 81 ROSEWOOD DRIVE, #03-55 PARC  
 ROSEWOOD, 737788, Singapore  
 86994377  
 peter.cktan@yahoo.com

### Claim Handler

CHAN Kian Chuan  
 6568804269  
 kianchuan.chan@axa.com.sg

### Additional Instructions

Messages   Invoices   History   Documents   Assessment   Metrics   Notes

[New Message](#)

TYPE	SENT	FROM	SUBJECT	BODY	
	6/20/18 1:17 PM	CHAN Kian Chuan	PROCEED DS	LIAB CLEAR FOR DS, QUANTUM AS PROPOSED SETTLEMENT ...	
	6/19/18 4:15 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Re:VNI	Dear KC, We refer to your message. Please be infor...	
	6/1/18 10:50 AM	LKK AUTO CONSULTANTS PTE LTD (TP)	RE: Re:VNI	Dear Sir / Madam, We refer to your message dated ...	



SERVICE REQUESTS

MESSAGES

CLAIMS



## PROCEED DS

Type

Question

Message

LIAB CLEAR FOR DS, QUANTUM AS PROPOSED SETTLEMENT NOT EXCEEDING \$1,757.49

Reply

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SJV 1712M (Insd veh)	Model:	MERCEDES BENZ C180 KOMP (A)
	SJP 5765R (TP veh)		
Date of Accident:	09/04/2018		

Global Sum Settlement	:	[ ] Yes	[ X ] No	
Repair Estimate	:		<input checked="" type="checkbox"/>	\$ 1,337.50
Final Repair Cost	:		<input checked="" type="checkbox"/>	\$ 1,070.00
Loss of Use	:		<input checked="" type="checkbox"/>	\$ 240.00    3 days at \$80.00 per day
Rental (if any)	:		<input checked="" type="checkbox"/>	\$                    days
LTA / GIA Search Fee	:		<input checked="" type="checkbox"/>	\$ 2.00

Others: : \$

Final Settlement Sum : \$ 1,312.00

Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

\_\_\_\_\_

\_\_\_\_\_

Payment Instruction: Payee's Breakdown		
1)	ALAN'S UNITED AUTO PTE. LTD.	\$ 1,312.00

NUR SHAQILAH BTE ABDOL  
WAHAB

02/11/2018  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18007750/Kua3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN		Date : 02-11-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJV 1712M	Veh. Inspected	SJP 5765R
Policy No.	P1870595	Coverage (\$)	0.00
Claim No.	S8M00DK8	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	26/04/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C180 KOMP (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WDD2040462A243405	Colour	METALLIC BLACK
Odometer	171755	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 ZR17	MICHELIN	6 mm
L/H Front Tyre	225/45 ZR17	MICHELIN	6 mm
R/H Rear Tyre	225/45 ZR17	MICHELIN	3 mm
L/H Rear Tyre	225/45 ZR17	MICHELIN	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/04/2018	Inspection Date	30/04/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 5765R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO PANEL BEATING LH DOOR, REAR LH FENDER AND REPAIR REAR BUMPER.		450.00	400.00
	TO PUTTY AND SPRAY ABOVE REPAIR PARTS.		800.00	600.00
			1,250.00	1,000.00
	<b>GRAND TOTAL</b>		<b>1,250.00</b>	<b>1,000.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,000.00</b>

Report Ref No. CC4/ASM18007750/Kua3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.