

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJV1712M (AXA)

Accident Date : 09-04-2018

Our Ref : SJP5765R /CHAN 218076

YEW HUP HUAT TRADING
C/O ALAN'S UNITED AUTO PTE LTD
BLK 7 SIN MING IND.EST. SECTOR C
#01-76
SINGAPORE 575642

Date : 26-04-2018

*Not Withheld
Return After Paint
\$1000 3days*

ESTIMATE COST OF REPAIR FOR MERCEDES-BENZ C180 1.8 (A) SJP5765R

TO PANEL BEATING REAR LH DOOR, REAR LH FENDER AND REPAIR REAR BUMPER

\$450.00 *400*

TO PUTTY AND SPRAY ABOVE REPAIR PARTS

\$800.00 *600*
\$1,250.00

Singapore Dollars One Thousand Two Hundred Fifty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: