

Surveyor:

AOPHAN

DOI:

ASSIGNMENT

26/4/18

Date / Time:

26/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKU 14U

Name of Insured:

Yeo Lee Kion Anthea

Insured Tel No.:

HP:

D.O.A: 26/4/18

Claim No.:

SNM18002160102

Policy No.:

DMPCSN3085771623

Make / Model:

Land Rova

Place of Accident:

Farver Rd

Excess Sec II :SS

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Yeo Lee Kion

Driver Tel No.:

90119657

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SCG 11 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Modern



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

2/5/18

SCG 11 X

SKU 14U

NA/CTI 18007751/24 ; DOA: 26/4/18  
 - call LK 301084/4002 ; DOA: 31/5/18  
 - NA/CTI 19010681/44 ; DOA: 31/5/18

2/5/18

Spoke to OI, she confirmed the accident details. Informed TP claim and she agree to settle.

RECEIVED 02 OCT 2018

RECEIVED 02 NOV 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

JTHH 31/5/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

24/10/18

Confirm with:

Ms Chin

Email

Call

Final Liability:

%

100

Agreed / Assessed

BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

14391.50

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

1000.00 (\$ 100 x 10 days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

15393.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

15393.50

Name 1:

MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                 |                            |                                                                                     |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                                       |                                                                                 | Ref : CC6/CTI18007751/Aua3 |                                                                                     |  |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909                                                                                 |                                                                                 | Date : 26-04-2018          |  |  |
|                                                                                                                                           |                                                                                 | Code : CTI                 |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                 |                            |                                                                                     |  |
| Insured Veh.                                                                                                                              | SKU 14U                                                                         | Veh. Inspected             | SCG 11X                                                                             |  |
| Policy No.                                                                                                                                | DMPCSN3085771600                                                                | Coverage (\$)              | 0.00                                                                                |  |
| Claim No.                                                                                                                                 | SNM18D02160C02                                                                  | Excess (\$)                | 0.00                                                                                |  |
| Assign From                                                                                                                               |                                                                                 | Assign Date                | 26/04/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                 |                            |                                                                                     |  |
| Make & Model                                                                                                                              |                                                                                 | c.c                        | 0                                                                                   |  |
| Engine No.                                                                                                                                | HIDDEN                                                                          | Year of Reg.               |                                                                                     |  |
| Chassis No.                                                                                                                               |                                                                                 | Colour                     |                                                                                     |  |
| Odometer                                                                                                                                  | -                                                                               | Steering                   |                                                                                     |  |
| Brakes                                                                                                                                    |                                                                                 | Modification               |                                                                                     |  |
| General                                                                                                                                   |                                                                                 |                            |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                 |                            |                                                                                     |  |
|                                                                                                                                           | Size                                                                            | Make                       | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                            |                                                                                 |                            | mm                                                                                  |  |
| L/H Front Tyre                                                                                                                            |                                                                                 |                            | mm                                                                                  |  |
| R/H Rear Tyre                                                                                                                             |                                                                                 |                            | mm                                                                                  |  |
| L/H Rear Tyre                                                                                                                             |                                                                                 |                            | mm                                                                                  |  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                 |                            |                                                                                     |  |
|                                                                                                                                           |                                                                                 |                            |                                                                                     |  |
| <b>5. General Information</b>                                                                                                             |                                                                                 |                            |                                                                                     |  |
| Accident Date                                                                                                                             | 26/04/2018                                                                      | Inspection Date            | 26/04/2018                                                                          |  |
| Survey held at                                                                                                                            | MODERN AUTOMOTIVE PTE LTD<br>BLK 3023A UBI ROAD 1<br>#01-61<br>SINGAPORE 408717 |                            |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                 |                            |                                                                                     |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                 |                            |                                                                                     |  |

## Mei Kwan (LKKAUTO)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Friday, 27 April, 2018 1:58 PM  
**To:** Mei Kwan (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving SKU14U (OI : CAI - SNM18D02160C02) AND SCG11X (TP : LKK REF - CC6/CTI18007751/ua3) on 26/04/2018  
**Attachments:** MNA118054939-SKU14U.pdf  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Dear Mei Kwan,

I have missed out the OI GIA report for the previous reply, we enclosed herewith the OI GIA on the above attachment fyi.

Lucas Lee  
Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6181  
Fax (65) 6222 7175  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Lucas Lee  
**Sent:** Friday, 27 April, 2018 1:45 PM  
**To:** 'Mei Kwan (LKKAUTO)'  
**Subject:** RE: Direct Settlement - Accident Involving SKU14U (OI : CAI - SNM18D02160C02) AND SCG11X (TP : LKK REF - CC6/CTI18007751/ua3) on 26/04/2018

Dear Sirs,

Kindly refer to the above attachment.

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Tel: 6389 6111 Fax: 6222 1033  
Website: www.sg.cntaiping.com  
Co. Reg. No. 200206394E

Our Reference: **SNM18D02160/C02/1**

Date : **27 APRIL 2018**

via Ordinary & Registered Mail

**YEO LEE KIOW ANTHEA  
14 SELETAR GREEN VIEW  
SINGAPORE 805119**

Dear Sir / Madam

**ACCIDENT INVOLVING SKU14U AND SCG11X ON 26 APRIL 2018  
ALONG FARRER ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SCG11X**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,  
Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd

Attn : THIN THIN

Ref : CC6/CT118007751/UA3

Contact No : 68412360

via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0575A) - OH GIM KONG

F01/LKKDS-2013

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                               |
|-------------------------------------|-------------------------------|
| <b>Vehicle Owner Particulars</b>    |                               |
| Owner ID Type:                      | Singapore NRIC                |
| Owner ID:                           | 1034C                         |
| <b>Vehicle Details</b>              |                               |
| Vehicle No.:                        | SCG11X                        |
| Vehicle to be Exported:             | Yes                           |
| Intended De-registration Date:      | 26 Apr 2018                   |
| Vehicle Make:                       | TOYOTA                        |
| Vehicle Model:                      | LEXUS LS600HL AUTO (5 SEATER) |
| Primary Colour:                     | Black                         |
| Manufacturing Year:                 | 2010                          |
| Engine No.:                         | 2UR2033371                    |
| Chassis No.:                        | JTHDU46F605012938             |
| Maximum Power Output:               | 290.0 kW (388 bhp)            |
| Open Market Value:                  | \$138,784.00                  |
| Original Registration Date:         | 04 Oct 2010                   |
| First Registration Date:            | 04 Oct 2010                   |
| Transfer Count:                     | 1                             |
| Actual ARF Paid:                    | \$83,271.00                   |
| <b>Intended PARF Rebate Details</b> |                               |
| PARF Eligibility:                   | Yes                           |
| PARF Eligibility Expiry Date:       | 03 Oct 2020                   |
| PARF Rebate Amount:                 | \$49,962.00                   |
| <b>Intended COE Rebate Details</b>  |                               |
| COE Expiry Date:                    | 03 Oct 2020                   |
| COE Category:                       | E - Open Category             |
| COE Period(Years):                  | 10                            |
| QP Paid:                            | \$43,565.00                   |
| COE Rebate Amount:                  | \$10,447.00                   |
| <b>Total Rebate Amount:</b>         | <b>\$60,409.00</b>            |

The information contained herein is correct as at 26 Apr 2018

OK

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

**CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**

3 Anson Road #16-00  
 Springleaf Tower  
 Singapore 079909  
 Tel : 6389 - 6111  
 Fax : 6224 - 7478 / 7175

**Quotation**

DATE : 26.04.2018  
 VEH NO : SCG11X  
 MODEL : Lexus LS600H  
 D O A : 26.04.2018  
 YR REF : SKU14U

*Thin Thin*

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SCG11X (LEXUS LS600H)

| <u>Item</u> | <u>Description</u>                                   | <u>Qty</u> | <u>Amt</u>                  |
|-------------|------------------------------------------------------|------------|-----------------------------|
| <b>NO</b>   | <b>LIST ITEMS</b>                                    |            |                             |
| 1           | Rear Bumper <i>Distorted</i>                         | 1          | 989.10 ✓                    |
| 2           | Rear Bumper Clips <i>m</i>                           | 1 set      | 30.00 ✓                     |
| 3           | Rear Bumper Side Holder - LH & RH <i>m</i>           | 2          | 276.20 ✓                    |
| 4           | Rear Bumper Tow Cover <i>del</i>                     | 1          | 45.10 ✓                     |
| 5           | Rear Bumper Sponge <i>Anti-C</i>                     | 1          | 186.10 ✓                    |
| 6           | Rear Bumper Reinforcement <i>Best</i>                | 1          | 701.10 ✓                    |
| 7           | Rear Bumper Reinforcement Cover <i>Distorted</i>     | 1          | 147.60 ✓                    |
| 8           | Rear Bumper Reinforcement Stay - LH & RH <i>Best</i> | 2          | 552.20 ✓                    |
| 9           | Rear Bumper Lower Garnish <i>del</i>                 | 1          | 487.50 ✓                    |
| 10          | Reverse Sensor <i>2 pieces damaged</i>               | 4          | <del>2,332.40</del> 760     |
| 11          | Rear End Panel <i>Distorted</i>                      | 1          | 785.60 ✓                    |
| 12          | Rear End Panel Top Garnish <i>del</i>                | 1          | 438.40 ✓                    |
| 13          | Rear End Panel Top Garnish Clips <i>m</i>            | 1 set      | 15.00 ✓                     |
| 14          | Taillamp - LH & RH <i>LH One side</i>                | 2          | <del>2,500.20</del> 1250.10 |
| 15          | Taillamp Side Cover - LH & RH <i>LH del</i>          | 2          | <del>476.20</del> 237.60    |
| 16          | Taillamp Panel - LH <i>Distorted</i>                 | 1          | 228.10 ✓                    |
| 17          | Bootlid <i>Buckled</i>                               | 1          | 1,154.10 ✓                  |
| 18          | Bootlid Lock <i>Dang</i>                             | 1          | 1,310.40 ✓                  |
| 19          | Bootlid Weatherstripe <i>lt</i>                      | 1          | 298.10 ✓                    |
| 20          | Bootlid Lock Sensor <i>New</i>                       | 1          | 155.40 ✓                    |
| 21          | Bootlid Reflector - LH & RH <i>LH lt</i>             | 2          | <del>995.40</del> 497.70    |
| 22          | Bootlid Outer Garnish <i>Canceled</i>                | 1          | 1,810.10 ✓                  |
| 23          | Bootlid Hinge - LH & RH <i>New</i>                   | 2          | 398.20 ✓                    |
| 24          | Bootlid Inner Trim Board <i>stream</i>               | 1          | 738.40 ✓                    |
| 25          | Bootlid Inner Trim Board Clips <i>m</i>              | 1 set      | 20.00 ✓                     |
| 26          | Rear Fender - LH <i>Repair</i>                       | 1          | 1,561.10 ✓                  |
| 27          | Rear Fender Inner Trim Board - LH <i>At Home</i>     | 1          | 896.50 ✓                    |
| 28          | Rear Fender Inner Trim Board Clips - LH <i>m</i>     | 1 set      | 30.00 ✓                     |



RE: ESTIMATE FOR ACCIDENT REPAIR SCG11X (LEXUS LS600H)

|    |                                                     |   |                              |   |
|----|-----------------------------------------------------|---|------------------------------|---|
| 29 | Rear Fender Inner Trim Board Cover - LH <i>He m</i> | 1 | 535.50                       | X |
| 30 | Rear Windscreen Moulding <i>He m</i>                | 1 | 228.60                       | X |
| 31 | Spare Tyre Panel Top Cover <i>Deformed</i>          | 1 | <del>1,358.10</del> 558      |   |
| 32 | Spare Tyre Panel Side Sponge - LH <i>Deformed</i>   | 1 | 331.40                       | / |
| 33 | Rear Exhaust Pipe <i>LH Bent</i>                    | 2 | <del>2,972.00</del> 1,486.20 |   |
| 34 | Rear Exhaust Mounting <i>He m</i>                   | 2 | 279.20                       | X |
| 35 | Lexus Logo <i>? He m</i>                            | 1 | 151.10                       | / |
| 36 | Lexus Wording <i>? He m</i>                         | 1 | 168.30                       | / |
| 37 | LS600HL Wording <i>? He m</i>                       | 1 | 166.40                       | / |
| 38 | Rear Camera <i>He m</i>                             | 1 | 1,710.10                     | X |

Less 10%

\$ 27,458.80

(2,745.88)

\$ 24,712.92

S/NETT ITEMS

|   |                                     |   |       |   |
|---|-------------------------------------|---|-------|---|
| 1 | Rear Number Plate <i>? He m</i>     | 1 | 30.00 | X |
| 2 | Rear Number Plate Holder <i>60</i>  | 1 | 30.00 | X |
| 3 | Rear End Panel Sealant <i>He m</i>  | 1 | 60.00 | / |
| 4 | Rear Windscreen Sealant <i>He m</i> | 1 | 60.00 | X |

\$ 180.00

Total parts

\$ 24,892.92

LABOUR CHARGE

|    |                                                  |             |      |
|----|--------------------------------------------------|-------------|------|
| 1  | To knocking out rear portion & renew above parts | \$ 1,600.00 | 1300 |
| 2  | To putty & spray up paint works                  | \$ 1,500.00 | 1200 |
| 3  | To check wiring system                           | \$ 100.00   | 50   |
| 4  | To remove reverse sensor                         | \$ 120.00   | 60   |
| 5  | To remove rear camera                            | \$ 100.00   | 60   |
| 6  | To underseal                                     | \$ 150.00   | 60   |
| 7  | To remove upholstery                             | \$ 150.00   | 100  |
| 8  | To transfer bootlid fittings                     | \$ 150.00   | 100  |
| 9  | To remove rear windscreen                        | \$ 180.00   | X    |
| 10 | To remove exhaust pipes                          | \$ 300.00   | 120  |

RE: ESTIMATE FOR ACCIDENT REPAIR SCG11X (LEXUS LS600H)

11 To perform diagnostic test

\$ 200.00 *100.*

Total Labour

\$ 4,550.00

Grand Total

**\$ 29,442.92**

*3150*

GST Will be reflected in the final bills

NOTE :-

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN  
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY  
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE  
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

*total 16810.44*  
*h/s: 13450.*  
*08 Days.*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18007751/Aua3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 05-11-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                  |                |            |
|--------------|------------------|----------------|------------|
| Insured Veh. | SKU 14U          | Veh. Inspected | SCG 11X    |
| Policy No.   | DMPCSN3085771600 | Coverage (\$)  | 0.00       |
| Claim No.    | SNM18D02160C02/1 | Excess (\$)    | 0.00       |
| Assign From  |                  | Assign Date    | 26/04/2018 |

## 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | LEXUS LS600HL     | c.c          | 4969       |
| Engine No.   | HIDDEN            | Year of Reg. | 2010       |
| Chassis No.  | JTHDU46F605012938 | Colour       | BLACK      |
| Odometer     | 203668            | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

## 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 245/45 R19 | DUNLOP | 6 mm    |
| L/H Front Tyre | 245/45 R19 | DUNLOP | 6 mm    |
| R/H Rear Tyre  | 245/45 R19 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 245/45 R19 | DUNLOP | 6 mm    |

## 4. Description of Damages

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

## 5. General Information

|                |                                                                                 |                 |            |
|----------------|---------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 26/04/2018                                                                      | Inspection Date | 26/04/2018 |
| Survey held at | MODERN AUTOMOTIVE PTE LTD<br>BLK 3023A UBI ROAD 1<br>#01-61<br>SINGAPORE 408717 |                 |            |

## 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 8 Working Days |
|-------------------------------------|----------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCG 11X

| Qty | Description of Parts                      | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>               |                      |                           |                   |
| 1   | REAR BUMPER                               | DISTORTED            | 989.10                    | 989.10            |
| 1   | SET REAR BUMPER CLIPS                     | NECESSARY            | 30.00                     | 30.00             |
| 2   | REAR BUMPER SIDE HOLDER-LH & RH           | NECESSARY            | 276.20                    | 276.20            |
| 1   | REAR BUMPER TOW COVER                     | DEFORMED             | 45.10                     | 45.10             |
| 1   | REAR BUMPER SPONGE                        | CRACKED              | 186.10                    | 186.10            |
| 1   | REAR BUMPER REINFORCEMENT                 | BENT                 | 701.10                    | 701.10            |
| 1   | REAR BUMPER REINFORCEMENT COVER           | DISTORTED            | 147.60                    | 147.60            |
| 2   | REAR BUMPER REINFORCEMENT STAY-LH & RH    | BENT                 | 552.20                    | 552.20            |
| 1   | REAR BUMPER LOWER GARNISH                 | DEFORMED             | 487.50                    | 487.50            |
| 4   | REVERSE SENSOR                            | DAMAGED (2 PCS ONLY) | 2,332.40                  | 760.00            |
| 1   | REAR END PANEL                            | DENTED               | 785.60                    | 785.60            |
| 1   | REAR END PANEL TOP GARNISH                | DEFORMED             | 438.40                    | 438.40            |
| 1   | SET REAR END PANEL TOP GARNISH CLIPS      | NECESSARY            | 15.00                     | 15.00             |
| 2   | TAILLAMP-LH & RH                          | N/S CRACKED          | 2,500.20                  | 1,250.10          |
| 2   | TAILLAMP SIDE COVER-LH & RH               | N/S DEFORMED         | 475.20                    | 237.60            |
| 1   | TAILLAMP PANEL-LH                         | DENTED               | 228.10                    | 228.10            |
| 1   | BOOTLID                                   | BUCKLED              | 1,154.10                  | 1,154.10          |
| 1   | BOOTLID LOCK                              | DAMAGED              | 1,310.40                  | 1,310.40          |
| 1   | BOOTLID WEATHERSTRIPE                     | CUT                  | 298.10                    | 298.10            |
| 1   | BOOTLID LOCK SENSOR                       | NOT NECESSARY        | 155.40                    | -                 |
| 2   | BOOTLID REFLECTOR-LH & RH                 | N/S CUT              | 995.40                    | 497.70            |
| 1   | BOOTLID OUTER GARNISH                     | CRACKED              | 1,810.10                  | 1,810.10          |
| 2   | BOOTLID HINGE-LH & RH                     | NOT NECESSARY        | 398.20                    | -                 |
| 1   | BOOTLID INNER TRIM BOARD                  | NOT NECESSARY        | 738.40                    | -                 |
| 1   | SET BOOTLID INNER TRIM BOARD CLIPS        | NECESSARY            | 20.00                     | 20.00             |
| 1   | REAR FENDER-LH                            | TO REPAIR SEE LABOUR | 1,561.10                  | -                 |
| 1   | REAR FENDER INNER TRIM BOARD-LH           | NOT NECESSARY        | 896.50                    | -                 |
| 1   | SET REAR FENDER INNER TRIM BOARD CLIPS-LH | NECESSARY            | 30.00                     | 30.00             |
| 1   | REAR FENDER INNER TRIM BOARD COVER-LH     | NOT NECESSARY        | 535.50                    | -                 |

Report Ref No. CC6/CT118007751/Aua3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

| Qty | Description of Parts                                                                         | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | REAR WINDSCREEN MOULDING                                                                     | NOT NECESSARY | 228.60                    | -                 |
| 1   | SPARE TYRE PANEL TOP COVER                                                                   | DEFORMED      | 1,358.10                  | 558.00            |
| 1   | SPARE TYRE PANEL SIDE SPONGE-LH                                                              | DEFORMED      | 331.40                    | 331.40            |
| 2   | REAR EXHAUST PIPE                                                                            | N/S BENT      | 2,972.60                  | 1,486.30          |
| 2   | REAR EXHAUST MOUNTING                                                                        | NOT NECESSARY | 279.20                    | -                 |
| 1   | LEXUS LOGO                                                                                   | NECESSARY     | 151.10                    | 151.10            |
| 1   | LEXUS WORDING                                                                                | NECESSARY     | 168.30                    | 168.30            |
| 1   | LS600HL WORDING                                                                              | NECESSARY     | 166.40                    | 166.40            |
| 1   | REAR CAMERA                                                                                  | NOT NECESSARY | 1,710.10                  | -                 |
|     | LESS 10% DISCOUNT                                                                            |               | -2,745.88                 | -1,511.16         |
|     |                                                                                              |               | 24,712.92                 | 13,600.44         |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                             |               |                           |                   |
| 1   | REAR NUMBER PLATE (SN)                                                                       | NOT NECESSARY | 30.00                     | -                 |
| 1   | REAR NUMBER PLATE HOLDER (SN)                                                                | NOT NECESSARY | 30.00                     | -                 |
| 1   | REAR END PANEL SEALANT (SN)                                                                  | NECESSARY     | 60.00                     | 60.00             |
| 1   | REAR WINDSCREEN SEALANT (SN)                                                                 | NOT NECESSARY | 60.00                     | -                 |
|     |                                                                                              |               | 180.00                    | 60.00             |
|     | <b><u>LABOUR</u></b>                                                                         |               |                           |                   |
|     | TO KNOCKING OUT REAR PORTION & RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER-LH. |               | 1,600.00                  | 1,300.00          |
|     | TO PUTTY & SPRAY UP PAINT WORKS.                                                             |               | 1,500.00                  | 1,200.00          |
|     | TO CHECK WIRING SYSTEM.                                                                      |               | 100.00                    | 50.00             |
|     | TO REMOVE REVERSE SENSOR.                                                                    |               | 120.00                    | 60.00             |
|     | TO REMOVE REAR CAMERA.                                                                       |               | 100.00                    | 60.00             |
|     | TO UNDERSEAL.                                                                                |               | 150.00                    | 60.00             |
|     | TO REMOVE UPHOLSTERY.                                                                        |               | 150.00                    | 100.00            |
|     | TO TRANSFER BOOTLID FITTINGS.                                                                |               | 150.00                    | 100.00            |
|     | TO REMOVE REAR WINDSCREEN.                                                                   | NOT NECESSARY | 180.00                    | -                 |
|     | TO REMOVE EXHAUST PIPES.                                                                     |               | 300.00                    | 120.00            |
|     | TO PERFORM DIAGNOSTIC TEST.                                                                  |               | 200.00                    | 100.00            |
|     |                                                                                              |               | 4,550.00                  | 3,150.00          |



|                                                                         |  |           |           |
|-------------------------------------------------------------------------|--|-----------|-----------|
| GRAND TOTAL                                                             |  | 29,442.92 | 16,810.44 |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |  |           | 13,450.00 |

Report Ref No. CC6/CT118007751/Aua3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.