

REF: NS/WC 1800755/Stbnz

# ASSIGNMENT

1/7/2016

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TPRES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: **EN 512**  
 Policy No: **50992750911**  
 Claims No: **MT/0991323 002**  
 Sum Insured: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: **SG 1721J** Yr Regn: \_\_\_\_\_  
 Type: M.Car / M.Cycle / **Bus** / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **MAN NL30P** G.C. **10518**  
 Colour: **Green** A/C: Insured / Std / NI / NA  
 Sp. Reading: **135962** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **WMAA 22 72 (S) 7002874**  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: **Nil** / S/Rim / STD A/Rim or  
 Tyre Size: F: **275/70R22.5**  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
**TOYO / YOKO** or **Fireza**

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6/6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6/6</u> mm
D.O.A.	<u>20/4/18</u>	D.O.I.	<u>26/4/18</u>

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_  
 Consistent? : Yes or No  
 Consistent? : Yes or No  
 G/A / PR Seen: \_\_\_\_\_  
 days Res.: Yes or No  
 Est. Repairs: \_\_\_\_\_  
 % 3 Val: Yes or No  
 Turn Sum: \_\_\_\_\_  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Survey held at **SMART**  
 Des. of Damages: Frt / Rear / **O/S** / N/S / UIC / Rooftop or  
0/5 Rear  
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction  
**SG 1721J**  
**EN 512 - X**  
**CC3/LR/17011561/Kp0902**

REF: 010617

Part by Part **12579.61** (Red: 2666.39: 14%)

22/5/2018

RECEIVED 23-MAY-2018

Date/Time, File Pass to?  : Preli. Report  
**23/5 Typist**  : Final Report  
 Date/Time, File Return to?

Days Of Repair: **7**  
 Resurvey No. of Trip: **2**

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

Survey Fee:  
 Transportation:  
 S - RS - SI  
 Photos  
 Other

Report Format:  
 Lump Sum / IB: (\$ **12579.61**)

160
TOTAL



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007755/Stb

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 27-04-2018  
189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EN 59Z	Veh. Inspected	SG 1721J
Policy No.	5099275694	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/04/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	20/04/2018	Inspection Date	26/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#) [Change Password](#) [Log Out](#)

[My Desktop](#)  
[Notice of Loss](#)

**Policy Query**

Policy No.  Date of Accident   
Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="checkbox"/>	5099275694	OPTIMUM FLEET LEASING	53342206W	GPC	drive CLASSIC	EN59Z	EN59Z	24/03/2018	23/03/2019

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0939315-003	SMRT BUSES LTD	SMB 1472A	SKJ 7179P	29/03/2017
2	MT/0995090-001	SMRT BUSES LTD	SMB 342Z	PC 8808D	14/09/2017
3	MT/0980389-002	SMRT BUSES LTD	SMB 5893S	PA 4137T	26/01/2018
4	MT/0939257-002	SMRT BUSES LTD	SMB 1582R	PA 8425K	25/03/2017
5	MT/0987666-002	SMRT BUSES LTD	SMB 1484R	SHB 8685R	27/2/2018
6	MT/0990787-002	SMRT BUSES LTD	SMB 1473Y	SJK 5147B	16/4/2018
7	MT/0985497-002	SMRT BUSES LTD	SMB 1515K	SGK454H	9/3/2018
8	MT/0989067-002	SMRT BUSES LTD	SMB 61J	SJH 4630U	2/4/2018
9	MT/0991323-002	SMRT BUSES LTD	SG 1721J	EN 59Z	20/4/2018

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/04/2018 15:11
Date Of Accident	20/04/2018 08:25
Exact Location Of Accident	SEGAR RD - BS: 44701 (BLK548B)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG1721J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE
<b>Vehicle Particulars</b>	
Manufacturer	MAN
Model	MAN A22
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	
<b>Driver</b>	
Name of Driver	SHARUDDIN BIN ABDULLAH
NRIC No	S7711244H
Date Of Birth	22/04/1977
Occupation	OUTDOOR
Date Of Driving Pass	21/06/2007
Driving Experience	10 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address NOADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 25

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

My bus was stationary and conducting passengers activities at Segar Rd (BS: 44701). Suddenly I heard a loud bang and felt an impact. My bus shake a bit. I checked my right view mirror and noticed a private car (EN59Z) had collided onto my bus from the rear and grazed against the right portion of my bus until the car stopped in front. I went down my bus to exchange particulars with the third party driver. He was reeked with alcohol smell and possibly intoxicated. Police and Field Team activated. Police arrived and after investigation, bus is allowed to leave the accident scene. Third party driver was detained by police for further investigation.

### Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number EN59Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver TOH KIAN BENG

NRIC/Passport Number S7015509E

Contact Number

Address

Postcode

Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

# Sketch Plan Pg. 1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name: BALQISH  
NRIC/FIN No.: S8340325Z



> [Back to OneMotoring](#)

### Enquire Transfer Fee

#### Vehicle Details

Vehicle No. :	SG1721J
Vehicle Type :	H20 - Public Transport Bus/Coach/Minibus
Vehicle Attachment 1 :	Air-Conditioned
Vehicle Scheme :	OmniBus (LTA-ARF exempted)
Vehicle Make :	MAN
Vehicle Model :	NL 320F (A22) 11L AUTO ABS TURBO
Chassis No. :	WMAA22ZZ0F7002894
Propellant :	Diesel
Engine No. :	50340742164077
Engine Capacity :	10518 cc
Maximum Power Output :	-
Maximum Laden Weight :	18000 kg
Unladen Weight :	11280 kg
Year Of Manufacture :	2015
Original Registration Date :	01 Sep 2016
Lifespan Expiry Date :	31 Aug 2033
Road Tax Expiry Date :	31 Aug 2018
Inspection Due Date :	31 Aug 2018
Intended Transfer Date :	25 May 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

#### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

You may print this page for reference.


OK

Print

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1721J  
Ref. No : BUS/04/18/5029  
Reg. Date : 01/09/2016  
Vehicle Type : BUS -12M  
Make : MAN  
Model : MAN  
Name of Driver : Sharuddin Bin Abdullah  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 20/04/2018 08:25:00 AM  
Accident Reported Date / Time : 23/04/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : IDAC  
Vehicle is Towed Back? : No  
Towed Back Date/Time : 01/01/2000  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024095787  
Special Instruction to ARC,if any :  
SG1721J - TAIL LIGHT & RIGHT REAR PORTION  
EN59Z (TP) - INSURED WITH NTUC  
Prepared Date : 25/04/2018 03:53:24 PM




Section B - To be Completed by Service Number, Accident Repair Centre

Chassis No : Mileage : 0  
Work Shop : Repair Completed Date / Time : 01/01/2000

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges	: 4,240.00	3,710.00
Total Spray Painting Charges	: 1,500.00	1,338.00
Total Material Charges	: 7,531.61	7,531.61
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 13,271.61</b>	<b>12,579.61</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 8.00	7.00 ✓
Prepared / Adjusted By	: Sim Kim Bock	Sebastian
Arc / Surveyor Sing Off Date	: 27/04/2018 02:39:18 PM	30/04/2018 02:27:11 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 25/04/2018 06:03:48 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : Prepared Date :

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	4,240.00	3,710.00 ✓
<b>Total Labour</b>	<b>4,240.00</b>	<b>3,710.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,500.00	1,338.00 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,500.00</b>	<b>1,338.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
A01001-CW564		6009992	RH SIDE PANEL R11	1	1,782.50	10.00	1,604.25	Replace	Replace ✓	No CRK
4000F06-ACCE4526		6009991	RH SIDE PANEL R10	1	192.70	10.00	173.43	Replace	Replace ✓	No CRK
F01001-CW273		6010062	REAR TAIL LAMP COVER RH	1	974.70	10.00	877.23	Replace	Replace ✓	No CRK
88-25320-6008		6010299	SIGNAL LAMP LED	1	1,274.10	10.00	1,146.69	Replace	Replace ✓	No CRK
88-25225-6039		6010298	STOP LAMP LED	2	1,141.70 2,283.40	10.00	2,055.06	Replace	Replace ✓	No CRK
A01001-CW567		6009988	RH SIDE PANEL R7	1	885.50	10.00	796.95	Replace	Replace ✓	No DT
A01001-CW568		6009987	RH SIDE PANEL R6	1	1,776.80	100.00	0.00	Replace	Repair P	No
	COMMO N	4005299	SMRT STICKER(B)	1	200.00	0.00	200.00	Replace	Replace ✓	No NEL
	COMMO N	4006314	SEALANT SIKAFLEX	14	37.00	0.00	518.00	Replace	Replace ✓	No NEL
	COMMO N	4006313	PRIMER	1	80.00	0.00	80.00	Replace	Replace ✓	No NEL
		4006315	ACTIVATOR	1	80.00	0.00	80.00	Replace	Replace ✓	No NEL
<b>TOTAL MATERIALS</b>								<b>7,531.61</b>	<b>7,531.61</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>7,531.61</b>	<b>7,531.61</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

7531.61  
+ 5048.00  
12579.61

Part by Part = \$ 12579.61


15787-70

Substation  
12/5/18

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1721J  
 Ref. No : BUS/04/18/5029  
 Reg. Date : 25/04/2018  
 Vehicle Type : BUS -12M  
 Make : MAN  
 Model : MAN  
 Name of Driver : Sharuddin Bin Abdullah  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 20/04/2018 08:25:00 AM  
 Accident Reported Date / Time : 23/04/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : IDAC  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC, if any :  
 SG1721J - TAIL LIGHT & RIGHT REAR PORTION  
 EN59Z (TP) - INSURED WITH NTUC  
 Prepared Date : 25/04/2018 03:53:24 PM



*Sebastian,*  
*26/4/18.*  
*- Part by part repair.*  
*- Photo Before Paint*

**LKK Auto Consultants** hence notify the Repairer of the following:
 

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer  
 Signature:  
 Date:

Chassis No :

Mileage

0

Work Shop :

Repair Completed Date / Time :

### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 3,180.00	0.00
Total Spray Painting Charges	: 1,200.00	0.00
Total Material Charges	: 9,500.73	9,500.73
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 13,880.73</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 8.00	<del>0.00</del> 7 days
Prepared / Adjusted By	: Sim Kim Bock	
Arc / Surveyor Sing Off Date	: 01/01/1900 12:00:00 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 25/04/2018 06:03:48 PM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :


Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :



**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	4,240.00	<del>0.00</del> 3710
<b>Total Labour</b>	<b>4,240.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,500.00	<del>0.00</del> 1338
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,500.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
A01001-CW564		6009992	RH SIDE PANEL R11	1	1,782.50	10.00	1,604.25	Replace	Replace	No ✓ CRK
4000F06-ACCE4526		6009991	RH SIDE PANEL R10	1	192.70	10.00	173.43	Replace	Replace	No ✓ CRK
F01001-CW273		6010062	REAR TAIL LAMP COVER RH	1	974.70	10.00	877.23	Replace	Replace	No ✓ CRK
88-25320-6008		6010299	SIGNAL LAMP LED	1	1,274.10	10.00	1,146.69	Replace	Replace	No ✓ CRK
88-25225-6039		6010298	STOP LAMP LED	2	1,141.70	10.00	2,055.06	Replace	Replace	No ✓ CRK
A01001-CW567		6009988	RH SIDE PANEL R7	1	885.50	10.00	796.95	Replace	Replace	No DT
A01001-CW568		6009987	RH SIDE PANEL R6	1	1,776.80	10.00	1,599.12	Replace	Replace	No R
	COMMO N	4005299	SMRT STICKER(B)	1	200.00	0.00	200.00	Replace	Replace	No ✓ REC
	COMMO N	4006314	SEALANT SIKAFLEX	24	37.00	0.00	888.00	Replace	Replace	No ✓ REC
	COMMO N	4006313	PRIMER	1	80.00	0.00	80.00	Replace	Replace	No ✓ REC
		4006315	ACTIVATOR	1	80.00	0.00	80.00	Replace	Replace	No ✓ REC
<b>TOTAL MATERIALS</b>								<b>9,500.73</b>	<b>9,500.73</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>9,500.73</b>	<b>9,500.73</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007755/Stbn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 25-05-2018
	Code: INC4



### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EN 59Z	Veh. Inspected	SG 1721J
Policy No.	5099275694	Coverage (\$)	0.00
Claim No.	MT/0991323-002	Excess (\$)	0.00
Assign From		Assign Date	26/04/2018

### 2. Vehicle Particulars & Condition

Make & Model	MAN NL 320F	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WMAA22ZZ0F7002894	Colour	GREEN
Odometer	135902	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	20/04/2018	Inspection Date	26/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 1721J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	RH SIDE PANEL R11	CRACKED	1,782.50	1,782.50
1	RH SIDE PANEL R10	CRACKED	192.70	192.70
1	REAR TAIL LAMP COVER RH	CRACKED	974.70	974.70
1	SIGNAL LAMP LED	CRACKED	1,274.10	1,274.10
2	STOP LAMP LED @\$1141.70	CRACKED	2,283.40	2,283.40
1	RH SIDE PANEL R7	DENTED	885.50	885.50
	LESS 10% DISCOUNT		-	-739.29
			7,392.90	6,653.61
<b>SPECIAL NETT ITEMS</b>				
1	SMRT STICKER (B)(SN)	NECESSARY	200.00	200.00
14	SEALANT SIKAFLEX @\$37.00 (SN)	NECESSARY	518.00	518.00
1	PRIMER (SN)	NECESSARY	80.00	80.00
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
1	RH SIDE PANEL RH (SN)	TO REPAIR SEE LABOUR	1,776.80	-
			2,654.80	878.00
<b>LABOUR</b>				
	TO REPAIR LH REAR PORTION.INCLUSIVE OF THE REPAIR OF RH SIDE PANEL RH.		4,240.00	3,710.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		1,500.00	1,338.00
			5,740.00	5,048.00
<b>GRAND TOTAL</b>			<b>15,787.70</b>	<b>12,579.61</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>12,579.61</b>

Report Ref No. NS/INC18007755/Stbn2

YEANG WAI KEEN  
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.