

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0489/2018/GW
Date : 25-Apr-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tay Cheow Lam
Address : 1 Leicester road
#04-11
Singapore 358828
Telephone : HP +65 96950022
Type of Claim : Own Damage Claims
Policy No. : 1700024688
Vehicle No : **SGZ 69 H**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Jul-17
Engine No : CVN 039018
Chassis No : WAUZZZF41HA164954
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Apr-18
Place of Accident : Macalister Rd Carpark H Exit Gantry

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGZ 69 H.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, lhs headlight and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,200.00	750
3	To respray front bumper, lhs front fender.	\$ 1,400.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>3,152.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGZ 69 H.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Reh d</i>	\$ 1,849.00	✓
2	FRONT AIR GUIDE GRILLE-LH <i>green</i>	\$ 118.00	✓
3	FRONT AIR GUIDE SECTION-LH	\$ 31.00	✓
4	LED HEADLIGHT-LH <i>cut</i>	\$ 6,973.00	✓
5	LED HEADLIGHT WASHER LIFT CYLINDER-LH	\$ 184.00	?
6	LED HEADLIGHT WASHER LIFT CYLINDER BRACKET-LH <i>net</i>	\$ 6.00	x
7	SUNDRIES	\$ 200.00	?
TOTAL SPARE PARTS CHARGES		\$ 9,361.00	
TOTAL LABOUR CHARGES		\$ 3,152.00	
GRAND TOTAL		\$ 12,513.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian L

Surveyed Date

: 27/04/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 04 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant