

ASS. REC. BY:

REF: CS/GAL18007765/Rlgbe2

Special Instruction:

Surveyor:

Rasel

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAL

Date/Time:

27042018 11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

FBK 3272E

Insured:

at Workshop m/s

Leong Seng Motor.

Tel:

6273 7469

of

Bik 1006 Bukit Merah Lane 2 #01-08

Policy No.:

Claim No.:

C1M0MVM000000255

Sum Insured:

Excess:

TBA 750

Make of Veh:

D.O.A.

27042018

(Client's Record)

CA / ~~REV~~ / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

27042018 11:00am

Person Contacted:

Joanne

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBK 3272E - NBA/GAL18007712/Y O.A: 270418
30/4/18 @ 7:27pm	revert to Rachel Tan by email.
08/5/18 @ 6:14pm	Rachel Tan informed c/a at LS \$4500 by email. \$ EX: 8750
09/5/18 @ 9:06am	informed Mr Teo c/a at LS \$4500 \$ EX: 8750.
	LS \$4500, 4 days CRed \$7059.50, 61%.
	* No need bill (Nac) to GAL as inscd already paid.

Surveyor *Rasul*


REF:

0382K

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP WS TP RES OD RES EVA INV MV
 To Inspect Vehicle No: **FBK 3272E**
 at Workshop m/s **LEONH SENG**
 of **1006, BUKIT MERAH LK2 # 01-18**
 Insured: **GAI**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: **TBA**
 (Client's Record)
 Make of Veh: _____

Veh No: **FBK 3272E** Yr Regn: **2015 / July**
 Type: M.Car M.Cycle Bus Van Lorry Taxi Prime Mover /
 Truck / Trailer or _____
 Make: **YAMAHA MW 125 3-WHEELER 125**
 Colour: **MULTI** A/C: Insured / Std / NI / NA
 Sp.Reading: **119387** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MLESE 782 0002363**
 Gen. Cond: Good / Fair Poor / Burnt
 Steering: In order Jammed / Leaked / Burnt or _____
 Brake: In order Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: **90/90-14**
 R: **110/90-12**
 BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____



(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: **3K**
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **4** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. **43/3** mm R/Bal. **4** mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. **22/04/18** D.O.I. **27/04/18**
 Survey held at **LEONH SENG**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

22/04/18 @ Spoken to workshop Leonh Seng, unable to repair bike at 3K. recommend as uneconomical to repair due to cost of repair above 3K.
Rasul
 pls check all parts prices.

RECEIVED 05 OCT 2018

Date/Time, File Pass to? : Preli. Report : Final Report
 1) *05/10/2018*
 Date/Time, File Return to?
 2) _____
 Report Format: **OD**
 Lump Sum / I.B.I: (\$) **4500**
 Days Of Repair: **4**
 Resurvey No. of Trip: **1**
 Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)
 Survey Fee: **350**
 Transportation: _____ S + RS _____ SI
 Photos _____
 Others: **-20**
 TOTAL: **390**

Juma
24/5

Catherine Chong (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Friday, 27 April, 2018 11:00 AM
To: leongseng
Cc: LKK Assignments
Subject: RE: Fw: Gia report for FBK3272E
Attachments: FBK3272E_22042018.pdf; img417.pdf

Hi Leong Sen
We will be arranging for LKK to conduct OD survey.

Hi LKK
Please accept OD assignment. Attached GIA report and estimates.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Ngian, Kelvyna
Sent: Friday, April 27, 2018 10:38 AM
To: leongseng <leongsen@singnet.com.sg>; Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: FW: [External] Fw: Gia report for FBK3272E

Hi Rachel,

Kindly assist.

Thanks
Kelvyna

From: leongseng <leongsen@singnet.com.sg>
Sent: Thursday, April 26, 2018 5:20 PM
To: General Claims <GeneralClaims@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] Fw: Gia report for FBK3272E

Dear Sir/Mdm

Pls be informed that owner of FBK3272 (Certis Cisco) had appointed us to do an O/D claim for them.

Pls find enclosed accident report and our repair estimate.

Kindly arrange for your appointed surveyor to conduct damage survey at our workshop.

Pls be informed that our workshop is located at Blk 1006, Bukit Merah Lane 2, #01-08 S(159762) Tel 62737469.

Thanks

c s teo

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAuto)

From: Accounts (LKKAuto)
Sent: Wednesday, 3 October 2018 5:51 PM
To: 'Tan, Rachel'; Shiau Chan (LKKAuto)
Cc: assignments; SUR
Subject: RE: CLMOMVM000000255- FBK3272E

Dear Rachel

The Accident Reporting Fee was billed and paid by the Insured.

There is no NAC (BM) bill to GAI.

The Survey Fee remains.

Thank you.

Best Regards,

Chew Lian | Account Dept

LKK Auto Consultants

DID: 6742 9588 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]
Sent: Friday, 21 September, 2018 6:55 PM
To: Shiau Chan (LKKAuto)
Cc: assignments; SUR; account@lkkauto.com
Subject: RE: CLMOMVM000000255- FBK3272E

Hi

Please also submit the NAC (BM) bill too

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Tan, Rachel
Sent: Friday, September 21, 2018 6:52 PM
To: 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>
Cc: 'assignments' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Subject: RE: CLMOMVM000000255- FBK3272E

Hi

Please submit survey report. Attached OD invoice for your reference.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Tan, Rachel
Sent: Tuesday, May 8, 2018 6:14 PM
To: 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: CLMOMVM000000255- FBK3272E

Hi Shiau Chan

Please proceed if damage is consistent, excess \$750/-

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, May 8, 2018 5:59 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: [External] RE: CLMOMVM000000255- FBK3272E

Dear Rachel,

Please be informed that the repairer willing to undertake the repair cost at Lump Sum \$4,500.00.

Kindly advise on authorisation and excess if apply.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Tuesday, 8 May 2018 5:30 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: CLMOMVM000000255- FBK3272E

Hi Shiau Chan

For this case, we have to maintain at Lump sum repair \$4,500 (before excess).

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, May 8, 2018 5:27 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Denise Tay (LKKAuto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Tuesday, 8 May 2018 6:14 PM
To: Shiau Chan (LKKAuto)
Cc: assignments; SUR
Subject: RE: CLMOMVM000000255- FBK3272E

Hi Shiau Chan

Please proceed if damage is consistent, excess \$750/-

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, May 8, 2018 5:59 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: [External] RE: CLMOMVM000000255- FBK3272E

Dear Rachel,

Please be informed that the repairer willing to undertake the repair cost at Lump Sum \$4,500.00.

Kindly advise on authorisation and excess if apply.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Tuesday, 8 May 2018 5:30 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: CLMOMVM000000255- FBK3272E

Hi Shiau Chan

For this case, we have to maintain at Lump sum repair \$4,500 (before excess).

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, May 8, 2018 5:27 PM

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 30 April 2018 2:22 PM
To: 'Tan, Rachel'
Cc: assignments; SUR
Subject: RE: Fw: Gia report for FBK3272E
Attachments: CSGAI18007765R1qb.pdf; FBK3272 EST.pdf

Dear Rachel,

Enclosed herewith preliminary advice of FBK 3272E.
Repair cost not economical.

We have not authorise repair.

Kindly advice on claim number.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 27 April 2018 11:47 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Fw: Gia report for FBK3272E

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Friday, 27 April, 2018 11:00 AM
To: leongseng <leongsen@singnet.com.sg>
Cc: LKK Assignments <assignments@lkkauto.com>
Subject: RE: Fw: Gia report for FBK3272E

Hi Leong Sen

We will be arranging for LKK to conduct OD survey.

Hi LKK

Please accept OD assignment. Attached GIA report and estimates.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Claim No. : TBA

Date: 30th April 2018

Our Ref: CS/GAI18007765/R1qb

The Motor Claims Department
Great American Insurance Company

Attn: Rachel

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. FBK 3272E .

We thank you for the instruction on 27/04/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/04/2018 at the premises of M/s LEONG SENG MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$	<u>11,559.50</u>	.
Revised Estimate Amount	: S\$	<u>5,919.50</u>	.
"Check" Items Amount	: S\$	<u>3,118.50</u>	.
Market Value	: S\$	<u>8,000.00</u>	.
Salvage Value	: S\$	<u>4,589.00</u>	.
Nett Value	: S\$	<u>3,411.00</u>	.

Description of Damage:
The motorbike sustained damages at the front & n/s portion.



Comments/ Present Status:
Damages consistent.
Repair cost not economical.
We have NOT authorise repair.

Yours faithfully

Rasul
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0882K
Vehicle Details	
Vehicle No.:	FBK3272E
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	YAMAHA
Vehicle Model:	MW 125 3-WHEELER
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	E3N9E028363
Chassis No.:	MLESE782000028363
Maximum Power Output:	-
Open Market Value:	\$2,838.00
Original Registration Date:	02 Jul 2015
First Registration Date:	02 Jul 2015
Transfer Count:	1
Actual ARF Paid:	\$426.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jul 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,401.00
COE Rebate Amount:	\$4,589.00
Total Rebate Amount:	\$4,589.00

The information contained herein is correct as at 30 Apr 2018

OK

8,000.00
 4,589.00

 3,411.00
 =====
 (3k)



(/)



Bike model

Yamaha MW125 Tricity

Type

Any

Price From

Any

Price To

Any

Class

Any

MORE SEARCH OPTIONS ▾

Q SEARCH VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Yamaha MW125 Tricity (/listing/usedbike/yamaha-yamaha-mw125-tricity/7235/)



(/listing/usedbike/yamaha-yamaha-mw125-tricity/7235/)

scd\$10300

Reg : 18/02/2016

Type: Three Wheeler

125cc

-

Visit us at Ah Fook Motor. Well maintained condition. Trade in welcome / Loan available.

Posted on : 22/04/2018

★ PAID AD ★ DEALER AD

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-MW125-TRICITY/7235/)

Yamaha MW125 Tricity (/listing/usedbike/yamaha-yamaha-mw125-tricity/1563/)



(/listing/usedbike/yamaha-yamaha-mw125-tricity/1563/)

-

Reg : 05/08/2015

Type: Three Wheeler

125cc

6500km

Excellent condition. Very low mileage 6,500km Well maintained. Selling due to the purchase of the car. Servicing promptly. Tip top condition. Very suitable for the new rider. Sincere buying o...

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/04/2018 15:53
Date Of Accident	22/04/2018 05:30
Exact Location Of Accident	ALONG TAI SENG LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK3272E
Insured/Policyholder	
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Co Reg No	200900882K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94703081
Alternative Phone No	OFFICE-94703081

Vehicle Particulars

Manufacturer	YAMAHA
Model	MW 125 3-WHEELER-125CC
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	MT20171699

Driver

Name of Driver	LIEW JUN SHEN
Passport No/FIN	G2956775T
Date Of Birth	02/03/1992
Occupation	OUTDOOR
Date Of Driving Pass	15/08/2017
Driving Experience	0 YEAR AND 8 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94703081
Fax Number	
Contact Number	OTHERS-94703081
Email Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. You must report correctly the details of the accident covered by the claim process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information you do must be as truthful and accurate as possible. Any false information provided will enable insurers to repudiate policy liability.
4. The insured and/or insurer may have a statutory obligation to file an admission of policy liability on the part of the insured or insureds.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurer if the insured is a Member of the Road Users' Mutualities Fund established by the Government of Singapore. Information of this policy is also for information and that upon completion will be available to the relevant authorities.
7. By the submission of this report to the insurer, you hereby consent to the admission of this report for the insured and insureds or insureds being made available to the relevant authorities.
8. **Consent under the Personal Data Protection Act (PDPA)** ⁽¹⁾

I, the undersigned, acknowledge, agree and consent that:

- (a) My insurer, my employer and the relevant authority (such as the Singapore Civil Defence Centre, Singapore Fire Department, Singapore Police and/or process my personal data (personal information) set out in this form) and my other personal information provided by me or assessed by my insurer, collectively the "Personal Information", and disclose and transfer such Personal Information to all insurers who have issued vehicles involved in this accident (or insurers who have issued vehicles involved in this accident shall be collectively referred to as the "Insurers", the insurer, lawyer(s) firm, the Monetary Authority of Singapore and any relevant government agency/authority such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of my claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or insurance;
 - (iii) carrying out and/or dealing with my obligations or requests to my insurer(s);
 - (iv) administering the claims, including the making of arrangements for payment, recovery, repair or replacement, which could involve disclosure of certain personal data about me to third parties about drivers of the vehicles involved in external events of interest (such as accidents and/or);
 - (v) compliance with applicable law, administrative provisions, directives and/or orders with the claims subject to the **Purposes**;
- (b) all insurers who have issued vehicles involved in this accident and the relevant lawyer(s) firm may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the insurers who submit to a third party service providers or agents including their lawyers, law firms, which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to process claims, for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (b) above may be shared, disclosed:
 - (i) to my insurers and/or any other third parties that assist in dealing with the claims, such as my insurer's medical fund, regulatory, law enforcement and government agencies as may be required for the purposes stated in (b);
 - (ii) to complying with requirements under any regulations, laws or court orders;

Policyholder / Insured
Date & Time

Driver's signature
(if driver is not the policyholder)
Date & Time

Reporting Centre/Insurer's signature
Name
No.

Sketch Plan #3



SINGAPORE
POLICE FORCE



201804250108

Police Station Of Origin
Traffic Police Division HQ
10 Collyer Avenue SINGAPORE 408888
Tel No: 67470000

Report No: 201804250108

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 25/04/2018 15:52	Vide Report No	Station Diary No
---	----------------	------------------

Informant's Particulars

Name of Informant LIEW JUN SHEN		Address NO 4 JALAN JERAU 10 80400 TAMAN PELANGI JOHOR BAHRU	
IC Type / ID No FIN NO / G2056775T		Contact No	Mobile: 94703081
Nationality MALAYSIAN		Email	
Sex Male	Age 26	Date of Birth 02/03/1992	Type of Informant Rider
Race		Language	Institution / School Name
Occupation COMPLIANCE OFFICER		Driving Licence Information Class: 2B 3C	Date of Expiry

General Information of the Accident

Type of Accident	Injury Conveyed By Ambulance	Drink Drive No	Date/Time of Accident 22/04/2018 05:30	Type of Location Straight Road
Location Along Road 1 TAI SENG LINK				
Weather Clear		Road Surface Dry		Road Speed Limit
Traffic Flow Two Way		Traffic Control Not Controlled		Traffic Volume Light
Type of Collision Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance Yes

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
FBK3272E	Motorcycle					0

Details of Person Involved

Any Pedestrian Involved	No
No. of Pedestrians Injured	NIL
Use of Pedestrian Crossing	NA

5971.50

1145.00

7116.50

20%

5693.20

45-5,700

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Repair limit \$4,500

4 days

Veh No : FBK3272E

Model : MW125

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Front panel		\$ 260.00		CRA /
2	Ignition cover	6635	\$ 165.00		CRA /
3	Inner panel	109	\$ 290.00		CRA /
4	Inner side panel	2	\$ 480.00	X	? xsu
5	Front cover	2	\$ 640.00		CRA /
6	Front side panel		\$ 95.00		SCA /
7	Front tie rod assy	Note: Parts PRICES UNAVAILABLE		\$ 385.00	? PA /
8	Front tie rod holder		\$ 265.00		? PA /
9	Front fender	2	\$ 460.00		CRA /
10	Front fender cover	2	\$ 390.00		CRA /
11	Front fork assy	2	\$ 1,960.00		CRA /
12	Fork under bracket	2	\$ 920.00	X	? xsu
13	Steering cone & bearing	2	\$ 180.00		na /
14	Front wheel rim		\$ 365.00	X	X ? xsu
15	Front wheel bearing	2	\$ 50.00	X	X ? xsu
16	Handle bar		\$ 250.00	X	? xsu
17	Handle balancer		\$ 35.00		cut /
18	Brake lever		\$ 50.00		SCA /
19	Mirror		\$ 70.00		SCA /
20	Lower panel		\$ 285.00		CRA /
21	Maintenance cover		\$ 155.00	X	? xsu
22	Side cover		\$ 335.00	X	Repair
23	Tail bar		\$ 280.00	X	Repair
24	Main stand		\$ 290.00	X	Repair
25	Clutch cover		\$ 380.00		SCA /
26	Clutch cover gasket		\$ 45.00		na /
27	Air filter box		\$ 320.00	X	X su
28	Headlamp assy		\$ 680.00		? CRA /
29	Headlamp stay		\$ 330.00	X	? xsu
30	Rear shock absorber		\$ 295.00	X	X su
31	Rear box		s/n \$ 200.00		150 n.s /
32	Respray		\$ 450.00		250
33	Co logo stickers		\$ 350.00		200 na /
34	Frame alignment		\$ 380.00		150 180
35	Transport 2 way		\$ 120.00		300 40
36	Labour		\$ 350.00		200 250
37	Rear box base		s/n \$ 75.00		CRA /
38					
39					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

\$ 10,705.00 \$ 1,925.00

Less 10%

\$ 1,070.50

\$ 9,634.50

11459.50

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBK3272E

Model : MW125

S/Nd	Parts Description	QTY	List Price	Nett Price	Remark
1	Front panel		\$ 260.00		CRA /
2	Ignition cover		\$ 165.00		CRA /
3	Inner panel		\$ 290.00		CRA /
4	Inner side panel	2	\$ 480.00		?
5	Front cover	2	\$ 640.00		CRA /
6	Front side panel		\$ 95.00		SCR /
7	Front tie rod assy		\$ 385.00	← 67	?
8	Front tie rod holder		\$ 265.00	← 67	?
9	Front fender	2	\$ 460.00		CRA /
10	Front fender cover	2	\$ 390.00		CRA /
11	Front fork assy	2	\$ 1,960.00		CRA /
12	Fork under bracket	2	\$ 920.00		?
13	Steering cone & bearing	2	\$ 180.00		SCR /
14	Front wheel rim		\$ 365.00		X
15	Front wheel bearing	2	\$ 50.00		X
16	Handle bar		\$ 250.00		?
17	Handle balancer		\$ 35.00		cut /
18	Brake lever		\$ 50.00		SCR /
19	Mirror		\$ 70.00		SCR /
20	Lower panel		\$ 285.00		CRA /
21	Maintenance cover		\$ 155.00		?
22	Side cover		\$ 335.00		Repair
23	Tail bar		\$ 280.00		Repair
24	Main stand		\$ 290.00		Repair
25	Clutch cover		\$ 380.00		SCR /
26	Clutch cover gasket		\$ 45.00		SCR /
27	Air filter box		\$ 320.00		X
28	Headlamp assy		\$ 680.00	← 67	?
29	Headlamp stay		\$ 330.00		?
30	Rear shock absorber		\$ 295.00		X
31	Rear box			\$ 200.00	150 MIS /
32	Respray			\$ 450.00	250
33	Co logo stickers			\$ 350.00	200 SCR /
34	Frame alignment			\$ 380.00	150 180
35	Transport 2 way			\$ 120.00	38 40
36	Labour			\$ 350.00	200 250
37	Rear box base			\$ 75.00	CRA /
38					
39					

Less 10%

\$ 10,705.00 \$ 1,925.00

\$ 1,070.50

\$ 9,634.50

Signature:
30/5/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

TO WHOM IT MAY CONCERN

I hereby acknowledge having received from the under-mentioned repairer my vehicle No. FBK 3272 E which has been repaired to my satisfaction and I admit that the payment of the account for such repaired by Leong Seng Motor Pte is in full discharge of my claim under No. _____ in respect of the damage caused to the said vehicle as a result of the accident which occurred on 22/4/18 at along Tai Seng Link.

[Signature]

Witnessed by Repairer

DATE 30/5/18

Jeremy Quek
Manager
Hd, Fleet Management Section
Logistics Department
Certis CISCO

[Signature]

Signature of Insured

NRIC NO. S8138725 G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18007765/R1qbe2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 09-10-2018	
		Code : GAI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	FBK 3272E
Policy No.	MT20171699	Coverage (\$)	0.00
Claim No.	CLMOMVM000000255	Excess (\$)	750.00
Assign From	RACHEL TAN	Assign Date	27/04/2018
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA MW 125 3-WHEELER	c.c	125
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MLESE782000028363	Colour	MULTI COLOUR
Odometer	119387	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	90/90-14 (D)	DUNLOP	3/3 mm
L/H Front Tyre			mm
R/H Rear Tyre	110/90-12	DUNLOP	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/04/2018	Inspection Date	27/04/2018
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.		
5a. Remarks			
A)THE MARKET VALUE IS S\$8,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 3272E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT PANEL	CRACKED	260.00	260.00
1	IGNITION COVER	CRACKED	165.00	165.00
1	INNER PANEL	CRACKED	290.00	290.00
2	INNER SIDE PANEL	SERVICEABLE	480.00	-
2	FRONT COVER	CRACKED	640.00	640.00
1	FRONT SIDE PANEL	SCRATCHED	95.00	95.00
1	FRONT TIE ROD ASSY	BENT	385.00	385.00
1	FRONT TIE ROD HOLDER	BENT	265.00	265.00
2	FRONT FENDER	CRACKED	460.00	460.00
2	FRONT FENDER COVER	CRACKED	390.00	390.00
2	FRONT FORK ASSY	CUT	1,960.00	1,960.00
2	FORK UNDER BRACKET	SERVICEABLE	920.00	-
2	STEERING CONE & BEARING	NECESSARY	180.00	180.00
1	FRONT WHEEL RIM	SERVICEABLE	365.00	-
2	FRONT WHEEL BEARING	SERVICEABLE	50.00	-
1	HANDLE BAR	SERVICEABLE	250.00	-
1	HANDLE BALANCER	CUT	35.00	35.00
1	BRAKE LEVER	SCRATCHED	50.00	50.00
1	MIRROR	SCRATCHED	70.00	70.00
1	LOWER PANEL	CRACKED	285.00	285.00
1	MAINTENANCE COVER	SERVICEABLE	155.00	-
1	SIDE COVER	TO REPAIR SEE LABOUR	335.00	-
1	TAIL BAR	TO REPAIR SEE LABOUR	280.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	290.00	-
1	CLUTCH COVER	SCRATCHED	380.00	380.00
1	CLUTCH COVER GASKET	NECESSARY	45.00	45.00
1	AIR FILTER BOX	SERVICEABLE	320.00	-
1	HEADLAMP ASSY	CRACKED	680.00	680.00
1	HEADLAMP STAY	SERVICEABLE	330.00	-

Report Ref No. CS/GAI18007765/R1qbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SHOCK ABSORBER	SERVICEABLE	295.00	-
	LESS 10% DISCOUNT		-1,070.50	-663.50
			9,634.50	5,971.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOX (SN)	MISSING	200.00	150.00
1	CO LOGO STICKERS (SN)	NECESSARY	350.00	200.00
1	REAR BOX BASE (SN)	CRACKED	75.00	75.00
			625.00	425.00
	<u>LABOUR</u>			
	RESPRAY.		450.00	250.00
	FRAME ALIGNMENT.		380.00	180.00
	TRANSPORT 2 WAY.		120.00	40.00
	LABOUR. INCLUSIVE OF THE REPAIR OF SIDE COVER, TAIL BAR AND MAIN STAND.		350.00	250.00
			1,300.00	720.00
	GRAND TOTAL		11,559.50	7,116.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00
	LESS EXCESS			-750.00
	NETT LIABILITY			3,750.00

Report Ref No. CS/GAI18007765/R1qbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.