

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SKB969P

No.	Qty	List Items			
1	1	Rear bumper	B1	\$ 1,608.35	✓
2	1	Rear bumper lower centre spoiler	Del/br	\$ 380.90	✓
3	1	Rear bumper lower RH spoiler	\$ Bn	156.10	✓
4	1	Rear bumper tow cover	\$ Del	41.80	✓
5	2	Rear bumper reverse sensor	o/s Per	\$ 533.70	✓
6	1	Rear bumper RH reflector	\$	134.15	?
7	2	Rear bumper side retainer	\$ Sn	285.10	X
8	1	Rear bumper inner reinforcement	\$	867.10	?
9	1	Rear tailgate lower	B1	\$ 1,749.35	X
10	1	Rear tailgate centre "BMW" logo	\$ Nn	69.50	X
11	1	Rear tailgate "X5" emblem	\$ Nn	68.55	X
12	1	Rear tailgate top lock	\$ N	586.65	X
13	1	Rear tailgate weatherstrip	\$	270.45	?
14	1	RH taillamp	\$ Sn	453.45	X
15	1	Rear end panel	\$	1,140.45	?
16	1	Rear end panel top garnish	\$	217.45	?
17	1	Rear lower exhaust silencer/pipe Assy	\$	2,836.40	?
18	1	Rear RH lower exhaust chrome tail pipe	\$ Del	281.95	✓
19	1	Rear RH lower exhaust pipe heat shield	\$	363.25	?
20	1	Rear RH axle bracket	\$	318.10	?
			\$	12,362.75	
			Less 5%	\$ 618.14	
			Total :	\$ 11,744.61	

Special Nett Items				
21	1 set	Rear end panel sealant	\$ 80.00	?
			Total :	\$ 80.00

Labour				
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,200.00	?	
2	To putty and spray Spray Paintings charges.	\$ 1,100.00	7601	
3	To check wirings and lightings.	\$ 50.00	201	
4	To remove, refit and reset reverses sensors.	\$ 120.00	501	
5	To remove, refit rear tailgate fittings.	\$ Nn 80.00	X	
6	To remove, refit rear upholstery and attachments.	\$ 120.00	?	
7	To remove, refit rear lower exhaust pipe Assy.	\$ 150.00	201	
8	To supply and apply anti-rust treatment	\$ 90.00	?	

the Repairer of the following: Total : \$ 2,910.00

• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices subject to confirmation
Total Parts and Labour : \$ 14,734.61

• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notarised
L1 Sur &?
Resurvey After Paint