

ASS. REC. BY:

REF:

CS/CTI18007776/R164

Special Instruction:

SURVIVOR

Rasul

ASSIGNMENT (Office)

From (Person):

Adeline Ong

of

CT

Date/Time: 26/04/2018 624pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKH 640E

Insured:

GT 4072C

at Workshop n/s

Munich Automobile

Tel:

97228323

of

30 Tabern Gardens Crescent

Policy No:

DMCVSN1756541700

Claim No:

SNM18002143 CO2

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

24/04/2018

CA / REV / REP. / REV 24 HRS DS

08052018 @ 10am - 11am

H.O.D. Endorsement

Date/Time:

27/04/2018 936am

Person Contacted:

Wilber

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKH 640E - +
	GT 4072C - X
	Part by Part \$16027.42 (Red: 10529.78 : 39%)

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

D.O.A.

28/04/18

D.O.I

08/05/18

Survey held at

Munich

Des. of Damages: Frt / Res / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS DS

DS

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

[Signature]
28/6/2018

RECEIVED 20 JUN 2018

Date/Time: File Pass to?

☐

Preli. Report

08/6 Typist

☒

Final Report

Date/Time: File Return to?

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

} \$ - RS. \$

} Photos

} Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B. (\$) :

16027.42

Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

Refer to attach email.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

25 April 2018 at 2:45 PM

Date/Time:

25 April 2018 at 2:45 PM



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-062937
Date of Request: 25/04/2018

Your Ref No: Online Purchase

Munich Automobiles Pte Ltd
30 Teban Gardens Crescent
Singapore 608927

Dear Sir/Madam,

Enquiry Date: 25/04/2018
Enquiry By: Tan Kok Ting
TP Vehicle No.: GT4072C
Accident Date: 24/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GT4072C	China Taiping Insurance (Singapore) Pte. Ltd.	02/09/2017-01/09/2018	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0037**

Invoice Name & Address:

China Taiping Insurance (Singapore)
3 Anson Road #16-00
Springleaf Tower

Singapore

079909

Customer Name & Address:

Mr Lawrence Lee Mun Kong
75 Kismis Avenue

598252

Email: lawrenceleemk@yahoo.com.sg

Inv. Printed By: WIL Service Advisor:

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 54848	0	0		08/05/2018	10:59	1
Reg No.	Chassis No.	Model		Reg Date	Date In	Mileage
SKH640E	DX95946	FV92 F10	M5	31/10/2012		0
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	5199000	Remove damaged body parts and replace effected body parts		672.00	12.50		0.00	8,400.00 3,000
2	5199000	Vehicle diagnosis - carrying out the ABL and delete fault code		50.00	12.50		0.00	625.00
3	6199000	Check and secure wiring and electrical system		50.00	12.50		0.00	625.00 500
4	9999000	Painting rear bumper trim		76.00	12.50		0.00	950.00
5	9999000	Painting rear trunk lid		76.00	12.50		0.00	950.00
6	SUN	Sundry items		200.00	1.00		0.00	200.00 50
7	9999000	Painting rear spoiler		40.00	12.50		0.00	500.00 350

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0037**

Invoice Name & Address:

China Taiping Insurance (Singapore)
3 Anson Road #16-00
Springleaf Tower

Singapore

079909

Customer Name & Address:

Mr Lawrence Lee Mun Kong
75 Kismis Avenue

598252

Email: lawrenceleemk@yahoo.com.sg

Inv. Printed By: WIL Service Advisor:

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 54848	0	0		08/05/2018	10:59	3
Reg No.	Chassis No.	Model		Reg Date	Date in	Mileage
SKH640E	DX95946	FV92 F10	M5	31/10/2012		0
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
23		B010650 Mount LH		1.00	142.55	EACH	5.00	135.43 ✓
24		B010650 Mount RH		1.00	142.55	EACH	5.00	135.43 ✓
25		Carrier bumper rea		1.00	714.25	EACH	5.00	678.54 ✓
26		C010976C PROTECT.FOI		1.00	15.55	EACH	5.00	14.78 ✓
27		PROTECT.FOIL		1.00	15.55	EACH	5.00	14.78 ✓
28		A051010 Foil		2.00	4.75	EACH	5.00	9.03 ✓
29		Guide centre rear		1.00	75.05	EACH	5.00	71.30 ✓
30		Insert rear (trim)		1.00	184.50	EACH	5.00	175.28 ✓
31		bumper trim rear w		1.00	1,650.65	EACH	5.00	1,568.12 ✓
32		Bumper Cover rear		1.00	272.50	EACH	5.00	258.88 ✓
33		Adapter trim panel		1.00	64.70	EACH	5.00	61.47 ✓
34		Diffusor rear		1.00	180.50	EACH	5.00	171.48 ✓
35		Electr.drive		1.00	517.80	EACH	5.00	491.91 ✓
36		Handle		1.00	13.70	EACH	5.00	13.02 ✓
37		A060582 Tension spri		1.00	39.40	EACH	5.00	37.43 ✓
38		Return spring		1.00	86.90	EACH	5.00	82.56 ✓

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0037**

Invoice Name & Address:

China Taiping Insurance (Singapore)
3 Anson Road #16-00
Springleaf Tower

Singapore

079909

Customer Name & Address:

Mr Lawrence Lee Mun Kong
75 Kismis Avenue

598252

Email: lawrenceleemk@yahoo.com.sg

Inv. Printed By: WIL Service Advisor:

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 54848	0	0		08/05/2018	10:59	5
Reg No.	Chassis No.	Model		Reg Date	Date In	Mileage
SKH640E	DX95946	FV92 F10	M5	31/10/2012		0
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
55		Gasket		1.00	115.25	EACH	5.00	109.49
56		C030218D Plastic Nut		2.00	0.55	EACH	5.00	1.05
57		R. reflector		1.00	35.20	EACH	5.00	33.44
58		R. reflector		1.00	35.20	EACH	5.00	33.44
59		C010760A RUB BUFFER		2.00	1.90	EACH	5.00	3.61
60		A010632C PDC sensor		4.00	368.80	EACH	5.00	1,401.44
61		C010658B Gasket		4.00	5.05	EACH	5.00	19.19
62	NOTES			0.00	0.00		0.00	0.00

Third party claim against GT4072C

LKK Auto Consults DOA: 24/05/2018

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts 9,542.92
Surcharge 0.00
Labour 12,875.00
Sublet 0.00
Menus 0.00

Menu Subtotal:

22,417.92

V	Rate	Service/Goods	GST	Net	
S	7.00	22417.92	1569.25	G.S.T.	1,569.25
				Total	23,987.17
				Deposit	0.00
				Owing	23,987.17

Resul
Hp 90010068
6 days
PH
08/05/18 @ 1050
Resurvey by part.

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0037**

Invoice Name & Address:

China Taiping Insurance (Singapore)
3 Anson Road #16-00
Springleaf Tower

Singapore

079909

Customer Name & Address:

Mr Lawrence Lee Mun Kong
75 Kismis Avenue

598252

Email: lawrenceleemk@yahoo.com.sg

Inv. Printed By: WIL Service Advisor: Wilber Kuang

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 54848	24840	0	BK	22/06/2018	09:38	1
Reg No.	Chassis No.	Model		Reg Date	Date In	Mileage
SKH640E	DX95946	FV92 F10	M5	31/10/2012	15/05/2018	102522
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	5199000	Remove damaged body parts and replace effected body parts		240.00	12.50		0.00	3,000.00
2	5199000	Vehicle diagnosis - carrying out the ABL and delete fault code		50.00	12.50		0.00	625.00
3	6199000	Check and secure wiring and electrical system		40.00	12.50		0.00	500.00
4	9999000	Painting rear bumper trim		76.00	12.50		0.00	950.00
5	9999000	Painting rear trunk lid		76.00	12.50		0.00	950.00
6	SUN	Sundry items		50.00	1.00		0.00	50.00
7	9999000	Painting rear spoiler		28.00	12.50		0.00	350.00

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0037**

Invoice Name & Address:

China Taiping Insurance (Singapore)
3 Anson Road #16-00
Springleaf Tower

Singapore

079909

Customer Name & Address:

Mr Lawrence Lee Mun Kong
75 Kismis Avenue

598252

Email: lawrenceleemk@yahoo.com.sg

Inv. Printed By: WIL Service Advisor: Wilber Kuang

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 54848	24840	0	BK	22/06/2018	09:38	2
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SKH640E	DX95946	FV92 F10	M5	31/10/2012	15/05/2018	102522
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
8	9999000			44.00	12.50		0.00	550.00
		Painting rear diffuser						
9		Screw		8.00	0.55 EACH		5.00	4.18
10		Nut		6.00	1.35 EACH		5.00	7.70
11		Nut		2.00	0.90 EACH		5.00	1.71
12		Screw		3.00	3.70 EACH		5.00	10.55
13		Hex nut		9.00	5.05 EACH		5.00	43.18
14		Bolt		1.00	1.20 EACH		5.00	1.14
15		Hex screw		2.00	1.35 EACH		5.00	2.57
16		Blnd rvt nut		3.00	2.90 EACH		5.00	8.27
17		Blind rivet		6.00	1.25 EACH		5.00	7.13
18		Trunk lid		1.00	1,602.40 EACH		5.00	1,522.28
19		Set of mount		1.00	62.60 EACH		5.00	59.47
20		PROTECT.FOIL		1.00	15.55 EACH		5.00	14.78
21		PROTECT.FOIL		1.00	15.55 EACH		5.00	14.78
22		bumper trim rear wit		1.00	1,650.65 EACH		5.00	1,568.12

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667866 Fax: +65 65659098



ESTIMATE

Account No. **C0037**

Invoice Name & Address:

China Taiping Insurance (Singapore)
3 Anson Road #16-00
Springleaf Tower

Singapore

079909

Customer Name & Address:

Mr Lawrence Lee Mun Kong
75 Kismis Avenue

598252

Email: lawrenceleemk@yahoo.com.sg

Inv. Printed By: WIL Service Advisor: Wilber Kuang

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 54848	24840	0	BK	22/06/2018	09:38	3
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SKH640E	DX95946	FV92 F10	M5	31/10/2012	15/05/2018	102522
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
23		Bumper Cover rear pr		1.00	272.50	EACH	5.00	258.88
24		Primed M-rear spoil		1.00	573.75	EACH	5.00	545.07
25		Adhes. tape		1.00	48.60	EACH	5.00	46.17
26		Plaque "BMW" hood		1.00	69.50	EACH	5.00	66.03
27		Grommet		2.00	0.80	EACH	5.00	1.52
28		Model lettering "M5"		1.00	79.95	EACH	5.00	75.96
Menu Subtotal:								11,234.49
29	5199000	Replace supplementary parts		144.00	12.50		0.00	1,800.00
30		Trim		1.00	195.80	EACH	5.00	186.01
31		Mount LH		1.00	142.55	EACH	5.00	135.43
32		Mount RH		1.00	142.55	EACH	5.00	135.43
33		Carrier bumper rear		1.00	714.25	EACH	5.00	678.54
34		Guide centre rear		1.00	75.05	EACH	5.00	71.30

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

* CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



Munich Automobiles Pte Ltd

Company Reg No: 200910960R
GST Reg No: 200910960
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0037**

Invoice Name & Address:

China Taiping Insurance (Singapore)
3 Anson Road #16-00
Springleaf Tower

Singapore

079909

Customer Name & Address:

Mr Lawrence Lee Mun Kong
75 Kismis Avenue

598252

Email: lawrenceleemk@yahoo.com.sg

Inv. Printed By: WIL Service Advisor: Wilber Kuang

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 54848	24840	0	BK	22/06/2018	09:38	4
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SKH640E	DX95946	FV92 F10	M5	31/10/2012	15/05/2018	102522
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
35		Adapter		1.00	64.70	EACH	5.00	61.47
36		Diffusor rear		1.00	180.50	EACH	5.00	171.48
37		Rear muffler		1.00	2,199.80	EACH	5.00	2,089.81
38		Clamp bush		1.00	66.80	EACH	5.00	63.46
Menu Subtotal:								5,392.93
39	NOTES			0.00	0.00		0.00	0.00
Third party claim against GT4072C								
DOA:24.05.2018								
Released on 24.05.2018								
Menu Subtotal:								0.00

Parts	7,852.42	V	Rate	Service/Goods	GST	Net	16,627.42
Surcharge	0.00	S	7.00	16627.42	1163.92	G.S.T.	1,163.92
Labour	8,775.00					Total	17,791.34
Sublet	0.00					Deposit	0.00
Menus	0.00					Owing	17,791.34

Customer's Signature

Authorized Signature

* CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2018		26 Apr 2018 18:24 Edit Adj Rpt	S\$16,027.42 Edit Estimates	S\$16,027.42 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SANLI M & E ENGINEERING PTE LTD, ID: -								
Main Claimant:	LAWRENCE LEE MUN KONG, ID: S2585433J								
Vehicle Reg. No.:	SKH640E	Date of Loss:	24/04/2018 10:00 - :59 [65 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02143C02	Policy/Cover Note No.:	DMCVSN1756541700						
Vehicle Reg. No. (Insured):	GT4072C	Policy No. (Claimant):	SD17V11660						
		Excess:	S\$0.00						
Repairer:	Munich Automobiles Pte Ltd (HQ) 30 Teban Gardens Crescent, 608927 West Coast - Tel: 6566-7666								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/05/2018]								
Adj Asg. Remarks:	DEAR MARCUS/KALVIN, PLEASE CONDUCT SURVEY, CHECK CONSISTENCY OF THE DAMAGES AND DO A DIRECT SETTLEMENT.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKH640E (SNM18D02143C02)
[GT4072C]
TP
LAWRENCE LEE MUN KONG
Apr 24 2018 10:00AM
[SANLI M & E ENGINEERING PTE LTD]
Munich Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Video			1 per page	☒	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	25/04/18 21:14	Video - Accident [Linked Accident Report Documents]		Load MP4	
2	25/04/18 21:14	Video - Accident [Linked Accident Report Documents]		Load MP4	
Assessment Reports			1 per page	☒	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	25/04/18 15:58	Accident Statement		Load HTM	
2	25/04/18 21:14	Addendum Sheet		Load JPG	☒
3	25/04/18 21:39	Accident Statement Addm. #1		Load HTM	
Photos/Images			3 per page	☒	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
14	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
15	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
16	25/04/18 15:56	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
17	25/04/18 15:56	Driving License [Linked Accident Report Documents]		Load JPG	☒
18	25/04/18 15:56	Driving License [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/06/18 15:39	General View		Load JPG	☒
2	28/06/18 15:39	General View		Load JPG	☒
3	28/06/18 15:39	General View		Load JPG	☒
4	28/06/18 15:39	General View		Load JPG	☒
5	28/06/18 15:39	General View		Load JPG	☒
6	28/06/18 15:39	General View		Load JPG	☒
7	28/06/18 15:39	General View		Load JPG	☒
8	28/06/18 15:39	General View		Load JPG	☒

Video			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
				☒
9	28/06/18 15:39	General View	 Load JPG	☒
10	28/06/18 15:39	General View	 Load JPG	☒
11	28/06/18 15:39	General View	 Load JPG	☒
12	28/06/18 15:39	General View	 Load JPG	☒
13	28/06/18 15:39	General View	 Load JPG	☒
14	28/06/18 15:39	General View	 Load JPG	☒
15	28/06/18 15:39	General View	 Load JPG	☒
16	28/06/18 15:39	General View	 Load JPG	☒
17	28/06/18 15:39	General View	 Load JPG	☒
18	28/06/18 15:39	General View	 Load JPG	☒
19	28/06/18 15:39	General View	 Load JPG	☒
20	28/06/18 15:39	General View	 Load JPG	☒
21	28/06/18 15:39	General View	 Load JPG	☒
22	28/06/18 15:39	General View	 Load JPG	☒
23	28/06/18 15:39	General View	 Load JPG	☒
24	28/06/18 15:39	General View	 Load JPG	☒
25	28/06/18 15:39	General View	 Load JPG	☒
26	28/06/18 15:39	General View	 Load JPG	☒
27	28/06/18 15:39	General View	 Load JPG	☒
28	28/06/18 15:39	General View	 Load JPG	☒
29	28/06/18 15:39	General View	 Load JPG	☒
30	28/06/18 15:39	General View	 Load JPG	☒
31	28/06/18 15:39	General View	 Load JPG	☒
32	28/06/18 15:39	General View	 Load JPG	☒
33	28/06/18 15:39	General View	 Load JPG	☒
34	28/06/18 15:39	General View	 Load JPG	☒
35	28/06/18 15:39	General View	 Load JPG	☒
36	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
37	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
38	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
39	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
40	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
41	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
42	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
43	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
44	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
45	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
46	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
47	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
48	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
49	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
50	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
51	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
52	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
53	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
54	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
55	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
56	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
57	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
58	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
59	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
60	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
61	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
62	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
63	28/06/18 15:40	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
64	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
65	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
66	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
67	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
68	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
69	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
70	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
71	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
72	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
73	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
74	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
75	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
76	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
77	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
78	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
79	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
80	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
81	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
82	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
83	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
84	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
85	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
86	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
87	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
88	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
89	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
90	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
91	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
92	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
93	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
94	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
95	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
96	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
97	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
98	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
99	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
100	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
101	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
102	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
103	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
104	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
105	28/06/18 15:40	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/04/18 18:24	THIRD PARTY SKH640E -FROM MUNICH AUTO -TP ESTIMATE	 Load PDF	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/04/18 15:53	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	25/04/18 15:53	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒
3	25/04/18 15:57	Individual Statement [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/06/18 11:04	SUPPLEMENTARY PART	 Load PDF	

Linked Accident Report Documents

View

Video				1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	25/04/18 21:14	Video - Accident		Load MP4	
2	25/04/18 21:14	Video - Accident		Load MP4	

Assessment Reports				1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	25/04/18 15:58	Accident Statement		Load HTM	
2	25/04/18 21:14	Addendum Sheet		Load JPG	☒
3	25/04/18 21:39	Accident Statement Addm. #1		Load HTM	

Photos/Images				3 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	25/04/18 15:56	Accident Photo		Load JPG	☒
2	25/04/18 15:56	Accident Photo		Load JPG	☒
3	25/04/18 15:56	Accident Photo		Load JPG	☒
4	25/04/18 15:56	Accident Photo		Load JPG	☒
5	25/04/18 15:56	Accident Photo		Load JPG	☒
6	25/04/18 15:56	Accident Photo		Load JPG	☒
7	25/04/18 15:56	Accident Photo		Load JPG	☒
8	25/04/18 15:56	Accident Photo		Load JPG	☒
9	25/04/18 15:56	Accident Photo		Load JPG	☒
10	25/04/18 15:56	Accident Photo		Load JPG	☒
11	25/04/18 15:56	Accident Photo		Load JPG	☒
12	25/04/18 15:56	Accident Photo		Load JPG	☒
13	25/04/18 15:56	Accident Photo		Load JPG	☒
14	25/04/18 15:56	Accident Photo		Load JPG	☒
15	25/04/18 15:56	Accident Photo		Load JPG	☒
16	25/04/18 15:56	Accident Photo		Load JPG	☒
17	25/04/18 15:56	Driving License		Load JPG	☒
18	25/04/18 15:56	Driving License		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail	Print
1	25/04/18 15:53	Sketch Plan		Load JPG	☒
2	25/04/18 15:53	Sketch Plan #2		Load JPG	☒
3	25/04/18 15:57	Individual Statement		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ⬆ ⬇				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007776/T1TBQ2

Date: 29/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1756541700

Claimant
Vehicle No : SKH640EInsured Vehicle
No : GT4072C

Date of Loss: 24/04/2018

Nature of Claim: TP

Claim
No: SNM18D02143C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKH640E

Make & Model: BMW M5,

Engine No: 21200296S63B44B

Reg. Date: 31/10/2012 (Man. Year: 2012)

Chassis No: WBSFV92010DX95946

Colour: Grey

Odometer: 101151 km

Engine Capacity: 4395 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/35Z R20

Rear Tyre Size: 265/35Z R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,225.71	7,902.42	4,323.29	35.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,475.00	8,125.00	6,350.00	43.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,700.71	16,027.42	10,673.29	39.97
+ GST 7.00/7.00% (S\$)	1,869.05	1,121.92	747.13	39.97
Nett Amount (S\$)	28,569.76	17,149.34	11,420.42	39.97

INSPECTION

Date of Assignment: 26/04/2018

Date Inspected: 08/05/2018 Inspected At:

Munich Automobiles Pte Ltd (HQ)
30 Teban Gardens Crescent
Singapore 608927

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2018)
Parts: 143	BMW M5 (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKH640E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY ITEMS	Necessary	200.00 FS	*50.00 FS
2	1		*SCREW (8 PCS)	Necessary	4.18 FS	*4.18 FS
3	1		*NUT (6 PCS)	Necessary	7.70 FS	*7.70 FS
4	1		*NUT (2 PCS)	Necessary	1.71 FS	*1.71 FS
5	1		*SCREW (3 PCS)	Necessary	10.55 FS	*10.55 FS
6	1		*HEX NUT (9 PCS)	Necessary	43.18 FS	*43.18 FS
7	1		*BOLT	Necessary	1.14 FS	*1.14 FS
8	1		*HEX SCREW (2 PCS)	Necessary	2.57 FS	*2.57 FS
9	1		*BIND RVT NU (3 PCS)	Necessary	8.27 FS	*8.27 FS
10	1		*BIND RIVET (6 PCS)	Necessary	7.13 FS	*7.13 FS
11	1		*LEFT TRUNK L	Serviceable	107.97 FS	*- FS
12	1		*RIGHT TRUNK	Serviceable	107.97 FS	*- FS
13	1		*TRUNK LID	Bent	1,522.28 FS	*1,522.28 FS
14	1		*MOUNTING	Serviceable	59.81 FS	*- FS
15	1		*SET OF MOUNT	Necessary	59.47 FS	*59.47 FS
16	1		*MOUNT LH	Cracked	135.43 FS	*135.43 FS
17	1		*MOUNT RH	Cracked	135.43 FS	*135.43 FS
18	1		*CARRIER BUMPER REA	Bent	678.54 FS	*678.54 FS
19	1		*PROTECT .FOI	Necessary	14.78 FS	*14.78 FS
20	1		*PROTECT .FOIL	Necessary	14.78 FS	*14.78 FS
21	2		*FOIL	Serviceable	9.03 FS	*- FS
22	1		*GUIDE CENTRE REAR	Cracked	71.30 FS	*71.30 FS
23	1		*INSERT REAR (TRIM)	Serviceable	175.28 FS	*- FS
24	1		*BUMPER TRIM REAR W	Deformed	1,568.12 FS	*1,568.12 FS
25	1		*BUMPER COVER REAR	Cut	258.88 FS	*258.88 FS
26	1		*ADAPTER TRIM PANEL	Cracked	61.47 FS	*61.47 FS
27	1		*DIFFUSOR REAR	Cracked	171.48 FS	*171.48 FS
28	1		*ELECTR .DRIVE	Serviceable	491.91 FS	*- FS
29	1		*HANDLE	Serviceable	13.02 FS	*- FS
30	1		*TENSION SPRI	Serviceable	37.43 FS	*- FS
31	1		*RETURN SPRING	Serviceable	82.56 FS	*- FS
32	1		*SPINDLE DRIV	Serviceable	496.52 FS	*- FS
33	1		*DRIVE	Serviceable	496.52 FS	*- FS
34	1		*BOWDEN CABLE	Serviceable	34.11 FS	*- FS
35	1		*BOWDEN CABLE	Serviceable	34.11 FS	*- FS
36	2		*BUFFER	Serviceable	53.01 FS	*- FS
37	1		*TRUNK LID LOCK TOP	Serviceable	201.26 FS	*- FS
38	1		*BOOT LID /TAILGATE	Serviceable	44.84 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	6		*PLUG	Serviceable	5.99 FS	*- FS
40	1		*HEAT INSULAT	Serviceable	30.50 FS	*- FS
41	1		*SOUND INSULA	Serviceable	30.50 FS	*- FS
42	1		*TRIM ,DRIP R	Serviceable	15.96 FS	*- FS
43	1		*TRIM ,DRIP R	Serviceable	15.96 FS	*- FS
44	1		*PRIMED M-REAR SPO	Necessary	545.07 FS	*545.07 FS
45	1		*ADHES ,TAPE	Necessary	46.17 FS	*46.17 FS
46	1		*LEFT SUPPORT	Serviceable	12.64 FS	*- FS
47	1		*RIGHT SUPPORT	Serviceable	14.73 FS	*- FS
48	1		*GASKET	Serviceable	109.49 FS	*- FS
49	2		*PLASTIC NUT	Serviceable	1.05 FS	*- FS
50	1		*R.REFLECTOR	Serviceable	33.44 FS	*- FS
51	1		*R.REFLECTOR	Serviceable	33.44 FS	*- FS
52	2		*RUB BUFFER	Serviceable	3.61 FS	*- FS
53	4		*PDC SENSOR	Serviceable	1,401.44 FS	*- FS
54	4		*GASKET	Serviceable	19.19 FS	*- FS
55	1		*PLAQUE BMW HOOD	Necessary	66.03 FS	*66.03 FS
56	1		*GROMMET (2 PCS)	Necessary	1.52 FS	*1.52 FS
57	1		*MODEL LETTERING M5	Necessary	75.96 FS	*75.96 FS
58	1		*TRIM	Cut	186.01 FS	*186.01 FS
59	1		*REAR MUFFLER	Bent	2,089.81 FS	*2,089.81 FS
60	1		*CLAMP BUSH	Necessary	63.46 FS	*63.46 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	12,225.71	7,902.42
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE DAMAGED BODY PARTS AND REPLACE EFFECTED BODY PARTS	New	8,400.00	3,000.00
2	VEHICLE DIAGNOSIS -CARRYING OUT THE ABL AND DELETE FAULT CODE	New	625.00	625.00
3	CHECK AND SECURE WIRING AND ELECTRICAL SYSTEM	New	625.00	500.00
4	PAINTING REAR BUMPER TRIM	New	950.00	950.00
5	PAINTING REAR TRUNK LID	New	950.00	950.00
6	PAINTING REAR SPOILER	New	500.00	350.00
7	PAINTING REAR DIFFUSER	New	625.00	550.00
8	LABOUR	New	1,800.00	1,200.00
Gross Labour Cost (S\$)			14,475.00	8,125.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >