

15/9/2011

INS. CASE OWNER:

Franchura

CC 4 / AXA 1800

7777, Flyb352

LKK:
IDAC:

Surveyor:

Enlin

DOI:

ASSIGNMENT

20/4/18

Date / Time:

27/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLH 8190Y

Claim No.:

S8MOUFES / 42084

Name of Insured:

BOMCO CAR RENTAL PLC

Policy No.:

VPK / P1305555

Insured Tel No.:

HP:

Make / Model:

HYUNDAI

Excess Sec II : \$\$

D.O.A.:

20/4/18

Place of Accident:

SIMEI AVE

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

WEO KHU KHU

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHC 6729C

SLH 8842A



INSRS:

WSP:

Tel:

Liability:

RMKS:

premier



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
9/5/18	SHC 6729C - 7	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OE:	
		After call ltr to OE:	24/5/2018 vic-ou 25/5
24/5/2018 2.10pm	Spoke to OJD, confirm 3 car chain collision. OJD is last car. Liability is clear, send letter to OJ.	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
		After call ltr to OE:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Towing Invoice	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
		Others:	<input type="checkbox"/> <input type="checkbox"/>
PRELIMINARY ADVICE	Date/Time: 21/6/18 Sent By: PM		

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS (days) Reduction: %		Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 21-6-18 Confirm with GARY		Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 28		If NO or B 28, Ass. Lia : 100
Repair Cost:	SS 12,305		(3 car chain collision, OJ last car)
Loss of Rental (LOR):	SS 659.49 (6.5 days) X 101.46		COPY SENT
Loss of Use (LOU):	SS (\$ x 6.5 days)		
Loss of Income (LOI):	SS 260 (\$ 40 x 6.5 days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search	SS 2.XX		1) Claim status: Normal/Reject/Private Settle
Medical:	SS -		2) Report Format:
Disbursement:	SS - (e.g. Tow/Independent)		3) Survey fee:
Legal Cost	SS -		
Total:	SS 13,226.49 Global Sum SS: 13,150.XX		
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 13,150.XX	Name 1: PREMIER AUTOMOTIVE SERVICES PTE LTD	
Payee 2: (Strike if N.A.)	SS X	Name 2: X	
Payee 3: (Strike if N.A.)	SS X	Name 3: X	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18007777/K1jb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 27-04-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLH 8190Y	Veh. Inspected	SHC 6329C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/04/2018	Inspection Date	26/04/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6329 C

1 pc	Bonnet ✓	\$	✓979.00
1 pc	Bonnet insulator X	\$	219.00
1 pc	Bonnet lock X	\$	36.00
1 pc	Bonnet lifter X	\$	70.00
1 pc	Bonnet lock base X	\$	13.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 X	\$	46.00
1 pc	Bonnet weatherstrip X	\$	58.00
1 pc	Bonnet lock cover X	\$	15.00
1 pc	Bonnet cable long X	\$	25.00
1 pc	Bonnet cable short X	\$	15.00
1 pc	Bonnet grille ✓	\$	✓385.00
1 pc	Support panel ✓	\$	✓645.00
1 pc	Front bumper ✓	\$	✓531.00
1 pc	Front bumper emblem ✓	\$	✓44.00
1 pc	Front bumper centre grille ✓	\$	✓174.00
1 pc	Front bumper lower stiffer X	\$	134.00
1 pc	Front bumper tow hook cover X	\$	14.00
1 pc	Front bumper lip X	\$	52.00
1 pc	Front bumper inner sponge ?	\$? 110.00
1 pc	Front bumper reinforcement ?	\$? 328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 ?	\$? 32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 ?	\$? 32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 ?	\$? 32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 n/s X o/s ✓	\$	2,056.00 ✓
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 X	\$	132.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00 X	\$	102.00
1 pc	Air con condenser ✓	\$	✓805.00
1 pc	Radiator ?	\$? 669.00
1 pc	Washer tank motor ?	\$? 48.00
1 pc	Washer tank ?	\$? 47.00
1 pc	Air duct ?	\$? 210.00
1 pc	Boot lid ✓	\$	✓1,119.00
1 pc	Boot lid lock X	\$	99.00
1 pc	Bootlid lock cable X	\$	35.00
1 pc	Bootlid striker X	\$	21.00
1 pc	Bootlid emblem ✓	\$	✓27.00
1 pc	Bootlid CRDi ✓	\$	✓29.00
1 pc	Boot lid rubber weatherstrip X	\$	96.00
1 pc	Boot lid lower garnish ✓	\$	✓290.00
2 pcs	Bootlid hinge @ \$66.00 ✓	\$	✓132.00
2 pcs	Bootlid hinge torsion bar @ \$33.00 X	\$	66.00
1 pc	Bootlid inner trim X	\$	190.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6329 C

1 pc	End panel /	\$ 250.00
1 pc	End panel garnish ?	\$ 74.00
1 pc	Towing hook bracket X	\$ 68.00
1 pc	Spare tyre clamp X	\$ 6.00
1 pc	Rear muffler assy /	\$ 1,009.00
1 pc	Rear exhaust pipe hanger X	\$ 49.00
1 pc	Exhaust pipe heat protector X	\$ 71.00
2 pcs	Rear o/s & n/s tail lamp @ \$421.00 /	\$ 842.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00 X	\$ 700.00
1 pc	Rear bumper /	\$ 696.00
1 pc	Rear bumper lower cover /	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	\$ 58.00
1 pc	Rear bumper inner sponge ? /	\$ 114.00
1 pc	Rear bumper reinforcement ? /	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$ 36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 /	\$ 92.00
		<hr/>
		\$ 15,184.00
	Less 10%	\$ 1,518.40
		<hr/>
		\$ 13,665.60

S/NETT

1 set	Rear bumper clips /	\$ 48.00
1 set	End panel inner garnish clips /	\$ 30.00
1 set	Bootlid inner trim clips X	\$ 52.00
1 set	Bootlid lower garnish clips X	\$ 60.00
1 set	Bootlid stickers /	\$ 100.00
1 set	Reverse sensor /	\$ 280.00 200.00
1 pc	Rear o/s fender sticker /	\$ 60.00
1 set	Floorboard compartment insulating paddings X	\$ 120.00
1 pc	Front no. plate with casing /	\$ 50.00 50.00
1 pc	Front bumper clips /	\$ 48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00 o/s o/s ✓ n/s X	\$ 12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00 o/s ✓ n/s X	\$ 6.00
1 set	Bonnet insulator clips X	\$ 52.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6329 C

Towing Fee	\$	50.00	✓
Sundry	\$	50.00	20
To check for wiring and to focus head lamps	\$	80.00	20
To dismantle / replace exhaust pipe	\$	120.00	60
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, rear o/s fender, etc.	\$	1,600.00	1200
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear o/s fender, front bumper, bonnet grille, bonnet	\$	2,000.00	1620
To apply rustproofing on the repaired and replaced panels.	\$	250.00	50
	\$	<u>19,033.60</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahri iUKK4
M 26/4/18 1530hr
8 Rep.
4/s
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dam(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

◀ Service Request Details

Claim

S8M00F8S

Reference

None 

Loss Date

April 26, 2018

Request Date

April 26, 2018

Due Date

May 4, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*26042018 @ 2.49pm
Vnort veh in.
Kalvin*

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHC6329C

Make

TPVD KIA

Service Address

...

Primary Contact/Insured

KOMOCO CAR RENTALS PTE LTD
253 ALEXANDRA ROAD, #01-02, 159936, Singapore
64758888

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6329 C

1 pc	Bonnet — <i>Det</i>	\$	979.00
1 pc	Bonnet insulator <i>X suc</i>	\$	219.00
1 pc	Bonnet lock <i>X suc</i>	\$	36.00
1 pc	Bonnet lifter <i>X suc</i>	\$	70.00
1 pc	Bonnet lock base <i>X suc</i>	\$	13.00
7 pc	Bonnet hinge o/s & n/s @ \$23.00 <i>X suc</i>	\$	46.00
1 pc	Bonnet weatherstrip <i>X suc</i>	\$	58.00
1 pc	Bonnet lock cover <i>X suc</i>	\$	15.00
1 pc	Bonnet cable long <i>X suc</i>	\$	25.00
1 pc	Bonnet cable short <i>X suc</i>	\$	15.00
1 pc	Bonnet grille — <i>con</i>	\$	385.00
1 pc	Support panel — <i>Det</i>	\$	645.00
1 pc	Front bumper — <i>Det</i>	\$	531.00
1 pc	Front bumper emblem — <i>nc</i>	\$	44.00
1 pc	Front bumper centre grille — <i>con</i>	\$	174.00
1 pc	Front bumper lower stiffener — <i>Det</i>	\$	134.00
1 pc	Front bumper tow hook cover <i>X suc</i>	\$	14.00
1 pc	Front bumper lip <i>X repair</i>	\$	52.00
1 pc	Front bumper inner sponge <i>✓</i>	\$	110.00
1 pc	Front bumper reinforcement <i>✓ Det</i>	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>✓ con</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>✓ con</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>✓ con</i>	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 <i>n/s x suc ob ✓ con</i>	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 <i>X suc</i>	\$	132.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00 <i>X suc</i>	\$	102.00
1 pc	Air con condenser — <i>Det</i>	\$	805.00
1 pc	Radiator <i>✓ Det</i>	\$	669.00
1 pc	Washer tank motor <i>X suc</i>	\$	48.00
1 pc	Washer tank <i>✓ con</i>	\$	47.00
1 pc	Air duct <i>✓ con</i>	\$	210.00
1 pc	Boot lid — <i>Det</i>	\$	1,119.00
1 pc	Boot lid lock — <i>and</i>	\$	99.00
1 pc	Bootlid lock cable <i>X suc</i>	\$	35.00
1 pc	Bootlid striker <i>X suc</i>	\$	21.00
1 pc	Bootlid emblem — <i>nc</i>	\$	27.00
1 pc	Bootlid CRDi — <i>nc</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X suc</i>	\$	96.00
1 pc	Boot lid lower garnish — <i>con</i>	\$	290.00
2 pcs	Bootlid hinge @ \$66.00 — <i>Det</i>	\$	132.00
2 pcs	Bootlid hinge torsion bar @ \$33.00 <i>X suc</i>	\$	66.00
1 pc	Bootlid inner trim <i>X suc</i>	\$	190.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6329 C

1 pc	End panel — <i>dent</i>	\$ 250.00
1 pc	End panel garnish <i>✓ cr</i>	\$ 74.00
1 pc	Towing hook bracket <i>x su</i>	\$ 68.00
1 pc	Spare tyre clamp <i>x su</i>	\$ 6.00
1 pc	Rear muffler assy — <i>dent</i>	\$ 1,009.00
1 pc	Rear exhaust pipe hanger — <i>to</i>	\$ 49.00
1 pc	Exhaust pipe heat protector <i>x su</i>	\$ 71.00
2 pcs	Rear o/s & n/s tail lamp @ \$421.00 — <i>cr</i>	\$ 842.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00 <i>x su</i>	\$ 700.00
1 pc	Rear bumper — <i>dent</i>	\$ 696.00
1 pc	Rear bumper lower cover — <i>cr</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>x su</i>	\$ 58.00
1 pc	Rear bumper inner sponge <i>?</i> — <i>to</i>	\$ 114.00
1 pc	Rear bumper reinforcement <i>?</i> — <i>cr</i>	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>✓ cr</i>	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>✓ cr</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>✓ cr</i>	\$ 36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 — <i>cr</i>	\$ 92.00
		\$ 15,184.00
	Less 10%	\$ 1,518.40
		\$ 13,665.60 <i>10800</i>

S/NETT

1 set	Rear bumper clips — <i>acc</i>	\$ 48.00
1 set	End panel inner garnish clips — <i>acc</i>	\$ 30.00
1 set	Bootlid inner trim clips <i>x "</i>	\$ 52.00
1 set	Bootlid lower garnish clips <i>x "</i>	\$ 60.00
1 set	Bootlid stickers — <i>acc</i>	\$ 100.00
1 set	Reverse sensor — <i>shorted</i>	\$ 280.00 <i>200</i>
1 pc	Rear o/s fender sticker — <i>acc</i>	\$ 60.00
1 set	Floorboard compartment insulating paddings <i>x "</i>	\$ 120.00
1 pc	Front no. plate with casing — <i>missing</i>	\$ 50.00 <i>30</i>
1 pc	Front bumper clips — <i>acc</i>	\$ 48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00 <i>o/s ✓ n/s x "</i>	\$ 12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00 <i>o/s ✓ n/s x "</i>	\$ 6.00
1 set	Bonnet insulator clips <i>x "</i>	\$ 52.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6329 C

Towing Fee	\$	50.00 ✓
Sundry <i>net</i>	\$	50.00 20
To check for wiring and to focus head lamps	\$	80.00 20
To dismantle / replace exhaust pipe	\$	120.00 60
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, rear o/s fender, etc.	\$	1,600.00 1200
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear o/s fender, front bumper, bonnet grille, bonnet	\$	2,000.00 1620
To apply rustproofing on the repaired and replaced panels.	\$	250.00 50
	\$	<u>19,033.60</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahiri 10/10/14
N 26/4/18 1530km
8 Rep.
4/5
After Repair photo

9/5/18
total 45 \$11500 / 7 Rep.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

« Re:IA uploaded

Type

🔔 Question

Message

PLS VERIFY IS THE IS THE HEADLAMP DAMAGED THAT NEED TO BE REPLACED? IS THE RADIATOR DAMAGED?

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE L, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 07/05/2018

Survey Details:

Date of loss	26-Apr-18
Date of appointment	26-Apr-18
Date of survey	26-Apr-18
Location of survey	PREMIER AUTOMOTIVE SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 6329C
Make and Model	KIA OPTIMA 1.7 A
Date of registration	6/1/2015
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$	19,033.60
------------------	----	-----------

Proposed/Revised repair cost:

Parts	\$	9,533.60
Check items (estimate)	\$	1,585.80
Labour	\$	3,090.00
Total	\$	14,209.40
Lump Sum(if applicable)		\$

Number of days for repair	8
---------------------------	---

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLH 8190Y (Insd veh)	Model:	KIA OPTIMA 1.7(A) DIESEL
	SHC 6329C (TP veh)		
Date of Accident:	26/04/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$	20,365.95	
Final Repair Cost	:	\$	12,305.00	
Loss of Token Sum	:	\$	260.00	6.5 days at \$40.00 per day
Rental (if any)	:	\$	659.49	6.5 days
LTA / GIA Search Fee	:	\$	2.00	

Others: : \$

: \$

Final Settlement Sum (GLOBAL SUM) : \$ 13,150.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	PREMIER AUTOMOTIVE SERVICES PTE LTD	: \$ 13,150.00

NUR SHAQILAH BTE ABDOL
WAHAB

27/06/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

CLAIMS

MESSAGES

SERVICE REQUESTS

Service Request Details

Claim	S8M00F8S
Reference	CC4/ASM18007777/KI/ISS Date
Request Date	April 26, 2018
Due Date	April 26, 2018
Vendor Name	April 26, 2019
Type of Loss	LKK AUTO CONSULTANTS PTE LOSS LTD (TP)
Services	Third Party Vehicle Damage

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle

SHC6329C

Registration #

TPVD KIA

Make

OPTIMA-1.7 D (A)

Service Address

Model

Primary

Contact/Insured

KOMOCO CAR RENTALS PTE LTD

253 ALEXANDRA ROAD, #01-02,

159936, Singapore

64758888

Claim Handler

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP - LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 16, 2018
SLH8842A.pdf	Reports & Statement	GIA Report	CHAN Kian Chuan	May 8, 2018
Immediate Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	May 7, 2018
TP ESTIMATE-MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	April 27, 2018
SLH8190Y GIA REPORT.PDF	Reports & Statement	GIA Report	SHAH Kushal	April 26, 2018
SHC6329C GIA REPORT.PDF	Reports & Statement	GIA Report	SHAH Kushal	April 26, 2018
SLH8842A GIA REPORT.PDF	Reports & Statement	GIA Report	SHAH Kushal	April 26, 2018

Service Request Details

Claim	S8M00F8S
Reference	CC4/ASM18007777/K11jps Date
Request Date	April 26, 2018
Due Date	April 26, 2018
Vendor Name	April 26, 2019
Type of Loss	LKK AUTO CONSULTANTS PTE LOSS LTD (TP)
Services	Third Party Vehicle Services Damage

Vehicle Information

Incident Vehicle	SHC6329C
Registration #	TPVD KIA
Make	TPVD KIA
Model	OPTIMA-1.7 D (A)
Contact/Insured	Primary
	KOMOCO CAR RENTALS PTE LTD 253 ALEXANDRA ROAD, #01-02, 159936, Singapore 64758888

Actions

- Next Step
- Finish the work
- Complete Work
- More

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SHC6329C

Purchase Date
mm/dd/yyyy

Registration State

SINGAPORE

Registration Date *

01/06/2015

Mileage

451426

Age of Vehicle

3

Driver Details

CATEGORY Manufacturing Year

CATEGORY Driver Name

POLICY INFORMAT...

ASSESSMENT INFO... 2014

FNOL INFORMATI... KIONG NEO CHEE

CATEGORY Make

POST SURVEY INF...

CATEGORY Engine No
POLICY INFORMAT ...
ASSESSMENT INFO ... D4FDEH311890

CATEGORY Engine Capacity
POLICY INFORMAT ...
ASSESSMENT INFO ... 1685 cc

CATEGORY Sum Insured
POLICY INFORMAT ...
ASSESSMENT INFO ... 0

CATEGORY Market Value
POLICY INFORMAT ...
ASSESSMENT INFO ... 0

FNOL INFORMATI... 0
POST SURVEY INF ...
CATEGORY Driver License #

FNOL INFORMATI...
POST SURVEY INF ...

CATEGORY License Type
FNOL INFORMATI...
POST SURVEY INF ...

CATEGORY License Issue Date
FNOL INFORMATI...
POST SURVEY INF ... mm/dd/yyyy

CATEGORY License Expiration Date
FNOL INFORMATI...
POST SURVEY INF ... mm/dd/yyyy

CATEGORY Address

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

ACHILLES 7mm

Front right side

ACHILLES 7mm

Rear left side

ACHILLES 7mm

Rear right side

ACHILLES 7mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BITTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)		
	1	1			BONNET			Damaged	979		10		881.1		
	2	1			BONNET INSULATOR			Serviceable	0		10		0		
	3	1			BONNET LOCK			Serviceable	0		10		0		
	4	1			BONNET LIFTER			Serviceable	0		10		0		
	5	1			BONNET LOCK BASE			Serviceable	0		10		0		
	6	2			BONNET HINGE O/S & N/S			Serviceable	0		10		0		
	7	1			BONNET WEATHERSTRIP			Serviceable	0		10		0		
	8	1			BONNET LOCK COVER			Serviceable	0		10		0		
	9	1			BONNET CABLE LONG			Serviceable	0		10		0		
	10	1			BONNET CABLE SHORT			Serviceable	0		10		0		
	11	1			BONNET GRILLE			Cracked	385		10		346.5		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPL/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
<input type="checkbox"/>		26	2		FRONT BUMPER O/S & N/S FOG LAMP COVER		Serviceable	Serviceable	0		10		0
<input type="checkbox"/>		27	2		FRONT BUMPER O/S & N/S PROTECTOR		Serviceable	Serviceable	0		10		0
<input type="checkbox"/>		28	1		AIR CON CONDENSER		Bent	Bent	805		10		724.5
<input type="checkbox"/>		29	1		RADIATOR		Bent	Bent	669		10		602.1
<input type="checkbox"/>		30	1		WASHER TANK MOTOR		Serviceable	Serviceable	0		10		0
<input type="checkbox"/>		31	1		WASHER TANK MOTOR		Cracked	Cracked	47		10		42.3
<input type="checkbox"/>		32	1		AIR DUCT		Cracked	Cracked	210		10		189
<input type="checkbox"/>		33	1		BOOT LID		Damaged	Damaged	1119		10		1007.1
<input type="checkbox"/>		34	1		BOOT LID LOCK		Necessary	Necessary	99		10		89.1
<input type="checkbox"/>		35	1		BOOTLID LOCK CABLE		Serviceable	Serviceable	0		10		0
<input type="checkbox"/>		36	1		BOOTLID STRIKER		Serviceable	Serviceable	0		10		0
<input type="checkbox"/>		37	1		BOOTLID EMBLEM		Necessary	Necessary	27		10		24.3
<input type="checkbox"/>		38	1		BOOTLID CRDI		Necessary	Necessary	29		10		26.1
<input type="checkbox"/>		39	1		BOOT LID RUBBER WEATHERSTRIP		Serviceable	Serviceable	0		10		0
<input type="checkbox"/>		40	1		BOOT LID LOWER GARNISH		Cracked	Cracked	290		10		261

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
<input type="checkbox"/>	56	1			REAR BUMPER INNER SPONGE		Damaged	114	10				102.5
<input type="checkbox"/>	57	1			REAR BUMPER REINFORCEMENT		Cracked	507	10				546.3
<input type="checkbox"/>	58	2			REAR BUMPER STAY O/S & N/S		Cracked	54	10				97.2
<input type="checkbox"/>	59	2			REAR BUMPER REINFORCEMENT LOWER BRACKET		Cracked	16	10				32.4
<input type="checkbox"/>	60	2			REAR BUMPER REINFORCEMENT UPPER BRACKET		Cracked	18	10				32.4
<input type="checkbox"/>	61	2			REAR BUMPER REFLECTOR N/S & O/S		Cracked	46	10				82.8

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>	1		TOWING FEE.	50	0	0	Reviewing	
<input type="checkbox"/>	2		TO CHECK FOR WIRING AND TO FOCUS HEAD LAMPS.	20	0	0	Reviewing	
<input type="checkbox"/>	3		TO DISMANTLE / REPLACE EXHAUST PIPE.	60	0	0	Reviewing	
<input type="checkbox"/>	4		TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	20	0	0	Reviewing	
<input type="checkbox"/>	5		TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	50	0	0	Reviewing	

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary EDIT SR NO NAME ACTION AMOUNT COMMENT REMOVE

 1 DAYS OF REPAIR Reviewing 7 

 2 SET REAR BUMPER CLIPS Reviewing 48 NECESSARY 

 3 SET END PANEL INNER GARNISH CLIPS Reviewing 30 NECESSARY 

 4 SET BOOTLID INNER TRIM CLIPS Reviewing 0 NOT NECESSARY 

 5 SET BOOTLID LOWER GARNISH CLIPS Reviewing 0 NOT NECESSARY 

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	13	FRONT N/S & O/S HEAD LAMP SIDE CLIP	Reviewing	3	O/S NECESSARY / N/S NOT NECESSARY	
<input type="checkbox"/>	14	SET BONNET INSULATOR CLIPS	Reviewing	0	NOT NECESSARY	
<input type="checkbox"/>	15	SUNDRY	Reviewing	20	NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary Claim Amount \$14,420.00 Claim Amount \$14,420.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$3,070.00	\$3,070.00
Miscellaneous	\$550.00	\$550.00

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

<input type="button" value=""/>	1	FINAL LUMP SUM	Reviewing	11500		<input type="button" value=""/>
---------------------------------	---	----------------	-----------	-------	--	---------------------------------