

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	6	SET BOOTLID STICKERS	Reviewing	100	NECESSARY	
	7	SET REVERSE SENSOR	Reviewing	200	SHORTED	
	8	REAR O/S FENDER STICKER	Reviewing	60	NECESSARY	
	9	SET FLOORBOARD COMPARTMENT INSULATING PADDINGS	Reviewing	0	NOT NECESSARY	
	10	FRONT NO. PLATE WITH CASING	Reviewing	35	MISSING	
	11	FRONT BUMPER CLIPS	Reviewing	48	NECESSARY	
	12	FRONT N/S & O/S HEAD LAMP LOWER CLIP	Reviewing	6	O/S NECESSARY / N/S NOT NECESSARY	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/> 	6		TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT / WELD, CUT-OFF THE THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FLOORBOARD COMPARTMENT, REAR O/S FENDER, ETC.	1200	0	0	Reviewing	
<input type="checkbox"/> 	7		TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, FLOORBOARD COMPARTMENT, END PANEL, REAR O/S FENDER, FRONT BUMPER, BONNET GRILLE, BONNET.	1620	0	0	Reviewing	
<input type="checkbox"/> 	8		TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	50	0	0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
<input type="checkbox"/>	41	2			BOOTLID HINGE			Bent	66		10		118.8
<input type="checkbox"/>	42	2			BOOTLID HINGE TORSION BAR			Serviceable	0		10		0
<input type="checkbox"/>	43	1			BOOTLID INNER TRIM			Serviceable	0		10		0
<input type="checkbox"/>	44	1			END PANEL			Damaged	250		10		225
<input type="checkbox"/>	45	1			END PANEL GARNISH			Cracked	74		10		66.6
<input type="checkbox"/>	46	1			TOWING HOOK BRACKET			Serviceable	0		10		0
<input type="checkbox"/>	47	1			SPARE TYRE CLAMP			Serviceable	0		10		0
<input type="checkbox"/>	48	1			REAR MUFFLER ASSY			Bent	1009		10		908.1
<input type="checkbox"/>	49	1			REAR EXHAUST PIPE HANGER			Damaged	49		10		44.1
<input type="checkbox"/>	50	1			EXHAUST PIPE HEAT PROTECTOR			Serviceable	0		10		0
<input type="checkbox"/>	51	2			REAR O/ S & N/S TAIL LAMP			Cracked	421		10		757.8
<input type="checkbox"/>	52	2			BOOTLID N/S & O/S REFLECTOR			Serviceable	0		10		0
<input type="checkbox"/>	53	1			REAR BUMPER			Deformed	696		10		626.4
<input type="checkbox"/>	54	1			REAR BUMPER LOWER COVER			Cracked	206		10		185.4
<input type="checkbox"/>	55	2			REAR BUMPER SIDE BRACKET O/S & N/S			Serviceable	0		10		0

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTRR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)
	12	1			SUPPORT PANEL			Bent	645		10		580.5
	13	1			FRONT BUMPER			Deformed	531		10		477.9
	14	1			FRONT BUMPER EMBLEM			Necessary	44		10		39.6
	15	1			FRONT BUMPER CENTRE GRILLE			Cracked	174		10		156.6
	16	1			FRONT BUMPER LOWER STIFFER			Bent	134		10		120.6
	17	1			FRONT BUMPER TOW HOOK COVER			Serviceable	0		10		0
	18	1			FRONT BUMPER LIP			Repair	0		10		0
	19	1			FRONT BUMPER INNER SPONGE			Damaged	110		10		99
	20	1			FRONT BUMPER REINFORCEMENT			Bent	328		10		295.2
	21	2			FRONT BUMPER O/S & N/S SIDE RETAINER			Cracked	16		10		28.8
	22	2			FRONT BUMPER O/S & N/S UPPER BRACKET			Cracked	16		10		28.8
	23	2			FRONT BUMPER O/S & N/S SUPPORT BRACKET			Cracked	16		10		28.8
	24	1			N/S & O/S HEADLAMP (N/S)			Serviceable	0		10		0
	25	1			N/S & O/S HEADLAMP (O/S)			Cut	1028		10		925.2

Detailed Assessment

Inspection Date *

04/26/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/65R16

Rear Tyre Size

205/65R16

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... 57011657Z

POLICY INFORMAT... TPVD KIA

ASSESSMENT INFO... KIA

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy 

CATEGORY Model

POLICY INFORMAT... OPTIMA-1.7 D (A)

CATEGORY Age

ASSESSMENT INFO... OPTIMA 1.7(A) DIESEL

FNOL INFORMATI... 0

CATEGORY Type

POST SURVEY INF...

POLICY INFORMAT...

CATEGORY Occupation

ASSESSMENT INFO... 

FNOL INFORMATI... Unknown

CATEGORY Type of Paint

POLICY INFORMAT...

CATEGORY Education Qualification

ASSESSMENT INFO...

FNOL INFORMATI... Other

CATEGORY Chassis No

POLICY INFORMAT...

CATEGORY Driving Experience

ASSESSMENT INFO... KNAGM414MF5561403

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Messages
Invoices
History

Pending verification -
Direct Settlement

Additional Instructions

Add

Documents	Assessment	Metrics	Notes	STATUS	SHARE	CLONE
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	6/1/18 4:27 PM	11500	11500	Open	Share	Clone
SHAH Kushal	4/26/18 12:17 PM	14420	14420	Open	Share	Clone

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Pending verification -
Direct Settlement

Additional Instructions

Messages

Invoices

History

Documents Assessment Metrics Notes Document Type Document Sub Type



Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 1, 2018
IA - FOR QUANTUM MANDATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 1, 2018
SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 1, 2018
RE-SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 1, 2018