

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6329 C

1 pc	Bonnet ✓	\$	979.00
1 pc	Bonnet insulator X	\$	219.00
1 pc	Bonnet lock X	\$	36.00
1 pc	Bonnet lifter X	\$	70.00
1 pc	Bonnet lock base X	\$	13.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 X	\$	46.00
1 pc	Bonnet weatherstrip X	\$	58.00
1 pc	Bonnet lock cover X	\$	15.00
1 pc	Bonnet cable long X	\$	25.00
1 pc	Bonnet cable short X	\$	15.00
1 pc	Bonnet grille ✓	\$	385.00
1 pc	Support panel ✓	\$	645.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper centre grille ✓	\$	174.00
1 pc	Front bumper lower stiffer X	\$	134.00
1 pc	Front bumper tow hook cover X	\$	14.00
1 pc	Front bumper lip X	\$	52.00
1 pc	Front bumper inner sponge ?	\$	110.00
1 pc	Front bumper reinforcement ?	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 ?	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 nb x ob ✓	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 X	\$	132.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00 X	\$	102.00
1 pc	Air con condenser ✓	\$	805.00
1 pc	Radiator ?	\$	669.00
1 pc	Washer tank motor ?	\$	48.00
1 pc	Washer tank ?	\$	47.00
1 pc	Air duct ?	\$	210.00
1 pc	Boot lid ✓	\$	1,119.00
1 pc	Boot lid lock X	\$	99.00
1 pc	Bootlid lock cable X	\$	35.00
1 pc	Bootlid striker X	\$	21.00
1 pc	Bootlid emblem ✓	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	Boot lid rubber weatherstrip X	\$	96.00
1 pc	Boot lid lower garnish ✓	\$	290.00
2 pcs	Bootlid hinge @ \$66.00 ✓	\$	132.00
2 pcs	Bootlid hinge torsion bar @ \$33.00 X	\$	66.00
1 pc	Bootlid inner trim X	\$	190.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6329 C

1 pc	End panel /	\$	250.00
1 pc	End panel garnish ?	\$	74.00
1 pc	Towing hook bracket X	\$	68.00
1 pc	Spare tyre clamp X	\$	6.00
1 pc	Rear muffler assy /	\$	1,009.00
1 pc	Rear exhaust pipe hanger X	\$	49.00
1 pc	Exhaust pipe heat protector X	\$	71.00
2 pcs	Rear o/s & n/s tail lamp @ \$421.00 /	\$	842.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00 X	\$	700.00
1 pc	Rear bumper /	\$	696.00
1 pc	Rear bumper lower cover /	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	\$	58.00
1 pc	Rear bumper inner sponge /	\$	114.00
1 pc	Rear bumper reinforcement /	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 /	\$	92.00
		\$	15,184.00
		Less 10%	\$ 1,518.40
			\$ 13,665.60

S/NETT

1 set	Rear bumper clips /	\$	48.00
1 set	End panel inner garnish clips /	\$	30.00
1 set	Bootlid inner trim clips X	\$	52.00
1 set	Bootlid lower garnish clips X	\$	60.00
1 set	Bootlid stickers /	\$	100.00
1 set	Reverse sensor /	\$	280.00 200
1 pc	Rear o/s fender sticker /	\$	60.00
1 set	Floorboard compartment insulating paddings X	\$	120.00
1 pc	Front no. plate with casing /	\$	50.00 35
1 pc	Front bumper clips /	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00 o/s o/s ✓ n/s X	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00 o/s ✓ n/s X	\$	6.00
1 set	Bonnet insulator clips X	\$	52.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6329 C

Towing Fee	\$	50.00	✓
Sundry	\$	50.00	20
To check for wiring and to focus head lamps	\$	80.00	20
To dismantle / replace exhaust pipe	\$	120.00	60
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, rear o/s fender, etc.	\$	1,600.00	1200
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear o/s fender, front bumper, bonnet grille, bonnet	\$	2,000.00	1620
To apply rustproofing on the repaired and replaced panels.	\$	250.00	50
	\$	<u>19,033.60</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahri 10/11/14
M 26/4/18 1530hr
8 Rep.
4/3
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: