

ASS. REC. BY:

REF:

CS/ET118007783/As.6n2

Special Instruction:

Surveyor

Adrian

## ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

TEL

Date/Time:

27042018 244pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

STX 313A

Insured:

YN 155S

at Workshop m/s

Cruise Autocare

Tel:

9760 8848

of

53 Ubi Ave1 #03-53

Policy No:

Claim No:

DSMCV1800828

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

27042018 2:50pm

Person Contacted:

Tock

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

STX 313A - X

YN 155S - CS/ET116012849/Kth3d1

D.O.A: 150416

08/11/18

Confirmed H/S \$1,800/- @ 4 days with Adrian.  
( \$592.24 Red - 25% )



**Catherine Chong (LKK Auto)**

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Friday, 27 April, 2018 2:44 PM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : YN155S / TP : SFX313A/LKK / DOA : 24/04/2018  
**Attachments:** YN155S - SAS.pdf; SFX313A - SAS.pdf; SFX313A - ESTIMATE.pdf; SFX313A - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **CRUISE AUTOCARE PTE LTD,**

ADDRESS : 53 UBI AVENUE 1  
#03-53 PAYA UBI INDUSTRIAL PARK  
SINGAPORE 408934

PERSON TO CONTACT : TOCK @ 9760 8848 / 6841 6760

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimates, insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# CRUISE AUTOCARE PTE LTD

## QUOTATION

MS: ERGO INSURANCE PTE LTD

TO: CLAIM DEPARTMENT

Fax: 6829 9247

*Shirley.*

Quotation No: QCA160184

Quote Date: 27-Apr-18

Contact No: 68416760

Fax No: 68413527

Veh No. SFX313A		Make / Model: VW GOLF		Page: 1 of 1.
<u>S/N</u>	<u>Description</u>	<u>LIST PRICE</u>	<u>Qty</u>	<u>Amount</u>
<b>PARTS</b>				
1	REAR BUMPER <i>Red</i>	827.65	1	\$792.00 ✓
2	REAR BUMPER RETAINER, RH <i>den</i>	\$35.65	1	\$35.65 ✓
3	REAR BUMPER REVERSE SENSOR, RH <i>den</i>	744.88	1	\$158.40 x
4	VW SPORT RIM <i>ut</i>	\$1,336.50	1	\$1,336.50
		<i>SA. 850</i>		<i>850 (sw)</i>

DISCOUNT GIVEN 10 %

(\$232.26)

### LABOUR

- 1 LABOUR TO PANEL BEAT REAR RH FENDER, REPLACE AND ALIGN PARTS
- 2 LABOUR TO REMOVE AND REPLACE TYRE
- 3 SPRAY PAINTING ON REAR BUMPER AND REAR RH FENDER

*750*

\$400.00 *300*

\$50.00

\$450.00 *400*

LUMP SUM DISCOUNT

(\$598.06)

*2990.30*

Sub Total \$2,392.24

GST @ 7% \$167.46

Total: **\$2,559.69**

Cruise Autocare Pte Ltd.

Signature of Customer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
53 Ubi Avenue 1, Paya Ubi Industrial Park #03-53 Singapore 408934  
Signature: TEL: 6841 6760 FAX: 6841 3527  
Date: Email: [cruiseac@singnet.com.sg](mailto:cruiseac@singnet.com.sg)

*Adnan Ling*  
*1/s 27/04/18.*

*04 days.*  
*total 2344.88*  
*1/s: 1.8K ✓*

# CRUISE AUTOCARE PTE LTD

## QUOTATION

MS: ERGO INSURANCE PTE LTD

TO: CLAIM DEPARTMENT

Fax: 6829 9247

Quotation No: QCA160184

Quote Date: 27-Apr-18

Contact No: 68416760

Fax No: 68413527

Veh No. SFX313A		Make / Model: VW GOLF		Page: 1 of 1.
S/N.	Description	LIST PRICE	Qty	Amount
<u>PARTS</u>				
1	REAR BUMPER	\$792.00	1	\$792.00
2	REAR BUMPER RETAINER, RH	\$35.65	1	\$35.65
3	REAR BUMPER REVERSE SENSOR, RH	\$158.40	1	\$158.40
4	VW SPORT RIM	\$1,336.50	1	\$1,336.50

DISCOUNT GIVEN 10 % (\$232.26)


<u>LABOUR</u>		
1	LABOUR TO PANEL BEAT REAR RH FENDER, REPLACE AND ALIGN	\$400.00
<u>PARTS</u>		
2	LABOUR TO REMOVE AND REPLACE TYRE	\$50.00
3	SPRAY PAINTING ON REAR BUMPER AND REAR RH FENDER	\$450.00

LUMP SUM DISCOUNT (\$588.06)

Sub Total \$2,392.24  
 GST @ 7% \$167.46  
 Total: \$2,559.69

Cruise Autocare Pte Ltd.

Signature of Customer





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18007783/Asbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 08-11-2018		
		Code : EGI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YN 155S	Veh. Inspected	SFX 313A	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1800828	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	27/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN GOLF	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WWWZZZAUZGW068101	Colour	BLUE	
Odometer	42735	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	PIRELLI	6 mm	
L/H Front Tyre	225/40 R18	PIRELLI	6 mm	
R/H Rear Tyre	225/40 R18	PIRELLI	6 mm	
L/H Rear Tyre	225/40 R18	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/04/2018	Inspection Date	27/04/2018	
Survey held at	CRUISE AUTOCARE PL 53 UBI AVE 1 PAYA UBI IND. PARK #03-53 SINGAPORE 408934			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFX 313A**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BUMPER	DEFORMED	792.00	792.00
1	REAR BUMPER RETAINER,RH	NECESSARY	35.65	35.65
1	REAR BUMPER REVERSE SENSOR,RH	NOT NECESSARY	158.40	-
	LESS 10% DISCOUNT		-98.60	-82.77
			887.45	744.88
1	VW SPORT RIM (SN)	CUT	1,336.50	850.00
	LESS 10% DISCOUNT		-133.65	-
			1,202.85	850.00
	<b>LABOUR</b>			
	LABOUR TO PANEL BEAT REAR RH FENDER,REPLACE AND ALIGN PARTS.		400.00	300.00
	LABOUR TO REMOVE AND REPLACE TYRE.		50.00	50.00
	SPRAY PAINTING ON REAR BUMPER AND REAR RH FENDER.		450.00	400.00
			900.00	750.00
	<b>GRAND TOTAL</b>		<b>2,990.30</b>	<b>2,344.88</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,800.00</b>

Report Ref No. CS/EGI18007783/Asbn2

**ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.