

Not Withheld
 1/1 Surp & ?
 Resurvey After Paint
 6 days



KHOO CHYE TENG
 BLK 218A #14-269
 BOON LAY AVENUE
 SINGAPORE 641218

File No :
 Date : 26-April-2018

Estimated cost of repair for vehicle no: **SJP5683T HYUNDAI HD AVANTE**
 Accident involving vehicle no: **SJP5683T & SDB5962H on 25-April-2018**

Description	Quantity	List Price
Bonnet	1	\$ Bu 1,017.00 ✓
Bonnet Insulator	1	\$ Sn 191.80 X
Bonnet insulator clips	1	\$ Nu 38.00 ✓
Bonnet Lock	1	\$ D-Y 87.90 ✓
LH bonnet hinge	1	\$ D-Y 78.20 ✓
LH front fender	1	\$ Bu 806.00 ✓
LH front fender badge 'VVT'	1	\$ Nu 34.40 ✓
Front support panel	1	\$ Bu 1 CM 791.30 ✓
LH head lamp	1	\$ My CM 456.80 ✓
Grille emblem	1	\$ CM 366.50 ✓
Grille clips @ 1 set	1	\$ Nu 28.00 ✓
Bumper	1	\$ Bu 1 CM 485.00 ✓
Air cleaner top air duct	1	\$ CM 124.50 ✓
Bumper insulator spongh	1	\$ CM 199.80 ✓
Bumper reinforcement	1	\$ Bu 354.00 ✓
Bumper center air grille	1	\$ D-Y 87.20 ✓
LH bumper cover	1	\$ D-Y 75.80 ✓
RH bumper cover	1	\$ Sn 75.80 X
Bumper bomttom duct panel	1	\$ 98.60 ?
LH bumper metal retainer	1	\$ Bu 38.90 ✓
LH bumper plastic retainer	1	\$ D-Y 79.20 ✓
Bumper clips @ 1 set	1	\$ Nu 38.00 ✓
LH condensor wind garnish	1	\$ 85.00 ?
RH front fender wheel cowlng	1	\$ CM 52.20 ✓
LH front fender wheel cowlng	1	\$ CM 52.20 ✓
Radiator	1	\$ 653.00 ?
Air condensor	1	\$ 975.75 ?
		\$ 7,370.85
		Less 10% \$ 737.08
		\$ 6,633.77
Radiator coolant water	1	SN \$ Nu 205a 35.00
Front number plate	1	SN \$ Bu 45.00 ✓
Towing charges	1	\$ 100.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

KHOO CHYE TENG
BLK 218A #14-269
BOON LAY AVENUE
SINGAPORE 641218

File No :
Date : 26-April-2018

Estimated cost of repair for vehicle no: SJP5683T HYUNDAI HD AVANTE
Accident involving vehicle no: SJP5683T & SDB5962H on 25-April-2018

Description	Quantity	List Price
To spray paint the front accident and repair areas	1	\$ <i>750</i> 850.00
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	1	\$ 35.00 <i>201</i>
To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality.	1	\$ 120.00 <i>1001</i>
Labour to remove radiator and check engine coolant fan, top up radiator coolant , install and check for functionality.	1	\$ 80.00 <i>501</i>
Labour to remove front damaged parts, jack out LH front chassis repair, panel beating, renew , install and adjust body bonnet bumper alignment.	1	\$ 950.00 <i>7001</i>
		<u>\$ 8,848.77</u>

T/Party: AIG ASIA PACIFIC INSURANCE PTE LTD