

22/03/2002

ASS. REC. BY:

REF:

CS/CTU18007789 / Ag bez

Special Instruction:

Surveyor

Maimun

Adam

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

27042018 2:49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDV 1116E

Insured:

SKZ 1166G

at Workshop m/s

Kah motor.

Tel:

6014 5687

of

15 ubi Rd 4

Policy No:

OMPcsN1603391802

Claim No:

SNM18D 0216400.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26042018

CA / REV / REP. / REV 24 HRS WP

30042018 @ 10.15am

H.O.D. Endorsement:

Date/Time:

27042018 3:10pm

Person Contacted:

Liew

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SDV 1116E - x

SKZ 1166G - x

01/6/18 @ 5:23pm. confirmed with Mr Liew final fig \$5223.32, 5 days.

CRed \$1478.44, 22%.

REF: CT2

ASSIGNMENT

From: Date: 30042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDV 1116E

at Workshop m/s Kah Motor

of 15 Ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: New

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: - % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SDV1116E.

Yr Regn: 2017 / May.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV

C.C 1486.

Colour

White.

A/C: Insured / Std / NI / NA

Sp. Reading

23327.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMR41810G X201969.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

215/60R16.

R:

215/60R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I.

30/04/18

Survey held at

Kah Motor.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chng.

Date/Time, File Pass to?

1) 04/6/18

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

5773.32)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Apr 2018		27 Apr 2018 14:49 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	IVY KUAH RONG XUAN		
Vehicle Reg. No.:	SDV1116E	Date of Loss:	26/04/2018 00:00 - :59
Claim Type:	TP / SNM18D02164C02	Policy/Cover Note No.:	DMPCSN1603391802
Vehicle Reg. No. (Insured):	SKZ1166G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/05/2018]		
Adj Asg. Remarks:	EST \$7162.30, ASSIGN LKK AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 1 June 2018 5:23 PM
To: 'Liew Thye Wui'; SUR
Cc: Faeaz
Subject: RE: PRE-INVOICE FOR VEHICLE SDV1116E

Dear Mr Liew,

Confirm final fig \$5,223.32 before GST and 5 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Liew Thye Wui [mailto:twliew@honda.com.sg]

Sent: Thursday, 31 May 2018 8:30 PM

To: SUR <sur@lkkauto.com>

Cc: Faeaz <faeaz@honda.com.sg>

Subject: PRE-INVOICE FOR VEHICLE SDV1116E

Dear Sir / Mdm,

We enclosed the total final repair costs of...

Vehicle No.	SDV1116E
Final Repair Costs (include GST)	\$5588.94
Repair Period*(Working Day)	05

*Note: Repair period does not include Sunday and Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Best Regards

TW LIEW

Kah Motor Co. Sdn. Bhd.

15 Ubi Road 4

Singapore 408610

DID: 6514 5687

Fax: 6748 0770

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/04/2018 10:03
Date Of Accident	26/04/2018 13:25
Exact Location Of Accident	SLIP ROAD BETWEEN PIE TUAS AND EUNOS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDV1116E
Insured/Policyholder	
Name Of Registered Owner	IVY KUAH RONG XUAN
NRIC No	S1208596F
Email Address	RXKUAH16@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96308486
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	HR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	GOING FOR TUITION
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V05680 / VPC2 / R00
Cover Note Number	

Driver

Name of Driver	IVY KUAH RONG XUAN
NRIC No	S1208596F
Date Of Birth	16/07/1955
Occupation	OUTDOOR
Date Of Driving Pass	10/01/2000
Driving Experience	18 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96308486
Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	RXKUAH16@GMAIL.COM

Address	BLK429, TAMPINES STREET 41 #06-485
Postcode	520429
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHMENT REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ1166G
Vehicle Make/Model/Colour	
Details Of Properties	FRONT
Vehicle Category	PRIVATE CAR
Name of Driver	GOH HO TIAN
NRIC/Passport Number	
Contact Number	91997633
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle No SDY1116ESKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Please continue to Annex E

Vehicle No SDVIII6E

Annex E

Describe Circumstances of the Accident

I was driving out from P1E Tuar into the slip road which is a zebra crossing waiting to drive out into the Eunos Road. Suddenly a car hit me near of my car.

Declaration

We declare the foregoing particulars are true in every respect.

27/4/2018

8.30am.

Policyholder's Signature / Date & Time

27/4/2018
8.30

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

30/4/18
a

10.15 Survey

01/6
a

0 * C

IN

0223

380G

14.47+
6.22+
3.52+
14.47+
9.6+
7.35+
5.25+
60.0+
629.17+
34.77+
8.62+
8.62+
9.67+
10.57+
8.02+

1

1,143.32*

mount
Id GST

0 * C

10.0+

80.0+

300.0+

150.0+

120.0+

250.0+

450.0+

250.0+

1,120.0+

✓ 15.48

1,350.0+

✓ 6.66

=

✓ 3.77

4,080.0*

✓ 15.48

✓ 10.27

✓ 7.86

1,143.32+

✓ 5.62

4,080.0+

✓ 64.20

=

✓ 673.21

5,223.32*

✓ 372.11

✓ 74.07

✓ 74.07

✓ 9.22

✓ 9.22

✓ 10.35

✓ 11.31

✓ 342.40

Sum Item 1593.74 111.56 1,705.30

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SDV1116E
Chassis No : JHMRU1810GX201969
Model : HRV DX-SIN CVT YM 2016
Owner's Name : IVY KUAH RONG XUAN
Ins Policy No. :
Date of Accident : 26/4/2018

Document No
Date
Customer No
Svc Advisor
Engine No
Date | Time
Surveyor Na
Survey Date
Authorisation

Item Description Qty Unit P

TP DIRECT SETTLEMENT (J/NO:)

OWNER: IVY KUAH RONG XUAN

OWNER INSURER: SD17V05680 / VPC2 / R00

ACC DATE: 26/4/18

SURVEYED BY:

DATE:

REF NO:

TP INSURER: CHINA TAIPING

TP VEH: SKZ1166G

73215-T7A-003 RUBBER CR.WINDSHIELD DAM 1 19.30
73226-SZW-000 DAMPERSTD 5X5 1 8.30
76711-T6A-003 CAPPIVOT 1 4.70
73254-T7J-H01 RUBBER CL.WINDSHIELD DAMPER 1 19.30
91501-S70-003 FASTENER BW/SHIELD 4 3.20
91502-S70-003 FASTENER B 2 4.90
91536-SS0-J01 FASTENER AW/SHIELD 2 3.50
BO-WS-SEALANT WINDSCREEN SEALANT (N) 1 60.00
68100-T7A-J20ZZ TAIL GATE COMP 1 838
04715-T7A-900ZZ FACE,RR.BUMPER 1 463
04717-T7A-000ZZ FACER,RR.BUMPER CORNER 1 92.00
04718-T7A-000ZZ FACEL,RR.BUMPER CORNER 1 92.00
71593-T7A-000 SPACERR,RR.BUMPER SIDE 1 11.50
71598-T7A-000 SPACERL,RR.BUMPER SIDE 1 11.50
75722-T7W-A01 EMBLEMRR. 1 12.90
75725-T8N-T00 EMBLEM,RR. I-VTEC 1 14.10
NMRS-4P-TM3040L 4PCS ACT RR.SENSOR 1 320.00

BOSUN SUNDRIES 1 30.00

rec

10

✓



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SDV1116E
Chassis No : JHMRU1810GX201969
Model : HRV DX-SIN CVT YM 2016
Owner's Name : IVY KUAH RONG XUAN
Ins Policy No. :
Date of Accident : 26/4/2018

Document No. : SQT18001741 Page 2
Date : 27. Apr 2018
Customer No. : WZC008
Svc Advisor : LIEW THYE WEI
Engine No : L15B4531972
Date | Time : 27. Apr 2018 10:23:13 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	320.00		320.00	22.40	342.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BOMISC1	REMOVE, CHECK AND INSTALL SMART ENTRY SENSOR.	1	450.00		450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50
BOMISC1	REMOVE, CHECK AND INSTALL RR CAMERA.	1	450.00		450.00	31.50	481.50
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1400.00		1400.00	98.00	1498.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1500.00		1500.00	105.00	1605.00
Sum Labor					5100.00	357.00	5,457.00

Survey By

Date & Time

Excess

Status

Signature

Adrian Lim
30/04/18
Not Authorised
[Signature]

05 Days.

Total Amount 6,693.74 468.56 7,162.30
Total (Inclusive of GST) 7,162.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 27/4/2018 11:13:00 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

6701-26

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

*5 days
Appr: Adrian***SERVICE PRE-INVOICE**GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMRU1810GX201969
License No: SDV1116E
Mileage: 23923
Engine No: L15B4531972

Document No: SVO18026123
Printed By: TWLIEW
Order Date: 7. May 2018
Order Time: 11:29:36 AM
Service Advisor: LIEW THYE WEI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70437) OWNER: IVY KUAH RONG XUAN OWNER INSURER: SD17V05680 / VPC2 / R00 ACC DATE: 26/4/18 SURVEYED BY: ADRIAN LING DATE: 30/4/18 REF NO: (SNM18D02164C02) TP INSURER: CHINA TAIPING TP VEH: SKZ1166G						
73215-T7A-003	RUBBER CR.WINDSHIELD DAM	✓	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	✓	8.30	25	6.22	0.44	6.66
76711-T6A-003	CAPPVOT	✓	4.70	25	3.52	0.25	3.77
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	✓	19.30	25	14.47	1.01	15.48
91501-S70-003	FASTENER BW/SHIELD	✓	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	✓	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	✓	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	✓	60.00		60.00	4.20	64.20
68100-T7A-J20ZZ	TAIL GATE COMP	✓	838.90	25	629.17	44.04	673.21
04715-T7A-900ZZ	FACE,RR.BUMPER	✓	463.70	25	347.77	24.34	372.11
71593-T7A-000	SPACERR.RR.BUMPER SIDE	✓	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	✓	11.50	25	8.62	0.60	9.22
75722-T7W-A01	EMBLEMRR.	✓	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	✓	14.10	25	10.57	0.74	11.31
75701-T5A-000	EMBLEMH (S) . <i>Nec</i>	✓	10.70	25	8.02	0.56	8.58
	SUM PARTS:				1,143.32	80.02	1,223.34
BOSUN	0672	✓	10.00		10.00	0.70	10.70
	SUNDRIES						
BML02I	EXT-YJ	✓	80.00		80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BG02D	EXT-YJ	✓	300.00		300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN. (N)						
BMI02D	EXT-YJ	✓	150.00		150.00	10.50	160.50
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)						
BA02R	EXT-YJ	✓	120.00		120.00	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOMISC1	0626	✓	250.00		250.00	17.50	267.50
	REMOVE, CHECK AND INSTALL SMART ENTRY SENSOR.						
BKTG02R	EXT-YJ	✓	450.00		450.00	31.50	481.50
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BOMISC1	EXT-YJ	✓	250.00		250.00	17.50	267.50
	REMOVE, CHECK AND INSTALL RR CAMERA.						

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMRU1810GX201969
License No: SDV1116E
Mileage: 23923
Engine No: L15B4531972

Document No: SVO18026123
Printed By: TWLIEW
Order Date: 7. May 2018
Order Time: 11:29:36 AM
Service Advisor: LIEW THYE WEI

BKRP02S	EXT-YJ STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1,120.00	1,120.00	78.40	1,198.40
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1,350.00	1,350.00	94.50	1,444.50
			SUM LABOUR:	4,080.00	285.60	4,365.60
			TOTAL SGD	5,223.32	365.62	5,588.94
Total Payable (SGD)						5,588.94

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18002106	Page	1
	3 ANSON ROAD #16-00	Date	: 23. May 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: LIEW THYE WEI		
Registration No	: SDV1116E	Engine No	: L15B4531972		
Chassis No	: JHMRU1810GX201969	Date Time	: 23. May 2018 7:18:23 PM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: IVY KUAH RONG XUAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 28/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
SUPPLEMENTARY LABOUR & PARTS							
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
Sum Item					8.02	0.56	8.58

Survey By	_____						
Date & Time	_____						
Excess	_____						
Status	_____						
Signature	_____						
Total Amount					8.02	0.56	8.58
Total (Inclusive of GST)							8.58

Printed on 31/5/2018 8:26:38 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Apr 2018		27 Apr 2018 14:49 Edit Adj Rpt	S\$5,223.32 Edit Estimates	S\$5,223.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	IVY KUAH RONG XUAN								
Vehicle Reg. No.:	SDV1116E	Date of Loss:	26/04/2018 00:00 - :59 [11 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02164C02	Policy/Cover Note No.:	DMPCSN1603391802						
Vehicle Reg. No. (Insured):	SKZ1166G	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/05/2018]								
Adj Asg. Remarks:	EST \$7162.30, ASSIGN LKK AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDV1116E (SNM18D02164C02)**
[SKZ1166G]

TP
IVY KUAH RONG XUAN
Apr 26 2018 12:00AM
 [-]
Kah Motor Co Sdn Bhd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/06/18 15:49	General View		Load JPG	
2	01/06/18 15:49	General View		Load JPG	
3	01/06/18 15:49	General View		Load JPG	
4	01/06/18 15:49	General View		Load JPG	
5	01/06/18 15:49	General View		Load JPG	
6	01/06/18 15:49	General View		Load JPG	
7	01/06/18 15:49	General View		Load JPG	
8	01/06/18 15:49	General View		Load JPG	
9	01/06/18 15:49	General View		Load JPG	
10	01/06/18 15:49	General View		Load JPG	
11	01/06/18 15:49	General View		Load JPG	
12	01/06/18 15:49	General View		Load JPG	
13	01/06/18 15:49	General View		Load JPG	
14	01/06/18 15:49	General View		Load JPG	
15	01/06/18 15:49	General View		Load JPG	
16	01/06/18 15:49	General View		Load JPG	
17	01/06/18 15:49	General View		Load JPG	
18	01/06/18 15:50	Reinspection Photo		Load JPG	
19	01/06/18 15:50	Reinspection Photo		Load JPG	
20	01/06/18 15:50	Reinspection Photo		Load JPG	
21	01/06/18 15:50	Reinspection Photo		Load JPG	

Documentation

1 per page

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/04/18 14:48	REPAIR EST		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/06/18 12:40	Supplementary		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; width: 100%; height: 80px;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18007789/AQBE2

Date: 05/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1603391802

Claimant Vehicle
No : SDV1116EInsured Vehicle
No : SKZ1166G

Date of Loss: 26/04/2018

Nature of Claim: TP

Claim
No: SNM18D02164C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDV1116E

Make & Model: HONDA HR-V, 1.5 (A)

Engine No: L15B4531972

Reg. Date: 02/05/2017 (Man. Year: 2016)

Chassis No: JHMRU1810GX201969

Colour: White

Odometer: 23327 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,631.76	1,153.32	478.44	29.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,070.00	4,070.00	1,000.00	19.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,701.76	5,223.32	1,478.44	22.06
+ GST 7.00/7.00% (S\$)	469.12	365.63	103.49	22.06
Nett Amount (S\$)	7,170.88	5,588.95	1,581.93	22.06

INSPECTION

Date of Assignment: 27/04/2018

Date Inspected: 30/04/2018 Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2018)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDV1116E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RUBBER CR.WINDSHIELD DAM	Necessary	14.47 FS	*14.47 FS
2	1		*DAMPERSTD 5X5	Necessary	6.22 FS	*6.22 FS
3	1		*CAPPIVOT	Necessary	3.52 FS	*3.52 FS
4	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
5	4		*FASTENER BW/SHIELD	Necessary	9.60 FS	*9.60 FS
6	1		*FASTENER B (2PCS)	Necessary	7.35 FS	*7.35 FS
7	1		*FASTENER AW/SHIELD (2PCS)	Necessary	5.25 FS	*5.25 FS
8	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
9	1		*TAIL GATE COMP	Distorted	629.17 FS	*629.17 FS
10	1		*FACE,RR BUMPER	Deformed	347.77 FS	*347.77 FS
11	1		*FACER.RR.BUMPER CORNER	Not Necessary	69.22 FS	*- FS
12	1		*FACEL.RR.BUMPER CORNER	Not Necessary	69.22 FS	*- FS
13	1		*SPACERR.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
14	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
15	1		*EMBLEMRR	Necessary	9.67 FS	*9.67 FS
16	1		*EMBLEM,RR. I-VTEC	Necessary	10.57 FS	*10.57 FS
17	1		*4PCS ACT RR SENSOR	Not Necessary	320.00 FS	*- FS
18	1		*SUNDRIES	Necessary	30.00 FS	*10.00 FS
19	1		*EMBLEMH	Necessary	8.02 FS	*8.02 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **1,631.76** **1,153.32**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	80.00	80.00
2	REMOVE & INSTALL RR WINDSCREEN	New	300.00	300.00
3	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	320.00	150.00
4	REMOVE & RENEW REVERSE SENSORS - 4 PCS	New	120.00	120.00
5	REMOVE, CHECK AND INSTALL SMART ENTRY SENSOR	New	450.00	250.00
6	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	450.00	450.00
7	REMOVE, CHECK AND INSTALL RR CAMERA	New	450.00	250.00
8	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	1,400.00	1,120.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)	New	1,500.00	1,350.00
Gross Labour Cost (\$\$)			5,070.00	4,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >