



FALCON-AIR

LOW HONG AI
21 WOODLEIGH CLOSE #07-05
SINGAPORE 357916

Attention : Motor Claim Department
Contact : 98625973

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

Estimate : ES003166

Date : 27/04/2018
Vehicle Num. : SKC8918D
Make/Model : MERC BENZ C180-2012
Chassis/Eng# : WDD2040312A742407
Accident Date : 25/04/2018
Claim No. :
Reference : NTUC VS NTUC *EQ*
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

NETT ITEMS :				
1.	1	LH TAILLAMP		680.00 <i>cre</i>
2.	1	REAR BUMPER		1,285.00 <i>dl</i>
3.	1	REAR BUMPER CHROME CENTRE		175.00 <i>nd</i>
4.	2	REAR BUMPER CHROME MOULDING	125.00	250.00 <i>mt</i>
5.	1	REAR BUMPER SIDE RETAINER LH		35.00 <i>rel</i>
6.	1	REAR BUMPER REINFORCEMENT		635.00 <i>?</i>
7.	1	EXHAUST HEAT SHIELD		60.00 <i>?</i>
8.	1	REVERSE SENSOR		200.00 <i>nm</i>

Nett Total S\$:

3,320.00

10.00% Discount S\$:

332.00

2,988.00

LABOUR :

TO RESPRAY ACCIDENT DAMAGED AREAS
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING
TO REPAIR REAR END PANEL LH. REAR FENDER LH INCLUDES
KNOCKING & REPLACEMENT OF PARTS

750.00 *600*

100.00 *40*

550.00 *400*

Labour Total S\$:

1,400.00

E. & O.E.

Total S\$: 4,388.00



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Tanpin 97495749

Resurvey before paint up

7/5/18 @ 1pm

4 days

See @ Yuhant-ccr