

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 26/04/2018
TP Vehicle No. : SJL-5231-K
To : EQ INSURANCE COMPANY LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : MOHAMED AKBAR ALI S/O MASAVOO HAJAMAIDEEN
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5092783979
Vehicle No. : SLR-1415-T
Make & Model : TOYOTA HARRIER 2.0 PREMIUM 2WD CVT

Accident Date: 25/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	REAR BUMPER	\$1,385.67	—
1	REAR BUMPER LOWER GARNISH	\$350.20	X
1	REAR BUMPER RETAINER RH	\$85.70	X
1	REAR BUMPER RETAINER LH	\$85.70	X
10	REAR BUMPER CLIPS	\$70.00	—
1	REAR BUMPER REFLECTOR RH	\$56.30	X
1	REAR BUMPER REFLECTOR LH	\$56.30	X
1	REAR BUMPER EMBLEM "HARRIER"	\$73.70	X
1	TAILGATE	\$2,378.00	X
1	TAILGATE WEATHER	\$441.30	X
1	TAILGATE GLASS MOULDING	\$165.90	X
1	TAILLAMP RH	\$270.50	X
1	TAILLAMP LH	\$270.50	X
1	REAR END PANEL	\$715.30	X
1	REAR END PANEL TOP GARNISH	\$438.25	X
10	REAR END PANEL TOP GARNISH CLIPS	\$50.00	X
Sub Total		\$6,893.32	1455.67
Discount 25% on Parts		(\$1,723.33)	363.92
		\$5,169.99	1091.75

Special Nett

1	REAR BUMPER REVERSE SENSOR	\$350.00	200
1	REAR NUMBER PLATE & CASEING	\$45.00	X
1	REAR REVERSE CAMERA	\$450.00	300
Sub Total		\$845.00	500.00

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,800.00	300
TO SPRAY PAINT ON AFFECTED AREAS	\$1,800.00	400

Date : 26/04/2018
 TP Vehicle No. : SJL-5231-K
 To : EQ INSURANCE COMPANY LTD
 Attn : Motor Claim Department

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Owner : MOHAMED AKBAR ALI S/O MASAVOO HAJAMAIDEEN
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5092783979
 Vehicle No. : SLR-1415-T
 Make & Model : TOYOTA HARRIER 2.0 PREMIUM 2WD CVT

Accident Date: 25/04/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO TRANSFER ALL REAR TAILGATE, LH REAR SLIDING DOOR FITTING TO NEW	11 \$250.00	X
	TO REMOVE AND INSTALL REAR WINDSCREEN	11 \$150.00	X
	TO REALIGN REAR END PANEL AND REAR BOOT LID	\$150.00	60
	TO CHECK LIGHTING AND FOCUS TAILAMP	\$150.00	20
	TO DETACH & RENEW REVERSE SENSOR	\$150.00	50
	Sub Total	\$4,450.00	830.00
	Sub Total	\$10,464.99	2421.75
	GST 7%	\$732.55	
	Total	\$11,197.54	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: