

Please arrange to survey vehicle at  
8 KAKI BUKIT AVENUE 4 - GATE 2  
#07-48 PREMIER @ KAKI BUKIT  
SINGAPORE 415875



Date : 26/04/2018  
TP Vehicle No. : SJL-5231-K  
To : **EQ INSURANCE COMPANY LTD**  
Attn : **Motor Claim Department**

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Owner : MOHAMED AKBAR ALI S/O MASAVOO HAJAMAIDEEN  
NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No. : 5092783979  
Vehicle No. : SLR-1415-T  
Make & Model : TOYOTA HARRIER 2.0 PREMIUM 2WD CVT

Accident Date: 25/04/2018

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

### List Item

1	REAR BUMPER	\$1,385.67
1	REAR BUMPER LOWER GARNISH	\$350.20
1	REAR BUMPER RETAINER RH	\$85.70
1	REAR BUMPER RETAINER LH	\$85.70
10	REAR BUMPER CLIPS	\$70.00
1	REAR BUMPER REFLECTOR RH	\$56.30
1	REAR BUMPER REFLECTOR LH	\$56.30
1	REAR BUMPER EMBLEM " HARRIER"	\$73.70
1	TAILGATE	\$2,378.00
1	TAILGATE WEATHER	\$441.30
1	TAILGATE GLASS MOULDING	\$165.90
1	TAILLAMP RH	\$270.50
1	TAILLAMP LH	\$270.50
1	REAR END PANEL	\$715.30
1	REAR END PANEL TOP GARNISH	\$438.25
10	REAR END PANEL TOP GARNISH CLIPS	\$50.00
<b>Sub Total</b>		<b>\$6,893.32</b>
<b>Discount 25% on Parts</b>		<b>(\$1,723.33)</b>
		<b>\$5,169.99</b>

### Special Nett

1	REAR BUMPER REVERSE SENSOR	\$350.00
1	REAR NUMBER PLATE & CASEING	\$45.00
1	REAR REVERSE CAMERA	\$450.00
<b>Sub Total</b>		<b>\$845.00</b>

### Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,800.00
TO SPRAY PAINT ON AFFECTED AREAS	\$1,800.00

LINDA LIAO  
ABWIN SERVICE PTE LTD  
DID: 67139417  
Fax: 67139415  
HP: 97519596

Date : 26/04/2018  
TP Vehicle No. : SJL-5231-K  
To : **EQ INSURANCE COMPANY LTD**  
Attn : **Motor Claim Department**

Owner : MOHAMED AKBAR ALI S/O MASAVOO HAJAMAIDEEN  
NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Certificate No. : 5092783979  
Vehicle No. : SLR-1415-T  
Make & Model : TOYOTA HARRIER 2.0 PREMIUM 2WD CVT

Accident Date: 25/04/2018

## ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO TRANSFER ALL REAR TAILGATE, LH REAR SLIDING DOOR FITTING TO NEW	\$250.00	
	TO REMOVE AND INSTALL REAR WINDSCREEN	\$150.00	
	TO REALIGN REAR END PANEL AND REAR BOOT LID	\$150.00	
	TO CHECK LIGHTING AND FOCUS TAILAMP	\$150.00	
	TO DETACH & RENEW REVERSE SENSOR	\$150.00	
	<b>Sub Total</b>	<b>\$4,450.00</b>	
	<b>Sub Total</b>	<b>\$10,464.99</b>	
	<b>GST 7%</b>	<b>\$732.55</b>	
	<b>Total</b>	<b>\$11,197.54</b>	