

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 26/04/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D18MTHCVE000138 Accident Date : 23/04/2018
Vehicle No : YP -1424-Z Make & Model : ISUZU NMR85UH5A 3.0 Y (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	FRONT BUMPER	1,529.00	sch-
10	FRONT BUMPER CLIP	40.00	me-
1	FRONT BUMPER LAMP LH	525.00	7?
1	FRONT BUMPER LAMP BRACKET LH	186.00	X
1	HEADLAMP LH	984.00	pro-
1	HEADLAMP LOWER SEAL LH	157.00	DE-
1	SIGNAL LAMP LH	630.00	pro-
1	CORNER PANEL LH	690.00	sch-
1	STEP PANEL LH	395.00	sur-

Date : 26/04/2018

To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTHCVE000138

Accident Date : 23/04/2018

Vehicle No : YP -1424-Z

Make & Model : ISUZU NMR85UH5A 3.0 Y (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	STEP PANEL REFLECTOR LH	121.00	scr /
1	DOOR LH	1,650.00	BA /
1	DOOR LAMP LH	215.00	scr /
1	DOOR RUBBER LH	280.00	na /
1	DOOR HINGE LH (UPPER)	185.00	X
1	DOOR HINGE LH (LOWER)	185.00	X
1	DOOR ARCH GARNISH LH	389.00	scr /
1	DOOR CHECKER LH	175.00	X
1	"A" PILLAR LH	995.00	X
1	FRT WINDSCREEN MOULDING	205.00	X

Date : 26/04/2018

To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTHCVE000138

Accident Date : 23/04/2018

Vehicle No : YP -1424-Z

Make & Model : ISUZU NMR85UH5A 3.0 Y (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAIL LAMP LH	380.00	FA CLA -
1	TAIL LAMP RH	380.00	FA CLA -
2	REAR NUMBER PLATE LAMP	310.00	FA CLA -
2	REAR NUMBER PLATE LAMP COVER	178.00	FA CLA -
1	REAR NUMBER PLATE LAMP BRACKET	228.00	FA CLA -
1	REAR LAMP WIRING HARNESS	689.00	X
1	REAR CHASSIS CROSSMEMBER	1,210.00	R
1	REAR TOWING HOOK	412.00	R
1	REAR EXHAUST PIPE	984.00	FA CLA -
1	REAR EXHAUST PIPE RING BRACKET	182.00	FA CLA -

Date : 26/04/2018

To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTHCVE000138

Accident Date : 23/04/2018

Vehicle No : YP -1424-Z

Make & Model : ISUZU NMR85UH5A 3.0 Y (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR EXHAUST PIPE HOLDER BRACKET	158.00	Dis ✓
1	REAR EXHAUST PIPE MOUNTING	85.00	ne ✓
1	REAR STABILIZER BAR	782.00	PA ✓
2	REAR STABILIZER BAR BUSH	110.00	ner ✓
1	REAR STABILIZER BAR BUSH BRACKET	320.00	X
1	REAR EXHAUST PIPE EXTENSION	580.00	PA ?
1	REAR EXHAUST BOX	1,180.00	X
1	REAR EXHAUST DPD FILTER ASSY	8,500.00	X
1	REAR AXLE	3,850.00	?
1	REAR SHOCK ABSORBER	588.00	PA ✓

Date : 26/04/2018

To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTHCVE000138

Accident Date : 23/04/2018

Vehicle No : YP -1424-Z

Make & Model : ISUZU NMR85UH5A 3.0 Y (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	REAR LEAF SPRING ASSY	2,620.00	X
1	SPARE WHEEL CARRIER ASSY	684.00	PA -
1	SPARE WHEEL CARRIER MEMBER	950.00	PA -
4	REAR LEAF SPRING U BOLT	1,136.00	X
8	REAR LEAF SPRING U BOLT NUT	200.00	X
2	REAR LEAF SPRING SHACKLE	960.00	X
2	REAR LEAF SPRING BRACKET	576.00	X
8	REAR LEAF SPRING BUSH	656.00	X
1	PROPELLER SHAFT (FRT)	1,850.00	X
1	PROPELLER SHAFT (REAR)	2,380.00	X

Date : 26/04/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D18MTHCVE000138 Accident Date : 23/04/2018
Vehicle No : YP -1424-Z Make & Model : ISUZU NMR85UH5A 3.0 Y (M)
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	PROPELLER CENTRE BEARING	452.00	X
	Sub Total	43106.00	
	Discount 15% On Parts	(6465.90)	
	<u>Special Nett Item</u>		
1	FRONT STEEL RIM LH	894.00	R
1	FRONT STEEL RIM NUT LH (SET)	468.00	X
1	REAR BUMPER GUARD	1200 1,800.00	PA -
2	REAR BUMPER GUARD BRACKET	450 900.00	PA -
1	REAR NUMBER PLATE	35.00	PA -
1	REAR STEP WOODEN PLANK	300 550.00	CRA -

Date : 26/04/2018

To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTHCVE000138

Accident Date : 23/04/2018

Vehicle No : YP -1424-Z

Make & Model : ISUZU NMR85UH5A 3.0 Y (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAILGATE WOODEN LOWER BLOCK	950.00	cut -
2	REAR CHASSIS WOODEN BLOCK	5,000.00	? photo
1	TAILGATE LOWER MEMBER	1,350.00	X
2	REAR CHASSIS WOODEN BLOCK U BOLT	500.00	?
2	REAR CHASSIS WOODEN BLOCK BRACKET	700.00	?
1	REAR AXLE OIL	180.00	?
1	SPARE WHEEL	550.00	70% cut -
1	BRAKE FLUID	20.00	ac -
1	TOWING FEE	80.00	
1	ADVERTISEMENT STICKER	500.00	150250

Date : 26/04/2018

To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTHCVE000138

Accident Date : 23/04/2018

Vehicle No : YP -1424-Z

Make & Model : ISUZU NMR85UH5A 3.0 Y (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	14477.00	
	Labour & Misc		
	LABOUR TO CARRY OUT FRONT REPAIR	1,100.00	600
	LABOUR TO CARRY OUT REAR REPAIR	2,400.00	2200
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	
	TO SPRAY PAINT ON AFFECTED AREAS	1,200.00	600
	TO TRANSFER FRONT DOOR (LH) FITTING	150.00	80
	TO REPAIR CHASSIS FRAME	400.00	200 300
	TO REMOVE & RENEW REAR EXHAUST COMPONENTS	150.00	80
	TO FACILITATE REPAIR		

Date : 26/04/2018

To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D18MTHCVE000138

Accident Date : 23/04/2018

Vehicle No : YP -1424-Z

Make & Model : ISUZU NMR85UH5A 3.0 Y (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO REMOVE & RENEW REAR UNDERCARRIAGE LH RH TO ASSIST REPAIR	400.00	3200
	TO REMOVE & RENEW REAR AXLE TO ASSIST REPAIR	400.00	200
	TO REMOVE & RE-INSTALL DASHBOARD TO ASSIST REPAIR	350.00	X
	SPRAY RUST PROOF ON AFFECTED AREA	60.00	40
	TO REMOVE & REFIT ALL NECESSARY TRIM BOARDS, GARNISH, CARPET, FLOOR MATS & SEAT	150.00	X
	TO REMOVE & INSTALL FRONT WINDSCREEN GLASS	250.00	X
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	100.00	80

Date : 26/04/2018
To : AXA INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D18MTHCVE000138 Accident Date : 23/04/2018
Vehicle No : YP -1424-Z Make & Model : ISUZU NMR85UH5A 3.0 Y (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	7145.00	

58,262.10

Remarks:

19 days - Lumpsum

SUB TOTAL

GST 7.0 % 4,078.35

TOTAL 62,340.45

Surveyor's name:

Rasul - Hp 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

27/04/18 @ 1730

Reg after repair

PAGE : 10