

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002504

Date : 11/06/2018

Vehicle Num. : XE3805P

Make/Model : MITSUBISHI FP 51-2017

Chassis/Eng# : FP51SDA20245/OM457342170

Accident Date : 23/04/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BUMPER		bt 2,779.71
2.	1	BUMPER SIDE		cut 129.10
3.	1	BUMPER TOP PANEL, RHS		lats 208.07
4.	1	BUMPER TOP GARNISH		mis 177.66
5.	1	BUMPER TOP PANEL, CENTRE		X 814.26
6.	1	BUMPER TOP GARNISH, CENTRE		X 251.38
7.	1	HEADLAMP, RHS		X 1,183.88
8.	1	HEADLAMP BEZEL		de 193.72
9.	1	BUMPER SPOTLAMP		X 271.25
10.	1	BUMPER SPOTLAMP COVER		X 171.25
11.	1	HEADLAMP BRACKET		X 872.05
12.	1	BUMPER COVER RH		X 281.50

List TotalS\$:

7,333.83

25.00% Discount S\$:

1,833.46

5,500.37

LABOUR :

TO PANEL BEAT/REPAIR RH BODY

300 450.00

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

300 550.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002504

Date : 11/06/2018

Vehicle Num. : XE3805P

Make/Model : MITSUBISHI FP 51-2017

Chassis/Eng# : FP51SDA20245/OM457342170

Accident Date : 23/04/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LOSS OF USE : 3 DAYS @ \$ 250/DAY

Labour Total S\$:

1,000.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjin 9749 5749
 'wp'
 Lumpy
 Resurvey after repair
 03 days
 sue@lkkauto.com
 11/6/18 @ Spm.

Total S\$: 6,500.37

=====

SIN SHENG ENGINEERING SERVICES